

OWNER: PT. PREMIAIR
ADDRESS: TERMINAL BUILDING B33
 JAKARTA 13610
PHONE:
FAX:

OPERATOR: PT. PREMIAIR
ADDRESS: TERMINAL BUILDING B33
 JAKARTA 13610
PHONE:
FAX:

ANALYST: SHAHAB ABBASI
EMAIL: SABBASI@CAMPSYSTEMS.COM

514-636-2020 (OFFICE)
 514-636-7866 (FAX)
 WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
 631-980-4222 (EFAX-CARDS)

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

AIRCRAFT SERIAL/REGNO: 14501134/PK-RJA **MODEL:** EMB-135BJ - LEGACY 650 **MANUFACTURER:** EMBRAER

DATES		LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE:	16-DEC-2010	903.3 A/C HRS	as of 18-MAR-2017	A/C HRS	as of ___/___/___
		450 AFL	as of 18-MAR-2017	AFL	as of ___/___/___

APU SERIAL/PART: SP-E1028096/4504113A **MODEL:** APS500R/T-62T-40C14 **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 04-NOV-2010		LAST ACTUALS		CURRENT ACTUAL	
1.2 APU HRS		1300 APU HRS	as of 18-MAR-2017	APU HRS	as of ___/___/___
4 APUS		1290 APUS	as of 18-MAR-2017	APUS	as of ___/___/___

ENGINE NO. 1 SERIAL/PART: CAE-313249/23087636 **MODEL:** AE3007A2 **MANUFACTURER:** ROLLS ROYCE

INSTALLED ON 04-NOV-2010		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	903.3 ENG. HRS	as of 18-MAR-2017	ENG. HRS	as of ___/___/___
0 ENC		450 ENC	as of 18-MAR-2017	ENC	as of ___/___/___

ENGINE NO. 2 SERIAL/PART: CAE-313246/23087636 **MODEL:** AE3007A2 **MANUFACTURER:** ROLLS ROYCE

INSTALLED ON 03-NOV-2010		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	903.3 ENG. HRS	as of 18-MAR-2017	ENG. HRS	as of ___/___/___
0 ENC		450 ENC	as of 18-MAR-2017	ENC	as of ___/___/___



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
CHAPTER 05	TIME LIMITS/MAINTENANCE CHECKS								
05-LU06	LOW UTILIZATION-LU6						LOW UTILIZATION		
	PKG 5001	MOS	6	+15d/-15d	-36	21-JAN-2017	16-JUN-2017	01-JUL-2017	67 d
		HRS/MSC	250	+20/-20		884.1	1134.1	1154.1	230.8
	REF:	AFL				443			
05-LU12	LOW UTILIZATION-LU12						LOW UTILIZATION		
	PKG 5002	MOS	12	+15d/-15d	-13	21-JAN-2017	08-JAN-2018	23-JAN-2018	273 d
		HRS/MSC	900	+20/-20		884.1	1784.1	1804.1	880.8
	REF:	AFL	450	+20/-20		443	893	913	443
05-LU144	LOW UTILIZATION-LU144						LOW UTILIZATION		
	PKG 5024	MOS	144	+15d/-15d		16-DEC-2010	16-DEC-2022	31-DEC-2022	2076 d
		HRS/MSC	10800	+20/-20		0	10800	10820	9896.7
	REF:	AFL	5400	+20/-20		0	5400	5420	4950
05-LU192	LOW UTILIZATION-LU192						LOW UTILIZATION		
	PKG 5032	MOS	192	+15d/-15d		16-DEC-2010	16-DEC-2026	31-DEC-2026	3537 d
		HRS/MSC	14400	+20/-20		0	14400	14420	13496.7
	REF:	AFL	7200	+20/-20		0	7200	7220	6750
05-LU24	LOW UTILIZATION-LU24						LOW UTILIZATION		
	PKG 5004	MOS	24	+15d/-15d	-36	21-JAN-2017	16-DEC-2018	31-DEC-2018	615 d
		HRS/MSC	1000	+20/-20		884.1	1884.1	1904.1	980.8
	REF:	AFL				443			
05-LU288	LOW UTILIZATION-LU288						LOW UTILIZATION		
	PKG 5140	MOS	288			16-DEC-2010	16-DEC-2034		6459 d
		HRS/MSC	12000			0	12000		11096.7
	REF: SMRD LU 288 PACKAGE	AFL	6000			0	6000		5550
05-LU48	LOW UTILIZATION-LU48						LOW UTILIZATION		
	PKG 5008	MOS	48	+15d/-15d	-41	26-JAN-2015	16-DEC-2018	31-DEC-2018	615 d
		HRS/MSC	2000	+20/-20		532.4	2532.4	2552.4	1629.1
	REF:	AFL	1000	+20/-20		280	1280	1300	830
+ 05-LU48T288	THRESHOLD 288 MOS LOW UTILIZATION-L8						LOW UTILIZATION		
	PKG 5011	MOS	288	+15d/-15d			?		? ?
		HRS/MSC	12000	+20/-20			12000	12020	11096.7
	REF:	AFL	6000	+20/-20			6000	6020	5550

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
+ 05-LU48T96	THRESHOLD 96 MOS LOW UTILIZATION-LU48								
	PKG 5009	MOS	96	+15d/-15d		16-DEC-2010	LOW UTILIZATION	31-DEC-2018	615 d
		HRS/MSC	4000	+20/-20		0	4000	4020	3096.7
	REF:	AFL	2000	+20/-20		0	2000	2020	1550
05-LU72	LOW UTILIZATION-LU72								
	PKG 5012	MOS	72	+15d/-15d	-36	21-JAN-2017	LOW UTILIZATION	31-DEC-2022	2076 d
		HRS/MSC	5400	+20/-20		884.1	6284.1	6304.1	5380.8
	REF:	AFL	2700	+20/-20		443	3143	3163	2693
05-LU96	LOW UTILIZATION-LU96								
	PKG 5016	MOS	96	+15d/-15d		16-DEC-2010	LOW UTILIZATION	31-DEC-2018	615 d
		HRS/MSC	4000	+20/-20		0	4000	4020	3096.7
	REF:	AFL	2000	+20/-20		0	2000	2020	1550
05ROUTINE	ROUTINE INSPECTION REQUIREMENTS								
	PKG 1	MOS							
		HRS/MSC	A/R						
	REF:	AFL							



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
CHAPTER 00	INFORMATION									
00DC03	PERFORM DCA ENGINEERING TASK 00DC03R1 (SEE ATTACHMENT) BACKGROUND INFORMATION: THE REGULATORY AUTHORITIES MANDATE AN INSPECTION OF LAVATORY EQUIPMENT TO PREVENT A POSSIBLE FIRE HAZARD. THE REQUIREMENTS DISPLAYED IN THIS DCA TASK CARD WERE ACCOMPLISHED ON EMB 135 BJ FROM THE DATE OF DELIVERY BY ACCOMPLISHMENT OF FAA AD 74-08-09 & LTA D-2012-237.									
NATIONAL REQUIREMENT	REF:	MOS HRS/MSC AFL	1000				27-AUG-2012 79.02 63	1079.02		175.72
00DC04	UPDATE NAVIGATION DATABASE									
	REF:	DAYS HRS/MSC AFL	28	+10/-10			18-MAR-2017 903.3 450	15-APR-2017	25-APR-2017 5 d	(+10)
E135-120710	REVIEW MPG/SMRD REVISION 8 - CAMP CHANGE FORM									
REQUIREMENT CHANGE FORMS	REF: RCF E135	MOS HRS/MSC AFL	-				06-NOV-2012			
E135-121116	REVIEW MPG/SMRD TR 8-1 - CAMP CHANGE FORM									
REQUIREMENT CHANGE FORMS	REF: RCF E135	MOS HRS/MSC AFL	-				(EBT)			
E135-130215	REVIEW SMRD/MPG TR8-2 - CAMP CHANGE FORM									
REQUIREMENT CHANGE FORMS	REF: RCF E135	MOS HRS/MSC AFL	-				(EBT)			
E135-160422	REVIEW EMBRAER 135 (LEGACY 600/650) SMRD-1533, TR 11-2 DATED APRIL 22/16 AND MPG-1483, TR 11-3 DATED APRIL 22/16 - REQUIREMENT CHANGE FORM									
REQUIREMENT CHANGE FORMS	REF: RCF E135-160422	MOS HRS/MSC AFL	-				(EBT)			
E135-160829	REVIEW EMBRAER 135 - LEGACY 600/650 (E135) MISCELLANEOUS CORRECTIONS REQUIREMENT SUMMARY CHANGE FORM									
REQUIREMENT CHANGE FORMS	REF: RCF E135-160829	MOS HRS/MSC AFL	-				(EBT)			
APU Model : APS500R/T-62T-40C14 Serial # SP-E1028096 Part # 4504113A										
A135-160301	APU - REVIEW T-62T-40C14 EM REV 13									
REQUIREMENT CHANGE FORMS	REF: RCF A135	MOS HRS/MSC APUS	-							
ENGINE NO. 1 Model : AE3007A2 Serial # CAE-313249 Part # 23087636										



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
E307-121020	NO. 1 ENGINE - REVIEW	EMM TRANSMITTAL LETTER NO.64 - CAMP CHANGE FORM						29-JAN-2013		
REQUIREMENT CHANGE FORMS	REF: RCF E307	MOS HRS/MSC - ENC								
E307-130307	NO. 1 ENGINE - REVIEW	RR AE 3007A MAINTENANCE MANUAL REV.65 - CAMP CHANGE FORM					(EBT)			
REQUIREMENT CHANGE FORMS	REF: RCF E307	MOS HRS/MSC - ENC								
E307-160420	NO. 1 ENGINE - REVIEW	AE3007A MM REV 78					(EBT)			
REQUIREMENT CHANGE FORMS	REF: RCF E307	MOS HRS/MSC - ENC								
E307-160720	NO. 1 ENGINE - REVIEW	AE3700A MM REV 79					(EBT)			
REQUIREMENT CHANGE FORMS	REF: RCF E307	MOS HRS/MSC - ENC								
ENGINE NO. 2 Model : AE3007A2 Serial # CAE-313246 Part # 23087636										
E307-121020	NO. 2 ENGINE - REVIEW	EMM TRANSMITTAL LETTER NO.64 - CAMP CHANGE FORM						29-JAN-2013		
REQUIREMENT CHANGE FORMS	REF: RCF E307	MOS HRS/MSC - ENC								
E307-130307	NO. 2 ENGINE - REVIEW	RR AE 3007A MAINTENANCE MANUAL REV.65 - CAMP CHANGE FORM					(EBT)			
REQUIREMENT CHANGE FORMS	REF: RCF E307	MOS HRS/MSC - ENC								
E307-160420	NO. 2 ENGINE - REVIEW	AE3007A MM REV 78					(EBT)			
REQUIREMENT CHANGE FORMS	REF: RCF E307	MOS HRS/MSC - ENC								
E307-160720	NO. 2 ENGINE - REVIEW	AE3700A MM REV 79					(EBT)			
REQUIREMENT CHANGE FORMS	REF: RCF E307	MOS HRS/MSC - ENC								
CHAPTER 08 LEVELING AND WEIGHING										
08DC01	PERFORM WEIGHT AND BALANCE UPDATE (AIRCRAFT WEIGHING)									
NATIONAL REQUIREMENT	REF:	MOS HRS/MSC AFL	48				26-JAN-2015 532.4 280	26-JAN-2019		656 d
CHAPTER 12 SERVICING										

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
12-13-01-610-001-A00 (s)	SERVICE (REPLENISH) HYDRAULIC SYSTEM RESERVOIR						PKG			
	PKG 5001	MOS	6				21-JAN-2017			
		HRS/MSC	250				884.1			
SYSTEM	REF: AMM 12-13-01	AFL					443			
CHAPTER 20	STANDARD PRACTICES - AIRFRAME									
20-00-00-140-002-A00 (s)	RESTORE (CLEANING) CENTER FUSELAGE III LOWER SIDE INCLUDING WIRING, LINES AND OMEGA BEAMS (ZONES: 151, 152, 153, 154, 155, 156, 157). NOTE: EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 05-40-01	AFL	1800	+20/-20			280			
20-00-00-140-003-A00 (s)	RESTORE (CLEANING) CENTER FUSELAGE IV LOWER SIDE INCLUDING WIRING, LINES AND OMEGA BEAMS (ZONES: 161, 162). NOTE: EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 05-40-02	AFL	1800	+20/-20			280			
20-00-00-140-004-A00 (s)	RESTORE (CLEANING) CENTER FUSELAGE IV UPPER AND LATERAL SIDE INCLUDING ELT UNIT (ZONES: 262, 263, 264). NOTE: EWIS.(L650 ONLY)						PKG			
	PKG 5016	MOS	96	+15d/-15d			26-JAN-2015			
		HRS/MSC	7200	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 05-40-03	AFL	3600	+20/-20			280			
20-00-00-140-005-A00 (s)	RESTORE (CLEANING) REAR FUSELAGE I LOWER SIDE, INCLUDING WIRING AND LINES (ZONES: 171, 172). NOTE: EWIS .(L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 05-40-04	AFL	1800	+20/-20			280			
20-00-00-140-006-A00 (s)	RESTORE (CLEANING) REAR FUSELAGE I LATERAL SIDE, INCLUDING ELECTRONIC REAR COMPARTMENT WIRING (ZONES: 271, 272). NOTE: EWIS.(L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 05-40-05	AFL	1800	+20/-20			280			
20-00-00-140-007-A00 (s)	RESTORE (CLEANING) CENTER FUSELAGE II LOWER SIDE INCLUDING WIRING, LINES AND OMEGA BEAMS (ZONES: 141, 142). NOTE: EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 05-40-10	AFL	1800	+20/-20			280			
20-00-00-140-008-A00 (s)	RESTORE (CLEANING) CENTER FUSELAGE I LOWER SIDE INCLUDING WIRING, LINES AND OMEGA BEAMS (ZONES: 131, 132). NOTE: EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 05-40-14	AFL	1800	+20/-20			280			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-00-00-140-009-A00 (s)	RESTORE (CLEANING) NLG & FWD ELECTRONIC COMPARTMENTS, FWD PRESSURE BULKHEAD UPPER SIDE (ZONES: 113, 114, 213, 214, 215, 216). NOTE: EWIS.(L650 ONLY)						PKG			
	PKG 5016	MOS	96	+15d/-15d						
LOW UTILIZATION	REF: AMM 05-40-11	HRS/MSC	7200	+20/-20						
		AFL	3600	+20/-20						
20-00-00-140-010-A00 (s)	RESTORE (CLEANING) COCKPIT LATERAL SIDE AND FWD PRESSURE BULKHEAD UPPER SIDE (ZONES: 221, 222, 223, 224). NOTE: EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d				26-JAN-2015		
LOW UTILIZATION	REF: AMM 05-40-13	HRS/MSC	3600	+20/-20				532.4		
		AFL	1800	+20/-20				280		
20-00-00-140-011-A00 (s)	RESTORE (CLEANING) COCKPIT LOWER SIDE AND FWD PRESSURE BULKHEAD LOWER SIDE (ZONES: 121, 122, 123, 124) NOTE: EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d				26-JAN-2015		
LOW UTILIZATION	REF: AMM 05-40-12	HRS/MSC	3600	+20/-20				532.4		
		AFL	1800	+20/-20				280		
20-00-00-212-002-A00 (s)	INSPECT (GENERAL VISUAL) CENTER FUSELAGE III LOWER SIDE - EWIS COMPONENTS OF APU AND ENGINES GENERATORS POWER CABLES, HYDRAULIC PUMPS POWER CABLES AND WIRING BUNDLES (ZONES: 151, 152, 153, 154, 155, 156, 157). NOTE: EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d				26-JAN-2015		
LOW UTILIZATION	REF: AMM 05-40-01	HRS/MSC	3600	+20/-20				532.4		
		AFL	1800	+20/-20				280		
20-00-00-212-003-A00 (s)	INSPECT (GENERAL VISUAL) CENTER FUSELAGE IV LOWER SIDE - EWIS COMPONENTS OF APU AND ENGINES GENERATORS POWER CABLES, HYDRAULIC PUMPS POWER CABLES AND WIRING BUNDLES (ZONES: 161, 162). NOTE: EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d				26-JAN-2015		
LOW UTILIZATION	REF: AMM 05-40-02	HRS/MSC	3600	+20/-20				532.4		
		AFL	1800	+20/-20				280		
20-00-00-212-007-A00 (s)	INSPECT (GENERAL VISUAL) REAR FUSELAGE I, PRESSURE BULKHEAD PRESSURIZED AREA SIDE - EWIS COMPONENTS OF APU POWER CABLES AND WIRING BUNDLES (ZONES: 275, 276) NOTE: EWIS).(L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d				26-JAN-2015		
LOW UTILIZATION	REF: AMM 05-40-07	HRS/MSC	3600	+20/-20				532.4		
		AFL	1800	+20/-20				280		
20-00-00-212-008-A00 (s)	INSPECT (GENERAL VISUAL) REAR FUSELAGE II, STRUCTURAL AREA AFT OF REAR PRESSURE BULKHEAD - EWIS COMPONENTS OF POWER CABLES AND WIRING BUNDLES (ZONES: 311, 312). NOTE: EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d				26-JAN-2015		
LOW UTILIZATION	REF: AMM 05-40-08	HRS/MSC	3600	+20/-20				532.4		
		AFL	1800	+20/-20				280		
20-00-00-212-011-A00 (s)	INSPECT (GENERAL VISUAL) FWD AUXILIARY FUEL TANK FAIRINGS, VENTRAL FUEL TANK FAIRINGS AND WING-TO-FUSELAGE ATTACHMENT FAIRINGS - EWIS COMPONENTS OF WIRING BUNDLES (ZONES: 191, 193, 194, 195, 196, 1924 AND 1932) NOTE: EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d				26-JAN-2015		
LOW UTILIZATION	REF: AMM 05-40-09	HRS/MSC	3600	+20/-20				532.4		
		AFL	1800	+20/-20				280		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-00-00-212-012-A00 (s)	INSPECT (GENERAL VISUAL) NLG ELECTRONIC COMPARTMENT - EWIS COMPONENTS OF WIRING BUNDLES (ZONES: 113, 114). NOTE: EWIS.(L650 ONLY)						PKG			
	PKG 5016	MOS	96	+15d/-15d						
LOW UTILIZATION	REF: AMM 05-40-11	HRS/MSC	7200	+20/-20						
		AFL	3600	+20/-20						
20-00-00-212-013-A00 (s)	INSPECT (GENERAL VISUAL) ENGINE PYLON - EWIS COMPONENTS OF ENGINES GENERATORS POWER CABLES AND WIRING BUNDLES (ZONES: 414, 424). NOTE: EWIS (L650 ONLY)						PKG			
	PKG 5004	MOS	24	+15d/-15d				21-JAN-2017		
LOW UTILIZATION	REF: AMM 05-40-15	HRS/MSC	1000	+20/-20				884.1		
		AFL						443		
20-00-00-212-014-A00 (s)	INSPECT (GENERAL VISUAL) ENGINES - EWIS COMPONENTS OF ENGINES GENERATORS POWER CABLES (ZONES: 415, 425). NOTE: EWIS (L650 ONLY)						PKG			
	PKG 5004	MOS	24	+15d/-15d				21-JAN-2017		
LOW UTILIZATION	REF: AMM 05-40-18	HRS/MSC	1000	+20/-20				884.1		
		AFL						443		
20-00-00-212-015-A00 (s)	INSPECT (GENERAL VISUAL) WING LEADING EDGE - EWIS COMPONENTS OF WIRING BUNDLES (ZONES: 511, 512, 513, 611, 612, 613). NOTE: EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d				26-JAN-2015		
LOW UTILIZATION	REF: AMM 24-00-02	HRS/MSC	3600	+20/-20				532.4		
		AFL	1800	+20/-20				280		
20-00-00-212-016-A00 (s)	INSPECT (GENERAL VISUAL) EWIS COMPONENTS OF TRAILING EDGE HARNESS (ZONES: 532, 5711, 5721, 5731, 5732, 632, 6711, 6721, 6731, 6732). NOTE: EWIS (L650 ONLY)						PKG			
	PKG 5004	MOS	24	+15d/-15d				21-JAN-2017		
LOW UTILIZATION	REF: AMM 24-00-03	HRS/MSC	1000	+20/-20				884.1		
		AFL						443		
20-00-00-212-017-A00 (s)	INSPECT (GENERAL VISUAL) WING STUB HARNESS - EWIS COMPONENTS OF WIRING BUNDLES (ZONE 192). NOTE: EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d				26-JAN-2015		
LOW UTILIZATION	REF: AMM 24-00-04	HRS/MSC	3600	+20/-20				532.4		
		AFL	1800	+20/-20				280		
20-00-00-212-018-A00 (s)	INSPECT (GENERAL VISUAL) REAR FUSELAGE I LOWER SIDE - EWIS COMPONENTS OF APU AND ENGINES GENERATORS POWER CABLES, HYDRAULIC PUMPS POWER CABLES AND WIRING BUNDLES (ZONES: 171, 172). NOTE: EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d				26-JAN-2015		
LOW UTILIZATION	REF: AMM 05-40-04	HRS/MSC	3600	+20/-20				532.4		
		AFL	1800	+20/-20				280		
20-00-00-212-019-A00 (s)	INSPECT (GENERAL VISUAL) REAR FUSELAGE I LATERAL SIDE - EWIS COMPONENTS OF ENGINES GENERATORS POWER CABLES AND WIRING BUNDLES (ZONES: 271, 272). NOTE: EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d				26-JAN-2015		
LOW UTILIZATION	REF: AMM 05-40-05	HRS/MSC	3600	+20/-20				532.4		
		AFL	1800	+20/-20				280		

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-00-00-220-001-A00 (s)	INSPECT (DETAILED INSPECTION) EWIS COMPONENTS OF WING TANK UNIT HARNESS (ZONES: 155, 156, 157, 531, 631, 541, 641). NOTE: EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 28-41-03	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
20-00-00-220-003-A00 (s)	INSPECT (DETAILED INSPECTION) ELECTRIC FUEL PUMP CONNECTOR (ZONES: 155, 156, 157, 531, 631). NOTE: EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 28-21-01	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
20-00-00-220-006-A00 (s)	INSPECT (DETAILED INSPECTION) VENTRAL FUEL TANK - EWIS COMPONENTS OF VENTRAL TANK UNIT HARNESS (ZONE: 1972). NOTE: (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 28-41-06	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
20-00-00-220-008-A00 (s)	INSPECT (DETAILED INSPECTION) WING MIDDLE SECTION - EWIS COMPONENTS OF VENT VALVE HARNESS INSIDE THE CONDUIT (ZONES: 541, 641). NOTE: EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 28-23-04	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
20-00-00-220-009-A00 (s)	INSPECT (DETAILED INSPECTION) FWD ELECTRONIC COMPARTMENT/ FWD PRESSURE BULKHEAD UPPER SIDE - EWIS COMPONENTS OF WIRING BUNDLES (ZONES: 213, 214, 215, 216). NOTE: EWIS.(L650 ONLY)						PKG			
	PKG 5016	MOS	96	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: See Workcard	HRS/MSC	7200	+20/-20			532.4			
		AFL	3600	+20/-20			280			
20-00-00-220-010-A00 (s)	INSPECT (DETAILED INSPECTION) COCKPIT LOWER SIDE - EWIS COMPONENTS OF POWER CABLES AND WIRING BUNDLES (ZONES: 123, 124). NOTE: EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-40-12	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
20-00-00-220-011-A00 (s)	INSPECT (DETAILED INSPECTION) COCKPIT LATERAL SIDE - EWIS COMPONENTS OF POWER CABLES (ZONES: 223, 224). NOTE: EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-40-13	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
20-00-00-220-012-A00 (s)	INSPECT (DETAILED INSPECTION) CENTER FUSELAGE I LOWER SIDE - EWIS COMPONENTS OF APU AND ENGINES GENERATORS POWER CABLES, HYDRAULIC PUMPS POWER CABLES AND WIRING BUNDLES (ZONES: 131, 132). NOTE: EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-40-14	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
20-00-00-220-013-A00 (s)	INSPECT (DETAILED INSPECTION) CENTER FUSELAGE II LOWER SIDE - EWIS COMPONENTS OF APU AND ENGINES GENERATORS POWER CABLES, HYDRAULIC PUMPS POWER CABLES AND WIRING BUNDLES (ZONES: 141, 142). NOTE: EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-40-10	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
20-00-00-220-014-A00 (s)	INSPECT (DETAILED INSPECTION) AFT FUEL TANK - EWIS COMPONENTS OF AFT FUEL TANK UNITS HARNESS (ZONES 271, 272) NOTE: EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 28-46-02	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
20-00-00-220-015-A00 (s)	INSPECT (DETAILED INSPECTION) FUEL PUMP ELECTRICAL HARNESS (ZONES 155, 156, 157). NOTE: EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 28-21-01	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
20-00-00-220-017-A00 (s)	INSPECT (DETAILED INSPECTION) EWIS COMPONENTS OF FWD FUEL TANK UNIT HARNESS (ZONE 197). NOTE: EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 28-46-04	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
20-00-00-220-019-A00 (s)	INSPECT (DETAILED INSPECTION) EWIS COMPONENTS OF W1642 INTRINSICALLY SAFE HARNESS (ZONES 123, 124, 131, 132, 141, 142, 151, 152, 153, 154, 161, 162, 171, 172, 271). NOTE: EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 28-41-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
CHAPTER 21 AIR CONDITIONING										
21-20-00-710-001-A00 (s)	OPERATIONALLY CHECK CONDITIONED AIR DISTRIBUTION SYSTEM						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: AMM 21-20-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
21-21-00-720-001-A00 (s)	FUNCTIONALLY CHECK DISPLAY VENTILATION SYSTEM						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 21-21-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
21-25-01-211-001-A00 (s)	VISUALLY CHECK FLAP OF RAM AIR VALVES						PKG			
	PKG 5004	MOS	24	+15d/-15d			21-JAN-2017			
LOW UTILIZATION	REF: AMM 21-25-01	HRS/MSC	1000	+20/-20			884.1			
		AFL					443			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
21-25-01-710-001-A00 (s)	OPERATIONALLY CHECK RAM AIR VALVE						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 21-25-01	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
21-26-00-710-001-A00 (s)	OPERATIONALLY CHECK ELECTRONIC COMPARTMENT VENTILATION SYSTEM						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 21-26-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
21-26-08-960-001-A01	DISCARD EXHAUST HOSES OF THE ELECTRONIC BAY COMPARTMENT									
		MOS	180	+60d/-60d			16-DEC-2010	16-DEC-2025	14-FEB-2026	3172 d (+60)
SYSTEM	REF: AMM 21-26-08	HRS/MSC					0			
		AFL					0			
21-27-00-710-001-A00 (s)	OPERATIONAL CHECK BAGGAGE COMPARTMENT VENTILATION SYSTEM (INCLUDING HIGH AND LOW SPEED OF FAN)						PKG			
	PKG 5008	MOS	48	+15d/-15d			21-JAN-2017			
LOW UTILIZATION	REF: AMM 21-27-00	HRS/MSC	2000	+20/-20			884.1			
		AFL	1000	+20/-20			443			
21-27-02-640-001-A00 (s)	LUBRICATE BAGGAGE COMPARTMENT CHECK VALVES						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 21-27-02	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
21-27-02-710-001-A00 (s)	OPERATIONALLY CHECK BAGGAGE COMPARTMENT CHECK VALVES (MANUAL CHECK FOR FREE MOVEMENT AND CORRECTED SEATING)						PKG			
	PKG 5004	MOS	24	+15d/-15d			21-JAN-2017			
LOW UTILIZATION	REF: AMM 21-27-02	HRS/MSC	1000	+20/-20			884.1			
		AFL					443			
21-31-00-710-001-A00 (s)	OPERATIONALLY CHECK PRESSURIZATION CONTROL SYSTEM IN MANUAL MODE						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: AMM 21-31-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
21-31-00-720-002-A00 (s)	FUNCTIONALLY CHECK OUTFLOW VALVES PRESSURE RELIEF DEVICES						PKG			
	PKG 5024	MOS	144	+15d/-15d			21-JAN-2017			
LOW UTILIZATION	REF: See Workcard	HRS/MSC	6000	+20/-20			884.1			
		AFL	3000	+20/-20			443			
21-31-00-720-005-A00 (s)	FUNCTIONALLY CHECK LINE FOR LEAKAGE						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: AMM 21-31-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
21-31-03-140-001-A00 (s)	RESTORE (CLEANING) ELECTROPNEUMATIC OUTFLOW VALVE (NON-SMOKING FLIGHTS)						PKG			
	PKG 5008	MOS	48	+15d/-15d			21-JAN-2017			
LOW UTILIZATION	REF: AMM 21-31-03	HRS/MSC	2000	+20/-20			884.1			
		AFL	1000				443			
21-31-03-140-001-A01	RESTORE (CLEANING) ELECTROPNEUMATIC OUTFLOW VALVE (SMOKING FLIGHTS)									
		MOS					21-JAN-2017			
		HRS/MSC	N/A				884.1			
	REF: AMM 21-31-03	AFL					443			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
21-31-04-140-001-A00 (s)	RESTORE (CLEANING) PNEUMATIC OUTFLOW VALVE (NON-SMOKING FLIGHTS)						PKG			
	PKG 5002	MOS	12	+15d/-15d			21-JAN-2017			
LOW UTILIZATION	REF: AMM 21-31-04	HRS/MSC	900	+20/-20			884.1			
		AFL	450	+20/-20			443			
21-31-04-140-001-A01	RESTORE (CLEANING) PNEUMATIC OUTFLOW VALVE (SMOKING FLIGHTS)									
		MOS					16-DEC-2010			
	REF: AMM 21-31-04	HRS/MSC	N/A				0			
		AFL					0			
21-31-08-960-001-A00	DISCARD AIR FILTER ELEMENT (NON-SMOKING FLIGHTS)									
		MOS					16-DEC-2010			
SYSTEM	REF: AMM 21-31-08	HRS/MSC	3200				0	3200		2296.7
		AFL					0			
21-31-08-960-001-A01	DISCARD AIR FILTER ELEMENT (SMOKING FLIGHTS)									
		MOS					16-DEC-2010			
	REF: AMM 21-31-08	HRS/MSC	N/A				0			
		AFL					0			
21-32-01-720-001-A00 (s)	FUNCTIONALLY CHECK CABIN PRESSURE ACQUISITION MODULE (CPAM) POST-MOD. S.B. 145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: AMM 21-32-01	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
21-51-00-710-001-A00 (s)	OPERATIONALLY CHECK COOLING PACK SYSTEM TO VERIFY ECS OFF SIGNAL						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 21-51-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
21-51-00-720-001-A00 (s)	FUNCTIONALLY CHECK COOLING PACK SYSTEM						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: AMM 21-51-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
21-51-00-720-003-A00 (s)	FUNCTIONALLY CHECK PACK DUCT OVERTEMPERATURE PROTECTION						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 21-51-09	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
21-51-01-130-001-A00 (s)	RESTORE (CLEANING) PACK VALVE FILTER USING ULTRASONIC METHOD						PKG			
	PKG 5008	MOS	48	+15d/-15d			21-JAN-2017			
LOW UTILIZATION	REF: AMM 21-51-01	HRS/MSC	2000	+20/-20			884.1			
		AFL	1000	+20/-20			443			
21-51-02-170-001-A00 (s)	RESTORE (CLEANING) DUAL HEAT EXCHANGER AND VISUALLY CHECK CONDITION OF CORE.						PKG			
	PKG 5016	MOS	96	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 21-51-02	HRS/MSC	4000	+20/-20			532.4			
		AFL	2000	+20/-20			280			
21-51-02-170-002-A00 (s)	RESTORE (CLEANING) DUAL HEAT EXCHANGER - ON THE AIRCRAFT						PKG			
	PKG 5004	MOS	24	+15d/-15d			21-JAN-2017			
LOW UTILIZATION	REF: AMM 21-51-02	HRS/MSC	1000	+20/-20			884.1			
		AFL					443			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
21-51-10-710-001-A00 (s)	OPERATIONALLY CHECK PACK LEAK SWITCH PKG 5012	MOS	72	+15d/-15d			PKG 21-JAN-2017 884.1			
LOW UTILIZATION	REF: AMM 21-51-10	HRS/MSC AFL	3000 1500	+20/-20 +20/-20			443			
21-51-13-211-001-A00 (s)	VISUALLY CHECK WATER SPRAY NOZZLES NOTE: EMB-RECOMM PKG 5001	MOS	6	+15d/-15d			PKG 21-JAN-2017 884.1			
LOW UTILIZATION	REF: AMM 21-51-13	HRS/MSC AFL	250	+20/-20			443			
21-60-00-710-001-A00 (s)	OPERATIONALLY CHECK TEMPERATURE CONTROL PKG 5016	MOS	96	+15d/-15d			PKG 16-DEC-2010 0			
LOW UTILIZATION	REF: AMM 21-60-00	HRS/MSC AFL	7200 3600	+20/-20 +20/-20			0			
21-60-08-960-001-A00	DISCARD TORQUE-MOTOR DUAL-VALVE FILTER PKG 5032	MOS	192	+15d/-15d			16-DEC-2010 0	16-DEC-2026 8000	31-DEC-2026 8020	3537 d (+15) 7096.7 (+20)
LOW UTILIZATION	REF: AMM 21-60-08	HRS/MSC AFL	8000 4000	+20/-20 +20/-20			0	4000	4020	3550 (+20)
21-71-01-900-001-A00 (s)	RESTORE (CLEANING) NO. 1 OZONE/OXYGEN CONVERTER - BLEED SYSTEM 60A523-101 PKG 5012 0156/0774	MOS	72	+15d/-15d			PKG			
LOW UTILIZATION	REF: AMM 21-70-01	HRS/MSC AFL	5400 2700	+20/-20 +20/-20						
21-71-01-900-001-A00 (s)	RESTORE (CLEANING) NO. 2 OZONE/OXYGEN CONVERTER - BLEED SYSTEM 60A523-101 PKG 5012 0232/1056	MOS	72	+15d/-15d			PKG			
LOW UTILIZATION	REF: AMM 21-70-01	HRS/MSC AFL	5400 2700	+20/-20 +20/-20						
212104-0101	GASPER ASSY-GASPER,AIR CONDITIONING SYS VALVE 145-22301-401 0000636312	MOS			TSN:0		16-DEC-2010 0			
	REF:	HRS/MSC AFL	O/C		TSN:0 TSN:0		0			
212104-0102	LEFT ASSY-GASPER,AIR CONDITIONING SYS VALVE 145-22301-401 0000636313	MOS			TSN:0		16-DEC-2010 0			
	REF:	HRS/MSC AFL	O/C		TSN:0 TSN:0		0			
212104-0103	RIGHT ASSY-GASPER,AIR CONDITIONING SYS VALVE 145-22301-401 0000636479	MOS			TSN:0		16-DEC-2010 0			
	REF:	HRS/MSC AFL	O/C		TSN:0 TSN:0		0			
212200-0101	FWD VALVE -DISTRIBUTION,AIR COND SYS,PAX CABIN ASSEMBLY 135-03776-401 0000618761	MOS			TSN:0		16-DEC-2010 0			
	REF: AMM 21-22-06	HRS/MSC AFL	O/C		TSN:0 TSN:0		0			
212200-0102	AFT VALVE -DISTRIBUTION,AIR COND SYS,PAX CABIN ASSEMBLY 135-03776-401 0000621862	MOS			TSN:0		16-DEC-2010 0			
	REF: AMM 21-22-06	HRS/MSC AFL	O/C		TSN:0 TSN:0		0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
212200-0201	C FLOOR VALVE ASSY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
212201-0101	C FLOOR VALVE ASSY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
212300-0101	LEFT RECIRCULATION & GASPER FAN AE1115A00 L0435 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
212300-0102	GASPER RECIRCULATION & GASPER FAN AE1115A00 L0437 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
212300-0103	RIGHT RECIRCULATION & GASPER FAN AE1115A00 L0436 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
212500-0101	LEFT ELECTROMECHANICAL LINEAR-FLAPPER VALVE,APU ACTUATOR SYLC51836-1 2325 REF: AMM 21-25-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
212500-0102	RIGHT ELECTROMECHANICAL LINEAR-FLAPPER VALVE,APU ACTUATOR SYLC51836-1 2326 REF: AMM 21-25-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
212600-0101	LEFT ACTUATOR LINEAR -ELECTROMECHANICAL,CONTROL GUST LOCK ASSEMBLY SYLC53229-3 475 REF: AMM 21-26-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
212600-0102	RIGHT ACTUATOR LINEAR -ELECTROMECHANICAL,CONTROL GUST LOCK ASSEMBLY SYLC53229-3 478 REF: AMM 21-26-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
212600-0103	LH FWR ELECTRONIC COMPARTMENT FAN 526484 110282304 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
212600-0104	RH FWR ELECTRONIC COMPARTMENT FAN 526484 110282308 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
212600-0201	LH REAR ELECTRONIC COMPARTMENT FAN 526484 110282310 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
212600-0202	RH REAR ELECTRONIC COMPARTMENT FAN 526484 110282311 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
212603-0101	NO. 1 NOSE 28 VDC/12 VDC,FAN,ELECTRONIC EQUIPMENT EQUIPMENT,FWD FUSLG INVERTER 524864 E10341919 REF: AMM 21-26-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
212603-0102	NO. 2 NOSE 28 VDC/12 VDC,FAN,ELECTRONIC EQUIPMENT EQUIPMENT,FWD FUSLG INVERTER 524864 E10341920 REF: AMM 21-26-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
212603-0103	NO. 3 NOSE 28 VDC/12 VDC,FAN,ELECTRONIC EQUIPMENT EQUIPMENT,FWD FUSLG INVERTER 524864 E10341921 REF: AMM 21-26-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
212603-0104	NOSE 28 VDC/12 VDC,FAN,ELECTRONIC EQUIPMENT EQUIPMENT,FWD FUSLG INVERTER 524864 E10341922 REF: AMM 21-26-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
212701-0101	CLASS C, BAGGAGE COMPARTMENT FAN 011768500 C10320142 REF: AMM 21-27-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
212703-0101	CARGO CP PRESSURIZATION EQUILIZATION VALVE ASSEMBLY 120-48865-001 0000642863 REF: AMM 21-27-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
213000-0201	LEFT REGULATING-PRESSURE/DEICING,PNEUMATIC SYS VALVE 38E109-20A N101351 REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
213000-0202	RIGHT REGULATING-PRESSURE/DEICING,PNEUMATIC SYS VALVE 38E109-20A N101467 REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
213100-0101	PRESS SYS - REAR FUSLG 1,41 KFT PNEUMATIC VALVE 2113A010101 05152 REF: AMM 21-31-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
213100-0102	PRESS SYS - REAR FUSLG 1,41 KFT, 10V ELETROPNEUMATIC VALVE 2112A010101 05054 REF: AMM 21-31-00	MOS HRS/MSC AFL	O/C	TSN:1505 TSR:0			01-MAR-2011 25.43 10			
213101-0101	CSL CENT DIGITAL CONTROLLER-PRESSURIZATION,COCKPIT UNIT 91132A010101 05018 REF: AMM 21-31-01	MOS HRS/MSC AFL	O/C	TSN:614 TSR:0			01-MAR-2011 25.43 10			
213102-0101	CSL CENT CONTROL-MANUAL PRESSURE REGULATOR 41 KFT,CTL CSL,COCKPIT UNLT 2114A010101 05148 REF: AMM 21-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
213107-0201	LH REAR STATIC-HEATED,PRESSURIZATION SYS,28VDC PORT ST300-2PT 1483101 REF: AMM 21-31-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
213107-0202	RH REAR STATIC-HEATED,PRESSURIZATION SYS,28VDC PORT ST300-2PT 1483103 REF: AMM 21-31-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
213201-0101	CABIN PRESSURE - RH LATERAL CONSOLE, DATA ACQUISITION MODULE 2014AB1 3086 REF: AMM 21-32-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
215100-0101	LH PACK ENVIRONMENTAL CONTROL UNIT 816626.2 2010090010 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
215100-0102	RH PACK ENVIRONMENTAL CONTROL- ECU, AIR CONDITIONING SYS UNIT 816636-2 2010090010 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
215101-0101	LH PIL CHECK-BLEED SYS,REAR FUSLG I/II VALVE 816604-2 2014040011 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			17-FEB-2016 758.2 377			
215101-0102	RH PIL CHECK-BLEED SYS,REAR FUSLG I/II VALVE 816604-2 2010090948 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
215102-0101	LH HEAT EXCHANGER UNIT 816630-1 2008080976 REF: AMM 21-51-02	MOS HRS/MSC AFL	O/C				26-JAN-2015 532.4 280			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
215102-0102	RH HEAT EXCHANGER UNIT 816630-2 200310105 REF: AMM 21-51-02	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0			26-JAN-2015 532.4 280			
215106-0201	LH ENG PACK,AIR CONDITIONING SYS - OVERPRESSURE SWITCH 782100-11 2983 REF: AMM 21-51-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
215106-0202	RH ENG PACK, AIR CONDITIONING SYS - OVERPRESSURE SWITCH 782100-11 2984 REF: AMM 21-51-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
216002-0101	PAX AMBIENT TEMPERATURE,ECU,A/C SYS SENSOR 815289-2 17625 REF: AMM 21-60-02	MOS HRS/MSC AFL	O/C				26-JAN-2015 532.4 280			
216002-0102	CREW CAB AMBIENT TEMPERATURE,ECU,A/C SYS SENSOR 815289-2 17626 REF: AMM 21-60-02	MOS HRS/MSC AFL	O/C				26-JAN-2015 532.4 280			
216004-0101	LEFT TEMPERATURE ASSY-DIGITAL,AIR CONDITIONING SYS CONTROLLER C142398-4-006 09023442 REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
216004-0102	RIGHT TEMPERATURE ASSY-DIGITAL,AIR CONDITIONING SYS CONTROLLER C142398-4-006 10023453 REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
216005-0101	MANUAL, AIR COND SYS, RH CONSOLE, TEMPERATURE CONTROL MODULE 812546-4 2010080010 REF: AMM 21-60-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
216006-0101	BOX - PAX TEMPERATURE CONTROLLER,MM SYS ASSEMBLY 990-8000-004 10070059645 REF: AMM 21-60-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
217001-0101	NO. 1 OZONE/OXYGEN CONVERTER - BLEED SYSTEM 60A523-101 0156/0774 REF: AMM 21-70-01	MOS HRS/MSC AFL	O/C				21-JAN-2017 884.1 443			
217001-0102	NO. 2 OZONE/OXYGEN CONVERTER - BLEED SYSTEM 60A523-101 0232/1056 REF: AMM 21-70-01	MOS HRS/MSC AFL	O/C				21-JAN-2017 884.1 443			

CHAPTER 22 AUTO FLIGHT

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
22-11-00-710-001-A00 (s)	OPERATIONALLY CHECK AFCS GO-AROUND MODE NOTE: ALSO CHECK TCS MODE PKG 5008	MOS	48	+15d/-15d			PKG 26-JAN-2015			
LOW UTILIZATION	REF: AMM 22-11-00	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
22-11-00-720-003-A00 (s)	FUNCTIONALLY CHECK CATEGORY II MONITORING FUNCTION NOTE: ONLY FOR CAT II OPERATION PKG 5002	MOS	12	+15d/-15d			PKG 21-JAN-2017			
LOW UTILIZATION	REF: AMM 22-11-00	HRS/MSC AFL	900 450	+20/-20 +20/-20			884.1 443			
22-11-00-720-004-A00 (s)	FUNCTIONALLY CHECK AFCS ALTITUDE HOLD MODE AND ALTITUDE PRE-SELECT MODE NOTE: ONLY FOR RVSM OPERATION PKG 5008	MOS	48	+15d/-15d			PKG 26-JAN-2015			
LOW UTILIZATION	REF: AMM 22-11-00	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
221001-0101	CSL CENT AUTOPILOT PC400, INSTRUMENT PANEL CONTROLLER UNIT 7003897-925 10084028	MOS		TSN:0			16-DEC-2010			
	REF: AMM 22-11-02	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
221002-0101	CSL CENT GC 550, GUIDANCE AUTOPILOT SYS, GLARESHIELD CONTROL PANEL 7021170-953 10062179	MOS		TSN:0			16-DEC-2010			
	REF: AMM 22-11-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
221003-0101	FORWARD FUSELAGE,AUTO PILOT, AILERON SERVO 145-20449-407 0000632039	MOS		TSN:0			16-DEC-2010			
	REF: AMM 22-11-03	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
221003-0201	RUDDER ELECTROMECHANICAL ASSY-FLIGHT CONTROL,AUTO PILOT ACTUATOR 4006719-906 MOD N 0901J698	MOS		TSN:0			16-DEC-2010			
	REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
221003-0202	ELEVATOR ELECTROMECHANICAL ASSY-FLIGHT CONTROL,AUTO PILOT ACTUATOR 4006719-906 MOD N 0901J701	MOS		TSN:0			16-DEC-2010			
	REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
221003-0203	AILERON ELECTROMECHANICAL ASSY-FLIGHT CONTROL,AUTO PILOT ACTUATOR 4006719-906 MOD N 0901J694	MOS		TSN:0			16-DEC-2010			
	REF:	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
221004-0101	FORWARD ASSY-ELEVATOR, AUTO PILOT, HORIZONTAL TAIL SERVO 145-20454-409 0000623270	MOS		TSN:0			16-DEC-2010			
	REF: AMM 22-11-04	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
221005-0101	REAR ASSY-RUDDER, AUTO PILOT, VERTICAL TAIL SERVO 145-20452-407 0000624819	MOS		TSN:0			16-DEC-2010			
	REF: AMM 22-11-05	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			

CHAPTER 23 COMMUNICATIONS

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
23-15-03-212-001-A00 (s)	INSPECT (GENERAL VISUAL) OF SATCOM ANTENNA PART NUMBER 10101-00 NOTE: EMB RECOMM PKG 5002	MOS	12	+15d/-15d			PKG 21-JAN-2017 884.1 443			
LOW UTILIZATION	REF: AMM 23-15-03	HRS/MSC AFL	900 450	+20/-20 +20/-20						
23-24-01-960-001-A00	DISCARD CMU BATTERY NOTE: CMU BATTERY CHANGE IN ACCORDANCE WITH MANUFACTURER'S DATA PLATE EXPIRATION DATE, IF INSTALLED PN SN-UNKNOWN	MOS	72				16-JUN-2016 800.1 396	16-JUN-2022		1893 d
DISCARD	REF: AMM 23-24-01	HRS/MSC AFL								
23-35-21-710-001-A00 (s)	OPERATIONALLY CHECK ENTERTAINMENT CABINET FANS PKG 5008	MOS	48	+15d/-15d			PKG 26-JAN-2015 532.4 280			
LOW UTILIZATION	REF: AMM 23-35-21	HRS/MSC AFL	3600 1800	+20/-20 +20/-20						
23-51-00-710-001-A00 (s)	OPERATIONALLY CHECK AUDIO SYSTEM EMERGENCY MODE PKG 5001	MOS	12	+15d/-15d			PKG 21-JAN-2017 884.1 443			
LOW UTILIZATION	REF: AMM 23-51-00	HRS/MSC AFL	500	+20/-20						
23-60-00-720-001-A00 (s)	FUNCTIONALLY CHECK STATIC DISCHARGER PKG 5012	MOS	72	+15d/-15d			PKG 21-JAN-2017 884.1 443			
LOW UTILIZATION	REF: AMM 23-60-00	HRS/MSC AFL	3000 1500	+20/-20 +20/-20						
23-71-00-710-001-A00	OPERATIONALLY CHECK VOICE RECORDER 4 CHANNELS AND AREA MICROPHONE NOTE: OR IN ACCORDANCE WITH LOCAL REGULATORY AUTHORITY REQUIREMENTS	MOS	48	+30d/-30d			21-JAN-2017 884.1 443	21-JAN-2021 4884.1	20-FEB-2021	1382 d (+30) 3980.8
SYSTEM	REF: AMM 23-71-00	HRS/MSC AFL	4000							
23-71-02-710-001-A00	OPERATIONALLY CHECK UNDERWATER LOCATOR BEACON	MOS	24	+30d/-30d			21-JAN-2017 884.1 443	21-JAN-2019	20-FEB-2019	651 d (+30)
SYSTEM	REF: AMM 23-71-02	HRS/MSC AFL								
23-71-02-960-001-A00	DISCARD CVR UNDERWATER LOCATOR BEACON NOTE: ULB BATTERY CHANGE IN ACCORDANCE WITH MANUFACTURERS DATAPLATE EXPIRATION DATE	MOS					26-AUG-2016 854.7 424	28-FEB-2022 M		1785 d
SYSTEM	REF: AMM 23-71-02	HRS/MSC AFL	DUE							
231102-0101	REAR I KRX1053 HF COMM W/SELCAL COMPATIBILITY TRANSCEIVER 064-01073-0102 KRX1053-5147	MOS			TSN:0		16-DEC-2010 0			
	REF: AMM 23-11-02	HRS/MSC AFL	O/C		TSN:0 TSN:0		0 0			
231102-0102	REAR I KRX1053 HF COMM W/SELCAL COMPATIBILITY TRANSCEIVER 064-01073-0102 KRX1053-5157	MOS			TSN:0		16-DEC-2010 0			
	REF: AMM 23-11-02	HRS/MSC AFL	O/C		TSN:0 TSN:0		0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
231103-0101	NO. 1 REAR POWER- KPA 1052 AMPLIFIER 064-01072-0101 KPA1052-4603 REF: AMM 23-11-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
231103-0102	NO. 2 REAR I POWER- KPA 1052 AMPLIFIER 064-01072-0101 KPA1052-4615 REF: AMM 23-11-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
231104-0101	NO. 1 REAR I HF ANTENNA COUPLER - KAC1052, KHF1050 SYSTEM 064-01074-0101 KAC1052-4631 REF: AMM 23-11-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
231104-0102	NO. 2 REAR I HF ANTENNA COUPLER - KAC1052, KHF1050 SYSTEM 064-01074-0101 KAC1052-4706 REF: AMM 23-11-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
231114-0101	PILOT MODULE -KHF1 SYSTEM,MAIN PANEL,COCKPIT ASSEMBLY 135-18744-401 0000634851 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
231114-0102	COPILOT MODULE -KHF1 SYSTEM,MAIN PANEL,COCKPIT ASSEMBLY 135-18744-401 0000642131 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
231201-0101	NO.1 NOSE VHF-COMM RCZ833K,RADIO NAV/COMM SYS ACCESSORIES UNIT 7510733-666 1403D241 REF: AMM 23-00-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-JUN-2015 653 333			
231201-0102	NO.2 NOSE VHF-COMM RCZ833K,RADIO NAV/COMM SYS ACCESSORIES UNIT 7510733-666 1007C736 REF: AMM 23-00-01	MOS HRS/MSC AFL	O/C				26-JAN-2015 532.4 280			
231201-0201	NOSE VHF-COMMUNICATION UNIT,RADIO NAV/COMM SYS BOX 7510700-833 1007C750 REF: AMM 23-00-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
231204-0201	VHF 1 VHF ANTENNA 16-21B MOD.1 25308 REF: AMM 23-12-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
231204-0202	VHF 2 VHF ANTENNA 16-21B MOD.1 25309 REF: AMM 23-12-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
231204-0203	VHF 3 VHF ANTENNA 16-21B MOD.1 25310 REF: AMM 23-12-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
231501-0101	REAR FUS UNIT,TRANSCEPTOR-IRIDIUM TELEPHONE SYSTEM 400-10680-001 REV.D 1068014248 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
231501-0102	REAR FUS UNIT,TRANSCEPTOR-IRIDIUM TELEPHONE SYSTEM 400-10680-001 REV.D 1068014252 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
231503-0101	FLITEFONE, SATELLITE COMMUNICATION SYS ANTENNA 015-10306-001 10535 REF: AMM 23-15-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
231503-0102	FLITEFONE, SATELLITE COMMUNICATION SYS ANTENNA 015-10306-001 10670 REF: AMM 23-15-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
231510-0101	TRANSCEIVER ,PAX BOARD TELEPHONE MANAGEMENT, AEROCON UNIT 936000-1 02-275 REF: AMM 23-15-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
231521-0101	SATCOM DATA SDU-7300/SATCOM SYS UNIT PN SN-UNKNOWN REF: AMM 23-15-21	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
231522-0101	HIGH POWER AMPLIFIER-AERO HPA-7400/SATCOM SYS UNIT PN SN-UNKNOWN REF: AMM 23-15-22	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
231523-0101	REAR FUS ACCESS POINT-WASP,WIRELESS,HSD SYS UNIT PN SN-UNKNOWN REF: AMM 23-15-23	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
231524-0101	REAR DIPLEXER/AMPLIFIER- DAU 7050 SYS HSD IRIDIUM UNIT PN SN-UNKNOWN REF: AMM 23-15-24	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
231525-0101	HIGH GAIN-HGA 7000,SATCOM SYS ANTENNA PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
232101-0101	HHCSL DECODER, SELECTIVE CALLING SYS, RADIOCOMM UNIT 2800-0012-102 1030G019 REF: AMM 23-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
232102-0101	CREW CAB SELCAL HF+VHF 2 MODULE 145-46569-405 14500978 REF: AMM 23-21-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
232401-0101	NOSE CMU950, ARINC SYS, MANAGEMENT CONTROL UNIT 7519200-920 CMUMK3-01863 REF: AMM 23-24-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
232401-0201	CMU BATTERY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
232403-0101	NOSE IM 950,5V,CMU SYS,FWD ELEK COMPT, AIRCRAFT PERSONALITY MODULE 964-0465-001 APM-03913 REF: AMM 23-24-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
233101-0101	PASSENGER WARNING SYSTEM AMPLIFIER 5482-1 MOD.D 1311 REF: AMM 23-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
233102-0101	OVERH P MODULE -ICU ASSEMBLY 145-30767-405 0000637156 REF: AMM 23-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
233104-0101	ELECTRICAL COMPARTMENT SERVICE PANEL, AFT LH, CEILING SPEAKER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
233104-0102	ELECTRICAL COMPARTMENT SERVICE PANEL, AFT LH, CEILING SPEAKER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
233104-0103	ELECTRICAL COMPARTMENT SERVICE PANEL, AFT LH, CEILING SPEAKER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
233104-0104	ELECTRICAL COMPARTMENT SERVICE PANEL, AFT LH, CEILING SPEAKER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
233104-0105	ELECTRICAL COMPARTMENT SERVICE PANEL, AFT LH, CEILING SPEAKER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
233104-0106	ELECTRICAL COMPARTMENT SERVICE PANEL, AFT LH, CEILING SPEAKER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
233501-0101	DIGITAL INTERFACE-ENTERTAINMENT,AIRSHOW,PAX CABIN UNIT 925000-100 NG34B REF: AMM 23-35-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
233504-0101	AUDIO/VIDEO SYS, PAX ENTERTAINMENT CABINET VIDEO CASSETTE PLAYER 990-4720-001 16030069391 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-AUG-2016 857.6 426			
233505-0101	DIGITAL VIDEO DISC -AUDIO/VIDEO SYS, PAX ENTERTAINMENT CABINET ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
233505-0102	DIGITAL VIDEO DISC -AUDIO/VIDEO SYS,PAX ENTERTAINMENT CABINET ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
233515-0101	FORWARD AUDIO ASSY-M1021,AIRSHOW SYS AMPLIFIER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
233515-0102	FORWARD AUDIO ASSY-M1021,AIRSHOW SYS AMPLIFIER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
234101-0101	ATTEND 1 INTERPHONE-FLIGHT ATTENDANT/PAX CABIN UNIT 5483-1-8 4720 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
235101-0101	NO.1 CREW CAB AUDIO -AV-850 PANEL 7511001-975 1006D823 REF: AMM 23-51-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
235101-0102	NO. 2 CREW CAB AUDIO -AV-850 PANEL 7511001-975 1007D833 REF: AMM 23-51-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
235101-0103	NO. 3 CREW CAB AUDIO -AV-850 PANEL 7511001-975 1006D824 REF: AMM 23-51-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
235103-0201	PILOT DYNAMIC-COCKPIT MICROPHONE 602-3375 0943869 REF: AMM 23-51-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
235103-0202	COPILOT DYNAMIC-COCKPIT MICROPHONE 602-3375 0943859 REF: AMM 23-51-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
235107-0101	CREW CAB MODULE -OBSERVER JACKS PANEL ASSEMBLY 135-23748-403 0000637138 REF: AMM 23-51-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
237101-0101	SSCVR, RADIO/NAV SYS, COCKPIT VOICE RECORDER 2100-1025-22 000668688 REF: AMM 23-71-01	MOS HRS/MSC AFL	O/C	TSN:73 TSN:884.1 TSN:443			21-JAN-2017 884.1 443			
237101-0201	CVR UNDERWATER LOCATOR BEACON DK120 SD62536 REF: AMM 23-71-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			26-AUG-2016 854.7 424			
237102-0101	OVERH P RADIO/NAVIGATION SYS, CVR CONTROL PANEL S161-0080-00 000664806 REF: AMM 23-71-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
237103-0101	CREW CAB CVR,RADIO/NAV SYS MICROPHONE S056-0051-00 000661983 REF: AMM 23-71-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
237104-0101	REAR IMPACT SWITCH 5930-4-000 4980 REF: AMM 23-71-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
237104-0102	REAR IMPACT SWITCH 5930-4-000 5012 REF: AMM 23-71-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
238101-0101	CSL CENT RADIO MANAGEMENT RM-855, COMM SYS, W/HF CONTROL UNIT 7013270-977 10077325 REF: AMM 23-81-01	MOS HRS/MSC AFL	O/C				26-JAN-2015 532.4 280			



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
238101-0102	CSL CENT RADIO MANAGEMENT 7013270-977 10077330 REF: AMM 23-81-01	RM-855, COMM SYS, W/HF CONTROL UNIT MOS HRS/MSC O/C AFL					26-JAN-2015 532.4 280			
CHAPTER 24 ELECTRICAL POWER										
24-31-00-710-001-A00 (s)	OPERATIONALLY CHECK MAIN GENERATION SWITCHING CIRCUIT PKG 5016	MOS	96	+15d/-15d			26-JAN-2015 532.4 280			
LOW UTILIZATION	REF: AMM 24-31-00	AFL	2000	+20/-20			280			
24-31-00-710-002-A00 (s)	OPERATIONALLY CHECK MAIN GENERATION OVERCURRENT PROTECTION CIRCUIT PKG 5016	MOS	96	+15d/-15d			26-JAN-2015 532.4 280			
LOW UTILIZATION	REF: AMM 24-31-00	AFL	2000	+20/-20			280			
24-31-01-900-001-A01	RESTORE (OVERHAUL) LH INBOARD (NO.3) GENERATOR POWER UNIT PART NUMBER 30086-011 (IF INSTALLED) 30086-011 P1714 REF: AMM 24-31-01	MOS HRS/MSC AFL	60 3600				08-JAN-2016 729 362	08-JAN-2021 4329		1369 d 3425.7
SYSTEM										
24-31-01-900-001-A01	RESTORE (OVERHAUL) LH OUTBOARD (NO.1) GENERATOR POWER UNIT PART NUMBER 30086-011 (IF INSTALLED) 30086-011 P2459 REF: AMM 24-31-01	MOS HRS/MSC AFL	60 3600				08-JAN-2016 729 362	08-JAN-2021 4329		1369 d 3425.7
SYSTEM										
24-31-01-900-001-A01	RESTORE (OVERHAUL) RH INBOARD (NO.2) GENERATOR POWER UNIT PART NUMBER 30086-011 (IF INSTALLED) 30086-011 P2165 REF: AMM 24-31-01	MOS HRS/MSC AFL	60 3600				08-JAN-2016 729 362	08-JAN-2021 4329		1369 d 3425.7
SYSTEM										
24-31-01-900-001-A01	RESTORE (OVERHAUL) RH OUTBOARD (NO.4) GENERATOR POWER UNIT PART NUMBER 30086-011 (IF INSTALLED) 30086-011 Y10756 REF: AMM 24-31-01	MOS HRS/MSC AFL	60 3600				08-JAN-2016 729 362	08-JAN-2021 4329		1369 d 3425.7
SYSTEM										
24-34-00-710-001-A00 (s)	OPERATIONALLY CHECK APU GENERATION OVERCURRENT PROTECTION CIRCUIT PKG 5016	MOS	96	+15d/-15d			26-JAN-2015 532.4 280			
LOW UTILIZATION	REF: AMM 24-34-00	AFL	2000	+20/-20			280			
24-34-00-710-002-A00 (s)	OPERATIONALLY CHECK APU GENERATION SWITCHING CIRCUIT PKG 5016	MOS	96	+15d/-15d			26-JAN-2015 532.4 280			
LOW UTILIZATION	REF: AMM 24-34-00	AFL	2000	+20/-20			280			
24-35-01-720-001-A00	FUNCTIONALLY CHECK NOSE EMERGENCY-ELECTRICAL EQUIPMENT, BACK-UP BATTERY 501-1228-04 PKG 5001 83955 REF: AMM 24-35-01	MOS HRS/MSC AFL	6 250	+15d/-15d +20/-20			21-JAN-2017 884.1 443	21-JUL-2017 1134.1	05-AUG-2017	102 d (+15) 230.8 (+20)
LOW UTILIZATION										
24-35-01-900-001-A00	RESTORE (REPLACEMENT) NOSE EMERGENCY-ELECTRICAL EQUIPMENT, BACK-UP BATTERY 501-1228-04 83955 REF: AMM 24-35-01	MOS HRS/MSC AFL	12				21-JAN-2017 884.1 443	21-JAN-2018		286 d
SYSTEM										

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
24-36-01-900-001-A00	RESTORE (OVERHAUL) NO.1 NOSE 44AH, NI-CD BATTERY SAFT MAIN BATTERY NOTE: IF INSTALLED									
	442CH1	MOS	12				21-JAN-2017	21-JAN-2018		286 d
	201605777	HRS/MSC	1000				884.1	1884.1		980.8
RESTORE	REF: AMM 24-36-01	AFL					443			
24-36-01-900-001-A00	RESTORE (OVERHAUL) NO.2 NOSE 44AH, NI-CD BATTERY SAFT MAIN BATTERY. (IF INSTALLED)									
	442CH1	MOS	12				21-JAN-2017	21-JAN-2018		286 d
	201605778	HRS/MSC	1000				884.1	1884.1		980.8
RESTORE	REF: AMM 24-36-01	AFL					443			
24-40-00-720-001-A00 (s)	FUNCTIONALLY CHECK GPU OVERVOLTAGE PROTECTION						PKG			
	PKG 5016	MOS	96	+15d/-15d			26-JAN-2015			
		HRS/MSC	4000	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 24-40-00	AFL	2000	+20/-20			280			
24-60-00-710-001-A00 (s)	OPERATIONALLY CHECK ELECTRICAL EMERGENCY TRANSFER CIRCUIT						PKG			
	PKG 5016	MOS	96	+15d/-15d			26-JAN-2015			
		HRS/MSC	4000	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 24-60-00	AFL	2000	+20/-20			280			
24-60-00-710-002-A00 (s)	OPERATIONALLY CHECK ELECTRICAL EMERGENCY ABNORMAL ALARM						PKG			
	PKG 5001	MOS	12	+15d/-15d			21-JAN-2017			
		HRS/MSC	500	+20/-20			884.1			
LOW UTILIZATION	REF: AMM 24-60-00	AFL					443			
240000-0101	OVERH P MODULE -CONTROL,ELECTRIC SYS,OVER HEAD PANEL ASSEMBLY									
	135-14918-407	MOS					TSN:0	16-DEC-2010		
	0000639961	HRS/MSC	O/C				TSN:0	0		
	REF: AMM 24-00-01	AFL					TSN:0	0		
242103-0101	PAX STATIC ASSY, FUSLG CTL I INVERTER									
	SS200	MOS					TSN:0	16-DEC-2010		
	966	HRS/MSC	O/C				TSN:0	0		
	REF:	AFL					TSN:0	0		
242104-0101	OVERH P MODULE -ILLUMINATED PANEL,IFE/PC POWER,COCKPIT ASSEMBLY									
	135-04632-409	MOS					TSN:0	16-DEC-2010		
	0000637841	HRS/MSC	O/C				TSN:0	0		
	REF:	AFL					TSN:0	0		
243101-0201	LH OUTBOARD (NO.1) GENERATOR POWER UNIT									
	30086-011	MOS					TSO:0	08-JAN-2016		
	P2459	HRS/MSC	O/C				TSO:0	729		
	REF: AMM 24-31-01	AFL					TSO:0	362		
243101-0202	LH INBOARD (NO.3) GENERATOR POWER UNIT									
	30086-011	MOS					TSO:0	08-JAN-2016		
	P1714	HRS/MSC	O/C				TSO:0	729		
	REF: AMM 24-31-01	AFL					TSO:0	362		
243101-0203	RH INBOARD (NO.2) GENERATOR POWER UNIT									
	30086-011	MOS					TSO:0	08-JAN-2016		
	P2165	HRS/MSC	O/C				TSO:0	729		
	REF: AMM 24-31-01	AFL					TSO:0	362		

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
243101-0204	RH OUTBOARD (NO.4) GENERATOR POWER UNIT 30086-011 Y10756 REF: AMM 24-31-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			08-JAN-2016 729 362			
243102-0201	LH CSL (GCU 1) GENERATOR CONTROL-ELECTRICAL EQUIPMENT,CONSOLE,COCKPIT UNIT 51545-002A P2268 REF: AMM 24-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
243102-0202	LH CSL (GCU 3) GENERATOR CONTROL-ELECTRICAL EQUIPMENT,CONSOLE,COCKPIT UNIT 51545-002A P2270 REF: AMM 24-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
243102-0203	RH CSL (GCU 2) GENERATOR CONTROL-ELECTRICAL EQUIPMENT,CONSOLE,COCKPIT UNIT 51545-002A P2279 REF: AMM 24-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
243102-0204	RH CSL (GCU 4) GENERATOR CONTROL-ELECTRICAL EQUIPMENT,CONSOLE,COCKPIT UNIT 51545-002A P2282 REF: AMM 24-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
243401-0101	APU STARTER GENERATOR-400A/28VDC,APU UNIT 23080-013A Y10546 REF: AMM 24-34-01	MOS HRS/MSC AFL	O/C				26-JAN-2015 532.4 280			
243402-0101	CREW CAB GCU - GENERATOR CONTROL UNIT 51525-014A P1335 REF: AMM 24-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
243501-0101	NOSE EMERGENCY-ELECTRICAL EQUIPMENT, BACK-UP BATTERY 501-1228-04 83955 REF: AMM 24-35-01	MOS HRS/MSC AFL	O/C				21-JAN-2017 884.1 443			
243502-0101	NOSE MODULE -RELAY BOX,BATTERY BACKUP,ELECTRONIC COMPARTMENT ASSEMBLY 135-08601-401 0000635520 REF: AMM 24-35-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
243601-0101	NO.1 NOSE 44AH, NI-CD BATTERY 442CH1 201605777 REF: AMM 24-36-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			21-JAN-2017 884.1 443			
243601-0102	NO.2 NOSE 44AH, NI-CD BATTERY 442CH1 201605778 REF: AMM 24-36-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			21-JAN-2017 884.1 443			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
243602-0101	NOSE BATTERY 1 RELAY BOX- ASSEMBLY 135-26488-401 0000638279 REF: AMM 24-36-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
243602-0102	NOSE BATTERY 2 RELAY BOX- ASSEMBLY 145-31118-407 0000630745 REF: AMM 24-36-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
246005-0101	LEFT DC DISTRIBUTION BOX 135-18757-405 0000640996 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
246005-0102	RIGHT DC DISTRIBUTION BOX 135-18756-403 0000640998 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
APU Model : APS500R/T-62T-40C14 Serial # SP-E1028096 Part # 4504113A										
24-34-01-220-001-A00	APU - INSPECT (DETAILED INSPECTION) APU STARTER/GENERATOR BRUSHES	MOS HRS/MSC APUS	400				21-JAN-2017 1278 1275	1678		378
SYSTEM	REF: AMM 24-34-01									
24-34-01-900-001-A00	APU - RESTORE (OVERHAUL) APU STARTER/GENERATOR	MOS HRS/MSC APUS	48 1200		-41		26-JAN-2015 783.7 785	16-DEC-2018 1983.7		615 d 683.7
SYSTEM	REF: AMM 24-34-01									
CHAPTER 25	EQUIPMENT/FURNISHINGS									
25-11-01-140-001-A00 (s)	RESTORE (CLEANING) FLIGHT CREW SEATS LOCKING SYSTEM PKG 5001	MOS HRS/MSC AFL	12 500	+15d/-15d +20/-20			21-JAN-2017 884.1 443			
LOW UTILIZATION	REF: AMM 25-11-01									
25-11-01-220-001-A00 (s)	INSPECT (DETAILED INSPECTION) COCKPIT SEATS FOR SECURITY OF ATTACHMENT TO THE TRACK, INCLUDING RESTRAINT SYSTEM. PKG 5008	MOS HRS/MSC AFL	48 3600 1800	+15d/-15d +20/-20 +20/-20			26-JAN-2015 532.4 280			
LOW UTILIZATION	REF: AMM 25-11-01									
25-21-00-212-001-A00 (s)	INSPECT (GENERAL VISUAL) PASSENGER CABIN SEATS (FABRIC, COVER, SAFETY BELT, SEAT MOVEMENT AND ATTACHMENTS TO TRACK) PKG 5008	MOS HRS/MSC AFL	48 3600 1800	+15d/-15d +20/-20 +20/-20			26-JAN-2015 532.4 280			
LOW UTILIZATION	REF: See Workcard									
25-21-00-220-002-A00 (s)	INSPECT (DETAILED INSPECTION) FLIGHT ATTENDANT SEATS HARNESS, INERTIAL REEL FOR CONDITION AND THE SEAT BOTTOM FOR FREEDOM OF MOVEMENT AND RETURNING BACK TO UPRIGHT POSITION. (NOTE: IF INSTALLED) PKG 5008	MOS HRS/MSC AFL	48 3600 1800	+15d/-15d +20/-20 +20/-20			26-JAN-2015 532.4 280			
LOW UTILIZATION	REF: AMM 25-21-02									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-26-00-212-001-A00 (s)	INSPECT (GENERAL VISUAL) CREDENZA, CLOSETS AND ENTERTAINMENT CABINET FOR INTEGRITY AND SECURITY. PKG 5008	MOS	48	+15d/-15d			PKG			
LOW UTILIZATION	REF: AMM 25-26-00	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			26-JAN-2015 532.4 280			
25-27-02-211-001-A00 (s)	VISUALLY CHECK LAVATORY/BAGGAGE DOOR SEALING FOR CONDITION, INTEGRITY AND SECURITY. PKG 5002	MOS	12	+15d/-15d			PKG			
LOW UTILIZATION	REF: AMM 25-27-02	HRS/MSC AFL	500	+20/-20			21-JAN-2017 884.1 443			
25-30-06-212-001-A00 (s)	INSPECT (GENERAL VISUAL) FORWARD GALLEY STRUCTURE LOWER ATTACHMENT POINTS (ON THE TRACKS). PKG 5008	MOS	48	+15d/-15d			PKG			
LOW UTILIZATION	REF: AMM 25-30-01	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			26-JAN-2015 532.4 280			
25-40-04-212-001-A00 (s)	INSPECT (GENERAL VISUAL) LAVATORY STRUCTURE LOWER ATTACHMENT POINTS. PKG 5008	MOS	48	+15d/-15d			PKG			
LOW UTILIZATION	REF: AMM 25-40-01	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			26-JAN-2015 532.4 280			
25-60-01-212-001-A00	INSPECT (GENERAL VISUAL) FIRST AID KIT FOR CONDITION AND VALIDATION. NOTE: OR IN ACCORDANCE WITH LOCAL REGULATORY AUTHORITY REQUIREMENTS. AFAK 052768019	MOS	6	+15d/-15d	-30		21-JAN-2017 884.1 443	22-JUN-2017	07-JUL-2017	73 d (+15)
SYSTEM	REF: AMM 25-60-01	HRS/MSC AFL								
25-60-02-900-001-ALL	RESTORE ATTEND 1 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) 63600-505 L1466755	MOS	120				01-SEP-2010	01-SEP-2020		1240 d
VENDOR RECOMMENDATION	REF: AMM 25-60-02	HRS/MSC AFL								
25-60-02-900-001-ALL	RESTORE COPILOT EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) 63600-505 L1498424	MOS	120				01-SEP-2010	01-SEP-2020		1240 d
VENDOR RECOMMENDATION	REF: AMM 25-60-02	HRS/MSC AFL								
25-60-02-900-001-ALL	RESTORE OBSERVER EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) 63600-505 L1498425	MOS	120				01-SEP-2010	01-SEP-2020		1240 d
VENDOR RECOMMENDATION	REF: AMM 25-60-02	HRS/MSC AFL								
25-60-02-900-001-ALL	RESTORE PAX 1 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) 63600-105 L1461335	MOS	120				01-JUN-2010	01-JUN-2020		1148 d
VENDOR RECOMMENDATION	REF: AMM 25-60-02	HRS/MSC AFL								
25-60-02-900-001-ALL	RESTORE PAX 10 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) 63600-105 L1461344	MOS	120				01-JUN-2010	01-JUN-2020		1148 d
VENDOR RECOMMENDATION	REF: AMM 25-60-02	HRS/MSC AFL								



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-60-02-900-001-ALL	RESTORE PAX 11 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) 63600-105 L1461352	MOS HRS/MSC AFL	120				01-JUN-2010	01-JUN-2020		1148 d
VENDOR RECOMMENDATION	REF: AMM 25-60-02									
25-60-02-900-001-ALL	RESTORE PAX 12 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) 63600-105 L1461356	MOS HRS/MSC AFL	120				01-JUN-2010	01-JUN-2020		1148 d
VENDOR RECOMMENDATION	REF: AMM 25-60-02									
25-60-02-900-001-ALL	RESTORE PAX 13 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) 63600-105 L1461394	MOS HRS/MSC AFL	120				01-JUN-2010	01-JUN-2020		1148 d
VENDOR RECOMMENDATION	REF: AMM 25-60-02									
25-60-02-900-001-ALL	RESTORE PAX 14 EMERGENCY EQUIPMENT LIFE JACKET 63600-105 L1461426	MOS HRS/MSC AFL	120				01-JUN-2010	01-JUN-2020		1148 d
VENDOR RECOMMENDATION	REF: AMM 25-60-02									
25-60-02-900-001-ALL	RESTORE PAX 2 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) 63600-105 L1461336	MOS HRS/MSC AFL	120				01-JUN-2010	01-JUN-2020		1148 d
VENDOR RECOMMENDATION	REF: AMM 25-60-02									
25-60-02-900-001-ALL	RESTORE PAX 3 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) 63600-105 L1461337	MOS HRS/MSC AFL	120				01-JUN-2010	01-JUN-2020		1148 d
VENDOR RECOMMENDATION	REF: AMM 25-60-02									
25-60-02-900-001-ALL	RESTORE PAX 4 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) 63600-105 L1461338	MOS HRS/MSC AFL	120				01-JUN-2010	01-JUN-2020		1148 d
VENDOR RECOMMENDATION	REF: AMM 25-60-02									
25-60-02-900-001-ALL	RESTORE PAX 5 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) 63600-105 L1461339	MOS HRS/MSC AFL	120				01-JUN-2010	01-JUN-2020		1148 d
VENDOR RECOMMENDATION	REF: AMM 25-60-02									
25-60-02-900-001-ALL	RESTORE PAX 6 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) 63600-105 L1461340	MOS HRS/MSC AFL	120				01-JUN-2010	01-JUN-2020		1148 d
VENDOR RECOMMENDATION	REF: AMM 25-60-02									
25-60-02-900-001-ALL	RESTORE PAX 7 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) 63600-105 L1461341	MOS HRS/MSC AFL	120				01-JUN-2010	01-JUN-2020		1148 d
VENDOR RECOMMENDATION	REF: AMM 25-60-02									
25-60-02-900-001-ALL	RESTORE PAX 8 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) 63600-105 L1461342	MOS HRS/MSC AFL	120				01-JUN-2010	01-JUN-2020		1148 d
VENDOR RECOMMENDATION	REF: AMM 25-60-02									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
25-60-02-900-001-ALL	RESTORE PAX 9 EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) 63600-105 L1461343	MOS HRS/MSC AFL	120				01-JUN-2010	01-JUN-2020		1148 d
VENDOR RECOMMENDATION	REF: AMM 25-60-02									
25-60-02-900-001-ALL	RESTORE PILOT EMERGENCY EQUIPMENT LIFE JACKET (25-60-02-900-001-A00/A01/A02/A03/A04/A05) 63600-505 L1498423	MOS HRS/MSC AFL	120				01-SEP-2010	01-SEP-2020		1240 d
VENDOR RECOMMENDATION	REF: AMM 25-60-02									
25-61-00-212-001-A00	INSPECT (GENERAL VISUAL) EMERGENCY LOCATOR TRANSMITTER FOR CONDITION PROPER INSTALLATION BATTERY CORROSION AND LEAKAGE NOTE: OR IN ACCORDANCE WITH LOCAL REGULATORY AUTHORITY REQUIREMENTS.	MOS HRS/MSC AFL	12	+15d/-15d	-33		21-JAN-2017 884.1 443	19-DEC-2017	03-JAN-2018	253 d (+15)
SYSTEM	REF: See Workcard									
25-61-00-710-001-A00	OPERATIONAL CHECK EMERGENCY LOCATOR TRANSMITTER SYSTEM - PROPER OPERATION- CRASH SWITCH OPERATION(NOTE: OR IN ACCORDANCE WITH LOCAL REGULATORY AUTHORITY REQUIREMENTS).	MOS HRS/MSC AFL	12	+15d/-15d	-57		21-JAN-2017 884.1 443	25-NOV-2017	10-DEC-2017	229 d (+15)
SYSTEM	REF: See Workcard									
25-63-00-710-001-A00	OPERATIONALLY CHECK PORTABLE EMERGENCY LOCATOR TRANSMITTER SYSTEM NOTE: OR IN ACCORDANCE WITH LOCAL REGULATORY AUTHORITY REQUIREMENTS. NOTE: IF INSTALLED	MOS HRS/MSC AFL	12				21-JAN-2017 884.1 443	21-JAN-2018		286 d
NATIONAL REQUIREMENT	REF:									
25-63-01-900-001-A01	RESTORE (OVERHAUL) NO. 1 LIFE RAFT WINSLOW (VACUUM PACKED) ASSEMBLY 69FASA-631-1-702 6UL-01397	MOS HRS/MSC AFL	36				01-DEC-2016	01-DEC-2019 M		965 d
SYSTEM	REF: AMM 25-60-05									
25-63-01-900-001-A01	RESTORE (OVERHAUL) NO. 2 LIFE RAFT WINSLOW (VACUUM PACKED) ASSEMBLY 69FASA-631-1-702 6UL-01395	MOS HRS/MSC AFL	36				22-JUL-2016 835.3 411	22-JUL-2019		833 d
SYSTEM	REF: AMM 25-60-05									
25-63-01-900-001-A01	RESTORE NO. 3 LIFE RAFT WINSLOW (VACUUM PACKED) ASSEMBLY 69FASA-6J1-1-702 6UL-01396	MOS HRS/MSC AFL	36				30-AUG-2016	30-AUG-2019 M		872 d
SYSTEM	REF: AMM 25-60-05									
25-63-02-960-001-A00	DISCARD PORTABLE ELT BATTERY ELTA PN: 05N62123 NOTE: PORTABLE ELT BATTERY CHANGE IN ACCORDANCE WITH MANUFACTURER'S DATA PLATE EXPIRATION DATE OR IN ACCORDANCE WITH LOCAL REGULATORY AUTHORITY REQUIREMENTS	MOS HRS/MSC AFL	N/A				16-DEC-2010 0 0			
REF:										
251101-0101	PILOT ASSY-PILOT SEAT 1471611-05 07T2451	MOS HRS/MSC AFL	O/C				16-DEC-2010 0 0			
REF:	AMM 25-11-01									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
251101-0102	COPILOT ASSY-CO-PILOT SEAT 1471610-05 10T0662 REF: AMM 25-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
251102-0101	OBSERVER ASSEMBLY SEAT PN SN-UNKNOWN REF: AMM 25-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
252102-0101	FLIGHT ATTENDANT SEAT ASSY 3DQF1101016BZCP 100823-48 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
253103-0101	GALLEY CABINET ELECTRICAL OVEN 400-2095-01-R 10-09-47497 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
253104-0101	GALLEY CABINET MICROWAVE OVEN 910-0022-01 11-01-48014 REF: AMM 25-31-04	MOS HRS/MSC AFL	O/C				16-DEC-2016 882.6 442			
253105-0101	GALLEY ELECTRICAL COFFEE MAKER 400-1794-10 10-06-47245 REF: AMM 25-31-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
253205-0101	OVEN REAR CABINET ,GALLEY CONTROL PANEL PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
255006-0101	BAGGAGE COMPARTMENT REAR BULKHEAD PANEL ASSY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
256001-0101	FIRST AID KIT AFAK 052768019 REF:	MOS HRS/MSC AFL	12 A/R				21-JAN-2017 884.1 443	31-JAN-2018 M		296 d
256002-0101	PILOT EMERGENCY EQUIPMENT LIFE JACKET 63600-505 L1498423 REF: AMM 25-60-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
256002-0102	COPILOT EMERGENCY EQUIPMENT LIFE JACKET 63600-505 L1498424 REF: AMM 25-60-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
256002-0103	OBSERVER EMERGENCY EQUIPMENT LIFE JACKET 63600-505 L1498425 REF: AMM 25-60-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
256002-0104	ATTEND 1 EMERGENCY EQUIPMENT LIFE JACKET 63600-505 L1466755 REF: AMM 25-60-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
256002-7101	PAX 1 EMERGENCY EQUIPMENT LIFE JACKET 63600-105 L1461335 REF: AMM 25-60-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
256002-7102	PAX 2 EMERGENCY EQUIPMENT LIFE JACKET 63600-105 L1461336 REF: AMM 25-60-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
256002-7103	PAX 3 EMERGENCY EQUIPMENT LIFE JACKET 63600-105 L1461337 REF: AMM 25-60-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
256002-7104	PAX 4 EMERGENCY EQUIPMENT LIFE JACKET 63600-105 L1461338 REF: AMM 25-60-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
256002-7105	PAX 5 EMERGENCY EQUIPMENT LIFE JACKET 63600-105 L1461339 REF: AMM 25-60-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
256002-7106	PAX 6 EMERGENCY EQUIPMENT LIFE JACKET 63600-105 L1461340 REF: AMM 25-60-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
256002-7107	PAX 7 EMERGENCY EQUIPMENT LIFE JACKET 63600-105 L1461341 REF: AMM 25-60-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
256002-7108	PAX 8 EMERGENCY EQUIPMENT LIFE JACKET 63600-105 L1461342 REF: AMM 25-60-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
256002-7109	PAX 9 EMERGENCY EQUIPMENT LIFE JACKET 63600-105 L1461343 REF: AMM 25-60-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
256002-7110	PAX 10 EMERGENCY EQUIPMENT LIFE JACKET 63600-105 L1461344 REF: AMM 25-60-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
256002-7111	PAX 11 EMERGENCY EQUIPMENT LIFE JACKET 63600-105 L1461352 REF: AMM 25-60-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
256002-7112	PAX 12 EMERGENCY EQUIPMENT LIFE JACKET 63600-105 L1461356 REF: AMM 25-60-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
256002-7113	PAX 13 EMERGENCY EQUIPMENT LIFE JACKET 63600-105 L1461394 REF: AMM 25-60-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
256002-7114	PAX 14 EMERGENCY EQUIPMENT LIFE JACKET 63600-105 L1461426 REF: AMM 25-60-02	MOS HRS/MSC AFL	O/C							
256003-7101	NO. 1 LIFE RAFT 69FASA-631-1-702 6UL-01397 REF:	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			25-JAN-2017 885.7 444			
256003-7102	NO. 2 LIFE RAFT 69FASA-631-1-702 6UL-01395 REF:	MOS HRS/MSC AFL	O/C				29-JUL-2016 835.3 411			
256003-7103	NO. 3 LIFE RAFT 69FASA-6J1-1-702 6UL-01396 REF:	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			19-OCT-2016 865.9 431			
256100-0101	CREW CAB MODULE -ELT ASSEMBLY PN SN-UNKNOWN REF: AMM 25-61-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
256104-0101	ELT - RADIO/NAVIGATION SYS, EMERGENCY LOCATOR TRANSMITTER 453-5000 170-12953 REF: AMM 25-61-01	MOS HRS/MSC AFL	O/C	TSN:27 TSN:97.92 TSN:83			05-MAR-2013 97.92 83			
256104-0101D	DISCARD EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY (NOTE: IN ACCORDANCE WITH MANUFACTURERS DATAPLATE EXPIRATION DATE OR LOCAL REGULATORY AUTHORITY REQUIREMENTS). PN SN-UNKNOWN REF: AMM 25-61-04	MOS HRS/MSC AFL	60				26-JAN-2015 532.4 280	01-JAN-2020 M		996 d
SYSTEM										

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
256104-0102	EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	C/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
259500-0201	REAR ELT ANTENNA 110-328-01 7580-01 REF: AMM 25-61-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
259502-7302	ASSY- AFT DIVAN SEAT 3DQF1101018BZCP 100823-49 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
259502-7304	NO.1 DOUBLE, SERIES 200 SEAT 3AQF1203002BZCP 100823-42 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
259502-7305	NO. 2 DOUBLE, SERIES 200 SEAT 3AQF1203003BZCP 100823-43 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
259502-7306	FWD DIVAN SEAT 3DQF1101019BZCP 100823-44 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
259502-7307	MID DIVAN SEAT 3DQF1101014BZCP 100823-47 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
259502-7308	SINGLE SERIES 200 SEAT 3AQF1103003BZCP 100823-40 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
259502-7309	SINGLE SERIES 200 SEAT 3AQF1103006BZCP 100823-38 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
259502-7310	SINGLE SERIES 200 SEAT 3AQF1103008BZCP 100823-41 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
259502-7311	SINGLE SERIES 200 SEAT 3AQF1103009BZCP 100823-39 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
259502-7312	SINGLE SERIES 200 SEAT 3DQF1101021BZCP 100823-45 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
259502-7313	SINGLE SERIES 200 SEAT 3DQF1101023BZCP 100823-46 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
CHAPTER 26	FIRE PROTECTION									
26-14-00-710-001-A00 (s)	OPERATIONALLY CHECK LAVATORY SMOKE DETECTOR (ACTUATING THE SMOKE SENSOR WITH SMOKE) NOTE: IF INSTALLED PKG 5012	MOS HRS/MSC AFL	72	+15d/-15d +20/-20 +20/-20			21-JAN-2017 884.1 443			
LOW UTILIZATION	REF: AMM 26-14-01									
26-14-01-960-001-A00	DISCARD JAMCO LAVATORY SMOKE DETECTOR (IF INSTALLED)	MOS HRS/MSC AFL	180				16-DEC-2010 0 0	16-DEC-2025		3172 d
SYSTEM	REF: AMM 26-14-01									
26-15-00-710-001-A00 (s)	OPERATIONALLY CHECK BAGGAGE SMOKE DETECTION SYSTEM PKG 5001	MOS HRS/MSC AFL	6	+15d/-15d +20/-20			21-JAN-2017 884.1 443			
LOW UTILIZATION	REF: AMM 26-15-00									
26-21-00-720-001-A00	FUNCTIONALLY CHECK ENGINE FIRE EXTINGUISHING SYSTEM NOTE: OR IN ACCORDANCE WITH LOCAL REGULATORY AUTHORITY REQUIREMENTS	MOS HRS/MSC AFL	36		-36		21-JAN-2017 884.1 443	16-DEC-2019		980 d
SYSTEM	REF: AMM 26-21-00									
26-21-02-280-001-A00	INSPECT (SPECIAL INSPECTION) LH ENGINE FIRE EXTINGUISHER BOTTLE FOR WEIGHT AND CHECK BOTTLE PRESSURE.(NOTE: OR IN ACCORDANCE WITH LOCAL REGULATORY AUTHORITY REQUIREMENTS). 33600057-5 62749D1 REF: AMM 26-21-02	MOS HRS/MSC AFL	12	+15d/-15d			21-JAN-2017	21-JAN-2018	05-FEB-2018	286 d (+15)
SYSTEM										
26-21-02-280-001-A00	INSPECT (SPECIAL INSPECTION) RH ENGINE FIRE EXTINGUISHER BOTTLE FOR WEIGHT AND CHECK BOTTLE PRESSURE.(NOTE: OR IN ACCORDANCE WITH LOCAL REGULATORY AUTHORITY REQUIREMENTS). 33600057-5 55741D1 REF: AMM 26-21-02	MOS HRS/MSC AFL	12	+15d/-15d	-43		21-JAN-2017	09-DEC-2017	24-DEC-2017	243 d (+15)
SYSTEM										
26-21-02-720-001-A00	FUNCTIONALLY CHECK (HYDROSTATIC TEST) LH ENGINE FIRE EXTINGUISHER BOTTLE 33600057-5 62749D1 REF: AMM 26-21-02	MOS HRS/MSC AFL	60				24-JUN-2013	24-JUN-2018		440 d
SYSTEM										
26-21-02-720-001-A00	FUNCTIONALLY CHECK (HYDROSTATIC TEST) RH ENGINE FIRE EXTINGUISHER BOTTLE 33600057-5 55741D1 REF: AMM 26-21-02	MOS HRS/MSC AFL	60				09-DEC-2014	09-DEC-2019 M		973 d
SYSTEM										

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
26-21-03-720-001-A00	FUNCTIONALLY CHECK L/H ENGINE FIRE EXTINGUISHING BOTTLE PRESSURE SWITCH	MOS HRS/MSC AFL	60				24-JUN-2013	24-JUN-2018		440 d
SYSTEM	REF: AMM 26-21-03									
26-21-03-720-001-A00	FUNCTIONALLY CHECK R/H ENGINE FIRE EXTINGUISHING BOTTLE PRESSURE SWITCH	MOS HRS/MSC AFL	60				09-DEC-2014	09-DEC-2019		973 d
SYSTEM	REF: AMM 26-21-03									
26-21-05-720-001-A00	FUNCTIONALLY CHECK TWO-WAY TEE CHECK VALVES	MOS HRS/MSC AFL	72 8000		-36		21-JAN-2017 884.1 443	16-DEC-2022 8884.1		2076 d 7980.8
SYSTEM	REF: AMM 26-21-05									
26-22-00-720-001-A00	FUNCTIONALLY CHECK APU FIRE-EXTINGUISHING SYSTEM (BETWEEN SWITCH AND BOTTLE CONNECTOR) AND VERIFY APU ISOLATION BY APU FUEL SHUTOFF VALVE ACTUATION. (NOTE: OR IN ACCORDANCE WITH LOCAL REGULATORY AUTHORITY REQUIREMENTS).	MOS HRS/MSC AFL	36		-36		21-JAN-2017 884.1 443	16-DEC-2019		980 d
SYSTEM	REF: AMM 26-22-00									
26-22-01-280-001-A00	INSPECT (SPECIAL INSPECTION) APU FIRE EXTINGUISHER, REAR APU BOTTLE FOR WEIGHT AND CHECK BOTTLE PRESSURE. (NOTE: OR IN ACCORDANCE WITH LOCAL REGULATORY AUTHORITY REQUIREMENTS).	MOS HRS/MSC AFL	12	+15d/-15d	-13		21-JAN-2017	08-JAN-2018	23-JAN-2018	273 d (+15)
SYSTEM	30100050-5 66321A1 REF: AMM 26-22-01									
26-22-01-720-001-A00	FUNCTIONALLY CHECK (HYDROSTATIC TEST) APU FIRE EXTINGUISHER, REAR APU BOTTLE	MOS HRS/MSC AFL	60				30-APR-2013	30-APR-2018 M		385 d
SYSTEM	30100050-5 66321A1 REF: AMM 26-22-01									
26-22-02-720-001-A00	FUNCTIONALLY CHECK APU FIRE EXTINGUISHING BOTTLE PRESSURE SWITCH	MOS HRS/MSC AFL	60		-23		08-JAN-2016 729 362	16-DEC-2020		1346 d
SYSTEM	REF: AMM 26-22-02									
26-23-00-720-001-A00 (s)	FUNCTIONALLY CHECK BAGGAGE-COMPARTMENT FIRE EXTINGUISHING SYSTEM (COVERING THE PRESSURE SWITCH, CARTRIDGE, BAGG FIRE EXTING. SWITCH AND ELECTRICAL HARDWARE).	MOS HRS/MSC AFL	48 3600 1800	+15d/-15d +20/-20 +20/-20			26-JAN-2015 532.4 280	PKG		
LOW UTILIZATION	PKG 5008 REF: AMM 26-23-00									
26-23-01-280-001-A00	INSPECT (SPECIAL INSPECTION) NO.1 BAGGAGE COMPARTMENT HIGH RATE FIRE EXTINGUISHER BOTTLE (HIGH RATE AND METERING) FOR WEIGHT.	MOS HRS/MSC AFL	12	+15d/-15d	-13		21-JAN-2017	08-JAN-2018	23-JAN-2018	273 d (+15)
SYSTEM	33700027-1 70991D1 REF: AMM 26-23-01									
26-23-01-280-001-A00	INSPECT (SPECIAL INSPECTION) NO.2 BAGGAGE COMPARTMENT METERING FIRE EXTINGUISHER BOTTLE (HIGH RATE AND METERING) FOR WEIGHT.	MOS HRS/MSC AFL	12	+15d/-15d			21-JAN-2017	21-JAN-2018	05-FEB-2018	286 d (+15)
SYSTEM	34600073-3 31589F1 REF: AMM 26-23-01									

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
26-23-01-720-001-A00	FUNCTIONALLY CHECK (HYDROSTATIC TEST) NO.1 BAGGAGE COMPARTMENT HIGH RATE FIRE EXTINGUISHER BOTTLE 33700027-1 70991D1 REF: AMM 26-23-01	MOS HRS/MSC AFL	60				01-JUN-2015	01-JUN-2020		1148 d
SYSTEM										
26-23-01-720-001-A00	FUNCTIONALLY CHECK (HYDROSTATIC TEST) NO.2 BAGGAGE COMPARTMENT METERING FIRE EXTINGUISHER BOTTLE 34600073-3 31589F1 REF: AMM 26-23-01	MOS HRS/MSC AFL	60				01-AUG-2014	01-AUG-2019		843 d
SYSTEM										
26-23-04-720-001-A00 (s)	FUNCTIONALLY CHECK TWO-WAY CHECK TEE VALVE PKG 5012 REF: AMM 26-23-04	MOS HRS/MSC AFL	72	+15d/-15d 3000 1500			PKG 21-JAN-2017 884.1 443			
LOW UTILIZATION										
26-24-00-720-001-A00	FUNCTIONALLY CHECK COCKPIT PORTABLE FIRE EXTINGUISHER BOTTLE DISCARD FOR WEIGHT (SEE PLACARD ATTACHED TO THE BOTTLE) BA21741GSR-2 070271 REF: AMM 26-24-00	MOS HRS/MSC AFL	12				21-JAN-2017 884.1 443	21-JAN-2018		286 d
SYSTEM										
26-24-00-720-001-A00	FUNCTIONALLY CHECK FORWARD PORTABLE FIRE EXTINGUISHER (PAX CABIN) BOTTLE FOR WEIGHT (SEE PLACARD ATTACHED TO THE BOTTLE) BA21741GSR-2 070270 REF: AMM 26-24-00	MOS HRS/MSC AFL	12				21-JAN-2017 884.1 443	21-JAN-2018		286 d
SYSTEM										
26-25-00-280-001-A00	INSPECT (SPECIAL INSPECTION) GALLEY FIRE EXTINGUISHER WASTE DISPOSAL ASSEMBLY FOR WEIGHT (SEE PLACARD ATTACHED TO THE BOTTLE). BA22557-1 47667 REF: AMM 26-25-01	MOS HRS/MSC AFL	12				21-JAN-2017	21-JAN-2018		286 d
SYSTEM										
26-25-00-280-001-A00	INSPECT (SPECIAL INSPECTION) LAVATORY FIRE EXTINGUISHER WASTE DISPOSAL ASSEMBLY FOR WEIGHT (SEE PLACARD ATTACHED TO THE BOTTLE). BA22557-1 47283 REF: AMM 26-25-01	MOS HRS/MSC AFL	12				21-JAN-2017	21-JAN-2018		286 d
SYSTEM										
260000-0101	OVERH P FIRE EXTINGUISHING APU/BAGG MODULE 145-34156-401 0000637153 REF:	MOS HRS/MSC AFL	O/C			TSN:0 TSN:0 TSN:0	16-DEC-2010 0 0			
261101-0101	LH ENGINE ACC FIRE DETECTOR 3601-133-500/230C-9.0M 243949 REF: AMM 26-11-01	MOS HRS/MSC AFL	O/C			TSN:0 TSN:0 TSN:0	16-DEC-2010 0 0			
261101-0102	RH ENGINE ACC FIRE DETECTOR 3601-133-500/230C-9.0M 243977 REF: AMM 26-11-01	MOS HRS/MSC AFL	O/C			TSN:0 TSN:0 TSN:0	16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
261102-0101	LH ENGINE PYLON FIRE DETECTOR 3601-134-480/220C-2.7M 243968 REF: AMM 26-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
261102-0102	RH ENGINE PYLON FIRE DETECTOR 3601-134-480/220C-2.7M 243969 REF: AMM 26-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
261103-0101	LH CSL CONTROL-FIRE PROTECTION SYS, CONSOLE, COCKPIT MODULE 902081 3721 REF: AMM 26-11-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
261103-0102	RH CSL CONTROL-FIRE PROTECTION SYS, CONSOLE, COCKPIT MODULE 902081 3727 REF: AMM 26-11-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
261103-0103	LH CSL CONTROL-FIRE PROTECTION SYS, CONSOLE, COCKPIT MODULE 902081 3729 REF: AMM 26-11-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
261201-0101	APU APU FIRE DETECTOR 3601-135-470/200C-3.5M 244016 REF: AMM 26-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
261500-0101	BAGGAGE COMPARTMENT CEILING SMOKE DETECTOR 473597-13 4413 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
261500-0102	BAGGAGE BULKHEAD SMOKE DETECTOR 473597-13 4402 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
262101-0101	PILOT FIRE EXTINGUISHING, ENGINE OVERHEAD PANEL, PAX CABIN HANDLE 1-7054-3 2245 REF: AMM 26-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
262101-0102	COPILLOT FIRE EXTINGUISHING, ENGINE 2-OVERHEAD PANEL HANDLE 2-7054-3 2235 REF: AMM 26-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
262102-0101	LH ENGINE FIRE EXTINGUISHER BOTTLE 33600057-5 62749D1 REF: AMM 26-21-02	MOS HRS/MSC AFL	O/C	TSO:31 TSO:76 TSO:29			08-JAN-2016 729 362			



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
262102-0102	RH ENGINE FIRE EXTINGUISHER BOTTLE 33600057-5 55741D1 REF: AMM 26-21-02	MOS HRS/MSC AFL	O/C	TSO:13 TSO:76 TSO:29			08-JAN-2016 729 362			
262102-0201	NO. 1 LEFT ENGINE FIRE EXTINGUISHER BOTTLE CARTRIDGE 30903920 8007345613 REF: See Workcard	MOS HRS/MSC AFL	108				21-JAN-2017 884.1 443	29-APR-2021 M		1480 d
262102-0201A	DISCARD NO. 1 LEFT ENGINE FIRE EXTINGUISHER BOTTLE CARTRIDGE (26-21-04-960-001-A00) 30903920 8007345613 REF: AMM 26-21-04	MOS HRS/MSC AFL	72				21-JAN-2017	21-JAN-2023		2112 d
262102-0202	NO. 2 LEFT ENGINE FIRE EXTINGUISHER BOTTLE CARTRIDGE 30903920 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	108				21-JAN-2017 884.1 443	29-APR-2021 M		1480 d
262102-0202A	DISCARD NO. 2 LEFT ENGINE FIRE EXTINGUISHER BOTTLE CARTRIDGE (26-21-04-960-001-A00) 30903920 SN-UNKNOWN REF: AMM 26-21-04	MOS HRS/MSC AFL	72				21-JAN-2017	21-JAN-2023		2112 d
262102-0203	NO. 1 RIGHT ENGINE FIRE EXTINGUISHER BOTTLE CARTRIDGE 30903920 8008016881 REF: See Workcard	MOS HRS/MSC AFL	108	TSN:0 TSN:0 TSN:0			21-JAN-2017 884.1 443	13-NOV-2022 M		2043 d
262102-0203A	DISCARD NO. 1 RIGHT ENGINE FIRE EXTINGUISHER BOTTLE CARTRIDGE (26-21-04-960-001-A00) 30903920 8008016881 REF: AMM 26-21-04	MOS HRS/MSC AFL	72				21-JAN-2017	21-JAN-2023		2112 d
262102-0204	NO. 2 RIGHT ENGINE FIRE EXTINGUISHER BOTTLE CARTRIDGE 30903920 8007331699 REF: See Workcard	MOS HRS/MSC AFL	108				21-JAN-2017 884.1 443	29-MAY-2021 M		1510 d
262102-0204A	DISCARD NO. 2 RIGHT ENGINE FIRE EXTINGUISHER BOTTLE CARTRIDGE (26-21-04-960-001-A00) 30903920 8007331699 REF: AMM 26-21-04	MOS HRS/MSC AFL	72				21-JAN-2017	21-JAN-2023		2112 d
262201-0101	APU FIRE EXTINGUISHER, REAR APU BOTTLE 30100050-5 66321A1 REF: AMM 26-22-01	MOS HRS/MSC AFL	O/C	TSN:10 TSN:172.2 TSN:74			08-JAN-2016 729 362			
262201-0201	APU FIRE EXTINGUISHER BOTTLE CARTRIDGE 30903920 8008016881 REF: See Workcard	MOS HRS/MSC AFL	108	TSN:0 TSN:0 TSN:0			21-JAN-2017 884.1 443	13-NOV-2022 M		2043 d

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
262201-0201A	DISCARD APU FIRE EXTINGUISHER BOTTLE CARTRIDGE (26-22-03-960-001-A00) 30903920 8008016881 REF: AMM 26-22-03	MOS HRS/MSC AFL	72				21-JAN-2017	21-JAN-2023		2112 d
SERVICE LIFE LIMIT										
262301-0101	NO.1 BAGGAGE COMPARTMENT HIGH RATE FIRE EXTINGUISHER BOTTLE 33700027-1 70991D1 REF: AMM 26-23-01	MOS HRS/MSC AFL	O/C				08-JAN-2016 865.9 431			
262301-0102	NO.2 BAGGAGE COMPARTMENT METERING FIRE EXTINGUISHER BOTTLE 34600073-3 31589F1 REF: AMM 26-23-01	MOS HRS/MSC AFL	O/C				08-JAN-2016 865.9 431			
262301-0201	BAGGAGE COMPARTMENT HIGH RATE FIRE EXTINGUISHER BOTTLE CARTRIDGE 30903870 1258LE REF: AMM 26-23-02	MOS HRS/MSC AFL	180				27-SEP-2015	15-AUG-2020 M		1223 d
LIFE LIMIT										
262301-0201A	SERVICE LIFE BAGGAGE COMPARTMENT HIGH RATE FIRE EXTINGUISHER BOTTLE CARTRIDGE 30903870 1258LE REF: GENERIC NO REF	MOS HRS/MSC AFL	120				01-AUG-2010	01-AUG-2020		1209 d
SERVICE LIFE LIMIT										
262301-0202	BAGGAGE COMPARTMENT METERING FIRE EXTINGUISHER BOTTLE CARTRIDGE 30903870 0822RD REF: AMM 26-23-02 Manufacture Date: 01-JUL-2014	MOS HRS/MSC AFL	180				27-SEP-2015	01-JUL-2029		4465 d
LIFE LIMIT										
262301-0202A	SERVICE LIFE BAGGAGE COMPARTMENT METERING FIRE EXTINGUISHER BOTTLE CARTRIDGE (26-23-02-960-001-A00) 30903870 0822RD REF: GENERIC NO REF	MOS HRS/MSC AFL	120				27-SEP-2015	27-SEP-2025		3092 d
SERVICE LIFE LIMIT										
262400-0101	COCKPIT PORTABLE FIRE EXTINGUISHER BOTTLE DISCARD BA21741GSR-2 070271 REF: See Workcard Manufacture Date: 01-JUL-2010	MOS HRS/MSC AFL	120		TSN:0 TSN:0 TSN:0		01-JUL-2010	01-JUL-2020		1178 d
LIFE LIMIT										
262400-0102	FORWARD PORTABLE FIRE EXTINGUISHER (PAX CABIN) BOTTLE BA21741GSR-2 070270 REF: See Workcard Manufacture Date: 01-JUL-2010	MOS HRS/MSC AFL	120		TSN:0 TSN:0 TSN:0		01-JUL-2010	01-JUL-2020		1178 d
LIFE LIMIT										
262500-0101	LAVATORY FIRE EXTINGUISHER WASTE DISPOSAL ASSEMBLY BA22557-1 47283 REF: AMM 26-25-01	MOS HRS/MSC AFL	O/C		TSN:61 TSN:729 TSN:362		08-JAN-2016 729 362			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
262500-0102	GALLEY FIRE EXTINGUISHER WASTE DISPOSAL ASSEMBLY BA22557-1 47667 REF: AMM 26-25-01	MOS HRS/MSC AFL	O/C	TSN:61 TSN:729 TSN:362			08-JAN-2016 729 362			
264100-0101	LH WING FUEL QUANTITY TRANSMITTER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
CHAPTER 27 FLIGHT CONTROLS										
27-11-00-220-001-A00 (s)	INSPECT (DETAILED INSPECTION) AILERON PRIMARY MECHANICAL CONTROL FROM CONTROL WHEEL TO AILERON PCAS, CHECKING CABLES, PULLEYS, NRUS, QUADRANTS, DISCONNECT SYSTEM, AND MECHANICAL LINKS PKG 5008 REF: AMM 27-11-00	MOS HRS/MSC AFL	48 3600 1800	+15d/-15d +20/-20 +20/-20			PKG 26-JAN-2015 532.4 280			
LOW UTILIZATION										
27-11-00-640-001-A00 (s)	LUBRICATE CONTROL WHEEL CHAIN PKG 5008 REF: AMM 27-11-00	MOS HRS/MSC AFL	48 3600 1800	+15d/-15d +20/-20 +20/-20			PKG 26-JAN-2015 532.4 280			
LOW UTILIZATION										
27-11-00-720-001-A00 (s)	FUNCTIONALLY CHECK AILERON PRIMARY MECHANICAL CONTROL BACKLASH PKG 5009,5016 REF: AMM 27-11-00	MOS HRS/MSC AFL	96 4000 2000	+15d/-15d +20/-20 +20/-20			PKG 16-DEC-2010 0 0			
LOW UTILIZATION										
27-11-01-720-001-A00	FUNCTIONALLY CHECK TENSION OF AILERON CONTROL CABLES. PKG 5008 REF: AMM 27-11-01	MOS HRS/MSC AFL	48 3600 1800	+15d/-15d			26-JAN-2015 532.4 280	26-JAN-2019 4132.4 2080	10-FEB-2019	656 d (+15) 3229.1 1630
LOW UTILIZATION										
27-12-00-720-001-A00 (s)	FUNCTIONALLY CHECK AILERON HYDRAULIC ACTUATION PKG 5016 REF: AMM 27-12-00	MOS HRS/MSC AFL	96 7200 3600	+15d/-15d +20/-20 +20/-20			PKG 16-DEC-2010 0 0			
LOW UTILIZATION										
27-12-00-720-003-A01	FUNCTIONALLY CHECK EXTERNAL LEAKAGE OF AILERON HYDRAULIC ACTUATOR PKG 5004 REF: AMM 27-12-00	MOS HRS/MSC AFL	24 1800 900	+15d/-15d +20/-20 +20/-20	-36		21-JAN-2017 884.1 443	16-DEC-2018 2684.1 1343	31-DEC-2018	615 d (+15) 1780.8 (+20) 893 (+20)
LOW UTILIZATION										
27-12-00-720-003-A02	FUNCTIONALLY CHECK EXTERNAL LEAKAGE OF AILERON HYDRAULIC ACTUATOR REF: AMM 27-12-00	MOS HRS/MSC AFL	N/A				07-JAN-2013 93.67 78			
LOW UTILIZATION										
27-12-01-212-001-A00 (s)	INSPECT (GENERAL VISUAL) AILERON PCA HOSES PKG 5008 REF: AMM 27-12-01	MOS HRS/MSC AFL	48 3600 1800	+15d/-15d +20/-20 +20/-20			PKG 26-JAN-2015 532.4 280			
LOW UTILIZATION										

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-12-01-212-002-A01	INSPECT (GENERAL VISUAL) AILERON PCA ROD ENDS/FITTING LUGS FOR INTEGRITY AND GENERAL CONDITION PKG 5002	MOS	12	+15d/-15d			21-JAN-2017	19-DEC-2017	03-JAN-2018	253 d (+15)
		HRS/MSC	900	+20/-20			884.1	1784.1	1804.1	880.8 (+20)
LOW UTILIZATION	REF: AMM 27-12-01	AFL	450	+20/-20			443	893	913	443 (+20)
27-12-01-212-002-A02	INSPECT (GENERAL VISUAL) AILERON PCA ROD ENDS/FITTING LUGS FOR INTEGRITY AND GENERAL CONDITION	MOS					07-JAN-2013			
		HRS/MSC	N/A				93.67			
	REF: AMM 27-12-01	AFL					78			
27-12-01-720-001-A01	FUNCTIONALLY CHECK AILERON-ACTUATOR DAMPING COMPONENTS AND MONITORING DEVICES PKG 5002	MOS	12	+15d/-15d			21-JAN-2017	19-DEC-2017	03-JAN-2018	253 d (+15)
		HRS/MSC	900	+20/-20			884.1	1784.1	1804.1	880.8 (+20)
LOW UTILIZATION	REF: AMM 27-12-01	AFL	450	+20/-20			443	893	913	443 (+20)
27-12-01-720-001-A02	FUNCTIONALLY CHECK AILERON-ACTUATOR DAMPING COMPONENTS AND MONITORING DEVICES	MOS					21-JAN-2017			
		HRS/MSC	N/A				884.1			
	REF: AMM 27-12-01	AFL					443			
27-12-01-720-002-A00	FUNCTIONALLY CHECK AILERON ACTUATOR FORCE FIGHT	MOS					07-JAN-2013			
		HRS/MSC	N/A				93.67			
	REF: AMM 27-12-01	AFL					78			
27-12-01-720-002-A01 (s)	FUNCTIONAL CHECK AILERON ACTUATOR FORCE FIGHT (FOR AIRCRAFT UNDER ANAC/FAA CERTIFICATIONS) PKG 5004	MOS	24	+15d/-15d			21-JAN-2017	PKG		
		HRS/MSC	1800	+20/-20			884.1			
LOW UTILIZATION	REF: AMM 27-12-01	AFL	900	+20/-20			443			
27-12-03-212-001-A00	VISUALLY CHECK AILERON DAMPER ROD ENDS/FITTING LUGS FOR INTEGRITY AND GENERAL CONDITION PKG 5002	MOS	12	+15d/-15d			21-JAN-2017	12-DEC-2017	27-DEC-2017	246 d (+15)
		HRS/MSC	900	+20/-20			884.1	1784.1	1804.1	880.8 (+20)
LOW UTILIZATION	REF: AMM 27-12-03	AFL	450	+20/-20			443	893	913	443 (+20)
27-12-03-720-001-A00 (s)	FUNCTIONALLY CHECK AILERON-DAMPER DAMPING FORCE PKG 5004	MOS	24	+15d/-15d			21-JAN-2017	PKG		
		HRS/MSC	1800	+20/-20			884.1			
LOW UTILIZATION	REF: AMM 27-12-03	AFL	900	+20/-20			443			
27-12-03-720-002-A00 (s)	FUNCTIONALLY CHECK EXTERNAL LEAKAGE OF THE AILERON DAMPER PKG 5004	MOS	24	+15d/-15d			21-JAN-2017	PKG		
		HRS/MSC	1800	+20/-20			884.1			
LOW UTILIZATION	REF: AMM 27-12-03	AFL	900	+20/-20			443			
27-13-00-710-001-A00 (s)	OPERATIONALLY CHECK AILERON SOLENOID-MANIFOLD-SHUTOFF FUNCTION PKG 5008	MOS	48	+15d/-15d			26-JAN-2015	PKG		
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 27-13-00	AFL	1800	+20/-20			280			
27-14-00-720-001-A00 (s)	FUNCTIONALLY CHECK ROLL TRIM PKG 5008	MOS	48	+15d/-15d			26-JAN-2015	PKG		
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 27-14-00	AFL	1800	+20/-20			280			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-15-00-710-001-A00 (s)	OPERATIONALLY CHECK AILERON DISCONNECT SYSTEM PKG 5004	MOS	24	+15d/-15d			PKG 21-JAN-2017 884.1			
LOW UTILIZATION	REF: AMM 27-15-00	AFL	1000	+20/-20			443			
27-15-02-640-001-A00 (s)	LUBRICATE AILERON DISCONNECT SYSTEM (NOTE: THE PLATE MECHANISM IS BENCH LUBRICATED) PKG 5016	MOS	96	+15d/-15d			PKG 16-DEC-2010 0			
LOW UTILIZATION	REF: AMM 27-15-02	AFL	7200 3600	+20/-20 +20/-20			0 0			
27-21-00-710-001-A00	OPERATIONALLY CHECK RUDDER MOVABLE PRIMARY STOP MECHANISM	MOS					16-DEC-2010 0			
	REF: AMM 27-21-00	AFL	N/A				0			
27-21-01-220-001-A00 (s)	INSPECT (DETAILED INSPECTION) RUDDER PRIMARY MECHANICAL CONTROL CHECKING CABLES, PULLEYS AND QUADRANTS PKG 5008	MOS	48	+15d/-15d			PKG 26-JAN-2015 532.4			
LOW UTILIZATION	REF: AMM 27-21-01	AFL	3600 1800	+20/-20 +20/-20			280			
27-21-01-720-001-A00	FUNCTIONALLY CHECK RUDDER CONTROL CABLE ASSEMBLY TENSION OF RUDDER CONTROL CABLES PKG 5008	MOS	48	+15d/-15d			26-JAN-2015 532.4	26-JAN-2019	10-FEB-2019	656 d (+15) 3229.1
LOW UTILIZATION	REF: AMM 27-21-01	AFL	3600 1800	+20/-20 +20/-20			280	4132.4 2080		1630
27-21-02-220-001-A00 (s)	INSPECT (DETAILED INSPECTION) RUDDER MAIN CONTROL FEEDBACK PATH, PCU LINKAGE AND MOUNTING POINTS, RUDDER ACTUATOR ATTACHMENTS, HINGES AND CONNECTING RODS PKG 5008	MOS	48	+15d/-15d			PKG 26-JAN-2015 532.4			
LOW UTILIZATION	REF: AMM 27-21-02	AFL	3600 1800	+20/-20 +20/-20			280			
27-22-00-720-001-A00 (s)	FUNCTIONALLY CHECK RUDDER BACKLASH PKG 5008	MOS	48	+15d/-15d			PKG 26-JAN-2015 532.4			
LOW UTILIZATION	REF: AMM 27-22-00	AFL	3600 1800	+20/-20 +20/-20			280			
27-22-00-720-002-A00	FUNCTIONALLY CHECK RUDDER HYDRAULIC DAMPING NOTE: OR IN ACCORDANCE WITH LOCAL REGULATORY AUTHORITY REQUIREMENTS	MOS					21-JAN-2017 884.1			
	REF: AMM 27-22-00	AFL	N/A				443			
27-22-01-720-001-A00 (s)	FUNCTIONALLY CHECK RUDDER POWER CONTROL UNIT/ACTUATORS DIFFERENTIAL PRESSURE PKG 5008	MOS	48	+15d/-15d			PKG 26-JAN-2015 532.4			
LOW UTILIZATION	REF: AMM 27-22-01	AFL	3600 1800	+20/-20 +20/-20			280			
27-22-02-212-001-A00 (s)	INSPECT (GENERAL VISUAL) RUDDER ACTUATORS PKG 5008	MOS	48	+15d/-15d			PKG 26-JAN-2015 532.4			
LOW UTILIZATION	REF: AMM 27-22-02	AFL	3600 1800	+20/-20 +20/-20			280			



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-23-00-710-002-A00	OPERATIONALLY CHECK ALERTING FUNCTION OF THE RUDDER MOVABLE PRIMARY STOP	MOS					21-JAN-2017			
	REF: AMM 27-23-00	HRS/MSC AFL	N/A				884.1 443			
27-25-00-710-001-A00 (s)	OPERATIONALLY CHECK RUDDER PEDALS AUTO SHUTOFF AND RUDDER MANUAL SHUTOFF FUNCTIONS	MOS	24	+15d/-15d			21-JAN-2017			
	PKG 5004	HRS/MSC AFL	1000	+20/-20			884.1 443			
LOW UTILIZATION	REF: AMM 27-25-00									
27-31-00-720-001-A00 (s)	FUNCTIONALLY CHECK ELEVATOR PRIMARY MECHANICAL CONTROL BACKLASH	MOS	48	+15d/-15d			26-JAN-2015			
	PKG 5008	HRS/MSC AFL	3600	+20/-20			532.4 280			
LOW UTILIZATION	REF: AMM 27-31-00		1800	+20/-20						
27-31-01-220-001-A00 (s)	INSPECT (DETAILED INSPECTION) ELEVATOR CONTROL CABLES	MOS	48	+15d/-15d			26-JAN-2015			
	PKG 5008	HRS/MSC AFL	3600	+20/-20			532.4 280			
LOW UTILIZATION	REF: AMM 27-31-01		1800	+20/-20						
27-31-01-720-001-A00	FUNCTIONALLY CHECK TENSION OF THE ELEVATOR CONTROL CABLES.	MOS	48	+15d/-15d			26-JAN-2015	26-JAN-2019	10-FEB-2019	656 d (+15)
	PKG 5008	HRS/MSC AFL	3600				532.4 280	4132.4		3229.1
LOW UTILIZATION	REF: AMM 27-31-01		1800					2080		1630
27-31-04-710-001-A00 (s)	OPERATIONALLY CHECK SPRING AND SERVO TABS	MOS	12	+15d/-15d			21-JAN-2017			
	PKG 5002	HRS/MSC AFL	500	+20/-20			884.1 443			
LOW UTILIZATION	REF: AMM 27-31-04									
27-31-05-220-001-A00 (s)	INSPECT (DETAILED INSPECTION) SERVO TAB FAIL-SAFE ACTUATION LINK	MOS	48	+15d/-15d			26-JAN-2015			
	PKG 5008	HRS/MSC AFL	3600	+20/-20			532.4 280			
LOW UTILIZATION	REF: AMM 27-31-05		1800	+20/-20						
27-31-05-220-002-A00 (s)	INSPECT (DETAILED INSPECTION) SPRING TAB ATTACHMENT LINK	MOS	48	+15d/-15d			26-JAN-2015			
	PKG 5008	HRS/MSC AFL	3600	+20/-20			532.4 280			
LOW UTILIZATION	REF: AMM 27-31-05		1800	+20/-20						
27-35-00-640-001-A00 (s)	LUBRICATE ELEVATOR DISCONNECT SYSTEM (NOTE: THE PLATE MECHANISM IS BENCH LUBRICATIONRICATED).	MOS	96	+15d/-15d			16-DEC-2010			
	PKG 5016	HRS/MSC AFL	7200	+20/-20			0 0			
LOW UTILIZATION	REF: AMM 27-35-00		3600	+20/-20						
27-35-00-710-001-A00 (s)	OPERATIONALLY CHECK ELEVATOR DISCONNECT SYSTEM	MOS	24	+15d/-15d			21-JAN-2017			
	PKG 5004	HRS/MSC AFL	1000	+20/-20			884.1 443			
LOW UTILIZATION	REF: AMM 27-35-00									
27-36-00-710-001-A00 (s)	OPERATIONALLY CHECK STALL PROTECTION SYSTEM	MOS	12	+15d/-15d			21-JAN-2017			
	PKG 5001	HRS/MSC AFL	500	+20/-20			884.1 443			
LOW UTILIZATION	REF: AMM 27-36-00									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-36-00-720-001-A00 (s)	FUNCTIONALLY CHECK ICE/SPS SPEEDS INTERFACE CIRCUIT						PKG			
	PKG 5002	MOS	12	+15d/-15d			21-JAN-2017			
		HRS/MSC	500	+20/-20			884.1			
LOW UTILIZATION	REF: AMM 27-36-00	AFL					443			
27-40-00-710-002-A00 (s)	OPERATIONALLY CHECK BACKUP SYS CUTOFF PUSHBUTTON, MAIN SYS CUTOFF SWITCH, AND QUICK DISCONNECT SWITCH						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 27-40-00	AFL	1800	+20/-20			280			
27-40-00-710-003-A00 (s)	OPERATIONALLY CHECK LOCKOUT LOGIC OF HORIZONTAL STABILIZER CONTROL UNIT POST-MOD SB 145LEG-27-0016 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED.						PKG			
	PKG 5001	MOS	6	+15d/-15d			21-JAN-2017			
		HRS/MSC	450	+20/-20			884.1			
LOW UTILIZATION	REF: AMM 27-40-00	AFL					443			
27-40-00-720-001-A00 (s)	FUNCTIONALLY CHECK HORIZONTAL STABILIZER BACKLASH						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 27-40-00	AFL	1800	+20/-20			280			
27-40-02-220-001-A00 (s)	INSPECT (DETAILED INSPECTION) HORIZONTAL STABILIZER ACTUATOR INTEGRITY AND ATTACHMENTS						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 27-40-02	AFL	1800	+20/-20			280			
27-40-02-610-001-A00 (s)	SERVICE (REPLENISH) HORIZONTAL STABILIZER ACTUATOR AND CHECK FOR LEAKAGE.						PKG			
	PKG 5008	MOS	48	+15d/-15d			21-JAN-2017			
		HRS/MSC	2000	+20/-20			884.1			
LOW UTILIZATION	REF: AMM 27-40-02	AFL	1000	+20/-20			443			
27-51-00-212-001-A00 (s)	INSPECT (GENERAL VISUAL) FLAP MECHANICAL LINE						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 27-51-00	AFL	1800	+20/-20			280			
27-51-00-220-001-A00 (s)	INSPECT (DETAILED INSPECTION) FLAP FLEXIBLE SHAFT						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 27-51-00	AFL	1800	+20/-20			280			
27-51-00-610-001-A00	SERVICE (LUBRICATE) FLAP SCREWJACK ACTUATORS GEARBOX (PRE-MOD SB 145LEG-27-0026) (L600 ONLY)									
		MOS					16-DEC-2010			
		HRS/MSC	N/A				0			
	REF: AMM 27-51-00	AFL					0			
27-51-00-610-001-A01 (s)	SERVICE (LUBRICATE) FLAP SCREWJACK ACTUATORS GEARBOX (POST-MOD SB 145LEG-27-0026 OR WITH AN EQUIVALENT MODIFICATION FACTORY INCORPORATED)						PKG			
	PKG 5012	MOS	72	+15d/-15d			21-JAN-2017			
		HRS/MSC	5400	+20/-20			884.1			
LOW UTILIZATION	REF: AMM 27-51-00	AFL	2700	+20/-20			443			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
27-51-00-640-001-A00 (s)	SERVICE (LUBRICATE) FLAP SCREWJACK ACTUATOR (FSAS) PKG 5002	MOS	12	+15d/-15d			PKG 21-JAN-2017 884.1			
LOW UTILIZATION	REF: AMM 27-51-00	AFL	500	+20/-20			443			
27-51-01-720-001-A00 (s)	FUNCTIONALLY CHECK FLAP TRANSMISSION BRAKE HOLDING CAPABILITY PKG 5004	MOS	24	+15d/-15d			PKG 21-JAN-2017 884.1			
LOW UTILIZATION	REF: AMM 27-51-01	AFL	1000	+20/-20			443			
27-51-15-220-001-A00 (s)	INSPECT (DETAILED INSPECTION) FLAP ROLLERS FOR STRUCTURAL INTEGRITY PKG 5016	MOS	96	+15d/-15d			PKG 16-DEC-2010 0			
LOW UTILIZATION	REF: AMM 27-51-15	AFL	3600	+20/-20			0			
27-51-17-720-001-A00 (s)	FUNCTIONAL CHECK MTB FLAP DRIVE MOTOR UNIT(FDMU) HOLDING CAPABILITY PKG 5008	MOS	48	+15d/-15d			PKG 26-JAN-2015 532.4			
LOW UTILIZATION	REF: AMM 27-51-17	AFL	1800	+20/-20			280			
27-53-00-710-001-A00 (s)	OPERATIONALLY CHECK FLAP FAIL MESSAGE PKG 5001	MOS	12	+15d/-15d			PKG 21-JAN-2017 884.1			
LOW UTILIZATION	REF: AMM 27-53-00	AFL	500	+20/-20			443			
27-53-00-710-002-A00 (s)	OPERATIONALLY CHECK "TAKEOFF FLAPS" AURAL WARNING AND NO TAKEOFF CONFIGURATION VISUAL WARNING PKG 5001	MOS	12	+15d/-15d			PKG 21-JAN-2017 884.1			
LOW UTILIZATION	REF: AMM 27-53-00	AFL	500	+20/-20			443			
27-62-00-720-001-A00 (s)	FUNCTIONALLY CHECK GROUND SPOILER/SPEED BRAKE VALVES, CONTROL CIRCUIT, AND RELATED MESSAGES PKG 5016	MOS	96	+15d/-15d			PKG 16-DEC-2010 0			
LOW UTILIZATION	REF: AMM 27-62-00	AFL	3600	+20/-20			0			
27-63-01-710-001-A00 (s)	OPERATIONALLY CHECK SPOILER SYSTEM PKG 5008	MOS	48	+15d/-15d			PKG 26-JAN-2015 532.4			
LOW UTILIZATION	REF: AMM 27-63-01	AFL	1800	+20/-20			280			
27-71-00-220-001-A00 (s)	INSPECT (DETAILED INSPECTION) ELECTROMECHANICAL GUST LOCK MECHANISM PKG 5008	MOS	48	+15d/-15d			PKG 26-JAN-2015 532.4			
LOW UTILIZATION	REF: AMM 27-71-00	AFL	1800	+20/-20			280			
+ 27-71-00-710-004-A00 (s)	OPERATIONALLY CHECK ELECTROMECHANICAL GUST LOCK SOLENOID FUNCTION PKG 5001	MOS	12	+15d/-15d			PKG 21-JAN-2017 884.1			
LOW UTILIZATION	REF: AMM 27-71-00	AFL	500	+20/-20			443			
270000-0101	CENTRAL CONSOLE, TRIM CONTROL MODULE 145-34177-407	MOS					16-DEC-2010 0			
	0000638275	HRS/MSC	O/C				TSN:0 0			
	REF:	AFL					TSN:0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
270000-0201	OVERHEAD PANEL, FLIGHT CONTROL MODULE 145-21333-403 0000635891 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
270101-0101	RUDDER VII BALANCING ASSEMBLY 135-20922-401 0000648560 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
271100-0101	DISCONNECTION ASSY - AILERON, FUSELAGE FORWARD DEVICE 145-37755-409 0000643244 REF: AMM 27-15-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
271102-0301	LH WING AILERON ASSEMBLY 135-25301-401 0000640228 REF: AMM 27-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
271102-0302	RH WING AILERON ASSEMBLY 135-25301-402 0000640231 REF: AMM 27-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
271103-0201	LEFT AILERON CONTROL CABLE ASSY PN SN-UNKNOWN REF: AMM 27-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
271103-0202	RIGHT AILERON CONTROL CABLE ASSY PN SN-UNKNOWN REF: AMM 27-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
271103-0301	LH PIL AILERON FORCE, COCKPIT SENSOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
271103-0302	LH COPIL AILERON FORCE, COCKPIT SENSOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
271103-0303	RH PIL AILERON FORCE, COCKPIT SENSOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
271103-0304	RH COPIL AILERON FORCE, COCKPIT SENSOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
271200-0101	LH WING NEUTRAL RECOVERY-AILERON CONTROL UNIT 373600-1001 2276 REF: AMM 27-11-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
271200-0102	RH WING NEUTRAL RECOVERY-AILERON CONTROL UNIT 373600-1001 2275 REF: AMM 27-11-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
271200-0301	LH REAR MANIFOLD -HYDRAULIC, AILERON SOLENOID ASSEMBLY 353570-1001 2311 REF: AMM 27-12-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
271200-0302	RH REAR MANIFOLD -HYDRAULIC, AILERON SOLENOID ASSEMBLY 353570-1001 2312 REF: AMM 27-12-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
271200-0401	LH WING DAMPER ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
271200-0402	RH WING DAMPER ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
271200-0501	LH WING HYDRAULIC-AILERON ACTUATOR 418800-1007 2693A REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
271200-0502	RH WING HYDRAULIC-AILERON ACTUATOR 418800-1007 2721AB REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
271400-0101	FORWARD ELECTROMECHANICAL ACTUATOR 383300-1009 3778 REF: AMM 27-71-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
271400-0102	RUDDER ELECTROMECHANICAL ACTUATOR 383300-1009 3798 REF: AMM 27-71-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
271400-0201	FORWARD FEEL-POSITION, AILERON TRIM TAB UNIT 367000-1005 1155 REF: AMM 27-14-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
271500-0101	CREW CAB MODULE -AILERON DISCONNECTION,CENTRAL CONSOLE ASSEMBLY 145-23973-405 0000634854 REF: AMM 27-15-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
272100-0201	ASSY ACTUATOR 2108-0050-003 00561 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
272100-0202	ASSY ACTUATOR 2108-0050-003 00560 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
272100-0301	PROF COP ELEVATOR/RUDDER FORCE,COCKPIT SENSOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
272100-0302	PROF PIL ELEVATOR/RUDDER FORCE,COCKPIT SENSOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
272100-0303	RUD COP ELEVATOR/RUDDER FORCE,COCKPIT SENSOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
272100-0304	RUD PIL ELEVATOR/RUDDER FORCE,COCKPIT SENSOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
272100-0401	ROD ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
272100-0402	ROD ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
272100-0501	PILOT PEDAL ASSEMBLY 145-27402-405 0000640847 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
272100-0502	COPILOT PEDAL ASSEMBLY 145-27402-407 0000640849 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
272101-0101	LH PIL ACTUATOR LINEAR -ROTARY ELECTROMECHANICAL, CONTROL RUDDER ASSEMBLY 6375A0001-01 1031 REF: AMM 27-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
272101-0102	RH COPIL ACTUATOR LINEAR -ROTARY ELECTROMECHANICAL, CONTROL RUDDER ASSEMBLY 6375A0001-01 1035 REF: AMM 27-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
272102-0101	RUDDER II -PIN ASSEMBLY 120-61385-019 0000640300 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
272200-0101	RUDDER SYS - POWER CONTROL UNIT ASSEMBLY 360300-1001 1164 REF: AMM 27-22-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
272200-0201	HYDRAULIC SYS, FIN RUDDER HYDROMECHANIC ACTUATOR ASSEMBLY 360340-1005 2320 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
272200-0202	HYDRAULIC SYS, FIN RUDDER HYDROMECHANIC ACTUATOR ASSEMBLY 360340-1005 2322 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
272200-0301	UPPER FORWARD TAIL HYDRAULIC SYS BLEED VALVE 2238-0001-001 04740 REF: AMM 27-22-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
272200-0302	UPPER AFT TAIL HYDRAULIC SYS BLEED VALVE 2238-0001-001 04741 REF: AMM 27-22-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
272200-0303	LOWER FORWARD TAIL HYDRAULIC SYS BLEED VALVE 2238-0001-001 04746 REF: AMM 27-22-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
272200-0304	LOWER AFT TAIL HYDRAULIC SYS BLEED VALVE 2238-0001-001 04748 REF: AMM 27-22-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
272200-0401	MID PAX DOOR SYS, THREE WAY/TWO POSITIONS, SOLENOID VALVE 6005-1 1686 REF: AMM 27-22-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
272200-0402	PAX DOOR SYS, THREE WAY/TWO POSITIONS, SOLENOID VALVE 6005-1 1687 REF: AMM 27-22-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
272200-0403	PAX DOOR SYS, THREE WAY/TWO POSITIONS, SOLENOID VALVE 6005-1 1688 REF: AMM 27-22-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
272300-0101	SERVO CONTROL, RUDDER PRESSURE SENSOR UNIT 15H0048PH 1732 REF: AMM 27-23-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
272300-0102	SERVO CONTROL, RUDDER PRESSURE SENSOR UNIT 15H0048PH 1735 REF: AMM 27-23-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
273100-0101	ELEVATOR CONTROL, FUSELAGE FWD, DISCONNECTION ASSY DEVICE 145-37755-411 0000629551 REF: AMM 27-35-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
273100-0201	PILOT YOKE EQUIPPED CONTROLLER 145-48605-453 0000643632 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
273100-0202	COPILOT YOKE EQUIPPED CONTROLLER 145-48605-455 0000643633 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
273100-0301	ROD ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
273100-0302	ROD ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
273100-0401	C FLOOR TUBE ASSY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
273100-0402	C FLOOR TUBE ASSY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
273102-0101	LEFT ELEVATOR -HORIZONTAL TAIL ASSEMBLY 145-50845-419 0000643058 REF: AMM 27-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
273102-0102	RIGHT ELEVATOR -HORIZONTAL TAIL ASSEMBLY 145-50845-420 0000643057 REF: AMM 27-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
273103-0101	LEFT ELEVATOR CABLE TENSION REGULATOR 0501020-03 1285 REF: AMM 27-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
273103-0102	RIGHT ELEVATOR CABLE TENSION REGULATOR 0501020-01 1288 REF: AMM 27-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
273500-0101	CREW CAB MODULE -ELEVATOR DISCONNECTION,CENTRAL CONSOLE ASSEMBLY 145-22175-401 0000638267 REF: AMM 27-35-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
273601-0101	LEFT ANGLE OF ATTACK SENSOR 0861DT5 MOD.2 2805 REF: AMM 27-36-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
273601-0102	RIGHT ANGLE OF ATTACK SENSOR 0861DT5 MOD.2 2774 REF: AMM 27-36-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
273602-0201	PILOT STICK SHAKER ACTUATOR 0050N1 4052 REF: AMM 27-36-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
273602-0202	COPILOT STICK SHAKER ACTUATOR 0050N1 4040 REF: AMM 27-36-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
273603-0101	C FLOOR DATA PROCESSING-STALL PROTECTION CONTROL SYS COMPUTER 0020BN7 MOD 1A 1334 REF: AMM 27-36-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
273604-0101	FORWARD LINEAR ASSY-ELECTROMECHANICAL, STICK PUSHER ACTUATOR 6235-1 2009 REF: AMM 27-36-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
273605-0101	CSL CENT MODULE -STALL PROTECTION/FMS ASSEMBLY 145-34172-407 0000635285 REF: AMM 27-36-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
274000-0101	STABILIZER -HORIZONTAL EMPENAGE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
274100-0101	ACTUATOR, ELECTROMECHANICAL -HORIZONTAL STABILIZER ASSEMBLY 362200-1015 1235 REF: AMM 27-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
274302-0101	REAR CONTROL HORIZONTAL STABILIZER UNIT 362100-1017 1146 REF: AMM 27-40-01	MOS HRS/MSC AFL	O/C				08-JAN-2016 729 362			
275100-0102	LH WING FLEXIBLE ASSY-SEGMENT 2, FLAP CONTROL SHAFT 363400-1021 03633 REF: AMM 27-51-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
275100-0103	RH WING FLEXIBLE ASSY-SEGMENT 2, FLAP CONTROL SHAFT 363400-1021 03639 REF: AMM 27-51-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
275100-0503	LH WING BRAKE TRANSMISSION FLAP 363500-1003 03236 REF: AMM 27-51-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
275100-0504	RH WING BRAKE TRANSMISSION FLAP 363500-1003 03425 REF: AMM 27-51-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
275100-0701	LH WING FLAP FLEXIBLE 4 E 5 SHAFT 363400-1025 06769 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
275100-0702	RH WING FLAP FLEXIBLE 4 E 5 SHAFT 363400-1025 06766 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
275100-0703	LH WING FLAP FLEXIBLE 4 E 5 SHAFT 363400-1025 06779 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
275100-0704	RH WING FLAP FLEXIBLE 4 E 5 SHAFT 363400-1025 06768 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
275100-0705	LH WING FLAP FLEXIBLE 3 SHAFT 363400-1023 03808 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
275100-0706	RH WING FLAP FLEXIBLE 3 SHAFT 363400-1023 03809 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
275100-0801	LH WING ANGLE-ACTUATOR, INTERNAL CENTRAL FLAP ROOT, WING ADAPTER 363450-1001 04659 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
275100-0802	RH WING ANGLE-ACTUATOR, INTERNAL CENTRAL FLAP ROOT, WING ADAPTER 363450-1001 04660 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
275100-0803	LH WING ANGLE-ACTUATOR, EXTERNAL FLAP ROOT, WING ADAPTER 363450-1003 04611 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
275100-0804	RH WING ANGLE-ACTUATOR, EXTERNAL FLAP ROOT, WING ADAPTER 363450-1003 04610 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
275100-0901	LH WING SENSOR -VELOCITY, FLAP ASSEMBLY 363350-1003 06724 REF: AMM 27-51-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
275100-0902	RH WING SENSOR -VELOCITY, FLAP ASSEMBLY 363350-1003 06725 REF: AMM 27-51-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
275100-1001	LH WING ASSY, FLAP CONTROL ACTUATOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
275100-1002	RH WING ASSY, FLAP CONTROL ACTUATOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
275100-1003	LH WING ASSY, FLAP CONTROL ACTUATOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
275100-1004	RH WING ASSY, FLAP CONTROL ACTUATOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
275100-1005	LH WING ASSY, FLAP CONTROL ACTUATOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
275100-1006	RH WING ASSY, FLAP CONTROL ACTUATOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
275100-1007	LH WING ASSY, FLAP CONTROL ACTUATOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
275100-1008	RH WING ASSY, FLAP CONTROL ACTUATOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
275100-1101	LH FLAP - INBOARD, WING HALF ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
275100-1102	RH FLAP - INBOARD, WING HALF ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
275100-1103	LH FLAP - OUTBOARD, WING HALF ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
275100-1104	RH FLAP - OUTBOARD, WING HALF ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
275300-0101	W STUB POWER-DRIVE, FLAP ACTUATOR UNIT 363200-1003 01363 REF: AMM 27-53-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
275300-0201	LH WING FLAP FLEXIBLE 1 SHAFT 363400-1019 03547 REF: AMM 27-51-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
275300-0202	RH WING FLAP FLEXIBLE 1 SHAFT 363400-1019 03546 REF: AMM 27-51-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
275302-0101	WING/FUSLG FAIRING, FLAP CONTROL UNIT 363100-1013 5562 REF: AMM 27-53-02	MOS HRS/MSC AFL	O/C				26-JAN-2015 532.4 280			
275303-0101	FLAP SYS, CSL CENT, SELECTOR LEVER 363110-1009 1259 REF: AMM 27-53-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
276000-0101	LH WING GROUND SPOILER PANEL ASSEMBLY 135-25248-401 0000629900 REF: AMM 27-62-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
276000-0102	RH WING GROUND SPOILER PANEL ASSEMBLY 135-25248-402 0000625691 REF: AMM 27-62-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
276000-0201	LH WING SPEED BRAKE PANEL 135-25249-401 0000637096 REF: AMM 27-62-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
276000-0202	RH WING SPEED BRAKE PANEL 135-25249-402 0000629906 REF: AMM 27-62-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
276201-0101	LH WING GROUND SPOILER, HYDROMECHANICAL ACTUATOR ASSEMBLY 360440-1011 2383 REF: AMM 27-62-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
276201-0102	RH WING GROUND SPOILER, HYDROMECHANICAL ACTUATOR ASSEMBLY 360440-1011 2384 REF: AMM 27-62-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
276201-0201	W STUB ELECTROVALVE-SPOILER, HYDRAULIC SYSTEM 360450-1001 1196 REF: AMM 27-62-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
276201-0301	W STUB RESTRICTOR, HYDRAULIC SYS, SSTEEL VALVE 2236-0001-001 1279429/009 REF: AMM 27-22-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
276203-0101	LH WING HYDROMECHANICAL SPEED BRAKE ACTUATOR 360540-1011 2376 REF: AMM 27-62-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
276203-0102	RH WING HYDROMECHANICAL SPEED BRAKE ACTUATOR 360540-1011 2380 REF: AMM 27-62-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
276203-0201	W STUB BRAKE AERODYNAMIC VALVE 360550-1003 1203 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
276207-0101	MID PRESSURE REDUCER, HYDRAULIC SYS, WING STUB VALVE HP528200S2-27 2329 REF: AMM 27-62-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
276301-0101	LH WING SPOILER INBOARD PROXIMITY SWITCH 80-057-01 25539 REF: AMM 27-63-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
276301-0102	RH WING SPOILER INBOARD PROXIMITY SWITCH 80-057-01 25550 REF: AMM 27-63-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
276301-0103	LH WING SPOILER OUTBOARD PROXIMITY SWITCH 80-057-01 25551 REF: AMM 27-63-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
276301-0104	RH WING SPOILER OUTBOARD PROXIMITY SWITCH 80-057-01 25554 REF: AMM 27-63-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
276301-0105	LH WING SPOILER CENTER PROXIMITY SWITCH 80-057-01 25555 REF: AMM 27-63-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
276302-0101	SPEED BRAKE CONTROL, CENTRAL CONSOLE, LEVER ASSEMBLY 999-1003 1194 REF: AMM 27-63-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
276303-0101	CSL CENT SPOILER CONTROL, EQUIPPED UNIT 145-33022-415 0000628159 REF: AMM 27-63-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
277100-0101	ELECTROMECHANICAL,CONTROLS LOCKING ACTUATOR ASSEMBLY SYLC-53058 1193 REF: AMM 27-71-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
277100-0201	LEFT CARTRIDGE ASSY-GUST LOCK SYS SPRING KPD4235 KC2540 REF: AMM 27-71-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
277100-0202	RIGHT CARTRIDGE ASSY-GUST LOCK SYS SPRING KPD4235 KC2709 REF: AMM 27-71-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
CHAPTER 28 FUEL										
28-10-00-220-001-A00	INSPECT (DETAILED INSPECTION) OF FUEL TANKS (WINGS AND WING STUB) FOR PRESENCE OF MICROORGANISM (L600) REF: AMM 28-11-00	MOS HRS/MSC AFL	N/A				16-DEC-2010 0 0			
28-10-00-220-001-A01	INSPECT (DETAILED INSPECTION) OF FUEL TANKS (WINGS, WING STUB AND VENTRAL) FOR PRESENCE OF MICROORGANISM (L650) REF: AMM 28-11-00	MOS HRS/MSC AFL	12	+15d/-15d	-13		21-JAN-2017 884.1 443	08-JAN-2018	23-JAN-2018	273 d (+15)
28-11-00-280-001-A00 (s)	INSPECT (SPECIAL INSPECTION) FOR PRESENCE OF MICRO ORGANISMS IN THE FUEL TANKS PKG 5001 REF: AMM 28-11-00	MOS HRS/MSC AFL	6 450	+15d/-15d +20/-20			21-JAN-2017 884.1 443			PKG
28-11-00-280-001-A01	INSPECT (SPECIAL INSPECTION) FOR PRESENCE OF MICRO ORGANISMS IN THE FUEL TANKS REF: AMM 28-11-00	MOS HRS/MSC AFL	12	+15d/-15d	-13		21-JAN-2017 884.1 443	08-JAN-2018	23-JAN-2018	273 d (+15)
28-11-00-720-001-A00	FUNCTIONALLY CHECK CRITICAL BONDING INTEGRITY OF SELECTED CONDUITS INSIDE THE WING TANK, FUEL PUMP AND FQIS CONNECTORS AT TANK WALL BY CONDUCTIVITY MEASUREMENTS. (L600 ONLY) REF:	MOS HRS/MSC AFL	N/A				16-DEC-2010 0 0			
28-11-00-720-002-A01	FUNCTIONALLY CHECK CRITICAL BONDING INTEGRITY OF SELECTED CONDUITS INSIDE THE WING TANK, FUEL PUMP CONNECTORS AT TANK WALL BY CONDUCTIVITY MEASUREMENTS. NOTE: APPLICABLE TO FUEL PUMPS WITH TANK WALL HERMETIC CONNECTOR (L650 ONLY) PKG 5024 REF: AMM 28-11-00	MOS HRS/MSC AFL	144 10800 5400	+15d/-15d +20/-20 +20/-20			16-DEC-2010 0 0	16-DEC-2022 10800 5400	31-DEC-2022	2076 d (+15) 9896.7 (+20) 4950 (+20)

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
28-11-00-720-003-A01	FUNCTIONALLY CHECK CRITICAL BONDING INTEGRITY OF SELECTED CONDUITS INSIDE THE WING TANK, FQIS CONNECTORS AT TANK WALL BY CONDUCTIVITY MEASUREMENTS (L650 ONLY)									
	PKG 5024	MOS	144	+15d/-15d			16-DEC-2010	16-DEC-2022	31-DEC-2022	2076 d (+15)
		HRS/MSC	6000	+20/-20			0	6000	6020	5096.7 (+20)
LOW UTILIZATION	REF: AMM 28-11-00	AFL	3000	+20/-20			0	3000	3020	2550 (+20)
28-11-04-710-001-A00 (s)	OPERATIONALLY CHECK FLAP VALVES (RIBS 1 AND 7) (MANUAL CHECK FOR FREE MOVEMENT AND SEALING CONDITION) NOTE: CHECK DURING INTERNAL TANK INSPECTION.						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: AMM 28-11-04	AFL	3600	+20/-20			0			
28-12-01-710-001-A00 (s)	OPERATIONAL CHECK VENT FLOAT VALVES (MANUAL CHECK) (NOTE: CHECK DURING INTERNAL TANK INSPECTION).						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: AMM 28-12-01	AFL	3600	+20/-20			0			
28-12-04-710-001-A00 (s)	OPERATIONALLY CHECK FLAP VALVES (MANUAL CHECK FOR FREE MOVEMENT AND SEALING CONDITION). NOTE: CHECK DURING INTERNAL TANK INSPECTION.						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: AMM 28-12-04	AFL	3600	+20/-20			0			
28-12-05-211-001-A00 (s)	VISUALLY CHECK FLAME ARRESTOR FOR HONEY COMB CLOGGING, AND ATTACHING PARTS FOR SECURITY.						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 28-12-05	AFL	1800	+20/-20			280			
28-12-05-710-001-A00 (s)	OPERATIONAL CHECK FLAME ARRESTOR IN/OUT FLOW VALVES FOR FREEDOM MOVEMENT.						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 28-12-05	AFL	1800	+20/-20			280			
28-13-01-720-001-A00 (s)	FUNCTIONALLY CHECK AFT FUEL TANKS						PKG			
	PKG 5012	MOS	72	+15d/-15d			21-JAN-2017			
		HRS/MSC	3000	+20/-20			884.1			
LOW UTILIZATION	REF: AMM 28-13-01	AFL	1500	+20/-20			443			
28-13-01-720-003-A01	FUNCTIONALLY CHECK AFT FUEL TANK CRITICAL BONDING INTEGRITY OF FUEL PUMP CONNECTORS AT TANK WALL BY CONDUCTIVITY MEASUREMENTS (NOTE: APPLICABLE TO FUEL PUMPS WITH TANK WALL HERMETIC CONNECTOR) (L650 ONLY)									
	PKG 5024	MOS	144	+15d/-15d			16-DEC-2010	16-DEC-2022	31-DEC-2022	2076 d (+15)
		HRS/MSC	10800	+20/-20			0	10800	10820	9896.7 (+20)
LOW UTILIZATION	REF: AMM 28-13-01	AFL	5400	+20/-20			0	5400	5420	4950 (+20)
28-13-01-720-004-A01	FUNCTIONALLY CHECK AFT FUEL TANK CRITICAL BONDING INTEGRITY OF FQGS CONNECTORS AT TANK WALL BY CONDUCTIVITY MEASUREMENTS (L650 ONLY)									
	PKG 5024	MOS	144	+15d/-15d			16-DEC-2010	16-DEC-2022	31-DEC-2022	2076 d (+15)
		HRS/MSC	6000	+20/-20			0	6000	6020	5096.7 (+20)
LOW UTILIZATION	REF: AMM 28-13-01	AFL	3000	+20/-20			0	3000	3020	2550 (+20)

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING	
28-13-02-212-001-A00 (s)	INSPECT (GENERAL VISUAL)	AFT FUEL TANKS BLADDER NOTE: EMB RECOMENDED					PKG				
	PKG 5016	MOS	96				16-DEC-2010				
LOW UTILIZATION	REF: AMM 28-13-02	HRS/MSC	7200				0				
		AFL	3600				0				
28-13-02-960-001-A00	DISCARD AFT FUEL TANKS BLADDER										
		MOS	120	+60d/-60d			16-DEC-2010	16-DEC-2020	14-FEB-2021	1346 d (+60)	
SYSTEM	REF: AMM 28-13-02	HRS/MSC					0				
		AFL					0				
28-14-00-710-001-A00 (s)	OPERATIONALLY CHECK AFT FUEL TANK POSITIVE RELIEF SYSTEM						PKG				
	PKG 5002	MOS	12	+15d/-15d			21-JAN-2017				
LOW UTILIZATION	REF: AMM 28-14-00	HRS/MSC	500	+20/-20			884.1				
		AFL					443				
28-14-01-710-001-A00	OPERATIONAL CHECK AFT FUEL TANK FLOAT VENT VALVES PRE-MOD SB 145LEG-28-0019.(L600 ONLY)										
		MOS					16-DEC-2010				
	REF:	HRS/MSC	N/A				0				
		AFL					0				
28-14-04-720-001-A00 (s)	FUNCTIONALLY CHECK AFT TANK POSITIVE RELIEF VALVE						PKG				
	PKG 5004	MOS	24	+15d/-15d			21-JAN-2017				
LOW UTILIZATION	REF: AMM 28-14-13	HRS/MSC	1000	+20/-20			884.1				
		AFL					443				
28-14-05-720-001-A00 (s)	FUNCTIONALLY CHECK AFT TANKS NEGATIVE RELIEF VALVE						PKG				
	PKG 5004	MOS	24	+15d/-15d			21-JAN-2017				
LOW UTILIZATION	REF: AMM 28-14-14	HRS/MSC	1000	+20/-20			884.1				
		AFL					443				
28-14-06-960-001-A00 (s)	DISCARD AFT-FUEL-TANK AIR FILTER						PKG				
	PKG 5002	MOS	12	+15d/-15d			21-JAN-2017				
LOW UTILIZATION	REF: AMM 28-14-15	HRS/MSC	500	+20/-20			884.1				
		AFL					443				
28-14-07-220-001-A00 (s)	INSPECT (DETAILED INSPECTION) OF AFT FUEL TANKS FLAME ARRESTORS. NOTE: FLAME ARRESTORS INSTALLED IN THE SKIN OF THE FUSELAGE AND FLAME ARRESTORS INSTALLED CLOSE TO CONTAINER BOX, IF INSTALLED.						PKG				
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015				
LOW UTILIZATION	REF: AMM 28-14-09	HRS/MSC	3600	+20/-20			532.4				
		AFL	1800	+20/-20			280				
28-14-08-710-001-A00 (s)	OPERATIONALLY CHECK 3/4 ZERO LEAKAGE CHECK VALVES.						PKG				
	PKG 5004	MOS	24	+15d/-15d			21-JAN-2017				
LOW UTILIZATION	REF: AMM 28-14-17	HRS/MSC	1000	+20/-20			884.1				
		AFL					443				
28-14-09-710-001-A00 (s)	OPERATIONALLY CHECK 3/8 ZERO LEAKAGE CHECK VALVES.						PKG				
	PKG 5002	MOS	12	+15d/-15d			21-JAN-2017				
LOW UTILIZATION	REF: AMM 28-14-17	HRS/MSC	500	+20/-20			884.1				
		AFL					443				
28-14-10-710-001-A00 (s)	OPERATIONALLY CHECK AFT FUEL TANKS PRESSURIZATION VENT PLUMBING SHROUD						PKG				
	PKG 5004	MOS	24	+15d/-15d			21-JAN-2017				
LOW UTILIZATION	REF: AMM 28-14-00	HRS/MSC	1800	+20/-20			884.1				
		AFL	900	+20/-20			443				

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
28-15-03-710-001-A00 (s)	OPERATIONALLY CHECK FORWARD FUEL TANKS FLAP VALVES PKG 5016	MOS	96	+15d/-15d			PKG 16-DEC-2010			
LOW UTILIZATION	REF: AMM 28-15-03	HRS/MSC AFL	7200 3600	+20/-20 +20/-20			0 0			
28-15-04-720-002-A01	FUNCTIONALLY CHECK FWD FUEL TANK CRITICAL BONDING INTEGRITY OF FUEL PUMP CONNECTORS AT TANK WALL BY CONDUCTIVITY MEASUREMENTS (NOTE: APPLICABLE TO FUEL PUMPS WITH TANK WALL HERMETIC CONNECTOR)(L650 ONLY) PKG 5024	MOS	144	+15d/-15d			16-DEC-2010	16-DEC-2022	31-DEC-2022	2076 d (+15)
LOW UTILIZATION	REF: AMM 28-15-04	HRS/MSC AFL	10800 5400	+20/-20 +20/-20			0 0	10800 5400	10820 5420	9896.7 (+20) 4950 (+20)
28-15-04-720-003-A01	FUNCTIONALLY CHECK FWD FUEL TANK CRITICAL BONDING INTEGRITY OF FQGS CONNECTORS AT TANK WALL BY CONDUCTIVITY MEASUREMENTS (L650 ONLY) PKG 5024	MOS	144	+15d/-15d			16-DEC-2010	16-DEC-2022	31-DEC-2022	2076 d (+15)
LOW UTILIZATION	REF: AMM 28-15-04	HRS/MSC AFL	6000 3000	+20/-20 +20/-20			0 0	6000 3000	6020 3020	5096.7 (+20) 2550 (+20)
28-16-00-710-001-A00 (s)	OPERATIONALLY CHECK FUEL TANKS VENT OPEN CAUTION SYSTEM. PKG 5001	MOS	12	+15d/-15d			PKG 21-JAN-2017			
LOW UTILIZATION	REF: AMM 28-16-00	HRS/MSC AFL	500	+20/-20			884.1 443			
28-16-01-710-001-A00 (s)	OPERATIONALLY CHECK FORWARD FUEL TANKS FLOAT VALVES (MANUALLY CHECKED). PKG 5016	MOS	96	+15d/-15d			PKG 16-DEC-2010			
LOW UTILIZATION	REF: AMM 28-16-01	HRS/MSC AFL	7200 3600	+20/-20 +20/-20			0 0			
28-16-04-710-001-A00 (s)	OPERATIONALLY CHECK FORWARD FUEL TANKS AUTOMATIC FLOAT DRAIN VALVES. PKG 5016	MOS	96	+15d/-15d			PKG 16-DEC-2010			
LOW UTILIZATION	REF: AMM 28-16-04	HRS/MSC AFL	7200 3600	+20/-20 +20/-20			0 0			
28-16-05-220-001-A00 (s)	INSPECT (DETAILED INSPECTION) OF FORWARD FUEL TANK FLAME ARRESTORS. NOTE: FLAME ARRESTORS INSTALLED ON NACA AIR DUCT AND FLAME ARRESTORS INSTALLED ON REFUEL/OVERFILL VENTILATION LINE, IF INSTALLED. PKG 5008	MOS	48	+15d/-15d			PKG 26-JAN-2015			
LOW UTILIZATION	REF: See Workcard	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
28-17-01-720-002-A01	FUNCTIONALLY CHECK VENTRAL TANK CRITICAL BONDING INTEGRITY OF FUEL PUMP CONNECTORS AT TANK WALL BY CONDUCTIVITY MEASUREMENTS NOTE: APPLICABLE TO FUEL PUMPS WITH TANK WALL HERMETIC CONNECTOR (L650 ONLY) PKG 5024	MOS	144	+15d/-15d			16-DEC-2010	16-DEC-2022	31-DEC-2022	2076 d (+15)
LOW UTILIZATION	REF: AMM 28-17-01	HRS/MSC AFL	10800 5400	+20/-20 +20/-20			0 0	10800 5400	10820 5420	9896.7 (+20) 4950 (+20)
28-17-01-720-003-A01	FUNCTIONALLY CHECK VENTRAL TANK CRITICAL BONDING INTEGRITY OF FQGS CONNECTORS AT TANK WALL BY CONDUCTIVITY MEASUREMENTS (L650 ONLY) PKG 5024	MOS	144	+15d/-15d			16-DEC-2010	16-DEC-2022	31-DEC-2022	2076 d (+15)
LOW UTILIZATION	REF: AMM 28-17-01	HRS/MSC AFL	6000 3000	+20/-20 +20/-20			0 0	6000 3000	6020 3020	5096.7 (+20) 2550 (+20)

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
28-17-03-710-001-A00 (s)	OPERATIONALLY CHECK VENTRAL FUEL TANK FLAP VALVES (L650 ONLY)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: AMM 28-17-05	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
28-17-04-710-001-A00 (s)	OPERATIONALLY CHECK VENTRAL FUEL TANK BAFFLE VALVES (L650 ONLY)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: AMM 28-17-05	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
28-18-01-710-001-A00 (s)	OPERATIONALLY CHECK VENTRAL FUEL TANK FLOAT VENT VALVES (L650 ONLY)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: AMM 28-18-01	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
28-18-03-710-001-A00 (s)	OPERATIONALLY CHECK VENTRAL FUEL TANK FLOAT ACTUATED DRAIN VALVE (L650 ONLY)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: AMM 28-18-04	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
28-18-05-220-001-A00 (s)	INSPECT (DETAILED INSPECTION) OF VENTRAL FUEL TANK FLAME ARRESTORS. NOTE: FLAME ARRESTOR INSTALLED IN EACH NACA AIR INTAKE DUCT AND IN THE REFUEL/OVERFILL VENTILATION LINES CLOSE TO THE DC VENTRAL VENT MOV, IF INSTALLED. (L650)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 28-16-05	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
28-21-01-220-001-A00	INSPECT (DETAILED INSPECTION) WING ELECTRIC FUEL PUMP CONNECTOR									
		MOS					16-DEC-2010			
	REF:	HRS/MSC	N/A				0			
		AFL					0			
28-21-03-720-001-A00 (s)	FUNCTIONALLY CHECK RELIEF VALVE NOTE: BENCH TEST						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: AMM 28-21-03	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
28-21-04-710-001-A00 (s)	OPERATIONALLY CHECK FUEL CROSSFEED VALVE						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 28-21-04	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
28-21-10-710-001-A00 (s)	OPERATIONALLY CHECK FUEL FEED LINE SHROUD						PKG			
	PKG 5012	MOS	72	+15d/-15d			21-JAN-2017			
LOW UTILIZATION	REF: AMM 28-21-10	HRS/MSC	3000	+20/-20			884.1			
		AFL	1500	+20/-20			443			
28-22-03-710-001-A00 (s)	OPERATIONALLY CHECK APU FUEL FEED LINE SHROUD						PKG			
	PKG 5012	MOS	72	+15d/-15d			21-JAN-2017			
LOW UTILIZATION	REF: AMM 28-22-03	HRS/MSC	3000	+20/-20			884.1			
		AFL	1500	+20/-20			443			
28-23-04-220-001-A00	INSPECT (DETAILED INSPECTION) VENT VALVE HARNESS INSIDE THE CONDUIT (L600 ONLY)									
		MOS					16-DEC-2010			
	REF:	HRS/MSC	N/A				0			
		AFL					0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
28-23-04-220-001-A01	INSPECT (DETAILED INSPECTION) VENT VALVE HARNESS INSIDE THE CONDUIT (L650 ONLY)									
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010	16-DEC-2018	31-DEC-2018	615 d (+15)
		HRS/MSC	7200	+20/-20			0	7200	7220	6296.7 (+20)
LOW UTILIZATION	REF: AMM 28-23-04	AFL	3600	+20/-20			0	3600	3620	3150 (+20)
28-26-00-710-001-A00 (s)	OPERATIONALLY CHECK TRANSFER SYSTEM FWD PUMP AND CIRCUITRY						PKG			
	PKG 5004	MOS	24	+15d/-15d			21-JAN-2017			
		HRS/MSC	1000	+20/-20			884.1			
LOW UTILIZATION	REF: AMM 28-26-00	AFL					443			
28-26-00-720-001-A00 (s)	FUNCTIONALLY CHECK AFT/FWD TRANSFER FUEL TANKS TRANSFER CHECK RELIEF VALVES						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: AMM 28-26-00	AFL	3600	+20/-20			0			
28-26-16-710-001-A00 (s)	OPERATIONALLY CHECK FUEL TRANSFER LINE SHROUD.						PKG			
	PKG 5012	MOS	72	+15d/-15d			21-JAN-2017			
		HRS/MSC	3000	+20/-20			884.1			
LOW UTILIZATION	REF: AMM 28-13-01	AFL	1500	+20/-20			443			
28-26-18-710-001-A00 (s)	OPERATIONALLY CHECK AFT TANK ELECTRICAL ISOLATING SHUT-OFF VALVE AND CIRCUITRY						PKG			
	PKG 5002	MOS	12	+15d/-15d			21-JAN-2017			
		HRS/MSC	500	+20/-20			884.1			
LOW UTILIZATION	REF: AMM 28-26-18	AFL					443			
28-26-21-710-001-A00	OPERATIONALLY CHECK FORWARD TANKS LOW LEVEL SWITCH (L600 ONLY)									
		MOS					16-DEC-2010			
		HRS/MSC	N/A				0			
STRUCTURAL	REF: AMM 28-26-21	AFL					0			
28-26-21-710-001-A01 (s)	OPERATIONALLY CHECK FORWARD TANKS LOW LEVEL SENSOR (L650 ONLY)						PKG			
	PKG 5004	MOS	24	+15d/-15d			21-JAN-2017			
		HRS/MSC	1000	+20/-20			884.1			
LOW UTILIZATION	REF: AMM 28-26-21	AFL					443			
28-26-22-710-001-A00	OPERATIONALLY CHECK AFT TANKS LOW LEVEL SWITCH (L600 ONLY)									
		MOS					16-DEC-2010			
		HRS/MSC	N/A				0			
STRUCTURAL	REF: AMM 28-26-22	AFL					0			
28-26-22-710-001-A01 (s)	OPERATIONALLY CHECK AFT TANKS LOW LEVEL SENSOR (L650 ONLY)						PKG			
	PKG 5004	MOS	24	+15d/-15d			21-JAN-2017			
		HRS/MSC	1000	+20/-20			884.1			
LOW UTILIZATION	REF: AMM 28-26-22	AFL					443			
28-26-24-710-001-A00 (s)	OPERATIONALLY CHECK AFT TANKS TRANSFER CHECK VALVE						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: AMM 28-26-23	AFL	3600	+20/-20			0			
28-41-00-220-001-A01 (s)	INSPECT (DETAILED INSPECTION) W1642 INTRINSICALLY SAFE HARNESSSES FOR SLEEVE INTEGRITY (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 28-41-00	AFL	1800	+20/-20			280			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
28-41-00-710-001-A00	OPERATIONALLY CHECK ELECTRICAL FUEL QUANTITY INDICATING SYSTEM (FUEL LOW LEVEL LOGIC) (L600 ONLY)	MOS					16-DEC-2010			
	REF: AMM 28-41-00	HRS/MSC	N/A				0			
		AFL					0			
28-41-01-720-001-A01	FUNCTIONALLY CHECK THE SAFE LIFE FEATURES OF THE FUEL CONDITIONING UNIT (FCU). - INITIAL FUNCTIONAL CHECK, - EXTERNAL VISUAL INSPECTION, - INTERNAL VISUAL INSPECTION, -FUNCTIONAL CHECK OF THE SAFE LIFE FEATURE, - FINAL FUNCTIONAL CHECK. (L600 ONLY)	MOS					16-DEC-2010			
	REF:	HRS/MSC	N/A				0			
		AFL					0			
28-41-03-220-001-A00	INSPECT (DETAILED INSPECTION) FQIS HARNESS FOR CLAMP AND WIRE JACKET INTEGRITY (L600 ONLY)	MOS					16-DEC-2010			
	REF:	HRS/MSC	N/A				0			
		AFL					0			
28-41-03-220-001-A01	INSPECT (DETAILED INSPECTION) FQIS HARNESS FOR CLAMP AND WIRE JACKET INTEGRITY. (L650 ONLY)	MOS	96	+15d/-15d			16-DEC-2010	16-DEC-2018	31-DEC-2018	615 d (+15)
	PKG 5016	HRS/MSC	7200	+20/-20			0	7200	7220	6296.7 (+20)
LOW UTILIZATION	REF: AMM 28-41-03	AFL	3600	+20/-20			0	3600	3620	3150 (+20)
28-41-07-220-001-A01 (s)	INSPECT (DETAILED INSPECTION) VENTRAL TANK INTERNAL INSPECTION: FQGS HARNESS FOR CLAMP AND WIRE JACKET INTEGRITY.(L650 ONLY)	MOS	96	+15d/-15d			16-DEC-2010			
	PKG 5016	HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: AMM 28-41-06	AFL	3600	+20/-20			0			
28-43-00-720-001-A00 (s)	FUNCTIONALLY CHECK FUEL TEMPERATURE INDICATION SYSTEM	MOS	96	+15d/-15d			16-DEC-2010			
	PKG 5016	HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: AMM 28-43-00	AFL	3600	+20/-20			0			
28-44-00-720-001-A00 (s)	FUNCTIONALLY CHECK FUEL LOW LEVEL WARNING SYSTEM NOTE: CHECK DURING INTERNAL TANK INSPECTION	MOS	96	+15d/-15d			16-DEC-2010			
	PKG 5016	HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: AMM 28-44-00	AFL	3600	+20/-20			0			
28-45-00-710-001-A00 (s)	OPERATIONALLY CHECK FUEL LOW PRESSURE WARNING SYSTEM	MOS	24	+15d/-15d			21-JAN-2017			
	PKG 5004	HRS/MSC	1000	+20/-20			884.1			
LOW UTILIZATION	REF: AMM 28-45-00	AFL					443			
28-46-00-710-001-A00	OPERATIONAL CHECK "FUSELAGE FUEL IMB" WARNING SYSTEM (L600 ONLY)	MOS					12-DEC-2011			
	REF:	HRS/MSC	N/A				27			
		AFL					20			
28-46-00-710-001-A01 (s)	OPERATIONALLY CHECK "FUSELAGE FUEL IMB" AND "FUEL XFER CRITICAL" CAUTION SYSTEM (L650 ONLY)	MOS	12	+15d/-15d			21-JAN-2017			
	PKG 5002	HRS/MSC	900	+20/-20			884.1			
LOW UTILIZATION	REF: AMM 28-46-00	AFL	450	+20/-20			443			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
28-46-00-720-001-A00	FUNCTIONALLY CHECK "CHECK ACFT LOAD OR FUEL XFER CRITICAL" WARNING SYSTEM (L600 ONLY)	MOS					16-DEC-2010			
STRUCTURAL	REF: AMM 28-46-00	HRS/MSC AFL	N/A				0 0			
28-46-00-720-002-A00 (s)	FUNCTIONALLY CHECK AUXILIARY TANKS PROBES AND FCU	MOS	24	+15d/-15d			21-JAN-2017			
LOW UTILIZATION	REF: AMM 28-46-00	HRS/MSC AFL	1000	+20/-20			884.1 443			
28-46-02-220-001-A01 (s)	INSPECT (DETAILED INSPECTION) AFT FUEL TANK: FQGS HARNESS FOR CLAMP AND WIRE JACKET INTEGRITY.(L650 ONLY)	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: AMM 28-46-02	HRS/MSC AFL	7200 3600	+20/-20 +20/-20			0 0			
28-46-04-220-001-A01 (s)	INSPECT (DETAILED INSPECTION) FWD FUEL TANK INTERNAL INSPECTION: FQGS HARNESS FOR CLAMP AND WIRE JACKET INTEGRITY.(L650 ONLY)	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: AMM 28-46-04	HRS/MSC AFL	7200 3600	+20/-20 +20/-20			0 0			
28-46-05-720-001-A01	FUNCTIONALLY CHECK THE SAFE LIFE FEATURES OF THE AUXILIARY FUEL CONDITIONING UNIT (AFCU). - INITIAL FUNCTIONAL CHECK, - EXTERNAL VISUAL INSPECTION, - INTERNAL VISUAL INSPECTION, -FUNCTIONAL CHECK OF THE SAFE LIFE FEATURE, - FINAL FUNCTIONAL CHECK (L600 ONLY)	MOS					16-DEC-2010			
REF:		HRS/MSC AFL	N/A				0 0			
28-50-01-220-001-A01	DETAILED INSPECTION FUEL PUMP ELECTRICAL HARNESS AND CONNECTORS NOTE: APPLICABLE TO FUEL PUMPS WITH TANK WALL HERMETIC CONNECTOR (L650 ONLY)	MOS	48	+15d/-15d	-41		26-JAN-2015	16-DEC-2018	31-DEC-2018	615 d (+15)
LOW UTILIZATION	REF: See Workcard	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280	4132.4 2080	4152.4 2100	3229.1 (+20) 1630 (+20)
28-50-01-220-001-A02 (s)	INSPECT (DETAILED INSPECTION) FUEL PUMP ELECTRICAL HARNESS CHA (CABLE HARNESS ASSEMBLY) END FITTING (L650 ONLY)	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: See Workcard	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
28-50-01-720-001-A00 (s)	FUNCTIONALLY CHECK FUEL PUMP ELECTRICAL HARNESS FOR LEAKAGE NOTE: APPLICABLE TO AIRCRAFT WITH FUEL PUMP HARNESS WITH CORRUGATED CONDUIT. ZONE: 155/156 157/197 271/272 1972 (L650 ONLY)	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: See Workcard	HRS/MSC AFL	7200 3600	+20/-20 +20/-20			0 0			
28-50-02-220-001-A01 (s)	INSPECT (DETAILED INSPECTION) WING FUEL TANK UNITS (L650 ONLY)	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 28-41-02	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
28-50-03-220-002-A01 (s)	INSPECT (DETAILED INSPECTION) FWD FUEL TANK UNITS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 28-46-03	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
28-50-04-212-001-A01 (s)	INSPECT (GENERAL VISUAL) WING STUB HARNESS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: See Workcard	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
28-50-05-212-001-A01 (s)	INSPECT (GENERAL VISUAL) TRAILING EDGE HARNESS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 24-00-03	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
28-50-06-212-001-A01 (s)	INSPECT (GENERAL VISUAL) LEADING EDGE HARNESS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 24-00-02	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
28-50-07-220-001-A01 (s)	INSPECT (DETAILED INSPECTION) AFT FUEL TANK UNITS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 28-46-01	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
28-50-08-212-001-A00 (s)	INSPECT (GENERAL VISUAL) VENTRAL FUEL TANK EXTERNAL HARNESS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 28-27-01	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
28-50-08-220-001-A00 (s)	INSPECT (DETAILED INSPECTION) VENTRAL FUEL TANK UNITS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 28-41-05	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
28-50-09-212-001-A00 (s)	INSPECT (GENERAL VISUAL) FWD FUEL TANK EXTERNAL HARNESS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 28-26-01	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
28-50-10-212-001-A00 (s)	INSPECT (GENERAL VISUAL) AFT FUEL TANK EXTERNAL HARNESS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 28-26-08	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
281200-0101	LH WING FLOAT VENT VALVE									
	2930015-102	MOS				TSN:0	16-DEC-2010			
	7350	HRS/MSC	O/C			TSN:0	0			
	REF: AMM 28-12-01	AFL				TSN:0	0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
281200-0102	LH WING FLOAT VENT VALVE 2930015-102 7355 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281200-0103	RH WING FLOAT VENT VALVE 2930015-102 7289 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281200-0104	RH WING FLOAT VENT VALVE 2930015-102 7351 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281200-0105	FWR TK FLOAT VENT VALVE 2930015-102 7345 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281200-0106	FWR TK FLOAT VENT VALVE 2930015-102 7348 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281200-0107	FWR TK FLOAT VENT VALVE 2930015-102 7347 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281200-0108	FWR TK FLOAT VENT VALVE 2930015-102 7352 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281205-0201	LH WING FLAME ARRESTOR 130-0045-01 2617 REF: AMM 28-12-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281205-0202	RH WING FLAME ARRESTOR 130-0045-01 2621 REF: AMM 28-12-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281300-0101	LH REAR FUEL TANK ASSEMBLY PN SN-UNKNOWN REF: AMM 28-13-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281300-0102	RH REAR FUEL TANK ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
281300-0103	FORWARD FUEL TANK ASSEMBLY PN SN-UNKNOWN REF: AMM 28-15-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281301-0101	REAR LH ALL RUBBER FUEL TANK RAHE70371 225 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281301-0102	REAR RH ALL RUBBER FUEL TANK RAHE70370 233 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0101	REAR TK CHECK-TYPE BUTTERFLY,INTERNAL TANK,FUEL SYSTEM VALVE 2000034-102 10-0524246 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0102	REAR TK CHECK-TYPE BUTTERFLY,INTERNAL TANK,FUEL SYSTEM VALVE 2000034-102 10-0524236 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0103	REAR TK CHECK-TYPE BUTTERFLY,INTERNAL TANK,FUEL SYSTEM VALVE 2000034-102 10-0524254 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0104	REAR TK CHECK-TYPE BUTTERFLY,INTERNAL TANK,FUEL SYSTEM VALVE 2000034-102 10-0524249 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0105	REAR TK CHECK-TYPE BUTTERFLY,INTERNAL TANK,FUEL SYSTEM VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0106	REAR TK CHECK-TYPE BUTTERFLY,INTERNAL TANK,FUEL SYSTEM VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0201	REAR TK VALVE CHECK-FUEL TANK, FUSELAGE ASSEMBLY 869A-12BT 09-012932 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0202	REAR TK VALVE CHECK-FUEL TANK, FUSELAGE ASSEMBLY 869A-12BT 09-012938 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
281400-0203	REAR TK VALVE CHECK-FUEL TANK, FUSELAGE ASSEMBLY 869A-12BT 09-012945 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0204	REAR TK VALVE CHECK-FUEL TANK, FUSELAGE ASSEMBLY 869A-12BT 09-012940 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0301	REAR SEAT SHUTOFF ASSY-FUEL SYS VALVE PN SN-UNKNOWN REF: AMM 28-23-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0302	FWDSEAT SHUTOFF ASSY-FUEL SYS VALVE PN SN-UNKNOWN REF: AMM 28-23-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0303	X FEED SHUTOFF ASSY-FUEL SYS VALVE PN SN-UNKNOWN REF: AMM 28-23-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0304	REAR TK CROSSFEED SHUTOFF ASSY-FUEL SYS VALVE 2080125-101 00209 REF: AMM 28-21-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0305	FWRTK SHUTOFF ASSY-FUEL SYS VALVE 281400-0305 00198 REF: AMM 28-23-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0306	W STUB SHUTOFF ASSY-FUEL SYS VALVE PN SN-UNKNOWN REF: AMM 28-23-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0307	STUB SHUTOFF ASSY-FUEL SYS VALVE PN SN-UNKNOWN REF: AMM 28-23-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0308	APU SHUTOFF ASSY-FUEL SYS VALVE PN SN-UNKNOWN REF: AMM 28-23-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0309	LH ENG SHUTOFF ASSY-FUEL SYS VALVE PN SN-UNKNOWN REF: AMM 28-23-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
281400-0310	RH ENG SHUTOFF ASSY-FUEL SYS VALVE PN SN-UNKNOWN REF: AMM 28-23-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0311	LEFT REAR TK ENGINE SHUTOFF ASSY-FUEL SYS VALVE 2080125-101 00206 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0312	RIGHT REAR TK ENGINE SHUTOFF ASSY-FUEL SYS VALVE 2080125-101 00210 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0313	FWR TK SHUTOFF ASSY-FUEL SYS VALVE 2080125-101 00200 REF: AMM 28-23-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0314	REAR TK SHUTOFF VALVE ASSY 2080125-101 00208 REF: AMM 28-23-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0316	STUB SHUTOFF ASSY-FUEL SYS VALVE PN SN-UNKNOWN REF: AMM 28-23-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0401	REAR TK ASSY,RELIEF LINE-INT TNK,AL SENSOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0402	REAR TK ASSY,RELIEF LINE-INT TNK,AL SENSOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0501	FWR TK DRAIN-FUEL SYS VALVE 2990076-102 4278 REF: AMM 28-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0502	FWR TK DRAIN-FUEL SYS VALVE 2990076-102 4294 REF: AMM 28-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0503	REAR TK DRAIN-FUEL SYS VALVE 2990076-102 4298 REF: AMM 28-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
281400-0504	REAR TK DRAIN-FUEL SYS VALVE 2990076-102 4262 REF: AMM 28-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0601	REAR TK RELIEF-INTERNAL TANK,FUEL SYSTEM VALVE 2000062-103 2305 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			21-JAN-2017 884.1 443			
281400-0602	REAR TK RELIEF-INTERNAL TANK,FUEL SYSTEM VALVE 2000062-103 2337 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			21-JAN-2017 884.1 443			
281400-0701	LH REAR FUEL TANK RELIEF VALVE 2000031-102 0447 REF: See Workcard	MOS HRS/MSC AFL	O/C				26-JAN-2015 532.4 280			
281400-0702	RH REAR FUEL TANK RELIEF VALVE 2000031-102 0592 REF: See Workcard	MOS HRS/MSC AFL	O/C				26-JAN-2015 532.4 280			
281400-0801	FWR TK ARRESTOR-FLAME,VENT LINE AFF-10245 0891 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0802	FWR TK ARRESTOR-FLAME,VENT LINE AFF-10245 0898 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0803	REAR TK ARRESTOR-FLAME,VENT LINE AFF-10245 0893 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0804	REAR TK ARRESTOR-FLAME,VENT LINE AFF-10245 0895 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0901	LH WING CHECK-TYPE BUTTERFLY,INTERNAL TANK,FUEL SYSTEM VALVE 2000034-102 08-1213346 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0902	RH WING CHECK-TYPE BUTTERFLY,INTERNAL TANK,FUEL SYSTEM VALVE 2000034-102 08-1213345 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
281400-0903	LH WING CHECK-TYPE BUTTERFLY,INTERNAL TANK,FUEL SYSTEM VALVE 2000034-102 08-1213321 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281400-0904	RH WING CHECK-TYPE BUTTERFLY,INTERNAL TANK,FUEL SYSTEM VALVE 2000034-102 08-1213329 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281501-0101	REAR TK ELECTRICAL-FUEL SYSTEM, INTERNAL PUMP 1C7-25A 10BF73 REF: AMM 28-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281501-0102	REAR TK ELECTRICAL-FUEL SYSTEM, INTERNAL PUMP 1C7-25A 10BF63 REF: AMM 28-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281501-0103	FWR TK ELECTRICAL-FUEL SYSTEM, INTERNAL PUMP 1C7-25A 10BF61 REF: AMM 28-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281501-0104	FWR TK ELECTRICAL-FUEL SYSTEM,INTERNAL PUMP 1C7-25A 10BF64 REF: AMM 28-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281501-0105	FWR TK ELECTRICAL-FUEL SYSTEM,INTERNAL PUMP 1C7-25A 10BF65 REF: AMM 28-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281501-0106	FWR TK ELECTRICAL-FUEL SYSTEM,INTERNAL PUMP 1C7-25A 4BE81 REF: AMM 28-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281501-0201	FWR TK PRESSURE SWITCH F7-337-2 3135 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281501-0202	FWR TK PRESSURE SWITCH F7-337-2 3136 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281501-0203	FWR TK PRESSURE SWITCH F7-337-2 3142 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
281501-0204	FWR TK PRESSURE SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281501-0205	REAR TK PRESSURE SWITCH F7-337-2 3133 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281501-0206	REAR TK PRESSURE SWITCH F7-337-2 3137 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281501-0301	FWR TK INTERNAL, SOLENOID ASSY-REFUELLING VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281501-0302	FWR TK INTERNAL, SOLENOID ASSY-REFUELLING VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281501-0303	FWR TK INTERNAL, SOLENOID ASSY-REFUELLING VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281501-0304	FWR TK INTERNAL, SOLENOID ASSY-REFUELLING VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281501-0305	REAR TK INTERNAL, SOLENOID ASSY-REFUELLING VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281501-0306	REAR TK INTERNAL, SOLENOID ASSY-REFUELLING VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281501-0307	REAR TK INTERNAL, SOLENOID ASSY-REFUELLING VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281501-0308	REAR TK INTERNAL, SOLENOID ASSY-REFUELLING VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
281501-0401	FWR TK FUEL SYS - SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 28-23-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281501-0402	FWR TK FUEL SYS - SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 28-23-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281501-0403	REAR TK FUEL SYS - SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 28-23-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281501-0404	REAR TK FUEL SYS - SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 28-23-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281501-0501	FWR TK RELIEF-INTERNAL TANK,FUEL SYSTEM VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281501-0502	FWR TK RELIEF-INTERNAL TANK,FUEL SYSTEM VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281501-0503	LEFT RELIEF-INTERNAL TANK,FUEL SYSTEM VALVE 2000062-101 1498 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281501-0504	RIGHT RELIEF-INTERNAL TANK,FUEL SYSTEM VALVE 2000062-101 1559 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281501-0505	MID RELIEF-INTERNAL TANK,FUEL SYSTEM VALVE 2000062-101 1558 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281501-0601	FWR TK CHECK-TYPE THERMOSTATIC EXPANSION,TANK,FUEL SYS VALVE 2020035-101 0762 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281501-0602	FWR TK CHECK-TYPE THERMOSTATIC EXPANSION,TANK,FUEL SYS VALVE 2020035-101 0759 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
281501-0603	FWR TK CHECK-TYPE THERMOSTATIC EXPANSION,TANK,FUEL SYS VALVE 2020035-101 0776 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
281501-0604	FWR TK CHECK-TYPE THERMOSTATIC EXPANSION,TANK,FUEL SYS VALVE 2020035-101 0768 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282100-0101	REAR TK BALL-FUEL SYS VALVE 869A-12TT 09-0302106 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282100-0102	REAR TK BALL-FUEL SYS VALVE 869A-12TT 09-0302109 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282100-0201	LH WING EJECTOR-FUEL SYSTEM,COMPLETION PUMP 2010031-101 0583 REF: AMM 28-21-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282100-0202	RH WING EJECTOR-FUEL SYSTEM,COMPLETION PUMP 2010031-101 0584 REF: AMM 28-21-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282100-0301	LH WING ELECTRICAL-FUEL SYSTEM,TANK,REAR FUSELAGE PUMP 2C7-8A 4BF17 REF: AMM 28-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282100-0302	LH WING ELECTRICAL-FUEL SYSTEM,TANK,REAR FUSELAGE PUMP 2C7-8A 4BF18 REF: AMM 28-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282100-0303	LH WING ELECTRICAL-FUEL SYSTEM,TANK,REAR FUSELAGE PUMP 2C7-8A 4BF40 REF: AMM 28-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282100-0304	RH WING ELECTRICAL-FUEL SYSTEM,TANK,REAR FUSELAGE PUMP 2C7-8A 4BF42 REF: AMM 28-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282100-0305	RH WING ELECTRICAL-FUEL SYSTEM,TANK,REAR FUSELAGE PUMP 2C7-8A 4BF43 REF: AMM 28-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
282100-0306	RH WING ELECTRICAL-FUEL SYSTEM,TANK,REAR FUSELAGE PUMP 2C7-8A 4BF6 REF: AMM 28-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282100-0401	W STUB FUEL SYSTEM CHECK VALVE 2930006-101 2411 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282100-0402	W STUB FUEL SYSTEM CHECK VALVE 2930006-101 2418 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282100-0501	LH STUB POPPET-RELIEF, FUEL SYS, WING STUB JUNCTION VALVE 2930005-102 3092 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282100-0502	RH STUB POPPET-RELIEF, FUEL SYS, WING STUB JUNCTION VALVE 2930005-102 3095 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282100-0503	REAR TK POPPET-RELIEF, FUEL SYS, WING STUB JUNCTION VALVE 2930005-102 3093 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282100-0504	REAR TK POPPET-RELIEF, FUEL SYS, WING STUB JUNCTION VALVE 2930005-102 3090 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282100-0601	REAR TK PRESSURE,28VDC/25AMPS,ENGINE FUEL SYS SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282100-0602	REAR TK PRESSURE,28VDC/25AMPS,ENGINE FUEL SYS SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282100-0703	APU PRESSURE-FUEL SYS,STEEL SWITCH 12H0009G 1926 REF: AMM 28-45-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282100-0801	LH WING BALL-FUEL SYS VALVE 869A-12TT 09-0302103 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
282100-0802	RH WING BALL-FUEL SYS VALVE 869A-12TT 09-0302105 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282100-0901	LH ENG PRESSURE-FUEL SYS,STEEL SWITCH 21117-1 5683 REF: AMM 28-45-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			21-JAN-2017 884.1 443			
282100-0902	RH ENG PRESSURE-FUEL SYS,STEEL SWITCH 12H0009G 1928 REF: AMM 28-45-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282102-0101	OVERH P MODULE -FUEL CONTROL PANEL ASSEMBLY PN SN-UNKNOWN REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282103-0101	AUXILIARY FUEL SYS RELAY BOX 135-35400-401 765243 REF: AMM 28-20-02	MOS HRS/MSC AFL	O/C				12-JUN-2013 157.2 100			
282300-0101	PRESS FUELLING,PRESSURE,AL ADAPTER 2820052-102 1946 REF: AMM 28-23-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282300-0201	LH WING FUEL TANK SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 28-23-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282300-0202	RH WING FUEL TANK SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 28-23-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282300-0301	REAR TK PRESSURE SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282300-0302	REAR TK PRESSURE SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282300-0305	FWR TK PRESSURE SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
282300-0306	FWR TK PRESSURE SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282300-0307	LH PRESSURE SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282300-0308	RH PRESSURE SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282300-0501	LH WING FUEL TANK RELIEF VALVE PN SN-UNKNOWN REF: AMM 28-21-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282300-0502	RH WING FUEL TANK RELIEF VALVE PN SN-UNKNOWN REF: AMM 28-21-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282300-0601	FUEL REPEATER INDICATOR 366-927-001 2083 REF: AMM 28-23-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282300-0701	LH WING PRESSURE SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282300-0702	RH WING PRESSURE SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282300-0801	LH WING VALVE VENT -RELIEF,FUEL TANK ASSEMBLY 2810051-104 5016AA REF: AMM 28-23-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282300-0802	RH WING VALVE VENT -RELIEF,FUEL TANK ASSEMBLY 2810051-104 5020AA REF: AMM 28-23-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282300-0901	FORWARD RH WING/FUSLG FAIRING - REFUEL/DEFUEL CTRL PANEL ASSEMBLY PN SN-UNKNOWN REF: AMM 28-23-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
282301-0101	REAR TK VALVE -RELIEF, FUEL TANK, WING ASSEMBLY PN SN-UNKNOWN REF: AMM 28-21-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282301-0102	REAR TK VALVE -RELIEF, FUEL TANK, WING ASSEMBLY PN SN-UNKNOWN REF: AMM 28-21-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282301-0103	FWR TK VALVE -RELIEF, FUEL TANK, WING ASSEMBLY PN SN-UNKNOWN REF: AMM 28-21-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282301-0104	FWR TK VALVE -RELIEF, FUEL TANK, WING ASSEMBLY PN SN-UNKNOWN REF: AMM 28-21-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282302-0101	REAR TK REFUEL SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 28-24-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282302-0102	REAR TK REFUEL SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 28-24-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282302-0103	FWR TK REFUEL SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 28-24-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282302-0104	FWR TK REFUEL SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 28-24-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282304-0101	REAR TK LEVEL, FLOAT TYPE, FUEL SYS, WING SENSOR 057-030-001 0122 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282304-0102	REAR TK LEVEL, FLOAT TYPE, FUEL SYS, WING SENSOR 057-030-001 0116 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282304-0103	FWR TK LEVEL, FLOAT TYPE, FUEL SYS, WING SENSOR 057-030-001 0130 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
282304-0104	FWRWK LEVEL, FLOAT TYPE, FUEL SYS,WING SENSOR 057-030-001 0132 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282304-0105	LH WING FLOAT TYPE, FUEL SYS LEVEL SENSOR 057-030-001 0127 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282304-0106	RH WING FLOAT TYPE, FUEL SYS LEVEL SENSOR 057-030-001 0109 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282600-0101	REAR FUEL SYS, INTERNAL TANK PRESSURE SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
282600-0102	REAR FUEL SYS, INTERNAL TANK PRESSURE SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284100-0201	LH WING FUEL TANK UNIT PN SN-UNKNOWN REF: AMM 28-41-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284100-0202	RH WING FUEL TANK UNIT PN SN-UNKNOWN REF: AMM 28-41-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284100-0203	LH WING FUEL TANK UNIT PN SN-UNKNOWN REF: AMM 28-41-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284100-0204	RH WING FUEL TANK UNIT PN SN-UNKNOWN REF: AMM 28-41-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284100-0205	LH WING STUB TANK #1B UNIT PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284100-0206	RH WING STUB TANK #1B UNIT PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
284100-0301	LH WING FUEL QUANTITY TRANSMITTER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284100-0302	RH WING FUEL QUANTITY TRANSMITTER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284100-0303	LH WING TANK FUEL QUANTITY TRANSMITTER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284100-0304	RH WING TANK FUEL QUANTITY TRANSMITTER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284100-0305	RH WING FUEL QUANTITY TRANSMITTER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284100-0401	LH WING FUEL TANK,WING STUB PROBE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284100-0402	RH WING FUEL TANK,WING STUB PROBE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284100-0501	LH WING LOW LEVEL FUEL TANK SENSOR PN SN-UNKNOWN REF: AMM 28-44-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284100-0502	RH WING LOW LEVEL, FUEL TANK SENSOR PN SN-UNKNOWN REF: AMM 28-44-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284100-0601	CREW CAB SIGNAL CONDITIONING-LEVEL, FUEL SYS UNIT 367-507-001 1066 REF: AMM 28-41-01	MOS HRS/MSC AFL	O/C				21-JAN-2017 884.1 443			
284100-0602	CSL CENT SIGNAL CONDITIONING-LEVEL, FUEL SYS UNIT 367-507-001 1023 REF: AMM 28-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAR-2011 25.43 10			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
284100-0603	CSL CENT SIGNAL CONDITIONING-LEVEL, FUEL SYS UNIT PN SN-UNKNOWN REF: AMM 28-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284101-0101	FWR TK FUEL INDICATOR PROBE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284101-0102	FWR TK FUEL INDICATOR PROBE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284101-0103	FWR TK FUEL INDICATOR PROBE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284101-0104	FWR TK FUEL INDICATOR PROBE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284101-0105	FWR TK FUEL INDICATOR PROBE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284101-0106	FWR TK FUEL INDICATOR PROBE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284101-0107	FWR TK FUEL INDICATOR PROBE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284101-0108	FWR TK FUEL INDICATOR PROBE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284101-0201	FWR TK HARNESS FORWARD AUXILIARY TANK ASSEMBLY PN SN-UNKNOWN REF: AMM 28-46-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284101-0202	FWR TK HARNESS FORWARD AUXILIARY TANK ASSEMBLY PN SN-UNKNOWN REF: AMM 28-46-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
284102-0301	FORWARD CONTROL-LEVEL SWITCH, FUEL SYS UNIT PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284102-0302	FORWARD CONTROL-LEVEL SWITCH, FUEL SYS UNIT PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284103-0101	TANK UNIT HARNESS ASSEMBLY PN SN-UNKNOWN REF: AMM 28-41-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284401-0101	FWR TK LEVEL, FLOAT TYPE, FUEL SYS, WING SENSOR 057-030-001 0138 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284401-0102	FWR TK LEVEL, FLOAT TYPE, FUEL SYS, WING SENSOR 057-030-001 0159 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284600-0101	LEFT LOWER AUX TANK PRIMARY (TANK UNIT) PROBE PN SN-UNKNOWN REF: AMM 28-46-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284600-0102	LEFT LOWER AUX TANK MONITOR (TANK UNIT) PROBE PN SN-UNKNOWN REF: AMM 28-46-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284600-0103	RIGHT LOWER AUX TANK PRIMARY (TANK UNIT) PROBE PN SN-UNKNOWN REF: AMM 28-46-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284600-0104	RIGHT LOWER AUX TANK MONITOR (TANK UNIT) PROBE PN SN-UNKNOWN REF: AMM 28-46-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284600-0201	LEFT UPPER AUX TANK PRIMARY (TANK UNIT) PROBE PN SN-UNKNOWN REF: AMM 28-46-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284600-0202	LEFT UPPER AUX TANK MONITOR (TANK UNIT) PROBE PN SN-UNKNOWN REF: AMM 28-46-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
284600-0203	RIGHT UPPER AUX TANK PRIMARY (TANK UNIT) PROBE PN SN-UNKNOWN REF: AMM 28-46-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284600-0204	RIGHT UPPER AUX TANK MONITOR (TANK UNIT) PROBE PN SN-UNKNOWN REF: AMM 28-46-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284700-0101	REAR TK LEVEL, FLOAT TYPE, FUEL SYS, WING SENSOR 057-030-001 0156 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
284701-0101	REAR TK LEVEL, FLOAT TYPE, FUEL SYS, WING SENSOR 057-030-001 0123 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
CHAPTER 28-00 FUEL										
28-46-03-400-801	FWD FUEL QTY; FWD TANK SENSOR 020-240-026 0132 REF:	MOS HRS/MSC AFL	-	TSN:0 TSN:0 TSN:0			01-MAR-2011 25.43 10			
CHAPTER 29 HYDRAULIC POWER										
29-10-00-280-001-A00 (s)	INSPECT (SPECIAL INSPECTION) HYDRAULIC FLUID - ANALYSIS PKG 5008 REF: AMM 29-10-00	MOS HRS/MSC AFL	48 3600 1800	+15d/-15d +20/-20 +20/-20			PKG 26-JAN-2015 532.4 280			
29-10-00-710-001-A00 (s)	OPERATIONALLY CHECK ELECTRIC MOTOR-DRIVEN PUMP INPUT SIGNALS PKG 5008 REF: AMM 29-10-00	MOS HRS/MSC AFL	48 3600 1800	+15d/-15d +20/-20 +20/-20			PKG 26-JAN-2015 532.4 280			
29-10-00-790-001-A00 (s)	FUNCTIONALLY CHECK INTERNAL LEAKAGE OF HYDRAULIC POWER SYSTEM PKG 5016 REF: AMM 29-10-00	MOS HRS/MSC AFL	96 7200 3600	+15d/-15d +20/-20 +20/-20			PKG 16-DEC-2010 0 0			
29-10-01-710-001-A00 (s)	OPERATIONALLY CHECK SHUTOFF VALVE BY MEANS OF THE HYDRAULIC PANEL SWITCH PKG 5008 REF: AMM 29-10-01	MOS HRS/MSC AFL	48 3600 1800	+15d/-15d +20/-20 +20/-20			PKG 26-JAN-2015 532.4 280			
29-10-04-900-001-A00	DISCARD EMDP BRUSHES REF: AMM 29-10-04	MOS HRS/MSC AFL	6000				16-DEC-2010 0 0	6000	5096.7	

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
29-10-08-211-001-A00 (s)	VISUALLY CHECK DIFFERENTIAL PRESSURE INDICATOR FOR RED PINS POPPED OUT. PKG 5001	MOS	12	+15d/-15d			PKG 21-JAN-2017 884.1			
LOW UTILIZATION	REF: See Workcard	HRS/MSC AFL	500	+20/-20			443			
29-10-10-720-001-A00 (s)	FUNCTIONALLY CHECK RETURN FILTER BY-PASS VALVE PKG 5008	MOS	48	+15d/-15d			PKG 26-JAN-2015 532.4			
LOW UTILIZATION	REF: AMM 29-10-10	HRS/MSC AFL	3600	+20/-20			280			
29-10-13-720-001-A00 (s)	FUNCTIONALLY CHECK PRIORITY VALVE PKG 5008	MOS	48	+15d/-15d			PKG 26-JAN-2015 532.4			
LOW UTILIZATION	REF: AMM 29-10-13	HRS/MSC AFL	3600	+20/-20			280			
29-30-03-720-001-A00 (s)	FUNCTIONALLY CHECK HYDRAULIC FILTERS DIFFERENTIAL PRESSURE INDICATORS PKG 5008	MOS	48	+15d/-15d			PKG 26-JAN-2015 532.4			
LOW UTILIZATION	REF: AMM 29-10-10	HRS/MSC AFL	3600	+20/-20			280			
29-30-05-710-001-A00 (s)	OPERATIONALLY CHECK HYD SYS OVHT MESSAGE PKG 5016	MOS	96	+15d/-15d			PKG 16-DEC-2010 0			
LOW UTILIZATION	REF: AMM 29-30-05	HRS/MSC AFL	7200	+20/-20			0			
291001-0101	LH ENG SHUTOFF VALVE 2940003-102 2366	MOS					16-DEC-2010 0			
	REF: AMM 29-10-01	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		0			
291001-0102	RH ENG SHUTOFF VALVE 2940003-102 2361	MOS					16-DEC-2010 0			
	REF: AMM 29-10-01	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		0			
291003-0101	LH ENGINE DRIVEN HYDRAULIC PUMP 971808 MOD A MX742572	MOS					16-DEC-2010 0			
	REF: AMM 29-10-03	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		0			
291003-0102	RH ENGINE DRIVEN HYDRAULIC PUMP 971808 MOD A MX743013	MOS					16-DEC-2010 0			
	REF: AMM 29-10-03	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		0			
291004-0201	LH RACK DC ELECTRIC MOTOR DRIVEN HYDRAULIC PUMP 971533 MX723080	MOS					16-DEC-2010 0			
	REF: AMM 29-10-04	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		0			
291004-0202	RH RACK DC ELECTRIC MOTOR DRIVEN HYDRAULIC PUMP 971533 MX728984	MOS					16-DEC-2010 0			
	REF: AMM 29-10-04	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
291005-0101	LH RACK HYDRAULIC, GENERATOR UNIT RESERVOIR 368900-1003 2255 REF: AMM 29-10-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
291005-0102	RH RACK HYDRAULIC, GENERATOR UNIT RESERVOIR 368900-1003 2260 REF: AMM 29-10-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
291007-0101	LH RACK FILTER -MANIFOLD, HYDRAULIC SYS ASSEMBLY 368100-1007 2778 REF: AMM 29-10-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
291007-0102	RH RACK FILTER -MANIFOLD, HYDRAULIC SYS ASSEMBLY 368100-1007 2281 REF: AMM 29-10-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
291013-0101	W STUB ASSY-PRIORITY, SHUT OFF, HYDRAULIC SYS, LANDING GEAR VALVE 2226-0001-401 01267 REF: AMM 29-10-13	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
291014-0101	LH RACK CHECK-TYPE RETAINER HYDRAULIC SYSTEM, POWER UNIT VALVE CV26-63 09-0506249 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
291014-0102	RH RACK CHECK-TYPE RETAINER HYDRAULIC SYSTEM, POWER UNIT VALVE CV26-63 09-0506271 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
291015-0101	LEFT CHECK-TYPE RETAINER, ELECTRICAL PUMP, POWER UNIT VALVE 2662A-4EE 09-0129130 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
291015-0102	LEFT CHECK-TYPE RETAINER, ELECTRICAL PUMP, POWER UNIT VALVE 2662A-4EE 09-0129143 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
291015-0103	RIGHT CHECK-TYPE RETAINER, ELECTRICAL PUMP, POWER UNIT VALVE 2662A-4EE 09-012997 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
291015-0104	RIGHT CHECK-TYPE RETAINER, ELECTRICAL PUMP, POWER UNIT VALVE 2662A-4EE 09-012995 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
291016-0101	LEFT CHECK-TYPE RETAINER, HYDRAULIC SYSTEM VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
291016-0102	MID CHECK-TYPE RETAINER, HYDRAULIC SYSTEM VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
291016-0103	RIGHT CHECK-TYPE RETAINER, HYDRAULIC SYSTEM VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
293000-0101	OVERH P MODULE -HYDRAULIC POWER CONTROL ASSEMBLY 145-29739-403 0000636881 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
293002-0201	LH RACK PRESSURE-HYDRAULIC SYS TRANSMITTER APTE-24-1000-5000A 7577-8-161 REF: AMM 29-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
293002-0202	RH RACK PRESSURE-HYDRAULIC SYS TRANSMITTER APTE-24-1000-5000A 7577-8-163 REF: AMM 29-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
CHAPTER 30 ICE AND RAIN PROTECTION										
30-00-00-710-001-A00	OPERATIONALLY CHECK ANTI-ICING SYSTEM MESSAGES PKG 1 REF: AMM 30-00-00	MOS HRS/MSC AFL	6 100	+15d/-15d		-34	21-JAN-2017 884.1 443	18-JUN-2017 984.1	03-JUL-2017	69 d (+15) 80.8
30-11-00-720-001-A00 (s)	FUNCTIONALLY CHECK PRESSURE SENSORS OF THE WING THERMAL ANTI-ICING SYSTEM (BENCH TEST). PKG 5,5008 REF: AMM 30-11-00	MOS HRS/MSC AFL	48 3600 1800	+15d/-15d +20/-20 +20/-20			26-JAN-2015 532.4 280			PKG
30-11-05-710-001-A00 (s)	OPERATIONALLY CHECK WING LEAK THERMOSTAT PKG 5,5012 REF: AMM 30-11-05	MOS HRS/MSC AFL	72 5400 2700	+15d/-15d +20/-20 +20/-20			21-JAN-2017 884.1 443			PKG
30-12-00-710-001-A00 (s)	OPERATIONALLY CHECK ELECTRICAL HARDWARE OF THE HORIZONTAL STABILIZER THERMAL ANTI-ICING SYSTEM. PKG 5,5008 REF: AMM 30-12-00	MOS HRS/MSC AFL	48 3600 1800	+15d/-15d +20/-20 +20/-20			26-JAN-2015 532.4 280			PKG

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
30-12-00-720-001-A00 (s)	FUNCTIONALLY CHECK PRESSURE SENSORS OF THE HORIZONTAL STABILIZER THERMAL ANTI-ICING SYSTEM (BENCH TEST)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 30-12-00	AFL	1800	+20/-20			280			
30-12-05-710-001-A00 (s)	OPERATIONALLY CHECK HORIZONTAL-STABILIZER LEAK THERMOSTAT						PKG			
	PKG 5,5016	MOS	96	+15d/-15d			29-OCT-2012			
		HRS/MSC	7200	+20/-20			84.57			
LOW UTILIZATION	REF: AMM 30-12-05	AFL	3600	+20/-20			72			
30-20-00-220-001-A00 (s)	INSPECT (DETAILED INSPECTION) THERMAL ANTI-ICE (TAI) EXHAUST DUCT FOR CONDITION AND SECURITY OF INSTALLATION.						PKG			
	PKG 5,5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 30-20-00	AFL	1800	+20/-20			280			
30-20-01-720-001-A00 (s)	FUNCTIONALLY CHECK ENGINE THERMAL ANTI-ICE (TAI) INTERBULKHEAD ASSEMBLY FOR LEAKAGE						PKG			
	PKG 5,5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 30-20-01	AFL	1800	+20/-20			280			
30-21-00-720-001-A00 (s)	FUNCTIONALLY CHECK PRESSURE SENSORS OF THE ENGINE THERMAL ANTI-ICING SYSTEM (BENCH TEST)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 30-21-00	AFL	1800	+20/-20			280			
30-31-00-710-001-A00 (s)	OPERATIONALLY CHECK PITOT, ANEMOMETRIC STATIC PORT HEATING						PKG			
	PKG 5016	MOS	96	+15d/-15d			26-JAN-2015			
		HRS/MSC	4000	+20/-20			532.4			
LOW UTILIZATION	REF: See Workcard	AFL	2000	+20/-20			280			
30-31-00-710-002-A00 (s)	OPERATIONALLY CHECK PRESSURIZATION STATIC PORT HEATING						PKG			
	PKG 5,5016	MOS	96	+15d/-15d			26-JAN-2015			
		HRS/MSC	4000	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 30-31-00	AFL	2000	+20/-20			280			
30-31-08-710-001-A00 (s)	OPERATIONALLY CHECK PITOT LINES HEATER NOTE: IF INSTALLED						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: AMM 30-31-03	AFL	3600	+20/-20			0			
30-32-00-710-001-A00 (s)	OPERATIONALLY CHECK AOA SENSOR HEATING						PKG			
	PKG 5016	MOS	96	+15d/-15d			26-JAN-2015			
		HRS/MSC	4000	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 30-32-00	AFL	2000	+20/-20			280			
30-33-00-710-001-A00 (s)	OPERATIONALLY CHECK TAT SENSOR HEATING						PKG			
	PKG 5016	MOS	96	+15d/-15d			26-JAN-2015			
		HRS/MSC	4000	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 30-33-00	AFL	2000	+20/-20			280			
30-42-00-710-001-A00 (s)	OPERATIONALLY CHECK WINDSHIELD HEATING						PKG			
	PKG 5,5008	MOS	48	+15d/-15d			21-JAN-2017			
		HRS/MSC	3600	+20/-20			884.1			
LOW UTILIZATION	REF: AMM 30-42-00	AFL	1800	+20/-20			443			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
30-43-01-211-001-A00 (s)	VISUALLY CHECK RAIN REPELLENT COATING (RRC) PKG 5004	MOS	24	+15d/-15d			PKG 21-JAN-2017			
LOW UTILIZATION	REF: AMM 30-41-04	HRS/MSC AFL	1000	+20/-20			884.1 443			
300000-0101	OVERH P ELECTRICAL SYS, ICE PROTECTION MODULE 145-31656-409 0000633966 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
301100-0101	W STUB ELECTRONIC, ANTI ICE SYS, WING PRESSURE SWITCH APS-8-1000 8116-10-30 REF: AMM 30-11-03	MOS HRS/MSC AFL	O/C				26-JAN-2015 532.4 280			
301100-0301	LH WING WING ANTI ICE PICCOLO BURST MONITORING PRESSURE TRANSDUCER APS-6-1000 8184-5-176 REF: AMM 30-11-12	MOS HRS/MSC AFL	O/C				26-JAN-2015 532.4 280			
301100-0302	RH WING WING ANTI ICE PICCOLO BURST MONITORING PRESSURE TRANSDUCER APS-6-1000 8116-5-241 REF: AMM 30-11-12	MOS HRS/MSC AFL	O/C				26-JAN-2015 532.4 280			
301200-0101	AIRFRAME ANTI ICE SYSTEM OVERPRESSURE SWITCH 12949-4 2721 REF: AMM 30-11-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
301200-0102	LH WING AIRFRAME ANTI ICE SYSTEM OVERPRESSURE SWITCH 12949-4 2722 REF: AMM 30-11-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
301200-0103	RH WING AIRFRAME ANTI ICE SYSTEM OVERPRESSURE SWITCH 12949-4 2727 REF: AMM 30-11-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
301200-0201	PRESSURE-ELECTRONIC, ANTI ICE SYS, WING/STABILIZER HORI SWITCH APS-7-1000 8102-2-517 REF: AMM 30-12-03	MOS HRS/MSC AFL	O/C				26-JAN-2015 532.4 280			
301200-0202	LEFT PRESSURE-ELECTRONIC, ANTI ICE SYS, WING/STABILIZER HORI SWITCH APS-7-1000 8076-2-89 REF: AMM 30-12-03	MOS HRS/MSC AFL	O/C				26-JAN-2015 532.4 280			
301200-0203	PRESSURE-ELECTRONIC, ANTI ICE SYS, WING/STABILIZER HORI SWITCH APS-7-1000 8133-11-285 REF: AMM 30-12-03	MOS HRS/MSC AFL	O/C				26-JAN-2015 532.4 280			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
301200-0204	RIGHT PRESSURE-ELECTRONIC, ANTI ICE SYS, WING/STABILIZER HORI SWITCH APS-7-1000 8133-11-283 REF: AMM 30-12-03	MOS HRS/MSC AFL	O/C				26-JAN-2015 532.4 280			
301200-0301	REAR ANTI ICE, STABILIZER VALVE 1000649-2 9908065 REF: AMM 30-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
301200-0401	TAIL HORIZONTAL STABILIZER PICCOLO BURST PRESSURE SWITCH 83536-2 1330 REF: AMM 30-12-06	MOS HRS/MSC AFL	O/C				26-JAN-2015 532.4 280			
301300-0101	LH WING SHUTOFF/REGULATOR-AIR PRESSURE, ANTI ICE SYS, AIRFOILS VALVE 1000649-1 2010080706 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
301300-0102	RH WING SHUTOFF/REGULATOR-AIR PRESSURE, ANTI ICE SYS, AIRFOILS VALVE 1000649-1 2010080713 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
302000-0101	LH ENG PRESSURE-ELECTRONIC, ANTI ICE SYS TRANSDUCER APS-5-1500 8117-8-257 REF: AMM 30-21-06	MOS HRS/MSC AFL	O/C				26-JAN-2015 532.4 280			
302000-0102	RH ENG PRESSURE-ELECTRONIC, ANTI ICE SYS TRANSDUCER APS-5-1500 8127-3-171 REF: AMM 30-21-06	MOS HRS/MSC AFL	O/C				26-JAN-2015 532.4 280			
302000-0201	LH ENG ANTI ICE, AIR BLEED SYS VALVE C146009-4 3563 REF: AMM 30-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
302000-0202	RH ENG ANTI ICE, AIR BLEED SYS VALVE C146009-4 3555 REF: AMM 30-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
304201-0101	WINDSHIELD TEMPERATURE CONTROLLER 3801D2-C 2371 REF: AMM 30-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
304201-0102	WINDSHIELD TEMPERATURE CONTROLLER 3801D2-C 2376 REF: AMM 30-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
308000-0201	LH CSL ICE-FRONT FUSELAGE DETECTOR 0871HT3-1A 02985 REF: AMM 30-80-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
308000-0202	RH CSL ICE-FRONT FUSELAGE DETECTOR 0871HT3-1A 02984 REF: AMM 30-80-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
308002-0101	REAR PROCESSOR-DETECTION, CLEAR ICE, REAR FUSELAGE UNIT 0513AT1 2237 REF: AMM 30-80-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAR-2011 25.43 10			
308003-0101	LH WING ICE DETECTION SENSOR 135-18812-403 0000635177 REF: AMM 30-80-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
308003-0102	RH WING ICE DETECTION SENSOR 135-18812-403 0000635176 REF: AMM 30-80-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
CHAPTER 31 INDICATING/RECORDING SYSTEMS										
31-21-00-710-001-A00	OPERATIONALLY CHECK PILOT DIGITAL CLOCK INFORMATION NOTE: OR IN ACCORDANCE WITH LOCAL REGULATORY AUTHORITY REQUIREMENTS. CHECK TOGETHER WITH TASK 31-31-00-720-001-A00	MOS HRS/MSC AFL	48 4000	+30d/-30d	-41		26-JAN-2015 532.4 280	16-DEC-2018 4532.4	15-JAN-2019	615 d (+30) 3629.1
SYSTEM	REF: AMM 31-21-00									
31-31-00-720-001-A00	FUNCTIONALLY CHECK REAR FLIGHT DATA SSFDR ELECTRONIC SYSTEM RECORDER 2100-2045-22 000667752 REF: See Workcard	MOS HRS/MSC AFL	48 4000	+30d/-30d			26-JAN-2015 532.4 280	26-JAN-2019 4532.4	25-FEB-2019	656 d (+30) 3629.1
SYSTEM										
31-31-00-970-001-A00 (s)	DOWNLOAD FDR DATA - PERSONAL COMPUTER DOWNLOADING PKG 5002 REF: AMM 31-31-00	MOS HRS/MSC AFL	12 500	+15d/-15d +20/-20			PKG 21-JAN-2017 884.1 443			
LOW UTILIZATION										
31-31-02-710-001-A00 (s)	OPERATIONALLY CHECK FDR UNDERWATER LOCATOR BEACON PKG 5004 REF: AMM 31-31-02	MOS HRS/MSC AFL	24 1000	+15d/-15d +20/-20			PKG 21-JAN-2017 884.1 443			
LOW UTILIZATION										
31-31-02-960-001-A00	DISCARD FDR UNDERWATER LOCATOR BEACON (ULB) REF: AMM 31-31-02	MOS HRS/MSC AFL	DUE				21-JAN-2017 884.1 443	28-FEB-2022 M		1785 d
SYSTEM										
31-41-00-710-001-A00 (s)	OPERATIONALLY CHECK DAU CHANNEL REVERSION FUNCTION PKG 5008 REF: AMM 31-41-00	MOS HRS/MSC AFL	48 3600 1800	+15d/-15d +20/-20 +20/-20			PKG 26-JAN-2015 532.4 280			
LOW UTILIZATION										

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
31-CVR-001	READOUT COCKPIT VOICE RECORDER	MOS	12				21-JAN-2017 884.1 443	21-JAN-2018		286 d
	REF:	HRS/MSC AFL								
31-FDR-001	READOUT FLIGHT DATA RECORDER (FDR) AND ANALYSIS	MOS	12				21-JAN-2017 884.1 443	21-JAN-2018		286 d
	REF:	HRS/MSC AFL								
311300-0101	LH LIGHT PANEL MODULE	MOS		TSN:0			16-DEC-2010 0			
	145-35259-405	HRS/MSC	O/C	TSN:0						
	0000639154	AFL		TSN:0			0			
	REF:									
311300-0102	RH LIGHT PANEL MODULE	MOS		TSN:0			16-DEC-2010 0			
	145-35260-403	HRS/MSC	O/C	TSN:0						
	0000642121	AFL		TSN:0			0			
	REF:									
311700-0101	MODULE MAINTENANCE PANEL ASSEMBLY	MOS		TSN:0			16-DEC-2010 0			
	145-53623-403	HRS/MSC	O/C	TSN:0						
	0000629261	AFL		TSN:0			0			
	REF: AMM 31-17-01									
312102-0201	PILOT DIGITAL 2 POL CLOCK	MOS		TSN:0			16-DEC-2010 0			
	GMT4190-040	HRS/MSC	O/C	TSN:0						
	81	AFL		TSN:0			0			
	REF:									
312102-0202	COPILOT DIGITAL 2 POL CLOCK	MOS		TSN:0			16-DEC-2010 0			
	GMT4190-040	HRS/MSC	O/C	TSN:0						
	79	AFL		TSN:0			0			
	REF:									
313101-0101	REAR FLIGHT DATA SSFDR ELECTRONIC SYSTEM RECORDER	MOS		TSN:27			05-MAR-2013 97.92			
	2100-2045-22	HRS/MSC	O/C	TSN:97.92						
	000667752	AFL		TSN:83			83			
	REF: AMM 31-31-01									
313101-0201	FDR UNDERWATER LOCATOR BEACON	MOS		TSN:0			26-AUG-2016 854.7			
	DK120	HRS/MSC	O/C	TSN:0						
	SD62535	AFL		TSN:0			424			
	REF: AMM 31-31-02									
313102-0101	REAR TRI AXIAL ACCELEROMETER	MOS		TSN:0			16-DEC-2010 0			
	3001-01-111	HRS/MSC	O/C	TSN:0						
	0810-DTE6466	AFL		TSN:0			0			
	REF: AMM 31-31-03									
313106-0101	LH WING ROTARY-VARIABLE INDUCTIVE, 28VDC/50MA TRANSDUCER	MOS		TSN:0			16-DEC-2010 0			
	PN	HRS/MSC	O/C	TSN:0						
	SN-UNKNOWN	AFL		TSN:0			0			
	REF: AMM 31-31-06									

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
313106-0102	RH WING ROTARY-VARIABLE INDUCTIVE, 28VDC/50MA TRANSDUCER PN SN-UNKNOWN REF: AMM 31-31-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
313106-0103	ROTARY-VARIABLE INDUCTIVE, 28VDC/50MA TRANSDUCER PN SN-UNKNOWN REF: AMM 31-31-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
313106-0104	ROTARY-VARIABLE INDUCTIVE, 28VDC/50MA TRANSDUCER PN SN-UNKNOWN REF: AMM 31-31-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
313106-0105	TAIL ROTARY-VARIABLE INDUCTIVE, 28VDC/50MA TRANSDUCER PN SN-UNKNOWN REF: AMM 31-31-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
313107-0101	REAR FUS AFDAU - AUXILIARY FLIGHT DATA ACQUISITION UNIT PN SN-UNKNOWN REF: AMM 31-31-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
313108-0101	C FLOOR CONVERTER-ANALOGIC/DIGITAL, FLIGHT DATA RECORDING SYS UNIT PN SN-UNKNOWN REF: AMM 31-31-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
314101-0101	REAR I DATA ACQUISITION DA-800 PH, 9 UNIT 7013348-950 10057048 REF: AMM 31-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
314101-0102	C FLOOR DATA ACQUISITION DA-800 PH, 10 UNIT 7013348-950 10117123 REF: AMM 31-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-MAR-2011 25.43 10			
314102-0101	EICAS DISPLAY, EICAS/PFD/MFD SYS, MAIN PANEL UNIT K9321060A12 1890380226 REF: AMM 31-41-02	MOS HRS/MSC AFL	O/C				21-JAN-2017 884.1 443			
314102-0201	CONTROL-EICAS SYS, MAIN PANEL 7014332-951 10089485 REF: AMM 31-41-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
314102-0301	MFD 1 DISPLAY, EICAS/PFD/MFD SYS, MAIN PANEL UNIT K9321060A12 1890255164 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			02-FEB-2012 27.82 22			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
314102-0302	MFD 2 DISPLAY, EICAS/PFD/MFD SYS, MAIN PANEL UNIT K9321060A12 1890203121 REF: AMM 31-41-02	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			02-FEB-2012 27.82 22			
314102-0303	PFD 1 DISPLAY, EICAS/PFD/MFD SYS, MAIN PANEL UNIT K9321060A12 1890255169 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			02-FEB-2012 27.82 22			
314102-0304	PFD 2 DISPLAY, EICAS/PFD/MFD SYS, MAIN PANEL UNIT K9321060A12 1890205659 REF: AMM 31-41-02	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			02-FEB-2012 27.82 22			
314104-0101	CREW CAB CONTROL,EGPWS,NAVIGATION SYS,CTL CONSOLE,COCKPIT MODULE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
314201-0101	INTEGRATED COMPUTER IC-600 WITH AP CARD 7017000-82411 1005A191 REF: AMM 31-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
314201-0102	INTEGRATED COMPUTER IC-600 WITHOUT AP CARD 7017000-83414 1302A477 REF: AMM 31-42-01	MOS HRS/MSC AFL	O/C	TSN:4 TSN:296 TSN:151			08-APR-2015 562 292			
314202-0101	LEFT CONFIGURATION-IC-600 INTEGRATED COMPUTER, COCKPIT MODULE 7025973-03000 08116185 REF: AMM 31-42-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
314202-0102	RIGHT CONFIGURATION-IC-600 INTEGRATED COMPUTER, COCKPIT MODULE 7025973-03000 08116184 REF: AMM 31-42-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
314301-0101	MHE, PAX ENTERTAINMENT SYSTEM, BOX ASSY CONTROLLER 990-6800-004 10080060072 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
314302-0101	MHC25R, PAX CABIN CONTROLLER BOX ASSEMBLY 990-6812-001 10070059720 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
314303-0101	LAPTOP INETRFACE, PAX MHE AIRSHOW SYS, CONTROL ASSY PANEL 990-6820-001 10060059319 REF: AMM 31-43-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
314304-0101	MHR/IRS AIRSHOW,PAX ENTERTAINMENT CABINET RECEIVER 990-6913-001 10070059848 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
314305-0101	MHR INFRARED SENSOR CONTROL UNIT PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
314306-0101	MHI INTERFACE, ENT CABINET, CONTROL UNIT 990-4152-001 10060089442 REF: AMM 31-43-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
315101-0101	NOSE ALARM-AUDIO,ELECTRONIC EQUIPAMENT, FWD FUSLG UNIT 80-0694-2-8 2363 REF: AMM 31-51-01	MOS HRS/MSC AFL	O/C				26-JAN-2015 532.4 280			
315102-0101	CREW CAB MODULE -CONSOLE,MAIN PANEL,COCKPIT ASSEMBLY 145-42850-401 0000634846 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
316101-0101	C FLOOR BOX -DIODES,AVIONICS POWER SUPPLY,FLOOR,COCKPIT ASSEMBLY 145-33126-403 0000642123 REF: AMM 31-61-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
CHAPTER 32		LANDING GEAR								
32-10-00-210-801-L00 (s)	GENERAL VISUAL INSPECTION EXTERNALLY INSPECT THE MAIN LANDING GEAR COMPONENTS- TRAILING ARM - MLG (SSI 32-10-03). PKG 5016 REF: NDT 32-10-00	MOS HRS/MSC AFL	96 4000 2000	+15d/-15d +20/-20 +20/-20			26-JAN-2015 532.4 280			
32-10-00-210-C01-L00 (s)	GENERAL VISUAL INSPECTION EXTERNALLY INSPECT THE MAIN LANDING GEAR COMPONENTS- LEG STRUCTURE, EQUIPPED (LEFT) - MLG (SSI 32-10-01).- LEG STRUCTURE, EQUIPPED (RIGHT) - MLG (SSI 32-10-02).- UPPER SECONDARY BRACE STRUT ASSY - MLG (SSI 32-10-09).- LOWER SECONDARY BRACE STRUT ASSY - MLG (SSI 32-10-10). PKG 5008 REF: CPM 32-10-00	MOS HRS/MSC AFL	48 3600 1800	+15d/-15d +20/-20 +20/-20			26-JAN-2015 532.4 280			
32-10-00-210-C02-L00 (s)	GENERAL VISUAL INSPECTION EXTERNALLY INSPECT THE MAIN LANDING GEAR COMPONENTS- SHOCK ABSORBER PISTON TUBE ASSY - MLG (SSI 32-10-05).-SHOCK ABSORBER CYLINDER ASSY - MLG (SSI 32-10-06). PKG 5008 REF: CPM 32-10-00	MOS HRS/MSC AFL	48 3600 1800	+15d/-15d +20/-20 +20/-20			26-JAN-2015 532.4 280			
32-10-00-220-801-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF THE MAIN LANDING GEAR COMPONENTS- WHEEL AXLE - MLG (SSI 32-10-04). PKG 5008 REF: NDT 32-10-00	MOS HRS/MSC AFL	48 2000 1000	+15d/-15d +20/-20 +20/-20			21-JAN-2017 884.1 443			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-10-01-900-001-A00	RESTORE (OVERHAUL) LH MLG LEG OLEO STRUT ASSEMBLY 2309-1300-401 00012 REF: AMM 32-10-01	MOS HRS/MSC AFL	144	+60d/-60d			16-DEC-2010 0 0	16-DEC-2022	14-FEB-2023	2076 d (+60)
SYSTEM										
32-10-01-900-001-A00	RESTORE (OVERHAUL) RH MLG LEG OLEO STRUT ASSEMBLY 2309-1300-402 00012 REF: AMM 32-10-01	MOS HRS/MSC AFL	144	+60d/-60d			16-DEC-2010 0 0	16-DEC-2022	14-FEB-2023	2076 d (+60)
SYSTEM										
32-10-01-900-002-A00	RESTORE (OVERHAUL) LH MLG TRAILING ARM ASSY REF: AMM 32-10-01	MOS HRS/MSC AFL	144	+60d/-60d			16-DEC-2010 0 0	16-DEC-2022	14-FEB-2023	2076 d (+60)
SYSTEM										
32-10-01-900-002-A00	RESTORE (OVERHAUL) RH MLG TRAILING ARM ASSY REF: AMM 32-10-01	MOS HRS/MSC AFL	144	+60d/-60d			16-DEC-2010 0 0	16-DEC-2022	14-FEB-2023	2076 d (+60)
SYSTEM										
32-10-02-610-001-A00 (s)	SERVICE (REPLENISH) MLG SHOCK ABSORBER PKG 5002 REF: AMM 32-10-02	MOS HRS/MSC AFL	12 500	+15d/-15d +20/-20			PKG 21-JAN-2017 884.1 443			
LOW UTILIZATION										
32-10-02-900-001-A00	RESTORE (OVERHAUL) LH MLG SHOCK ABSORBER ASSEMBLY 2309-2005-401 02285 REF: AMM 32-10-02	MOS HRS/MSC AFL	144	+60d/-60d			16-DEC-2010 0 0	16-DEC-2022	14-FEB-2023	2076 d (+60)
SYSTEM										
32-10-02-900-001-A00	RESTORE (OVERHAUL) RH MLG SHOCK ABSORBER ASSEMBLY 2309-2005-401 02286 REF: AMM 32-10-02	MOS HRS/MSC AFL	144				(EBT)	16-DEC-2022		2076 d
SYSTEM										
32-10-03-900-001-A00	RESTORE (OVERHAUL) LH MLG UPPER MAIN SIDE STRUT ASSEMBLY 2309-2524-001 1256914/014 REF: AMM 32-10-03	MOS HRS/MSC AFL	144	+60d/-60d			16-DEC-2010 0 0	16-DEC-2022	14-FEB-2023	2076 d (+60)
SYSTEM										
32-10-03-900-001-A00	RESTORE (OVERHAUL) RH MLG UPPER MAIN SIDE STRUT ASSEMBLY 2309-2524-001 1296824/008 REF: AMM 32-10-03	MOS HRS/MSC AFL	144	+60d/-60d			(EBT)	16-DEC-2022	14-FEB-2023	2076 d (+60)
SYSTEM										
32-10-03-900-002-A00	RESTORE (OVERHAUL) LH MAIN SIDE ASSY (MLG) STRUT LOWER 2309-3500-503 01802 REF: AMM 32-10-03	MOS HRS/MSC AFL	144	+60d/-60d			16-DEC-2010 0 0	16-DEC-2022	14-FEB-2023	2076 d (+60)
SYSTEM										
32-10-03-900-002-A00	RESTORE (OVERHAUL) RH MAIN SIDE ASSY (MLG) STRUT LOWER 2309-3500-503 01803 REF: AMM 32-10-03	MOS HRS/MSC AFL	144	+60d/-60d			16-DEC-2010 0 0	16-DEC-2022	14-FEB-2023	2076 d (+60)
SYSTEM										

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-10-04-900-001-A00	RESTORE (OVERHAUL) LH MLG UPPER SECONDARY SIDE STRUT ASSEMBLY 2309-2611-003 1279726/002 REF: AMM 32-10-04	MOS HRS/MSC AFL	144	+60d/-60d			16-DEC-2010 0 0	16-DEC-2022	14-FEB-2023	2076 d (+60)
SYSTEM										
32-10-04-900-001-A00	RESTORE (OVERHAUL) RH MLG UPPER SECONDARY SIDE STRUT ASSEMBLY 2309-2611-003 1279726/012 REF: AMM 32-10-04	MOS HRS/MSC AFL	144	+60d/-60d		(EBT)		16-DEC-2022	14-FEB-2023	2076 d (+60)
SYSTEM										
32-10-04-900-002-A00	RESTORE (OVERHAUL) LH MLG SECONDARY SIDE STRUT (LOWER) ASSEMBLY 2309-2624-001 1261972/001 REF: AMM 32-10-04	MOS HRS/MSC AFL	144	+60d/-60d			16-DEC-2010 0 0	16-DEC-2022	14-FEB-2023	2076 d (+60)
SYSTEM										
32-10-04-900-002-A00	RESTORE (OVERHAUL) RH MLG SECONDARY SIDE STRUT (LOWER) ASSEMBLY 2309-2624-001 1265980/005 REF: AMM 32-10-04	MOS HRS/MSC AFL	144	+60d/-60d			16-DEC-2010 0 0	16-DEC-2022	14-FEB-2023	2076 d (+60)
SYSTEM										
32-10-05-900-002-A00	RESTORE (OVERHAUL) LH MLG SPRING CARTRIDGES ASSY REF: AMM 32-10-05	MOS HRS/MSC AFL	144	+60d/-60d			16-DEC-2010 0 0	16-DEC-2022	14-FEB-2023	2076 d (+60)
SYSTEM										
32-10-05-900-002-A00	RESTORE (OVERHAUL) RH MLG SPRING CARTRIDGES ASSY REF: AMM 32-10-05	MOS HRS/MSC AFL	144	+60d/-60d			16-DEC-2010 0 0	16-DEC-2022	14-FEB-2023	2076 d (+60)
SYSTEM										
32-20-00-210-801-L00 (s)	GENERAL VISUAL INSPECTION EXTERNALLY INSPECT THE NOSE LANDING GEAR COMPONENTS - STRUT (MAIN FITTING) - NLG (SSI 32-20-12).- LOWER LOCKING STRUT (SSI 32-20-16).- UPPER DRAG STAY - NLG (SSI 32-20-13).- UPPER LOCKING STAY - NLG (SSI 32-20-15).- TORQUE LINKS - NLG (SSI 32-20-17). PKG 5008 REF: NDT 32-20-00	MOS HRS/MSC AFL	48 3600 1800	+15d/-15d +20/-20 +20/-20			26-JAN-2015 532.4 280			
LOW UTILIZATION										
32-20-00-210-802-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) INSPECT THE NOSE LANDING GEAR COMPONENTS- SLIDING TUBE - NLG (SSI 32-20-18). PKG 5008 REF: NDT 32-20-00	MOS HRS/MSC AFL	48 2000 1000	+15d/-15d +20/-20 +20/-20			21-JAN-2017 884.1 443			
LOW UTILIZATION										
32-20-00-210-C01-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) INSPECT THE NOSE LANDING GEAR COMPONENTS- LOWER DRAG STAY - NLG (SSI 32-20-14). PKG 5008 REF: CPM 32-20-00	MOS HRS/MSC AFL	48 3600 1800	+15d/-15d +20/-20 +20/-20			26-JAN-2015 532.4 280			
LOW UTILIZATION										
32-20-00-220-801-L00 (s)	DETAILED INSPECTION (EXTERNAL) INSPECT THE NOSE LANDING GEAR COMPONENTS- WHEEL AXLE (SSI 32-20-19). PKG 5008 REF: NDT 32-20-00	MOS HRS/MSC AFL	48 2000 1000	+15d/-15d +20/-20 +20/-20			21-JAN-2017 884.1 443			
LOW UTILIZATION										



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-20-01-610-001-A00 (s)	SERVICE (REPLENISH) NLG SHOCK ABSORBER PKG 5002	MOS	12	+15d/-15d			PKG 21-JAN-2017 884.1			
LOW UTILIZATION	REF: AMM 32-20-01	HRS/MSC AFL	500	+20/-20			443			
32-20-01-720-001-A00	FUNCTIONALLY CHECK NLG LEG CENTERING CAM PLAY NOTE: PERFORM AT THE TIME OF NLG SLIDING TUBE ASSY RESTORATION	MOS	144	+15d/-15d			16-DEC-2010 0	16-DEC-2022 10800	31-DEC-2022	2076 d (+15) 9896.7
LOW UTILIZATION	REF: AMM 32-20-01	HRS/MSC AFL	10800				0	10800		10350
32-20-01-900-001-A00	RESTORE (OVERHAUL) LEG -NOSE LANDING GEAR ASSEMBLY 2233B0000-02	MOS	144	+60d/-60d			16-DEC-2010 0	16-DEC-2022	14-FEB-2023	2076 d (+60)
SYSTEM	REF: AMM 32-20-01	HRS/MSC AFL					0			
32-20-01-900-002-A00	RESTORE (OVERHAUL) NLG LEG STRUT SLIDING TUBE 2233-0401	MOS	144	+60d/-60d			16-DEC-2010 0	16-DEC-2022	14-FEB-2023	2076 d (+60)
SYSTEM	REF: AMM 32-20-01	HRS/MSC AFL					0			
32-20-01-900-003-A00	RESTORE (OVERHAUL) NLG LEG STRUT STEERING CUFF 1170-2301	MOS	144	+60d/-60d			16-DEC-2010 0	16-DEC-2022	14-FEB-2023	2076 d (+60)
SYSTEM	REF: AMM 32-20-01	HRS/MSC AFL					0			
32-20-01-900-004-A00	RESTORE (OVERHAUL) NO.1 NLG LEG STRUT TORQUE LINK 1170-0301	MOS	144	+60d/-60d			16-DEC-2010 0	16-DEC-2022	14-FEB-2023	2076 d (+60)
SYSTEM	REF: AMM 32-20-01	HRS/MSC AFL					0			
32-20-01-900-004-A00	RESTORE (OVERHAUL) NO.2 NLG LEG STRUT TORQUE LINK 1170-0301	MOS	144	+60d/-60d			16-DEC-2010 0	16-DEC-2022	14-FEB-2023	2076 d (+60)
SYSTEM	REF: AMM 32-20-01	HRS/MSC AFL					0			
32-20-02-900-001-A00	RESTORE (OVERHAUL) TOP NLG MAIN DRAG STRUT STAY PN	MOS	144	+60d/-60d			16-DEC-2010 0	16-DEC-2022	14-FEB-2023	2076 d (+60)
SYSTEM	REF: AMM 32-20-02	SN-UNKNOWN HRS/MSC AFL					0			
32-20-02-900-002-A00	RESTORE (OVERHAUL) BOTTOM NLG MAIN DRAG STRUT STAY PN	MOS	144	+60d/-60d			16-DEC-2010 0	16-DEC-2022	14-FEB-2023	2076 d (+60)
SYSTEM	REF: AMM 32-20-02	SN-UNKNOWN HRS/MSC AFL					0			
32-20-03-900-001-A00	RESTORE (OVERHAUL) NLG AUXILIARY DRAG STRUT (UPPER) ASSEMBLY 1173A0200-01	MOS	144	+60d/-60d			16-DEC-2010 0	16-DEC-2022	14-FEB-2023	2076 d (+60)
SYSTEM	REF: AMM 32-20-03	HM1525 HRS/MSC AFL					0			
32-20-03-900-002-A00	RESTORE (OVERHAUL) NLG AUXILIARY DRAG STRUT (LOWER) ASSEMBLY 1173A0100-02	MOS	144	+60d/-60d			16-DEC-2010 0	16-DEC-2022	14-FEB-2023	2076 d (+60)
SYSTEM	REF: AMM 32-20-03	HM1454 HRS/MSC AFL					0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-20-04-900-002-A00	RESTORE (OVERHAUL) NLG DOWN LOCK SPRING ASSY	MOS	144	+60d/-60d			16-DEC-2010	16-DEC-2022	14-FEB-2023	2076 d (+60)
SYSTEM	REF: AMM 32-20-04	HRS/MSC AFL					0 0			
32-32-00-710-001-A00 (s)	OPERATIONALLY CHECK LANDING GEAR EXTENSION AND RETRACTION (ELECTRICAL) INDICATION AND DOWNLOCK RELAYS BY CHANNELS A AND B (WITH JACKS)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 32-32-00	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
32-32-02-710-001-A00 (s)	OPERATIONALLY CHECK SOLENOID AND DOWLOCK RELEASE BUTTON OF THE LANDING GEAR CONTROL LEVER.						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: AMM 32-32-02	HRS/MSC AFL	7200 3600	+20/-20 +20/-20			0 0			
32-34-00-640-001-A00 (s)	LUBRICATE LANDING GEAR (MLG & NLG) AND STEERING SYSTEM						PKG			
	PKG 5001	MOS	6	+15d/-15d			21-JAN-2017			
LOW UTILIZATION	REF: AMM 32-34-00	HRS/MSC AFL	250	+20/-20			884.1 443			
32-34-00-710-001-A00 (s)	OPERATIONALLY CHECK LANDING GEAR EMERGENCY EXTENSION (OVERRIDE SWITCH)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 32-34-00	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
32-34-00-720-001-A01 (s)	FUNCTIONALLY CHECK LANDING GEAR EMERGENCY EXTENSION						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 32-34-00	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
32-34-03-720-001-A00 (s)	FUNCTIONALLY CHECK CONDITION AND TENSION OF FREE-FALL CONTROL CABLES						PKG			
	PKG 5012	MOS	72	+15d/-15d			21-JAN-2017			
LOW UTILIZATION	REF: AMM 32-34-03	HRS/MSC AFL	3000 1500	+20/-20 +20/-20			884.1 443			
32-41-00-720-001-A00 (s)	FUNCTIONALLY CHECK MAIN BRAKE SYSTEM						PKG			
	PKG 5008	MOS	48	+15d/-15d			21-JAN-2017			
LOW UTILIZATION	REF: AMM 32-41-00	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			884.1 443			
32-41-01-710-001-A00 (s)	OPERATIONALLY CHECK BRAKE-PEDAL POSITION TRANSDUCER						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: AMM 32-41-01	HRS/MSC AFL	7200 3600	+20/-20 +20/-20			0 0			
32-41-07-720-001-A00 (s)	FUNCTIONALLY CHECK MAIN BRAKE HYDRAULIC FUSES						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 32-41-07	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
32-41-09-710-001-A00 (s)	OPERATIONALLY CHECK RETURN-LINE CHECK VALVE OF MAIN BRAKE SYSTEM.						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 32-41-09	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-44-00-720-001-A00 (s)	FUNCTIONALLY CHECK EMERGENCY/PARKING BRAKE SYSTEM PKG 5016	MOS	96	+15d/-15d			PKG 21-JAN-2017 884.1			
LOW UTILIZATION	REF: AMM 32-44-00	AFL	3600	+20/-20			443			
32-44-02-720-001-A00 (s)	FUNCTIONALLY CHECK HYDRAULIC ACCUMULATOR FOR NITROGEN PRE-CHARGE PKG 5002	MOS	12	+15d/-15d			PKG 21-JAN-2017 884.1			
LOW UTILIZATION	REF: AMM 32-44-02	AFL	500	+20/-20			443			
32-44-06-720-001-A00 (s)	FUNCTIONALLY CHECK THERMAL RELIEF VALVE OF THE EMERGENCY/PARKING BRAKE SYSTEM PKG 5016	MOS	96	+15d/-15d			PKG 16-DEC-2010 0			
LOW UTILIZATION	REF: AMM 32-44-06	AFL	3600	+20/-20			0			
32-44-08	#4 WHEEL PRESSURE GAUGE GP10-147-174 13-0221161 REF:	MOS HRS/MSC AFL	 O/C				26-JAN-2015 532.4 280			
32-44-08-710-001-A00 (s)	OPERATIONALLY CHECK RETURN-LINE CHECK VALVE OF EMERGENCY/PARKING BRAKE SYSTEM PKG 5008	MOS	48	+15d/-15d			PKG 26-JAN-2015 532.4			
LOW UTILIZATION	REF: AMM 32-44-08	AFL	1800	+20/-20			280			
32-44-10-640-001-A00 (s)	LUBRICATE MECHANICAL HARDWARE (HANDLE) AND ROLLER OF EMERGENCY PARKING BRAKE VALVE PKG 5008	MOS	48	+15d/-15d			PKG 26-JAN-2015 532.4			
LOW UTILIZATION	REF: AMM 32-44-10	AFL	1800	+20/-20			280			
32-49-02-220-001-A00	INSPECT (DETAILED INSPECTION) LEFT NO. 1 MAIN LANDING GEAR OUTBOARD TIRE MLG WHEEL ASSY - WHEELS SPEED TRANSDUCER CLIP IN THE HUB CAP DRIVE CLIP NOTE: AT EACH TIRE CHANGE 302K62B1 01867539 REF: AMM 32-49-02	MOS HRS/MSC AFL	 T/C				16-DEC-2010 0 0			
SYSTEM										
32-49-02-220-001-A00	INSPECT (DETAILED INSPECTION) LEFT NO. 2 MAIN LANDING GEAR INBOARD TIRE MLG WHEEL ASSY - WHEELS SPEED TRANSDUCER CLIP IN THE HUB CAP DRIVE CLIP NOTE: AT EACH TIRE CHANGE 302K62B1 01877717 REF: AMM 32-49-02	MOS HRS/MSC AFL	 T/C				16-DEC-2010 0 0			
SYSTEM										
32-49-02-220-001-A00	INSPECT (DETAILED INSPECTION) RIGHT NO. 3 MAIN LANDING GEAR INBOARD TIRE MLG WHEEL ASSY - WHEELS SPEED TRANSDUCER CLIP IN THE HUB CAP DRIVE CLIP NOTE: AT EACH TIRE CHANGE 302K62B1 01867688 REF: AMM 32-49-02	MOS HRS/MSC AFL	 T/C				16-DEC-2010 0 0			
SYSTEM										
32-49-02-220-001-A00	INSPECT (DETAILED INSPECTION) RIGHT NO. 4 MAIN LANDING GEAR OUTBOARD TIRE MLG WHEEL ASSY - WHEELS SPEED TRANSDUCER CLIP IN THE HUB CAP DRIVE CLIP NOTE: AT EACH TIRE CHANGE 302K62B1 01877534 REF: AMM 32-49-02	MOS HRS/MSC AFL	 T/C				16-DEC-2010 0 0			
SYSTEM										

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-49-03-220-001-A00	INSPECT (DETAILED INSPECTION) LEFT NO. 1 MAIN LANDING GEAR OUTBOARD TIRE OF BRAKE WEAR INDICATOR NOTE: AT EACH TIRE CHANGE									
	302K62B1	MOS					16-DEC-2010			
	01867539	HRS/MSC	T/C				0			
SYSTEM	REF: AMM 32-49-03	AFL					0			
32-49-03-220-001-A00	INSPECT (DETAILED INSPECTION) LEFT NO. 2 MAIN LANDING GEAR INBOARD TIRE OF BRAKE WEAR INDICATOR NOTE: AT EACH TIRE CHANGE									
	302K62B1	MOS					16-DEC-2010			
	01877717	HRS/MSC	T/C				0			
SYSTEM	REF: AMM 32-49-03	AFL					0			
32-49-03-220-001-A00	INSPECT (DETAILED INSPECTION) RIGHT NO. 3 MAIN LANDING GEAR INBOARD TIRE OF BRAKE WEAR INDICATOR NOTE: AT EACH TIRE CHANGE									
	302K62B1	MOS					16-DEC-2010			
	01867688	HRS/MSC	T/C				0			
SYSTEM	REF: AMM 32-49-03	AFL					0			
32-49-03-220-001-A00	INSPECT (DETAILED INSPECTION) RIGHT NO. 4 MAIN LANDING GEAR OUTBOARD TIRE OF BRAKE WEAR INDICATOR NOTE: AT EACH TIRE CHANGE									
	302K62B1	MOS					16-DEC-2010			
	01877534	HRS/MSC	T/C				0			
SYSTEM	REF: AMM 32-49-03	AFL					0			
32-49-07-710-001-A00	OPERATIONALLY CHECK NO. 1 CARBON ASSY-LEG,MAIN LANDING GEAR BRAKE BRAKE SHUTTLE VALVE NOTE: AT EACH BRAKE REPLACEMENT									
	2-1741	MOS					16-DEC-2010			
	0051	HRS/MSC	C/C				0			
SYSTEM	REF: AMM 32-49-07	AFL					0			
32-49-07-710-001-A00	OPERATIONALLY CHECK NO. 2 CARBON ASSY-LEG,MAIN LANDING GEAR BRAKE BRAKE SHUTTLE VALVE NOTE: AT EACH BRAKE REPLACEMENT									
	2-1741	MOS					16-DEC-2010			
	0052	HRS/MSC	C/C				0			
SYSTEM	REF: AMM 32-49-07	AFL					0			
32-49-07-710-001-A00	OPERATIONALLY CHECK NO. 3 CARBON ASSY-LEG,MAIN LANDING GEAR BRAKE BRAKE SHUTTLE VALVE NOTE: AT EACH BRAKE REPLACEMENT									
	2-1741	MOS					16-DEC-2010			
	0050	HRS/MSC	C/C				0			
SYSTEM	REF: AMM 32-49-07	AFL					0			
32-49-07-710-001-A00	OPERATIONALLY CHECK NO. 4 CARBON ASSY-LEG,MAIN LANDING GEAR BRAKE BRAKE SHUTTLE VALVE NOTE: AT EACH BRAKE REPLACEMENT									
	2-1741	MOS					16-DEC-2010			
	0061	HRS/MSC	C/C				0			
SYSTEM	REF: AMM 32-49-07	AFL					0			
32-50-00-710-001-A00 (s)	OPERATIONALLY CHECK NOSE WHEEL STEERING SYSTEM DISENGAGEMENT									
	PKG 5001	MOS	6	+15d/-15d			21-JAN-2017			
		HRS/MSC	250	+20/-20			884.1			
LOW UTILIZATION	REF: AMM 32-50-00	AFL					443			



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
32-50-06-720-001-A00 (s)	FUNCTIONALLY CHECK 7-DEGREE PROXIMITY SWITCH. PKG 5008	MOS	48	+15d/-15d			PKG 26-JAN-2015 532.4			
LOW UTILIZATION	REF: AMM 32-50-06	AFL	1800	+20/-20			280			
32-62-00-710-001-A00 (s)	OPERATIONALLY CHECK LANDING-GEAR WARNING SYSTEM PKG 5001	MOS	6	+15d/-15d			PKG 21-JAN-2017 884.1			
LOW UTILIZATION	REF: AMM 32-62-00	AFL	250	+20/-20			443			
32-63-00-710-001-A00 (s)	OPERATIONALLY CHECK AIR/GROUND SYSTEM PKG 5001	MOS	6	+15d/-15d			PKG 21-JAN-2017 884.1			
LOW UTILIZATION	REF: AMM 32-63-00	AFL	250	+20/-20			443			
32-Z711-213-001-A00	EXTERNAL GENERAL VISUAL INSPECTION ZONES 113, 114, 115, 116, 711, 713, 714 (L600 ONLY)	MOS					16-DEC-2010 0			
REF:		HRS/MSC	N/A				0			
		AFL					0			
32-Z711-213-001-A01 (s)	GENERAL VISUAL INSPECTION EXTERNAL GENERAL VISUAL INSPECTION (ZONES 113, 114, 115, 116, 711, 713, 714) NOTE: EWIS.(L650 ONLY)	MOS	24	+15d/-15d			PKG 21-JAN-2017 884.1			
LOW UTILIZATION	REF: AMM 05-20-99	AFL	1000	+20/-20			443			
32-Z721-213-001-A00	EXTERNAL GENERAL VISUAL INSPECTION ZONES 721, 731, 722, 732, 532, 632 (L600 ONLY)	MOS					16-DEC-2010 0			
REF:		HRS/MSC	N/A				0			
		AFL					0			
32-Z721-213-001-A01 (s)	GENERAL VISUAL INSPECTION EXTERNAL GENERAL VISUAL INSPECTION (ZONES 721, 731, 722, 732, 532, 632). NOTE: EWIS.(L650 ONLY)	MOS	24	+15d/-15d			PKG 21-JAN-2017 884.1			
LOW UTILIZATION	REF: AMM 05-30-01	AFL	1000	+20/-20			443			
321000-0101	LH MLG LEG OLEO STRUT ASSEMBLY 2309-1300-401 00012	MOS				TSN:0	16-DEC-2010 0			
REF:		HRS/MSC	O/C			TSN:0	0			
		AFL				TSN:0	0			
321000-0102	RH MLG LEG OLEO STRUT ASSEMBLY 2309-1300-402 00012	MOS				TSN:0	16-DEC-2010 0			
REF:		HRS/MSC	O/C			TSN:0	0			
		AFL				TSN:0	0			
321000-0201	LH STRUT (MLG) LEG 2309-1300-401 00012	MOS				TSN:0	16-DEC-2010 0			
LIFE LIMIT	REF: AMM 32-10-01	AFL	60000			TSN:0	0	60000		59550



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
321000-0202	RH STRUT (MLG) LEG 2309-1300-402 00012	MOS HRS/MSC		TSN:0 TSN:0			16-DEC-2010 0			
LIFE LIMIT	REF: AMM 32-10-01	AFL	60000	TSN:0			0	60000		59550
321000-0203	LH STRUT (MLG) - PIVOT PN	MOS		TSN:0			16-DEC-2010 0			
LIFE LIMIT	REF: SN-UNKNOWN	AFL	60000	TSN:0			0	60000		59550
321000-0204	RH STRUT (MLG) - PIVOT PN	MOS		TSN:0			16-DEC-2010 0			
LIFE LIMIT	REF: SN-UNKNOWN	AFL	60000	TSN:0			0	60000		59550
321000-0301	LH NO. 1 TRUNNION (MLG) (LEG STRUT) AXLE 2309-3025-001 1347924/001	MOS HRS/MSC		TSN:0 TSN:0			16-DEC-2010 0			
LIFE LIMIT	REF:	AFL	60000	TSN:0			0	60000		59550
321000-0302	RH NO. 1 TRUNNION (MLG) (LEG STRUT) AXLE 2309-3025-001 1347924/005	MOS HRS/MSC		TSN:0 TSN:0			16-DEC-2010 0			
LIFE LIMIT	REF:	AFL	60000	TSN:0			0	60000		59550
321000-0401	LH ACTUATOR ATTACHMENT (MLG) (LEG STRUT) AXLE PN	MOS		TSN:0			16-DEC-2010 0			
LIFE LIMIT	REF: SN-UNKNOWN	AFL	O/C	TSN:0			0			
321000-0402	RH ACTUATOR ATTACHMENT (MLG) (LEG STRUT) AXLE PN	MOS		TSN:0			16-DEC-2010 0			
LIFE LIMIT	REF: SN-UNKNOWN	AFL	O/C	TSN:0			0			
321001-0101	LH TRAILING (MLG) (LEG STRUT) ARM 2309-1310-501 1328426/001	MOS HRS/MSC		TSN:0 TSN:0			16-DEC-2010 0			
LIFE LIMIT	REF: AMM 32-10-08	AFL	21454	TSN:0			0	21454		21004
321001-0102	RH TRAILING (MLG) (LEG STRUT) ARM 2309-1310-501 1335351/001	MOS HRS/MSC		TSN:0 TSN:0			16-DEC-2010 0			
LIFE LIMIT	REF: AMM 32-10-08	AFL	21454	TSN:0			0	21454		21004
321001-0201	LH TRAILING ARM (MLG) (LEG STRUT) AXLE 2309-1305-001 1342440/001	MOS HRS/MSC		TSN:0 TSN:0			16-DEC-2010 0			
LIFE LIMIT	REF: AMM 32-10-08	AFL	60000	TSN:0			0	60000		59550
321001-0202	RH TRAILING ARM (MLG) (LEG STRUT) AXLE 2309-1305-002 1341407/001	MOS HRS/MSC		TSN:0 TSN:0			16-DEC-2010 0			
LIFE LIMIT	REF: AMM 32-10-08	AFL	60000	TSN:0			0	60000		59550

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
321002-0101	LH MLG SHOCK ABSORBER ASSEMBLY 2309-2005-401 02285 REF: AMM 32-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
321002-0102	RH MLG SHOCK ABSORBER ASSEMBLY 2309-2005-401 02286 REF: AMM 32-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
321002-0201	LH MLG NO.1 SHOCK ABSORBER ATTACHMENT (LEG STRUT) AXLE 2309-1329-001 1330376/001 REF: AMM 32-10-02	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0	60000		59550
321002-0202	RH MLG NO.1 SHOCK ABSORBER ATTACHMENT (LEG STRUT) AXLE 2309-1329-001 1332050/002 REF: AMM 32-10-02	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0	60000		59550
321002-0203	LH MLG NO.2 SHOCK ABSORBER ATTACHMENT (LEG STRUT) AXLE 2309-1329-001 1332050/001 REF: AMM 32-10-02	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0	60000		59550
321002-0204	RH MLG NO.2 SHOCK ABSORBER ATTACHMENT (LEG STRUT) AXLE 2309-3025-001 1347924/004 REF: AMM 32-10-02	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0	60000		59550
321002-0301	LH SHOCK ABSORBER PISTON (MLG) (LEG STRUT) TUBE 2309-2058-001 1268078/004 REF: AMM 32-10-02	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0	60000		59550
321002-0302	RH SHOCK ABSORBER PISTON (MLG) (LEG STRUT) TUBE 2309-2058-001 1265996/004 REF: AMM 32-10-02	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0	60000		59550
321002-0401	LH SHOCK ABSORBER (MLG) (LEG STRUT) CYLINDER 2309-2056-005 1232732/002 REF: AMM 32-10-02	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0	60000		59550
321002-0402	RH SHOCK ABSORBER (MLG) (LEG STRUT) CYLINDER 2309-2056-005 1232732/003 REF: AMM 32-10-02	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0	60000		59550
321002-0501	LH SHOCK ABSORBER BEARING (MLG) (LEG STRUT) CAP 2309-2082-001 1307296/003 REF: AMM 32-10-02	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0	60000		59550



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
321002-0502	RH SHOCK ABSORBER BEARING (MLG) (LEG STRUT) CAP 2309-2082-001 1307296/013	MOS HRS/MSC		TSN:0 TSN:0			16-DEC-2010 0			
LIFE LIMIT	REF: AMM 32-10-02	AFL	60000	TSN:0			0	60000		59550
321003-0101	LH MAIN SIDE ASSY (MLG) STRUT 2309-3500-503 01802	MOS HRS/MSC	O/C	TSN:0 TSN:0			16-DEC-2010 0			
	REF: AMM 32-10-03	AFL		TSN:0			0			
321003-0102	RH MAIN SIDE ASSY (MLG) STRUT 2309-3500-503 01803	MOS HRS/MSC	O/C	TSN:0 TSN:0			16-DEC-2010 0			
	REF: AMM 32-10-03	AFL		TSN:0			0			
321003-0201	LH MAIN SIDE STRUT ATTACHMENT (MLG) (LEG STRUT) AXLE 2309-3032-005 1278307/001	MOS HRS/MSC		TSN:0 TSN:0			16-DEC-2010 0			
LIFE LIMIT	REF: AMM 32-10-10	AFL	60000	TSN:0			0	60000		59550
321003-0202	RH MAIN SIDE STRUT ATTACHMENT (MLG) (LEG STRUT) AXLE 2309-3032-005 1287307/002	MOS HRS/MSC		TSN:0 TSN:0			16-DEC-2010 0			
LIFE LIMIT	REF: AMM 32-10-10	AFL	60000	TSN:0			0	60000		59550
321003-0301	LH MLG UPPER MAIN SIDE STRUT ASSEMBLY 2309-2524-001 1256914/014	MOS HRS/MSC		TSN:0 TSN:0			16-DEC-2010 0			
LIFE LIMIT	REF: AMM 32-10-03	AFL	60000	TSN:0			0	60000		59550
321003-0302	RH MLG UPPER MAIN SIDE STRUT ASSEMBLY 2309-2524-001 1296824/008	MOS HRS/MSC		TSN:0 TSN:0			16-DEC-2010 0			
LIFE LIMIT	REF: AMM 32-10-03	AFL	60000	TSN:0			0	60000		59550
321003-0401	LH MAIN SIDE STRUT (MLG) (LOWER) ASSEMBLY 2309-2532-001 1360496/008	MOS HRS/MSC		TSN:0 TSN:0			16-DEC-2010 0			
LIFE LIMIT	REF: AMM 32-10-03	AFL	60000	TSN:0			0	60000		59550
321003-0402	RH MAIN SIDE STRUT (MLG) (LOWER) ASSEMBLY 2309-2532-001 1360496/003	MOS HRS/MSC		TSN:0 TSN:0			16-DEC-2010 0			
LIFE LIMIT	REF: AMM 32-10-03	AFL	60000	TSN:0			0	60000		59550
321003-0501	LH MAIN SIDE STRUT (MLG) SHAFT PN SN-UNKNOWN	MOS HRS/MSC		TSN:0 TSN:0			16-DEC-2010 0			
LIFE LIMIT	REF:	AFL	60000	TSN:0			0	60000		59550
321003-0502	RH MAIN SIDE STRUT (MLG) SHAFT PN SN-UNKNOWN	MOS HRS/MSC		TSN:0 TSN:0			16-DEC-2010 0			
LIFE LIMIT	REF:	AFL	60000	TSN:0			0	60000		59550

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
321003-0601	LH MAIN SIDE STRUT (MLG) PIVOT PIN 2309-3516-001 1315287/012	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0		60000	59550
LIFE LIMIT	REF:	AFL	60000	TSN:0			0		60000	59550
321003-0602	RH MAIN SIDE STRUT (MLG) PIVOT PIN 2309-3516-001 1315287/010	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0		60000	59550
LIFE LIMIT	REF:	AFL	60000	TSN:0			0		60000	59550
321003-0701	LH MAIN SIDE STRUT (MLG) CARDAN 2309-3530-003 1340064/003	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
LIFE LIMIT	REF: AMM 32-10-10	AFL		TSN:0			0			
321003-0702	RH MAIN SIDE STRUT (MLG) CARDAN 2309-3530-003 1340064/009	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
LIFE LIMIT	REF: AMM 32-10-10	AFL		TSN:0			0			
321004-0101	LH LDG ROD -SECONDARY,MAIN LANDING GEAR ASSEMBLY 2309-2600-507 02392	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
LIFE LIMIT	REF:	AFL		TSN:0			0			
321004-0102	RH LDG ROD -SECONDARY,MAIN LANDING GEAR ASSEMBLY 2309-2600-507 02394	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
LIFE LIMIT	REF:	AFL		TSN:0			0			
321004-0301	LH MLG UPPER SECONDARY SIDE STRUT ASSEMBLY 2309-2611-003 1279726/002	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0		60000	59550
LIFE LIMIT	REF: AMM 32-10-04	AFL	60000	TSN:0			0		60000	59550
321004-0302	RH MLG UPPER SECONDARY SIDE STRUT ASSEMBLY 2309-2611-003 1279726/012	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0		60000	59550
LIFE LIMIT	REF: AMM 32-10-04	AFL	60000	TSN:0			0		60000	59550
321004-0401	LH MLG SECONDARY SIDE STRUT (LOWER) ASSEMBLY 2309-2624-001 1261972/001	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0		60000	59550
LIFE LIMIT	REF: AMM 32-10-04	AFL	60000	TSN:0			0		60000	59550
321004-0402	RH MLG SECONDARY SIDE STRUT (LOWER) ASSEMBLY 2309-2624-001 1265980/005	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0		60000	59550
LIFE LIMIT	REF: AMM 32-10-04	AFL	60000	TSN:0			0		60000	59550
321004-0501	LH MLG SECONDARY SIDE STRUT CARDAN 2309-2618-001 1342425/003	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0		60000	59550
LIFE LIMIT	REF: AMM 32-10-11	AFL	60000	TSN:0			0		60000	59550

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
321004-0502	RH MLG SECONDARY SIDE STRUT CARDAN 2309-2618-001 1342425/006	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0		60000	59550
LIFE LIMIT	REF: AMM 32-10-11									
321004-0601	LH MLG SECONDARY SIDE STRUT AXLE 2309-2621-001 1323498/017	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0		60000	59550
LIFE LIMIT	REF:									
321004-0602	RH MLG SECONDARY SIDE STRUT AXLE 2309-2621-001 1337159/007	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0		60000	59550
LIFE LIMIT	REF:									
321004-0701	LH MLG SECONDARY SIDE STRUT BOLT 2309-2626-001 1267516/006	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0		60000	59550
LIFE LIMIT	REF:									
321004-0702	RH MLG SECONDARY SIDE STRUT BOLT 2309-2626-001 1267516/011	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0		60000	59550
LIFE LIMIT	REF:									
321004-0801	LH MLG SECONDARY SIDE STRUT PIVOT PIN 2309-2613-001 1287946/010	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0		60000	59550
LIFE LIMIT	REF:									
321004-0802	RH MLG SECONDARY SIDE STRUT PIVOT PIN 2309-2613-001 1287946/031	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0		60000	59550
LIFE LIMIT	REF:									
321004-0901	LH MLG SECONDARY SIDE STRUT NO.1 SPRING 2309-2651-005 1343033/016	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0		60000	59550
LIFE LIMIT	REF: AMM 32-10-05									
321004-0902	LH MLG SECONDARY SIDE STRUT NO.2 SPRING 2309-2651-005 1343033/019	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0		60000	59550
LIFE LIMIT	REF: AMM 32-10-05									
321004-0903	RH MLG SECONDARY SIDE STRUT NO.1 SPRING 2309-2651-005 1343033/009	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0		60000	59550
LIFE LIMIT	REF: AMM 32-10-05									
321004-0904	RH MLG SECONDARY SIDE STRUT NO.2 SPRING 2309-2651-005 1343033/017	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0		60000	59550
LIFE LIMIT	REF: AMM 32-10-05									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
321005-0101	LH WHEEL (MLG) (LEG STRUT) AXLE 2309-3040-001 1278737/004	MOS HRS/MSC		TSN:0 TSN:0			16-DEC-2010 0			
LIFE LIMIT	REF: AMM 32-49-02	AFL	60000	TSN:0			0	60000		59550
321005-0102	RH WHEEL (MLG) (LEG STRUT) AXLE 2309-3040-001 1278737/003	MOS HRS/MSC		TSN:0 TSN:0			16-DEC-2010 0			
LIFE LIMIT	REF: AMM 32-49-02	AFL	60000	TSN:0			0	60000		59550
321006-0101	LH (MLG) (LEG STRUT) CARDAN JOINT 2309-2048-005 1269161/008	MOS HRS/MSC		TSN:0 TSN:0			16-DEC-2010 0			
LIFE LIMIT	REF: AMM 32-10-10	AFL	60000	TSN:0			0	60000		59550
321006-0102	RH (MLG) (LEG STRUT) CARDAN JOINT 2309-2048-005 1241914/009	MOS HRS/MSC		TSN:0 TSN:0			16-DEC-2010 0			
LIFE LIMIT	REF: AMM 32-10-10	AFL	60000	TSN:0			0	60000		59550
321007-0101	LH (MLG) LINEAR HYDRAULIC (MANEUVERING ACTUATOR) ACTUATOR 2309-3700-503 01808	MOS HRS/MSC		TSN:0 TSN:0			16-DEC-2010 0			
RESTORE	REF:	AFL	20000	TSN:0			0	20000		19550
321007-0102	RH (MLG) LINEAR HYDRAULIC (MANEUVERING ACTUATOR) ACTUATOR 2309-3700-503 01809	MOS HRS/MSC		TSN:0 TSN:0			16-DEC-2010 0			
RESTORE	REF:	AFL	20000	TSN:0			0	20000		19550
321007-0201	LH MANEUVERING ACTUATOR (MLG) CYLINDER PN SN-UNKNOWN	MOS HRS/MSC	O/C	TSN:0 TSN:0			16-DEC-2010 0			
	REF:	AFL		TSN:0			0			
321007-0202	RH MANEUVERING ACTUATOR (MLG) CYLINDER PN SN-UNKNOWN	MOS HRS/MSC	O/C	TSN:0 TSN:0			16-DEC-2010 0			
	REF:	AFL		TSN:0			0			
321007-0301	LH MANEUVERING ACTUATOR (MLG) ROD END PN SN-UNKNOWN	MOS HRS/MSC		TSN:0 TSN:0			16-DEC-2010 0			
LIFE LIMIT	REF:	AFL	20000	TSN:0			0	20000		19550
321007-0302	RH MANEUVERING ACTUATOR (MLG) ROD END PN SN-UNKNOWN	MOS HRS/MSC		TSN:0 TSN:0			16-DEC-2010 0			
LIFE LIMIT	REF:	AFL	20000	TSN:0			0	20000		19550
321007-0401	LH MANEUVERING ACTUATOR ROD (MLG) PISTON PN SN-UNKNOWN	MOS HRS/MSC	O/C	TSN:0 TSN:0			16-DEC-2010 0			
	REF:	AFL		TSN:0			0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
321007-0402	RH MANEUVERING ACTUATOR ROD (MLG) PISTON PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
321007-0501	LH MANEUVERING ACTUATOR BEARING (MLG) CAP PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
321007-0502	RH MANEUVERING ACTUATOR BEARING (MLG) CAP PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
322000-0101	LEG -NOSE LANDING GEAR ASSEMBLY 2233B0000-02 05012 REF: AMM 32-20-01	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0	60000		59550
322000-0201	NLG LEG STRUT SLIDING TUBE 2233-0401 L1601 REF: AMM 32-20-08	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0	20000		19550
322000-0301	NLG LEG STRUT WHEEL AXLE 2233-0202 L246 REF:	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0	60000		59550
322000-0401	NLG LEG STRUT STEERING CUFF 1170-2301 L1792 REF:	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0	60000		59550
322000-0501	NO.1 NLG LEG STRUT TORQUE LINK 1170-0301 L3079 REF: AMM 32-20-10	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0	60000		59550
322000-0502	NO.2 NLG LEG STRUT TORQUE LINK 1170-0301 L3080 REF: AMM 32-20-10	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0	60000		59550
322000-0601	NO.1 NLG LEG STRUT TORQUE LINK PIN 1170-0001 L2823 REF: AMM 32-20-10	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0	60000		59550
322000-0602	NO.2 NLG LEG STRUT TORQUE LINK PIN 1170-0001 L2824 REF: AMM 32-20-10	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0	60000		59550

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
322000-0701	NLG LEG STRUT TORQUE LINK CENTRAL BOLT 1170-0002 L1969	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
LIFE LIMIT	REF: AMM 32-20-10		60000					60000		59550
322000-0801	NLG LEG STRUT MAIN FITTING 2233-0103 991	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
LIFE LIMIT	REF:		60000					60000		59550
322000-0901	(NLG) MAIN DRAG STRUT ATTACHMENT PIN 1170-0070 L1734	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
LIFE LIMIT	REF:		60000					60000		59550
322000-1101	NO. 1 NLG LEG STRUT PINTLE PIN 1170-0032 L3611	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
LIFE LIMIT	REF:		60000					60000		59550
322000-1102	NO. 2 NLG LEG STRUT PINTLE PIN 1170-0032 L3612	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
LIFE LIMIT	REF:		60000					60000		59550
322000-1201	(NLG) LEG STRUT ACTUATOR ATTACHMENT BOLT PIN 1170-0071 L1644	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
LIFE LIMIT	REF:									
322001-0101	TOP NLG MAIN DRAG STRUT STAY PN SN-UNKNOWN	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
LIFE LIMIT	REF:		6000					6000		5550
322001-0201	BOTTOM NLG MAIN DRAG STRUT STAY PN SN-UNKNOWN	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
LIFE LIMIT	REF:		30000					30000		29550
322001-0301	NO.1 NLG MAIN DRAG STRUT PINTLE PIN PN SN-UNKNOWN	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
LIFE LIMIT	REF:		6000					6000		5550
322001-0302	NO.2 NLG MAIN DRAG STRUT PINTLE PIN PN SN-UNKNOWN	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
LIFE LIMIT	REF:		6000					6000		5550
322001-0401	NLG MAIN DRAG STRUT HINGE POINT BOLT 1172-0001 HM428	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
LIFE LIMIT	REF:		60000					60000		59550

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
322001-0501	NLG MAIN DRAG STRUT ACTUATOR ATTACHMENT PIN PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
322001-0601	NLG MAIN DRAG STRUT ASSEMBLY 1172D0000-02 02184 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
322002-0101	NLG ROD -MAIN LOCKING,NOSE LANDING GEAR ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	63600	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0	63600	63150	
322003-0101	NLG AUXILIARY DRAG STRUT 1173B0000-03 02234 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
322004-0101	NLG AUXILIARY DRAG STRUT (UPPER) ASSEMBLY 1173A0200-01 HM1525 REF: AMM 32-20-09	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0	60000	59550	
322004-0201	NLG AUXILIARY DRAG STRUT (LOWER) ASSEMBLY 1173A0100-02 HM1454 REF: AMM 32-20-09	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0	60000	59550	
322004-0301	NO. 1 NLG AUXILIARY DRAG STRUT HINGE POINT BOLT 1173-0001 HM280 REF: AMM 32-20-09	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0	60000	59550	
322004-0401	NLG AUXILIARY DRAG STRUT (JOINT ATTACHING PARTS) CARDAN KSL 113608V KC1467 REF: AMM 32-20-09	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0	60000	59550	
322004-0501	NO. 1 NLG AUXILIARY DRAG STRUT SLEEVE 1173-0011 HM02T REF: AMM 32-20-09	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0	60000	59550	
322004-0601	NO. 1 NLG AUXILIARY DRAG STRUT DOWNLOCK SPRING 1173A0700-01 HM090405 REF: AMM 32-20-04	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0	20000	19550	
322004-0602	NO. 2 NLG AUXILIARY DRAG STRUT DOWNLOCK SPRING 1173A0700-01 HM090406 REF: AMM 32-20-04	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0	20000	19550	

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
322005-0101	NO. 1 NLG - NOSE LANDING GEAR DOOR ASSEMBLY 135-18799-401 0000637104 REF: AMM 32-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
322005-0102	NO.2 NLG - NOSE LANDING GEAR DOOR ASSEMBLY 135-18799-402 0000637107 REF: AMM 32-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
323201-0101	CSL CENT LANDING GEAR ELECTRONIC UNIT 355-022-003 5495 REF: AMM 32-32-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
323202-0101	CSL CENT CONTROL, LANDING GEAR, MAIN PANEL LEVER 7-45550-3 1321 REF: AMM 32-32-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
323301-0101	MID FREE-FALL SELECTOR VALVE 4702-5 1391 REF: AMM 32-33-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
323302-0101	MID SOLENOID 4 WASYS, 2 POS VALVE 2225-0100-003 01257 REF: AMM 32-33-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
323303-0101	NOSE ACTUATOR, HYDRAULIC -DOOR, NOSE LANDING GEAR ASSEMBLY 2118-0100-401 03165 REF: AMM 32-33-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
323303-0102	NOSE ACTUATOR, HYDRAULIC -DOOR, NOSE LANDING GEAR ASSEMBLY 2118-0100-401 03168 REF: AMM 32-33-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
323303-0201	NLG DOOR ACTUATOR PN SN-UNKNOWN REF: AMM 32-33-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
323304-0101	MID SOLENOID 4 WAY, 3 POS, VALVE 2227-0100-001 01203 REF: AMM 32-33-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
323305-0101	NLG MANEUVERING ACTUATOR 1300B0000-02 02165 REF: AMM 32-33-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
323305-0201	NLG MANEUVERING ACTUATOR CYLINDER PN SN-UNKNOWN REF: AMM 32-33-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
323305-0301	NLG MANEUVERING ACTUATOR PISTON ROD PN SN-UNKNOWN REF: AMM 32-33-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
323306-0101	NLG ACTUATOR -HYDRAULIC,UNLOCKING, NLG ASSEMBLY 1175B0000-01 02177 REF: AMM 32-33-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
323307-0101	NLG BOX UP LOCK -HYDRAULIC SYS,AUXILIARY LANDING GEAR ASSEMBLY 2309-2900-401 03484 REF: AMM 32-33-07	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0	60000	59550	
323307-0102	LH LDG BOX UP LOCK -HYDRAULIC SYS,AUXILIARY LANDING GEAR ASSEMBLY 2309-2900-401 03486 REF: AMM 32-33-07	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0	60000	59550	
323307-0103	RH LDG BOX UP LOCK -HYDRAULIC SYS,AUXILIARY LANDING GEAR ASSEMBLY 2309-2900-401 03490 REF: AMM 32-33-07	MOS HRS/MSC AFL	60000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0	60000	59550	
323309-0101	LH LDG UNLOCKING ACTUATOR ASSEMBLY 2309-2800-505 02354 REF: AMM 32-33-09	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0	20000	19550	
323309-0102	RH LDG UNLOCKING ACTUATOR ASSEMBLY 2309-2800-505 02353 REF: AMM 32-33-09	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0	20000	19550	
323311-0101	MID CHECK ASSY-HYDRAULIC SYS, FWD FUSLG VALVE 2241-0001-001 03611 REF: AMM 32-33-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
323311-0102	STUB CHECK ASSY-HYDRAULIC SYS, FWD FUSLG VALVE 2241-0001-001 03612 REF: AMM 32-33-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
323311-0103	RH RACK CHECK ASSY-HYDRAULIC SYS, FWD FUSLG VALVE 2241-0001-001 03578 REF: AMM 32-33-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
323312-0101	MID RESTRICTOR, HYDRAULIC SYS, SSTEEL VALVE 2236-0010-001 1363554/001 REF: AMM 32-33-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
323315-0101	MID HYDRAULIC ACCUMULATOR 0860202001 60202-2200NA REF: AMM 32-33-15	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
323316-0101	MID ONE-WAY RESTRICTOR VALVE 2237-0100-001 00968 REF: AMM 32-33-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
323319-0101	MID DRAIN-MANUAL, HYDRAULIC SYS, FWD/CTL FUSLG VALVE HV50-61 10-0920173 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
323319-0102	HYD SYST DRAIN-MANUAL, HYDRAULIC SYS, FWD/CTL FUSLG VALVE HV50-61 10-0920170 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
323319-0103	MID DRAIN-MANUAL, HYDRAULIC SYS, FWD/CTL FUSLG VALVE HV50-61 10-0920174 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324101-0201	LH PIL PEDAL, RUDDER CONTROL, FWD FUSLG TRANSDUCER 20-017500 831272 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324101-0202	LH COPIL PEDAL, RUDDER CONTROL, FWD FUSLG TRANSDUCER 20-017500 831199 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324101-0203	RH PIL PEDAL, RUDDER CONTROL, FWD FUSLG TRANSDUCER 20-017500 861657 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324101-0204	RH COPIL PEDAL, RUDDER CONTROL, FWD FUSLG TRANSDUCER 20-017500 831269 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324102-0101	C FLOOR CONTROL ASSY, BS, BRAKE SYS, COCKPIT BOX 42-951-6 1045 REF: AMM 32-41-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
324103-0101	LEFT NO. 1 WHEEL SPEED OUTBOARD TRANSDUCER 140-197 8888 REF: AMM 32-41-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324103-0102	LEFT NO. 2 WHEEL SPEED INBOARD TRANSDUCER 140-197 8848 REF: AMM 32-41-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324103-0103	RIGHT NO.3 WHEEL SPEED INBOARD TRANSDUCER 140-197 8845 REF: AMM 32-41-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324103-0104	RIGHT NO.4 WHEEL SPEED OUTBOARD TRANSDUCER 140-197 8847 REF: AMM 32-41-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324104-0101	LEFT PRESSURE SWITCH 15622-101 2641 REF: AMM 32-41-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324104-0102	RIGHT PRESSURE SWITCH 15622-101 2643 REF: AMM 32-41-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324105-0101	LH WING SHUTOFF,BRAKE VALVE 38-793500 2428 REF: AMM 32-41-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324105-0102	RH WING SHUTOFF,BRAKE VALVE 38-793500 2437 REF: AMM 32-41-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324106-0101	LH WING BRAKE CONTROL VALVE 39-807 2291 REF: AMM 32-41-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324106-0102	RH WING BRAKE CONTROL VALVE 39-807 2407 REF: AMM 32-41-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324107-0101	LH WING FUSE 38-791500 4788 REF: AMM 32-41-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
324107-0102	LH WING FUSE 38-791500 4791 REF: AMM 32-41-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324107-0201	RH WING FUSE 38-791500 4792 REF: AMM 32-41-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324107-0202	RH WING FUSE 38-791500 4794 REF: AMM 32-41-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324108-0201	LH WING PRESSURE-LANDING GEAR TRANSDUCER 52-565500-1 7566-10-250 REF: AMM 32-41-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324108-0202	RH WING PRESSURE-LANDING GEAR TRANSDUCER 52-565500-1 7566-10-242 REF: AMM 32-41-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324108-0203	LH WING PRESSURE-LANDING GEAR TRANSDUCER 52-565500-1 7566-10-254 REF: AMM 32-41-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324108-0204	RH WING PRESSURE-LANDING GEAR TRANSDUCER 52-565500-1 7566-10-248 REF: AMM 32-41-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324109-0101	W STUB CHECK ASSY-HYDRAULIC SYS, FWD FUSLG VALVE 2241-0020-001 03539 REF: AMM 32-41-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324109-0102	W STUB CHECK ASSY-HYDRAULIC SYS, FWD FUSLG VALVE 2241-0020-001 03679 REF: AMM 32-41-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			26-JAN-2015 532.4 280			
324109-0103	MID CHECK ASSY-HYDRAULIC SYS, FWD FUSLG VALVE 2241-0020-001 03540 REF: AMM 32-41-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324401-0101	HYD SYST EMERGENCY PARKING BRAKE VALVE 9067-40-4 1436 REF: AMM 32-44-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
324402-0101	EMERGENCY PARKING BRAKE HYDRAULIC ACCUMULATOR PN SN-UNKNOWN REF: AMM 32-44-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324405-0101	HYD SYST PRESSURE SWITCH 15782-101 0973 REF: AMM 32-44-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324406-0101	MID THERMAL RELIEF ASSY, VALVE 2228-0001-005 02543 REF: AMM 32-44-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324406-0102	RH RACK THERMAL RELIEF ASSY, VALVE 2228-0001-005 02562 REF: AMM 32-44-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324407-0101	LH WING PRESSURE-PARKING BRAKE SYS SWITCH 15851 1779 REF: AMM 32-44-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324701-0201	LH LDG INDICATOR,BRAKE TEMPERATURE SENSOR 0132AFU-2 J7492 REF: AMM 32-47-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324701-0202	LH LDG INDICATOR,BRAKE TEMPERATURE SENSOR 0132AFU-2 J7573 REF: AMM 32-47-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324701-0203	RH LDG INDICATOR,BRAKE TEMPERATURE SENSOR 0132AFU-2 J7497 REF: AMM 32-47-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324701-0204	RH LDG INDICATOR,BRAKE TEMPERATURE SENSOR 0132AFU-2 J7498 REF: AMM 32-47-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324702-0201	LEFT SIGNAL-BRAKE TEMPERATURE,WING STUB CONDITIONER 0510GW2 2326 REF: AMM 32-47-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324702-0202	RIGHT SIGNAL-BRAKE TEMPERATURE,WING STUB CONDITIONER 0510GW2 2334 REF: AMM 32-47-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
324900-0001	LEFT NO.1 MAIN LANDING GEAR OUTBOARD WHEEL AND TIRE ASSEMBLY PN SN-UNKNOWN REF: AMM 32-49-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324900-0002	LEFT NO. 2 MAIN LANDING GEAR INBOARD WHEEL AND TIRE ASSEMBLY PN SN-UNKNOWN REF: AMM 32-49-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324900-0003	RIGHT NO. 3 MAIN LANDING GEAR INBOARD WHEEL AND TIRE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324900-0004	RIGHT NO. 4 MAIN LANDING GEAR OUTBOARD WHEEL AND TIRE ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324900-0101	LEFT NO. 1 MAIN LANDING GEAR OUTBOARD WHEEL ASSEMBLY 135-25602-401 5152 REF: AMM 32-49-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			05-SEP-2016 857.6 426			
324900-0102	LEFT NO. 2 MAIN LANDING GEAR INBOARD WHEEL ASSEMBLY 135-25602-403 5341 REF: AMM 32-49-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-FEB-2016 752.9 373			
324900-0103	RIGHT NO. 3 MAIN LANDING GEAR INBOARD WHEEL ASSEMBLY 135-25602-403 5144 REF: AMM 32-49-02	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			10-FEB-2016 752.9 373			
324900-0104	RIGHT NO. 4 MAIN LANDING GEAR OUTBOARD WHEEL ASSEMBLY 135-25602-401 5081 REF: AMM 32-49-02	MOS HRS/MSC AFL	O/C				27-JUL-2016 835.3 411			
324900-0201	LEFT NO. 1 MAIN LANDING GEAR OUTBOARD TIRE 302K62B1 01867539 REF: AMM 32-49-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324900-0202	LEFT NO. 2 MAIN LANDING GEAR INBOARD TIRE 302K62B1 01877717 REF: AMM 32-49-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324900-0203	RIGHT NO. 3 MAIN LANDING GEAR INBOARD TIRE 302K62B1 01867688 REF: AMM 32-49-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
324900-0204	RIGHT NO. 4 MAIN LANDING GEAR OUTBOARD TIRE 302K62B1 01877534 REF: AMM 32-49-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324900-0301	L/H WHEEL NLG ASSEMBLY 135-25928-401 1428 REF:	MOS HRS/MSC AFL	O/C				08-JAN-2016 729 362			
324900-0302	R/H WHEEL NLG ASSEMBLY 135-25928-401 1481332 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			22-OCT-2015 697.2 345			
324900-0401	WHEEL NLG (LH) TIRE 196K02B1 00553544 REF: AMM 32-49-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324900-0402	WHEEL NLG (RH) TIRE 196K02B1 00563003 REF: AMM 32-49-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324903-0101	NO. 1 CARBON ASSY-LEG,MAIN LANDING GEAR BRAKE 2-1741 0051 REF: AMM 32-49-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324903-0102	NO. 2 CARBON ASSY-LEG,MAIN LANDING GEAR BRAKE 2-1741 0052 REF: AMM 32-49-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324903-0103	NO. 3 CARBON ASSY-LEG,MAIN LANDING GEAR BRAKE 2-1741 0050 REF: AMM 32-49-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
324903-0104	NO. 4 CARBON ASSY-LEG,MAIN LANDING GEAR BRAKE 2-1741 0061 REF: AMM 32-49-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
325001-0101	CSL CENT BOX CONTROL -STEERING, MANUAL, NOSE LANDING GEAR ASSEMBLY 123-02328-407 0000646134 REF: AMM 32-50-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
325003-0101	C FLOOR BOX ELECTRONIC-STEERING CONTROL, NOSE LANDING GEAR ASSEMBLY 308560-1019 1688 REF: AMM 32-50-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
325004-0101	MID HYDRALIC-STEERING SYS CONTROL, NOSE LDG MODULE 308570-1007 0280B REF: AMM 32-50-04	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0			01-MAR-2011 25.43 10			
325006-0101	NLG STEERING PROXIMITY SWITCH 80-057-01 25769 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
326101-0101	LH MLG UPLOCK 'A' PROXIMITY SWITCH 80-057-01 25088 REF: AMM 32-61-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
326101-0102	RH MLG UPLOCK 'A' PROXIMITY SWITCH 80-057-01 25673 REF: AMM 32-61-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
326101-0103	LH MLG UPLOCK 'B' PROXIMITY SWITCH 80-057-01 25682 REF: AMM 32-61-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
326101-0104	RH MLG UPLOCK 'B' PROXIMITY SWITCH 80-057-01 25097 REF: AMM 32-61-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
326102-0101	LH MLG DOWNLOCK 'A' PROXIMITY SWITCH 80-057-01 25684 REF: AMM 32-61-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
326102-0102	RH MLG DOWNLOCK 'A' PROXIMITY SWITCH 80-057-01 25674 REF: AMM 32-61-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
326102-0103	LH MLG DOWNLOCK 'B' PROXIMITY SWITCH 80-057-01 25686 REF: AMM 32-61-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
326102-0104	RH MLG DOWNLOCK 'B' PROXIMITY SWITCH 80-057-01 25677 REF: AMM 32-61-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
326301-0101	LH MLG WOW #1 PROXIMITY SWITCH PN SN-UNKNOWN REF: AMM 32-63-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
326301-0102	RH MLG WOW #1 PROXIMITY SWITCH 80-057-01 25681 REF: AMM 32-63-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
326301-0103	LH MLG WOW #2 PROXIMITY SWITCH PN SN-UNKNOWN REF: AMM 32-63-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
326301-0104	RH MLG WOW #2 PROXIMITY SWITCH 80-057-01 25683 REF: AMM 32-63-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
326302-0101	NLG WOW PROXIMITY SWITCH 80-057-01 25771 REF: AMM 32-63-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
326303-0101	NLG SEQUENCE DOOR PROXIMITY SWITCH 80-057-01 25773 REF: AMM 32-63-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
326304-0101	NLG OPEN DOOR PROXIMITY SWITCH 80-057-01 25774 REF: AMM 32-63-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
326304-0102	NLG OPEN DOOR PROXIMITY SWITCH 80-057-01 25775 REF: AMM 32-63-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
329500-0313	NLG PROXIMITY SWITCH 80-057-01 25778 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
329500-0314	NLG PROXIMITY SWITCH 80-057-01 25780 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
329500-0315	NLG PROXIMITY SWITCH 80-057-01 25083 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
329500-0316	NLG PROXIMITY SWITCH 80-057-01 25091 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

CHAPTER 33 LIGHTS

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
33-12-00-710-002-A00	OPERATIONALLY CHECK COCKPIT PUSHBUTTON LIGHTING	MOS					21-JAN-2017			
	REF: AMM 33-12-00	HRS/MSC	N/A				884.1			
		AFL					443			
33-47-03-720-001-A00	FUNCTIONALLY CHECK WHITE STROBE LIGHTING SYSTEM.									
	NOTE: THIS TASK IS APPLICABLE ONLY TO AIRCRAFT UNDER ANAC/FAA CERTIFICATIONS.									
	PKG 5002	MOS	12	+15d/-15d			21-JAN-2017	19-DEC-2017	03-JAN-2018	253 d (+15)
		HRS/MSC	900	+20/-20	-33		884.1	1784.1	1804.1	880.8 (+20)
LOW UTILIZATION	REF: AMM 33-47-03	AFL	450	+20/-20			443	893	913	443 (+20)
33-50-00-710-001-A00 (s)	OPERATIONALLY CHECK EMERGENCY LIGHTING SYSTEM						PKG			
	PKG 5001	MOS	12	+15d/-15d			21-JAN-2017			
LOW UTILIZATION	REF: AMM 33-50-00	HRS/MSC	500	+20/-20			884.1			
		AFL					443			
33-50-04-720-001-A00 (s)	FUNCTIONALLY CHECK NO. 2 EMERGENCY-NICAD,6VDC,5 AH BATTERY DLE MODEL IF INSTALLED						PKG			
	3400-22-10 PKG 5001	MOS	6	+15d/-15d			21-JAN-2017			
	012023	HRS/MSC	450	+20/-20			884.1			
LOW UTILIZATION	REF: AMM 33-50-04	AFL					443			
33-50-04-720-001-A00 (s)	FUNCTIONALLY CHECK NO.1 EMERGENCY-NICAD,6VDC,5 AH BATTERY DLE MODEL IF INSTALLED						PKG			
	3301-31 PKG 5001	MOS	6	+15d/-15d			21-JAN-2017			
	55106	HRS/MSC	450	+20/-20			884.1			
LOW UTILIZATION	REF: AMM 33-50-04	AFL					443			
33-51-01-720-001-A00 (s)	FUNCTIONALLY CHECK FLASHLIGHTS RECHARGEABLE BATTERIES (IF INSTALLED)						PKG			
	PKG 5002	MOS	12	+15d/-15d			21-JAN-2017			
		HRS/MSC	900	+20/-20			884.1			
LOW UTILIZATION	REF: AMM 33-51-01	AFL	450	+20/-20			443			
33-51-01-720-001-A01 (s)	FUNCTIONALLY CHECK FLASHLIGHTS NON-RECHARGEABLE BATTERIES (IF INSTALLED)						PKG			
	PKG 5002	MOS	12	+15d/-15d			21-JAN-2017			
		HRS/MSC	900	+20/-20			884.1			
LOW UTILIZATION	REF: AMM 33-51-01	AFL	450	+20/-20			443			
33-51-03-960-001-A00 (s)	DISCARD NON RECHARGEABLE FLASHLIGHT BATTERY PACK NOTE: IF INSTALLED									
		MOS					21-JAN-2017			
		HRS/MSC	N/A				884.1			
SYSTEM	REF: AMM 33-51-01	AFL					443			
330000-0101	OVERH P MODULE -INTERNAL LT CONT ASSEMBLY									
	145-32843-405	MOS				TSN:0	16-DEC-2010			
	0000638549	HRS/MSC	O/C			TSN:0	0			
	REF:	AFL				TSN:0	0			
330000-0201	OVERH P MODULE -EXT/CKPT/PAX LT CONTROL ASSEMBLY									
	145-21338-401	MOS				TSN:0	16-DEC-2010			
	0000636397	HRS/MSC	O/C			TSN:0	0			
	REF:	AFL				TSN:0	0			
330000-0301	OVERH P CONTROL ASSY-EXTERNAL NAVIGATION LIGHT,COCKPIT MODULE									
	145-21335-401	MOS				TSN:0	16-DEC-2010			
	0000636389	HRS/MSC	O/C			TSN:0	0			
	REF:	AFL				TSN:0	0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
330000-0401	OVERH P CONTROL ASSY-OVERHEAD PANEL EXTERNAL LIGHT,LDG,COCKPIT MODULE 145-21332-401 0000636896 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
331100-0101	CREW CAB LIGHT READING,COCKPIT CEILING ASSEMBLY 2LA 006 265-00 1488809 REF: AMM 33-11-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
331100-0102	CREW CAB LIGHT READING,COCKPIT CEILING ASSEMBLY 2LA 006 265-00 1488829 REF: AMM 33-11-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
331100-0103	CREW CAB LIGHT READING,COCKPIT CEILING ASSEMBLY 2LA 006 265-00 1488844 REF: AMM 33-11-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
331202-0101	NOSE DIMMER 1826-1 10378 REF: AMM 33-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
331202-0102	NOSE DIMMER 1826-1 10383 REF: AMM 33-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
331202-0103	NOSE DIMMER 1826-1 10415 REF: AMM 33-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
331202-0104	NOSE DIMMER 1826-1 10417 REF: AMM 33-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
331202-0105	NOSE DIMMER 1826-1 10418 REF: AMM 33-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
331202-0106	NOSE DIMMER 1826-1 10419 REF: AMM 33-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
331501-0101	CSL CENT PROJECTOR,GLARESHIELD CENTRAL CONSOLE,COCKPIT PANEL 10-123T 424004 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
331501-0102	CSL CENT PROJECTOR, GLARESHIELD CENTRAL CONSOLE, COCKPIT PANEL 10-123C 364025 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
331501-0103	CSL CENT PROJECTOR, GLARESHIELD CENTRAL CONSOLE, COCKPIT PANEL 10-123B 332049 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
331503-0101	LH CSL LEFT, MAIN PANEL, CTL CONSOLE INVERTER 55-0531-6-21 546007 REF: AMM 33-15-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
331503-0102	RH CSL RIGHT, MAIN PANEL, CTL CONSOLE INVERTER 55-0521-4-21 508020 REF: AMM 33-15-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
334502-0101	UPPER LIGHT NAVIGATION, RED STROBE LIGHT ASSEMBLY 2LA 002 760-70 1657015 REF: AMM 33-47-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
334503-0101	CENT FUS POWER, SUPPLY-ELECTRICAL, RED STROBE LIGHT 8ES456038-00 1663318 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
334702-0101	STROBE LIGHT POWER SUPPLY 60-5096-1 4045 REF: AMM 33-47-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
334702-0201	LH WING STROBE LIGHT POWER SUPPLY 60-5096-1 4040 REF: AMM 33-47-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
334702-0202	RH WING STROBE LIGHT POWER SUPPLY 60-5096-1 4048 REF: AMM 33-47-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
335002-0101	NO. 1 EMERGENCY LIGHTING SYSTEM POWER SUPPLY ASSEMBLY PN SN-UNKNOWN REF: AMM 33-50-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
335002-0102	NO. 2 EMERGENCY LIGHTING SYSTEM POWER SUPPLY ASSEMBLY PN SN-UNKNOWN REF: AMM 33-50-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
335004-0101	NO.1 EMERGENCY-NICAD,6VDC,5 AH BATTERY 3301-31 55106 REF: AMM 33-50-04	MOS HRS/MSC AFL	O/C				21-JAN-2017 884.1 443			
335004-0102	NO. 2 EMERGENCY-NICAD,6VDC,5 AH BATTERY 3400-22-10 012023 REF: AMM 33-50-04	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0		08-JAN-2016 729 362			
CHAPTER 34 NAVIGATION										
34-01-00-720-001-A00	FUNCTIONALLY CHECK INTEGRATED STANDBY INSTRUMENT SYSTEM - ISIS NOTE: OR IN ACCORDANCE WITH LOCAL REGULATORY AUTHORITY REQUIREMENTS	MOS HRS/MSC AFL	24 5000				21-JAN-2017 884.1 443	21-JAN-2019 5884.1		651 d 4980.8
NATIONAL REQUIREMENT	REF: AMM 34-01-01									
34-13-00-610-001-A00	SERVICE (CLEANING) PITOT AND STATIC SYSTEM (NOTE: OR IN ACCORDANCE WITH LOCAL REGULATORY AUTHORITY REQUIREMENTS).	MOS HRS/MSC AFL	72 8000	+30d/-30d		-36	21-JAN-2017 884.1 443	16-DEC-2022 8884.1	15-JAN-2023	2076 d (+30) 7980.8
SYSTEM	REF: See Workcard									
34-13-00-680-001-A00 (s)	SERVICE (DRAIN) PITOT LINES PKG 5001	MOS HRS/MSC AFL	6 250	+15d/-15d +20/-20			21-JAN-2017 884.1 443			
LOW UTILIZATION	REF: See Workcard									
34-13-00-790-001-A00 (s)	FUNCTIONALLY CHECK PITOT-STATIC SYSTEM FOR LEAKAGE NOTE: OR IN ACCORDANCE WITH LOCAL REGULATORY AUTHORITY REQUIREMENTS	MOS HRS/MSC AFL	48 3600 1800	+15d/-15d +20/-20 +20/-20			21-JAN-2017 884.1 443			
LOW UTILIZATION	REF: See Workcard									
34-13-04-280-001-A00	INSPECT (SPECIAL INSPECTION) RVSM CRITICAL REGION (SKIN) FOR WAVINESS	MOS HRS/MSC AFL	48 5000	+30d/-30d		-41	26-JAN-2015 532.4 280	16-DEC-2018 5532.4	15-JAN-2019	615 d (+30) 4629.1
RVSM	REF: AMM 34-13-04									
34-13-04-280-002-A00	INSPECT (SPECIAL INSPECTION) STATIC PORT SURROUNDING PLATE FOR FLUSHNESS AND INTEGRITY NOTE: ONLY FOR RVSM OPERATION	MOS HRS/MSC AFL	48 5000	+30d/-30d		-41	26-JAN-2015 532.4 280	16-DEC-2018 5532.4	15-JAN-2019	615 d (+30) 4629.1
RVSM	REF: AMM 34-13-04									
34-13-04-280-003-A00	INSPECT (SPECIAL INSPECTION) OXYGEN SERVICE PANEL FOR FLUSHNESS AND INTEGRITY (PASSENGER GASEOUS OXYGEN SYSTEM ONLY) NOTE: IF INSTALLED	MOS HRS/MSC AFL	48 5000	+30d/-30d		-41	26-JAN-2015 532.4 280	16-DEC-2018 5532.4	15-JAN-2019	615 d (+30) 4629.1
RVSM	REF: AMM 34-13-04									



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
34-15-00-720-001-A00 (s)	FUNCTIONAL CHECK NO.2 NOSE UNIT,AIR DATA PROCESSO-NAVIGATION COMPUTER (NOTE: OR IN ACCORDANCE WITH LOCAL REGULATORY AUTHORITY REQUIREMENTS)						PKG			
	7030700-71701 PKG 5004	MOS	24				21-JAN-2017			
	10072466	HRS/MSC	1800				884.1			
NATIONAL REQUIREMENT	REF: AMM 34-15-00	AFL	900				443			
34-15-00-720-001-A00 (s)	FUNCTIONALLY CHECK NO.1 NOSE UNIT,AIR DATA PROCESSO-NAVIGATION COMPUTER NOTE: OR IN ACCORDANCE WITH LOCAL REGULATORY AUTHORITY REQUIREMENTS						PKG			
	7030700-71701 PKG 5004	MOS	24				21-JAN-2017			
	10072456	HRS/MSC	1800				884.1			
NATIONAL REQUIREMENT	REF: AMM 34-15-00	AFL	900				443			
34-21-03-140-001-A00 (s)	RESTORE (CLEANING) AHRS FAN FILTER (NOTE: IF INSTALLED)						PKG			
	PKG 5002	MOS	12	+15d/-15d			21-JAN-2017			
		HRS/MSC	900	+20/-20			884.1			
LOW UTILIZATION	REF:	AFL	450	+20/-20			443			
34-22-00-710-001-A00 (s)	OPERATIONALLY CHECK ELECTRONIC FLIGHT INSTRUMENT SYSTEM REVERSION FUNCTION.						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 34-22-00	AFL	1800	+20/-20			280			
34-25-00-720-001-A00	FUNCTIONALLY CHECK STANDBY COMPASS FOR PROPER COMPENSATION									
	PGA1001WG	MOS	24	+30d/-30d	5		21-JAN-2017	26-JAN-2019	25-FEB-2019	656 d (+30)
	713613-06	HRS/MSC					884.1			
SYSTEM	REF: AMM 34-25-00	AFL					443			
34-27-03-140-001-A00 (s)	RESTORE (CLEANING) DUAL IRS MOUNTING TRAY FAN FILTER (NOTE: IF INSTALLED).						PKG			
	PKG 5001	MOS	6	+15d/-15d			21-JAN-2017			
		HRS/MSC	450	+20/-20			884.1			
LOW UTILIZATION	REF: AMM 34-27-03	AFL					443			
34-41-00-710-003-A00 (s)	OPERATIONALLY CHECK EGPWS/WINDSHEAR						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 34-41-00	AFL	1800	+20/-20			280			
34-52-00-720-001-A00	FUNCTIONALLY CHECK NO. 1 TRANSPONDER SYSTEM									
		MOS	24	+30d/-30d			21-JAN-2017	21-JAN-2019	20-FEB-2019	651 d (+30)
		HRS/MSC					884.1			
SYSTEM	REF: See Workcard	AFL					443			
34-52-00-720-001-A00	FUNCTIONALLY CHECK NO. 2 TRANSPONDER SYSTEM									
		MOS	24	+30d/-30d	5		21-JAN-2017	26-JAN-2019	25-FEB-2019	656 d (+30)
		HRS/MSC					884.1			
SYSTEM	REF: See Workcard	AFL					443			
34-63-01-720-001-A00 (s)	FUNCTIONALLY CHECK ELECTRONIC FLIGHT BAG DISPLAY UNIT (EDU), BATTERY CAPACITY. NOTE: ONLY FOR AIRCRAFT EQUIPPED WITH EFB.						PKG			
	PKG 5002	MOS	12	+15d/-15d			21-JAN-2017			
		HRS/MSC	900	+20/-20			884.1			
LOW UTILIZATION	REF: AMM 34-63-02	AFL	450	+20/-20			443			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
340101-0101	CSL CENT CONTROL-INTEGRATED STANDBY INSTRUMENT SYS UNIT C16221GD05 C16221020624 REF: AMM 34-01-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
341300-0101	LEFT PITOT-ANEMOMETRIC SYSTEM,NICKEL TUBE 0851HU3 277607 REF: AMM 34-13-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
341300-0102	RIGHT PITOT-ANEMOMETRIC SYSTEM,NICKEL TUBE 0851HU3 277648 REF: AMM 34-13-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
341300-0201	FORWARD TUBE,PITOT STATIC-ANEMOMETRIC FWD FUSLG SYSTEM 0856NF 264783 REF: AMM 34-13-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
341300-0401	LEFT UP PORT,STATIC-HEATED,PRESSURIZATION 28VDC SYSTEM ST-300-2PTH 1460610 REF: AMM 34-13-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
341300-0402	LEFT LW PORT,STATIC-HEATED,PRESSURIZATION 28VDC SYSTEM ST-300-2PTH 1460608 REF: AMM 34-13-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
341300-0403	RIGHT UP PORT,STATIC-HEATED,PRESSURIZATION 28VDC SYSTEM ST-300-2PTH 1460607 REF: AMM 34-13-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
341300-0404	RIGHT LW PORT,STATIC-HEATED,PRESSURIZATION 28VDC SYSTEM ST-300-2PTH 1460606 REF: AMM 34-13-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
341501-0101	NO.1 NOSE UNIT,AIR DATA PROCESSO-NAVIGATION COMPUTER 7030700-71701 10072456 REF: AMM 34-15-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
341501-0102	NO.2 NOSE UNIT,AIR DATA PROCESSO-NAVIGATION COMPUTER 7030700-71701 10072466 REF: AMM 34-15-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
341502-0101	NOSE TOTAL TEMPERATURE SENSOR 102AU1AF A93962 REF: AMM 34-15-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
341502-0102	CREW CAB TOTAL, TEMPERATURE SENSOR 102AU1AF B5 REF: AMM 34-15-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
342202-0101	CONTROL-PFD SYS, MAIN PANEL 7014331-921 10087439 REF: AMM 34-22-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
342202-0102	CONTROL-PFD SYS, MAIN PANEL 7014331-921 10087441 REF: AMM 34-22-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
342202-0103	CONTROL-MFD SYS,MAIN PANEL 7014332-931 10079472 REF: AMM 34-22-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
342202-0104	CONTROL-MFD SYS,MAIN PANEL 7014332-931 10079479 REF: AMM 34-22-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
342204-0101	CREW CAB MODULE -REVERSIONARY PANEL ASSEMBLY 145-42334-401 0000640307 REF: AMM 34-22-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
342204-0102	CREW CAB MODULE -REVERSIONARY PANEL ASSEMBLY 145-42334-401 0000640308 REF: AMM 34-22-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
342205-0101	CREW CAB CONTROL-DISPLAY,FGC,GLARESHIELD PANEL UNIT 7016986-505 10070507 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
342205-0102	CREW CAB CONTROL-DISPLAY,FGC,GLARESHIELD PANEL UNIT 7016986-505 10080510 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
342501-0101	MAGNETIC-NAV SYS - WINDSHIELD MOUNTING BRACKET COMPASS PGA1001WG 713613-06 REF: AMM 34-25-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
342701-0101	NOSE INERTIAL REFERENCE UNIT HG2001GD03 56026275 REF: AMM 34-27-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
342701-0102	NOSE INERTIAL REFERENCE UNIT HG2001GD03 56026310 REF: AMM 34-27-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
342703-0101	CREW CAB MODE SELECT UNIT CG1042AB03 73740944 REF: AMM 34-27-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
342703-0102	CREW CAB MODE SELECT UNIT CG1042AB03 73740948 REF: AMM 34-27-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
343101-0101	LH RADIO ALTIMETER UNIT 7001840-937 1008G882 REF: AMM 34-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
343102-0101	NAVIGATION SYSTEM - RADIO ALTIMETER ANTENNA S67-2002 543-53111 REF: AMM 34-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
343102-0102	NAVIGATION SYSTEM - RADIO ALTIMETER ANTENNA S67-2002 543-53112 REF: AMM 34-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
343200-0101	NOSE COUPLER DMB-20-20 2942 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
343201-0101	NOSE NAV/ADF/DME,INTEGRATED,NAVIGATION SYS UNIT 7510100-631 1007C318 REF: AMM 34-32-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
343201-0102	NOSE NAV/ADF/DME,INTEGRATED,NAVIGATION SYS UNIT 7510100-631 1007C319 REF: AMM 34-32-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
343202-0101	CREW CAB CONTROL-EMERGENCY,NAVIGATION/COMMUNICATION SYS UNIT 7513000-835 10033893 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
343203-0101	NOSE DUAL GLIDE SLOPE ANTENNA S41422-2 111-6700 REF: AMM 34-32-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
343204-0101	LOWER MARKER BEACON ANTENNA 3165-82-00 316582-1123 REF: AMM 34-32-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
343205-0101	REAR VOR-LOC ANTENNA 19-78 11487 REF: AMM 34-32-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
343205-0102	REAR VOR-LOC ANTENNA 19-78 11490 REF: AMM 34-32-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
343205-0201	REAR DIVIDER,ANTENNA,VOR/ILS/MB SYS COUPLER CI120-7 271741 REF: AMM 34-32-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
344101-0101	L/H CSL EGPWS,NAVIGATION,COCKPIT CONTROL UNIT 965-0976-040-216-216 EMK5-31467 REF: AMM 34-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
344201-0101	NOSE WEATHER RADAR TRANSCIEVER 7021450-801 MOD A-Y 1210C585 REF: AMM 34-42-01	MOS HRS/MSC AFL	O/C				12-JUL-2016 819 404			
344202-0101	CSL CENT PANEL CONTROL WEATHER RADAR ASSEMBLY 7008471-407 1007B820 REF: AMM 34-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
344202-0102	CSL CENT PANEL CONTROL WEATHER RADAR ASSEMBLY 7008471-407 1008B864 REF: AMM 34-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
344301-0101	TCAS PROCESSOR UNIT 7517900-55012 20011076 REF: AMM 34-43-01	MOS HRS/MSC AFL	O/C				26-JAN-2015 532.4 280			
344302-0101	TCAS ANTENNA 7514081-915 ANE35237 REF: AMM 34-43-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
344303-0101	BAND 'L' (DME/TDR) ANTENNA 2430-87-00 243087-3348 REF: AMM 34-43-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
344303-0102	TDR TOP BAND 'L' (DME/TDR) ANTENNA 2430-87-00 243087-3329 REF: AMM 34-43-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
344303-0103	TDR BOT BAND 'L' (DME/TDR) ANTENNA 2430-87-00 243087-3364 REF: AMM 34-43-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
344303-0104	DMEL BAND 'L' (DME/TDR) ANTENNA 2430-87-00 243087-3366 REF: AMM 34-43-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
344303-0105	BAND 'L' (DME/TDR) ANTENNA 2430-87-00 243087-3324 REF: AMM 34-43-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
345203-0101	NOSE COAXIAL RELAY D2-729B005 564652 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
345203-0102	NOSE COAXIAL RELAY D2-729B005 564661 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
345302-0201	NO. 1 ADF ANTENNA 7510300-901 1007G898 REF: AMM 34-53-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
345302-0202	NO. 2 ADF ANTENNA 7510300-901 1105J239 REF: AMM 34-53-02	MOS HRS/MSC AFL	O/C				18-JUN-2013 157.2 100			
345601-0101	CENT FUS SENSOR,GPS,RADIO/NAVIGATION SYS (GNSSU) UNIT HG2021GD04 3360 REF: AMM 34-56-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-JUL-2016 819 404			
345601-0102	CENT FUS SENSOR,GPS,RADIO/NAVIGATION SYS (GNSSU) UNIT HG2021GD04 1237 REF: AMM 34-56-01	MOS HRS/MSC AFL	O/C				26-JAN-2015 532.4 280			
345602-0201	GPS 1 GPS ANTENNA S67-1575-135 818-2452 REF: AMM 34-56-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			26-JAN-2015 532.4 280			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
345602-0202	GPS 2 GPS ANTENNA S67-1575-135 818-2466 REF: AMM 34-56-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			26-JAN-2015 532.4 280			
346201-0101	NOSE FMS COMPUTER 7018879-03038 35579727 REF: AMM 34-61-01	MOS HRS/MSC AFL	O/C				26-JAN-2015 532.4 280			
346201-0102	NOSE FMS COMPUTER 7018879-03038 35580278 REF: AMM 34-61-01	MOS HRS/MSC AFL	O/C				26-JAN-2015 532.4 280			
346202-0101	CSL CENT CONTROL AND DISPLAY (FMS) UNIT 2888-07-1 C525239 REF: AMM 34-61-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
346202-0102	CSL CENT CONTROL AND DISPLAY (FMS) UNIT 2888-07-1 C525238 REF: AMM 34-61-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
346206-0101	CSL CENT DATA,LOADER-DUAL FMS/GPS SYS,CREW CABIN UNIT G7228-01 73 REF: AMM 34-61-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
346207-0101	NOSE CONFIGURATION-FMS,NAVIGATION SYS MODULE 7014940-902 06057028 REF: AMM 34-61-04	MOS HRS/MSC AFL	O/C				26-JAN-2015 532.4 280			
346207-0102	NOSE CONFIGURATION-FMS,NAVIGATION SYS MODULE 7014940-902 10088565 REF: AMM 34-61-04	MOS HRS/MSC AFL	O/C				26-JAN-2015 532.4 280			
34DC02	NO. 1 (CCD) CONTROL CURSOR DEVICE G7280-703 284 REF:	MOS HRS/MSC AFL	O/C				23-MAR-2015 556 288			
34DC02	NO. 2 (CCD) CONTROL CURSOR DEVICE G7280-703 273 REF:	MOS HRS/MSC AFL	O/C				22-JAN-2017 885.7 444			
CHAPTER 35 OXYGEN										
35-10-00-710-001-A00 (s)	OPERATIONALLY CHECK CREW/PAX OXYGEN MASKS						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 35-10-00	AFL	1800	+20/-20			280			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
35-10-00-910-001-A00	FUNCTIONALLY CHECK LEAK TEST CREW OXYGEN SYSTEM LINES NOTE: CHECK TOGETHER WITH TASK 35-10-07-720-002-A01	MOS HRS/MSC AFL	60				20-MAY-2015	20-MAY-2020		1136 d
EMB-RECOMM	REF: AMM 35-10-00									
35-10-07-720-001-A00	FUNCTIONALLY CHECK COCKPIT OXYGEN CYLINDER PRESSURE REGULATOR 4441009-050 513657201	MOS HRS/MSC AFL	60				05-JUN-2012	05-JUN-2017		56 d
SYSTEM	REF: AMM 35-10-07									
35-11-02-212-001-A00 (s)	VISUALLY CHECK PRESSURE TRANSDUCER INDICATION ON MFD COMPARED WITH EXTERNAL GAUGE INDICATION PKG 5004	MOS HRS/MSC AFL	24 1000	+15d/-15d +20/-20			21-JAN-2017 884.1 443			
LOW UTILIZATION	REF: AMM 35-11-02									
35-20-00-710-001-A00 (s)	OPERATIONALLY CHECK PASSENGER GASEOUS OXYGEN-SUBSYSTEM IN MANUAL MODE NOTE: IF INSTALLED PKG 5002	MOS HRS/MSC AFL	12 900 450	+15d/-15d +20/-20 +20/-20			21-JAN-2017 884.1 443			
LOW UTILIZATION	REF: AMM 35-20-00									
35-20-00-710-002-A00 (s)	OPERATIONALLY CHECK GASEOUS OXYGEN LOW PRESSURE INDICATING CIRCUIT.NOTE: IF INSTALLED. PKG 5004	MOS HRS/MSC AFL	24 1800 900	+15d/-15d +20/-20 +20/-20			21-JAN-2017 884.1 443			
LOW UTILIZATION	REF: AMM 35-11-04									
35-20-00-720-001-A00 (s)	FUNCTIONALLY CHECK PASSENGER GASEOUS OXYGEN SUBSYSTEM IN AUTOMATIC MODE(NOTE: IF INSTALLED). PKG 5008	MOS HRS/MSC AFL	48 3600 1800	+15d/-15d +20/-20 +20/-20			26-JAN-2015 532.4 280			
LOW UTILIZATION	REF: AMM 35-20-00									
35-20-02-211-001-A00 (s)	VISUALLY CHECK PASSENGER GASEOUS OXYGEN MASK ASSEMBLY (NOTE: IF INSTALLED). PKG 5008	MOS HRS/MSC AFL	48 3600 1800	+15d/-15d +20/-20 +20/-20			26-JAN-2015 532.4 280			
LOW UTILIZATION	REF: AMM 35-20-04									
35-20-04-720-001-A00	FUNCTIONALLY CHECK (HYDROSTATIC TEST) NO. 1 PASSENGER OXYGEN CYLINDER ASSEMBLY NOTE: IF INSTALLED 895-48015 C07050352	MOS HRS/MSC AFL	60				08-MAY-2012	08-MAY-2017 M		28 d
SYSTEM	REF: AMM 35-20-08									
35-20-06-900-001-A00	RESTORE (OVERHAUL) LH GASEOUS OXYGEN ELECTRIC PULSE/LATCHING ON-OFF VALVE NOTE: IF INSTALLED PN SN-UNKNOWN	MOS HRS/MSC AFL	60 2000	+30d/-30d	-23		08-JAN-2016 729 362	16-DEC-2020 2729	15-JAN-2021	1346 d (+30) 1825.7
SYSTEM	REF: AMM 35-20-10									
35-20-06-900-001-A00	RESTORE (OVERHAUL) RH GASEOUS OXYGEN ELECTRIC PULSE/LATCHING ON-OFF VALVE NOTE: IF INSTALLED PN SN-UNKNOWN	MOS HRS/MSC AFL	60 2000	+30d/-30d	-23		08-JAN-2016 729 362	16-DEC-2020 2729	15-JAN-2021	1346 d (+30) 1825.7
SYSTEM	REF: AMM 35-20-10									
35-20-07-900-001-A00	RESTORE (OVERHAUL) LH OXYGEN SEQUENCE REGULATOR NOTE: IF INSTALLED PN SN-UNKNOWN	MOS HRS/MSC AFL	60 2000	+30d/-30d	-23		08-JAN-2016 729 362	16-DEC-2020 2729	15-JAN-2021	1346 d (+30) 1825.7
SYSTEM	REF: AMM 35-20-11									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
35-20-07-900-001-A00	RESTORE (OVERHAUL) RH OXYGEN SEQUENCE REGULATOR NOTE: IF INSTALLED									
	PN	MOS	60	+30d/-30d			08-JAN-2016	16-DEC-2020	15-JAN-2021	1346 d (+30)
	SN-UNKNOWN	HRS/MSC	2000				729	2729		1825.7
SYSTEM	REF: AMM 35-20-11	AFL					362			
35-20-08-211-001-A00 (s)	VISUALLY CHECK PRESSURE TRANSDUCER INDICATOR ON MFD VERSUS GASEOUS OXYGEN CYLINDER GAUGE INDICATION (NOTE: IF INSTALLED).						PKG			
	PKG 5004	MOS	24	+15d/-15d			21-JAN-2017			
		HRS/MSC	1800	+20/-20			884.1			
LOW UTILIZATION	REF: AMM 35-20-08	AFL	900	+20/-20			443			
35-20-12-211-001-A00 (s)	VISUALLY CHECK PASSENGER GASEOUS OXYGEN PRESSURE INDICATOR GAUGE NOTE: IF INSTALLED						PKG			
	PKG 5004	MOS	24	+15d/-15d			21-JAN-2017			
		HRS/MSC	1800	+20/-20			884.1			
LOW UTILIZATION	REF: AMM 35-20-08	AFL	900	+20/-20			443			
35-20-15-790-001-A00 (s)	FUNCTIONALLY CHECK (LEAK) PASSENGER GASEOUS OXYGEN DISTRIBUTION (HP) LINES NOTE: IF INSTALLED						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 35-20-15	AFL	1800	+20/-20			280			
35-20-16-790-001-A00 (s)	FUNCTIONALLY CHECK (LEAK) PASSENGER GASEOUS OXYGEN DISTRIBUTION (LP) LINES NOTE: IF INSTALLED						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 35-20-16	AFL	1800	+20/-20			280			
35-30-01-211-001-A00	VISUALLY CHECK PORTABLE OXYGEN CYLINDER GAUGE PRESSURE INDICATION NOTE: OR IN ACCORDANCE WITH LOCAL REGULATORY AUTHORITY REQUIREMENTS									
		MOS	12	+15d/-15d			21-JAN-2017	26-NOV-2017	11-DEC-2017	230 d (+15)
		HRS/MSC	500				884.1	1384.1		480.8
SYSTEM	REF: AMM 35-30-01	AFL					443			
35-30-01-720-001-A00	FUNCTIONALLY CHECK PASSENGER CABIN PORTABLE OXYGEN BOTTLE PRESSURE REGULATOR NOTE: OR, AT OPERATOR DISCRETION, PERFORM THIS TASK AT EACH BOTTLE HYDROSTATIC TEST									
	5500-C1W-BF23A	MOS	60				30-APR-2013	30-APR-2018		385 d
	P13060686	HRS/MSC								
SYSTEM	REF: AMM 35-30-01	AFL								
35-30-01-720-002-A00	FUNCTIONALLY CHECK (HYDROSTATIC TEST) PASSENGER CABIN PORTABLE OXYGEN BOTTLE (NOTE: OR IN ACCORDANCE WITH LOCAL REGULATORY AUTHORITY REQUIREMENTS)									
	5500-C1W-BF23A	MOS	60				30-APR-2013	30-APR-2018		385 d
	P13060686	HRS/MSC								
SYSTEM	REF: AMM 35-30-01	AFL								
35-30-02-211-001-A00 (s)	VISUALLY CHECK CONTINUOUS-FLOW MASK ASSEMBLY						PKG			
	PKG 5004	MOS	24	+15d/-15d			21-JAN-2017			
		HRS/MSC	1000	+20/-20			884.1			
LOW UTILIZATION	REF: AMM 35-30-02	AFL					443			
351000-0101	PILOT MASK ASSY-STORAGE BOX									
	MXP138-1	MOS					16-DEC-2010			
	SE26166	HRS/MSC	O/C				0			
	REF: AMM 35-20-05	AFL					0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
351000-0102	COPILOT MASK ASSY-STORAGE BOX MXP138-1 SE41369 REF: AMM 35-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
351000-0201	PILOT OXYGEN ASSY-PRESSURE/DEMAND MASK MC10-16-105 141642 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
351000-0202	COPILOT OXYGEN ASSY-PRESSURE/DEMAND MASK MC10-16-105 141643 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
351000-0203	OBSERVER OXYGEN ASSY-PRESSURE/DEMAND MASK MC10-16-105 141644 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
351000-0301	OBSERVER LIDS ASSEMBLY MXP129 SE35147 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
351000-0401	DISCARD PROTECTIVE BREATHING EQUIPMENT 15-40F-11 27773028 REF: AMM 35-30-03 Manufacture Date: 01-APR-2010	MOS HRS/MSC AFL	120	TSN:0			01-APR-2010	01-APR-2020		1087 d
351007-0101	COCKPIT OXYGEN CYLINDER 4441009-050 513657201 REF: AMM 35-10-07 Manufacture Date: 01-JAN-2012	MOS HRS/MSC AFL	180				06-JUN-2015 633.6 321	01-JAN-2027		3553 d
351007-0101A	FUNCTIONALLY CHECK (HYDROSTATIC TEST) COCKPIT OXYGEN CYLINDER (35-10-07-720-002-A01) 4441009-050 513657201 REF: AMM 35-10-07	MOS HRS/MSC AFL	60				20-MAY-2015	20-MAY-2020		1136 d
351102-0101	PRESSURE ASSY-OXYGEN SYS TRANSDUCER 9233201 0509-015 REF: AMM 35-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
351102-0102	PRESSURE ASSY-OXYGEN SYS TRANSDUCER 9233201 0509-014 REF: AMM 35-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
352000-0101	CREW CAB MODULE -PASS OXYGEN CONTROL ASSEMBLY 135-06949-409 0000639152 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
352000-0201	CONTACTING ELEC SYS,OXYGEN BOX,CHEMICAL GENERATION ALTIMETER 214C40-1-83 K011682A REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
352006-0101	LH GASEOUS OXYGEN ELECTRIC PULSE/LATCHING ON-OFF VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
352006-0102	RH GASEOUS OXYGEN ELECTRIC PULSE/LATCHING ON-OFF VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
352007-0101	LH OXYGEN SEQUENCE REGULATOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
352007-0102	RH OXYGEN SEQUENCE REGULATOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
352008-7101	NO. 1 PASSENGER OXYGEN CYLINDER ASSEMBLY 895-48015 C07050352 REF: See Workcard Manufacture Date: 08-FEB-2007	MOS HRS/MSC AFL	180	TSO:0 TSO:0 TSO:0			22-OCT-2015 702.3 346	08-FEB-2022		1765 d
353001-0101	PASSENGER CABIN PORTABLE OXYGEN BOTTLE 5500-C1W-BF23A P13060686 REF: AMM 35-30-01	MOS HRS/MSC AFL	O/C				27-APR-2015 582.2 297			
353003-0101	NO.1 EMERGENCY PROTECTIVE BREATHING EQUIPMENT PBE 15-40F-11 27773032 REF: AMM 35-30-03 Manufacture Date: 01-APR-2010	MOS HRS/MSC AFL	120	TSN:0			01-APR-2010	01-APR-2020		1087 d
CHAPTER 36	PNEUMATIC									
36-10-01-130-001-A00 (s)	RESTORE (CLEANING) CROSS-BLEED VALVE FILTER BY ULTRASONIC METHOD PKG 5016 REF: AMM 36-10-01	MOS HRS/MSC AFL	96 4000 2000	+15d/-15d +20/-20 +20/-20			PKG 26-JAN-2015 532.4 280			
36-11-01-220-001-A00 (s)	INSPECT (DETAILED INSPECTION) ENGINE LOW PRESSURE BLEED AIR CHECK VALVES P/N 816603-3 NOTE: IF INSTALLED PKG 5008 REF: AMM 36-11-01	MOS HRS/MSC AFL	48 3600 1800	+15d/-15d +20/-20 +20/-20			PKG 26-JAN-2015 532.4 280			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
36-11-02-130-001-A00 (s)	RESTORE (CLEANING) HIGH-STAGE VALVE FILTER BY ULTRASONIC METHOD						PKG			
	PKG 5016	MOS	96	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 36-11-02	HRS/MSC	4000	+20/-20			532.4			
		AFL	2000	+20/-20			280			
36-11-03-130-001-A00 (s)	RESTORE (CLEANING) FAN-AIR VALVE FILTER BY ULTRASONIC METHOD						PKG			
	PKG 5016	MOS	96	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 36-11-03	HRS/MSC	4000	+20/-20			532.4			
		AFL	2000	+20/-20			280			
36-11-04-110-001-A00 (s)	RESTORE (CLEANING) PRE-COOLER BY CHEMICAL METHOD.						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 36-11-04	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
36-11-05-130-001-A00 (s)	RESTORE (CLEANING) ENGINE BLEED VALVE FILTER BY ULTRASONIC METHOD						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 36-11-05	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
36-11-11-710-001-A00 (s)	OPERATIONALLY CHECK THERMOSTAT SHUTOFF VALVE						PKG			
	PKG 5004	MOS	24	+15d/-15d			21-JAN-2017			
LOW UTILIZATION	REF: AMM 36-11-08	HRS/MSC	1000	+20/-20			884.1			
		AFL					443			
36-20-00-710-001-A00 (s)	OPERATIONALLY CHECK BLEED VALVE INDICATION FUNCTION						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: AMM 36-20-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
36-20-00-720-001-A00 (s)	FUNCTIONALLY CHECK OVERTEMPERATURE WARNING CIRCUIT						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: AMM 36-20-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
36-20-02-710-003-A00 (s)	OPERATIONALLY CHECK THERMAL SWITCH						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 36-20-02	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
36-20-05-710-002-A00 (s)	OPERATIONALLY CHECK BLEED AUTOMATIC SHUTOFF AND CIRCUITRY.						PKG			
	PKG 5002	MOS	12	+15d/-15d			21-JAN-2017			
LOW UTILIZATION	REF: AMM 36-20-02	HRS/MSC	500	+20/-20			884.1			
		AFL					443			
361001-0101	APU CROSS-BLEED VALVE									
	816606-1	MOS				TSN:0	16-DEC-2010			
	2010090156	HRS/MSC	O/C			TSN:0	0			
	REF: AMM 36-10-01	AFL				TSN:0	0			
361002-0101	RH REAR GROUND CHECK "J" SST VALVE									
	816605-2	MOS				TSN:0	16-DEC-2010			
	1719	HRS/MSC	O/C			TSN:0	0			
	REF: AMM 36-10-02	AFL				TSN:0	0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
361101-0104	APU CHECK-BLEED SYS,REAR FUSLG I/II VALVE 816603-3 6657 REF: AMM 36-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
361101-0201	LH ENG CHECK-BLEED SYS,REAR FUSLG I/II VALVE 816603-3 6673 REF: AMM 36-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
361101-0202	LH ENG CHECK-BLEED SYS,REAR FUSLG I/II VALVE 816603-3 6672 REF: AMM 36-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
361101-0203	RH ENG CHECK-BLEED SYS,REAR FUSLG I/II VALVE 816603-3 6670 REF: AMM 36-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
361101-0204	RH ENG CHECK-BLEED SYS,REAR FUSLG I/II VALVE 816603-3 6658 REF: AMM 36-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
361102-0101	LH PIL HIGH STAGE VALVE 816601-1 2010110286 REF: AMM 36-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
361102-0102	RH PIL HIGH STAGE VALVE 816601-1 2010110288 REF: AMM 36-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
361102-0201	LH ENG HIGH STAGE VALVE 816601-1 2010100091 REF: AMM 36-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
361102-0202	RH ENG HIGH STAGE VALVE 816601-1 2010100085 REF: AMM 36-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
361103-0101	LEFT REGULATION-TYPE BUTTERFLY,AIR,TURBOFAN ENGINE VALVE 816610-2 2010061469 REF: AMM 36-11-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
361103-0102	RIGHT REGULATION-TYPE BUTTERFLY,AIR,TURBOFAN ENGINE VALVE 816610-2 2010061472 REF: AMM 36-11-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
361106-0101	LEFT THERMOSTAT-FAN AIR ,ENGINE CONTROLLER 816624-10 2010050572 REF: AMM 36-11-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
361106-0102	RIGHT THERMOSTAT-FAN AIR ,ENGINE CONTROLLER 816624-10 2010050574 REF: AMM 36-11-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
361106-0103	LEFT THERMOSTAT-FAN AIR ,ENGINE CONTROLLER 816624-9 2010050579 REF: AMM 36-11-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
361106-0104	RIGHT THERMOSTAT-FAN AIR ,ENGINE CONTROLLER 816624-9 2010050605 REF: AMM 36-11-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
361107-0101	LH ENG PRESSURE HIGH STAGE,AIR BLEED SYS,ENGINE SWITCH 782100-8 3102 REF: AMM 36-11-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
361107-0102	RH ENG PRESSURE HIGH STAGE,AIR BLEED SYS,ENGINE SWITCH 782100-8 3100 REF: AMM 36-11-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
361201-0101	APU BLEED AIR VALVE PN SN-UNKNOWN REF: AMM 36-12-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
361300-0101	LH AIR BLEED SYS, ENGINE PYLON PRE-COOLER 145-30609-401 3462 REF: AMM 36-11-04	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			26-JAN-2015 532.4 280			
361300-0102	RH AIR BLEED SYS, ENGINE PYLON PRE-COOLER 145-30609-401 3806 REF: AMM 36-11-04	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			26-JAN-2015 532.4 280			
361700-0201	BLEED LH SOLENOID-THREE WAY/TWO POSITIONS,BLEED SYS VALVE 5303-21 1624 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
361700-0202	BLEED RH SOLENOID-THREE WAY/TWO POSITIONS,BLEED SYS VALVE 5303-21 1622 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
361700-0203	X BLEED SOLENOID-THREE WAY/TWO POSITIONS,BLEED SYS VALVE 5303-21 1621 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
361700-0204	X BLEED SOLENOID-THREE WAY/TWO POSITIONS,BLEED SYS,REAR FUSELAGE VALVE 5303-21 1625 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
362000-0101	OVERHEAD PANEL PNEUMATIC CONTROL MODULE 145-31625-425 0000636398 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
362001-0101	LH PYLON INDICATOR,BRAKE TEMPERATURE SENSOR 0132ADT H5591 REF: AMM 36-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
362001-0102	RH PYLON INDICATOR,BRAKE TEMPERATURE SENSOR 0132ADT H5580 REF: AMM 36-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
362001-0201	LH PACK INDICATOR,BRAKE TEMPERATURE SENSOR 0132ADT H5583 REF: AMM 36-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
362001-0202	RH PACK INDICATOR,BRAKE TEMPERATURE SENSOR 0132ADT H5589 REF: AMM 36-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
CHAPTER 38 WATER/WASTE										
38-10-00-610-001-A00	RESTORE (CLEANING) STERILIZE POTABLE WATER SYSTEM. (NOTE: OR IN ACCORDANCE WITH LOCAL REGULATORY AUTHORITY REQUIREMENTS)	MOS HRS/MSC AFL	6 500	+15d/-15d		-40	21-JAN-2017 884.1 443	12-JUN-2017 1384.1	27-JUN-2017	63 d (+15) 480.8
SYSTEM	REF: See Workcard									
38-10-00-710-001-A00	OPERATIONALLY CHECK POTABLE WATER HEATER SYSTEM. NOTE: APPLICABLE TO AIRCRAFT EQUIPPED WITH ONE (01) POTABLE WATER SERVICE PANEL.(L600 ONLY)	MOS HRS/MSC AFL	N/A				16-DEC-2010 0 0			
SYSTEM	REF: AMM 38-33-00									
38-10-03-960-001-A00 (s)	DISCARD WATER FILTER CARTRIDGE (IF INSTALLED) PKG 5004	MOS HRS/MSC AFL	24 1000	+15d/-15d +20/-20			PKG 21-JAN-2017 884.1 443			
LOW UTILIZATION	REF: AMM 38-10-12									



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
38-10-05-720-001-A00	FUNCTIONALLY CHECK OF MECHANICAL RELIEF VALVE GOODRICH PN 4E3263-1. NOTE: IF INSTALLED. (L600 ONLY)	MOS					16-DEC-2010			
	REF:	HRS/MSC	N/A				0			
		AFL					0			
38-10-05-720-001-A01 (s)	FUNCTIONALLY CHECK OF MECHANICAL RELIEF VALVE HYDRAFLOW PN VA046-SERIES. NOTE: IF INSTALLED.	MOS	48				16-DEC-2010			
	PKG 5008	HRS/MSC	3600				0			
LOW UTILIZATION	REF:	AFL	1800				0			
38-32-04-960-001-A00 (s)	DISCARD WASTE DRAIN VALVE O-RING	MOS	12	+15d/-15d			21-JAN-2017			
	PKG 5002	HRS/MSC	500	+20/-20			884.1			
LOW UTILIZATION	REF: AMM 38-32-04	AFL					443			
38-32-10-960-001-A00 (s)	DISCARD WASTE DRAIN VALVE CAP SEAL	MOS	48	+15d/-15d			26-JAN-2015			
	PKG 5008	HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 38-32-04	AFL	1800	+20/-20			280			
38-33-00-710-001-A00 (s)	OPERATIONALLY CHECK THE WASTE WATER HEATER SYSTEM	MOS	48	+15d/-15d			26-JAN-2015			
	PKG 5008	HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 38-33-00	AFL	1800	+20/-20			280			
383204-0101	LAVATORY WATER DRAIN VALVE	MOS					16-DEC-2010			
	0218-0032-1	HRS/MSC	O/C		TSN:0		0			
	144358	AFL			TSN:0		0			
	REF:				TSN:0		0			
CHAPTER 45	CENTRAL MAINT SYSTEM									
454501-0101	CREW CAB CENTRAL MAINTENANCE - CMC COMPUTER	MOS					16-DEC-2010			
	251-116-013-014	HRS/MSC	O/C		TSN:0		0			
	AE90943	AFL			TSN:0		0			
	REF: AMM 45-45-01				TSN:0		0			
CHAPTER 49	AIRBORNE AUXILIARY POWER									
49-17-00-160-001-A00 (s)	RESTORE (CLEANING) APU DRAINS POST MOD SB 145LEG-49-0006 OR WITH AN EQUIVALENT MODIFICATION FACTORY INCORPORATED	MOS	48	+15d/-15d			26-JAN-2015			
	PKG 5008	HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 49-19-02	AFL	1800	+20/-20			280			
49-62-00-710-001-A00 (s)	OPERATIONALLY CHECK APU EMERGENCY SHUTDOWN BY USING APU FUEL SHUTOFF SWITCH AND FIRE TEST SWITCH.	MOS	72	+15d/-15d			21-JAN-2017			
	PKG 5012	HRS/MSC	3000	+20/-20			884.1			
LOW UTILIZATION	REF: AMM 49-62-00	AFL	1500	+20/-20			443			
490000-0101	OVERH P APU CONTROL MODULE	MOS					16-DEC-2010			
	145-21330-415	HRS/MSC	O/C		TSN:0		0			
	0000637143	AFL			TSN:0		0			
	REF: AMM 26-12-02				TSN:0		0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
491000-0101	APU - AUXILIARY POWER UNIT COWLING 145-54858-419 0000632325 REF: AMM 49-15-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
492000-0101	APU - AUXILIARY POWER, T62/T40C14,MOD A UNIT 4504113A SP-E1028096 REF: AMM 49-14-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
496000-0101	APU - AUXILIARY POWER, FADEC CONTROL UNIT 4504205F 1199 REF: AMM 49-64-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
49APU1 49.APU1	APU 4504113A SP-E1028096 REF: AMM 49-14-01	MOS HRS/MSC AFL	E/C							
APU Model : APS500R/T-62T-40C14 Serial # SP-E1028096 Part # 4504113A										
49-31-00-710-001-A01	APU - OPERATIONALLY CHECK THE APU FADEC BITE DISDPLAY FOR FAULT MESSAGES FOR APU MODEL T-62T-40C14 (APS500R). (NOTE : IF INSTALLED).	MOS HRS/MSC APUS	400				21-JAN-2017 1278 1275	1678		378
SYSTEM	REF: AMM 49-64-03									
49-31-04-960-001-A01	APU - DISCARD APS 500R INLET FUEL FILTER FOR APU MODEL T-62T-40C14 (APS500R) ONLY. (NOTE: IF INSTALLED).	MOS HRS/MSC APUS	1200				16-JUN-2016 1131 1112	2331		1031
SYSTEM	REF: AMM 49-32-15									
49-41-03-220-001-A00	APU - INSPECT (DETAILED INSPECTION) IGNITER PLUG	MOS HRS/MSC APUS	1200				16-JUN-2016 1131 1112	2331		1031
SYSTEM	REF: AMM 49-44-03									
49-91-00-610-001-A00	APU - SERVICE (REPLENISH) CHECK OIL LEVEL AND SERVICE OIL SYSTEM AS REQUIRED	MOS HRS/MSC APUS	400				21-JAN-2017 1278 1275	1678		378
SYSTEM	REF: AMM 49-96-00									
49-91-00-680-001-A00	APU - SERVICE (DRAIN) AND REPLACE APU OIL SUPPLY	MOS HRS/MSC APUS	12 2000		-13		21-JAN-2017 1278 1275	08-JAN-2018 3278		273 d 1978
SYSTEM	REF: AMM 49-96-00									
49-91-01-960-001-A00	APU - DISCARD APU OIL FILTER ELEMENT	MOS HRS/MSC APUS	24 2000				21-JAN-2017 1278 1275	21-JAN-2019 3278		651 d 1978
SYSTEM	REF: AMM 49-96-01									

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
491010	APU - ELECTRICAL HARNESS 4504230B 1052 REF:	MOS HRS/MSC APUS	O/C	TSN:1.2 TSN:4			16-OCT-2010 0 0			
491015	APU - COMBUSTOR ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			16-OCT-2010 0 0			
491020	APU - COMBUSTOR LINER PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			16-OCT-2010 0 0			
491025	APU - COMBUSTOR HOUSING PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			16-OCT-2010 0 0			
491030	APU - OUTPUT SHAFT PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			16-OCT-2010 0 0			
491040	APU - (1 OF 3) STAR GEAR PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			16-OCT-2010 0 0			
491041	APU - (2 OF 3) STAR GEAR PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			16-OCT-2010 0 0			
491042	APU - (3 OF 3) STAR GEAR PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			16-OCT-2010 0 0			
491050	APU - FUEL MANIFOLD ASSEMBLY 4951509 05828347-01 REF:	MOS HRS/MSC APUS	O/C	TSN:1.2 TSN:4			16-OCT-2010 0 0			
491055	APU - SECONDARY FUEL MANIFOLD 4951510 05841711-01 REF:	MOS HRS/MSC APUS	O/C	TSN:1.2 TSN:4			16-OCT-2010 0 0			
491060	APU - MAIN FUEL SOLENOID 4952315-2 2139 REF:	MOS HRS/MSC APUS	O/C	TSN:1.2 TSN:4			16-OCT-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
491101-0101	APU - TURBINE WHEEL ASSEMBLY 4504847 HH373 REF:	MOS HRS/MSC APUS		TSN:0 TSN:0 TSN:0			16-OCT-2010 0 0		15000	13710
LIFE LIMIT			15000							
491120-0101	APU - IMPELLER ASSEMBLY 4504253 SIF761 REF:	MOS HRS/MSC APUS	O/C	TSN:1.2 TSN:4			16-OCT-2010 0 0			
492010	APU - QUILL SHAFT PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			16-OCT-2010 0 0			
492015	APU - THRUST BEARING 4502042 3900 REF:	MOS HRS/MSC APUS	O/C	TSN:1.2 TSN:4			16-OCT-2010 0 0			
492020	APU - TURBINE ASSEMBLY 4504115B 1423 REF:	MOS HRS/MSC APUS	O/C	TSN:1.2 TSN:4			16-OCT-2010 0 0			
492025	APU - GEARBOX ASSEMBLY 4504235E SP-G100713 REF:	MOS HRS/MSC APUS	O/C	TSN:1.2 TSN:4			16-OCT-2010 0 0			
492026	APU - GEARBOX HOUSING PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			16-OCT-2010 0 0			
492030	APU - IMPELLER ASSEMBLY 4504253 SIF761 REF:	MOS HRS/MSC APUS	O/C	TSN:1.2 TSN:4			16-OCT-2010 0 0			
492035	APU - ROTOR ASSEMBLY 4504257A SIF761 REF:	MOS HRS/MSC APUS	O/C	TSN:1.2 TSN:4			16-OCT-2010 0 0			
492040	APU - INTERMEDIATE GEAR 4504313 V4350209-W0410 REF:	MOS HRS/MSC APUS	O/C	TSN:1.2 TSN:4			16-OCT-2010 0 0			
492045	APU - RING GEAR 4504328 V10C1244 REF:	MOS HRS/MSC APUS	O/C	TSN:1.2 TSN:4			16-OCT-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
492050	APU - CONTAINMENT RING PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			16-OCT-2010 0 0			
492055	APU - TURBINE WHEEL PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			16-OCT-2010 0 0			
492060	APU - TURBINE NOZZLE PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			16-OCT-2010 0 0			
492065	APU - DIFFUSER 4507965 ALP-0128 REF:	MOS HRS/MSC APUS	O/C	TSN:1.2 TSN:4			16-OCT-2010 0 0			
492070	APU - ANTI-SURGE VALVE 4950899 2250 REF:	MOS HRS/MSC APUS	O/C	TSN:1.2 TSN:4			16-OCT-2010 0 0			
492075	APU - ROLLER BEARING 4951505 3331-2233 REF:	MOS HRS/MSC APUS	O/C	TSN:1.2 TSN:4			16-OCT-2010 0 0			
492080	APU - CARBON SEAL 4951586 15929 REF:	MOS HRS/MSC APUS	O/C	TSN:1.2 TSN:4			16-OCT-2010 0 0			
492081	APU - SEAL MATING RING 4951587 13022 REF:	MOS HRS/MSC APUS	O/C	TSN:1.2 TSN:4			16-OCT-2010 0 0			
493010	APU - FUEL PUMP 4503140D 3778 REF:	MOS HRS/MSC APUS	O/C	TSN:1.2 TSN:3			22-NOV-2010 0 0			
493015	APU - FUEL CONTROL ASSEMBLY 4504676A 06-10-07 REF:	MOS HRS/MSC APUS	O/C	TSN:1.2 TSN:3			22-NOV-2010			
493025	APU - FLOW DIVIDER 4951485 1321 REF:	MOS HRS/MSC APUS	O/C	TSN:1.2 TSN:4			16-OCT-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
493030	APU - FUEL CONTROL SERVO VALVE 4951558 1476 REF:	MOS HRS/MSC APUS	O/C	TSN:1.2 TSN:3			22-NOV-2010 0 0			
493035	APU - LOW OIL PRESSURE SWITCH 4952356 1521 REF:	MOS HRS/MSC APUS	O/C	TSN:1.2 TSN:4			16-OCT-2010 0 0			
494010	APU - EXCITER 4950745 J10350218 REF:	MOS HRS/MSC APUS	O/C	TSN:1.2 TSN:4			16-OCT-2010 0 0			
495010	APU - AIR HOUSING INLET 4504117B 1423 REF:	MOS HRS/MSC APUS	O/C	TSN:1.2 TSN:4			16-OCT-2010 0 0			
495015	APU - AIR INLET DUCT PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	TSN:0 TSN:0 TSN:0			16-OCT-2010 0 0			
495020	APU - BLEED AIR VALVE 4952829 3492 REF:	MOS HRS/MSC APUS	O/C	TSN:1.2 TSN:4			16-OCT-2010 0 0			
496010	APU - GEAR ASSEMBLY 4502716A V4350810-W685 REF:	MOS HRS/MSC APUS	O/C	TSN:1.2 TSN:4			16-OCT-2010 0 0			
496015	APU - DATA MEMORY MODULE 4505576A 2518 REF:	MOS HRS/MSC APUS	O/C	TSN:1.2 TSN:4			16-OCT-2010 0 0			
497010	APU - SPEED SENSOR 4504185C 129974 REF:	MOS HRS/MSC APUS	O/C	TSN:1.2 TSN:4			16-OCT-2010 0 0			
497020	APU - TEMP/PRESS SENSOR 4504196A V00-S147488 REF:	MOS HRS/MSC APUS	O/C	TSN:1.2 TSN:4			16-OCT-2010 0 0			
499010	APU - OIL PUMP GEAR 4504241 V4351209-W325 REF:	MOS HRS/MSC APUS	O/C	TSN:1.2 TSN:4			16-OCT-2010 0 0			

CHAPTER 49-00 AIRBORNE AUXILIARY POWER

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
01	READ OUT - PERFORM READ-OUT OF APU HOURS PERFORM PN SN-UNKNOWN REF:	MOS HRS/MSC AFL								
CHAPTER 52 DOORS										
52-00-00-211-001-A00 (s)	VISUALLY CHECK LOCKING RED MARKS NOTE: REPAINT IF NECESSARY						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 52-00-00	AFL	1800	+20/-20			280			
52-10-00-220-801-L00 (s)	DETAILED INSPECTION (INTERNAL) OF MAIN DOOR COMPONENTS: - MAIN DOOR STOP & BACK UP STRUCTURES (SSI 52-10-03) - MAIN DOOR FOLDING FLAP STOPS (SSI 52-10-04) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR SSI 52-10-04						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: NDT 52-10-00	AFL	1800	+20/-20			280			
52-10-00-220-802-L00 (s)	DETAILED INSPECTION (INTERNAL) OF MAIN DOOR COMPONENTS: - MAIN DOOR FOLDING FLAP STRUCTURE (SSI 52-10-02) - MAIN DOOR-TO-FUSELAGE ATTACHMENT FITTINGS & INTERFACE PARTS (SSI 52-10-05)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 52-10-00	AFL	3600	+20/-20			0			
52-10-00-220-803-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF MAIN DOOR COMPONENTS: - MAIN DOOR-TO-FUSELAGE ATTACHMENT FITTINGS & INTER- FACE PARTS (SSI 52-10-05) - MAIN DOOR FOLDING FLAP STRUC- TURE (SSI 52-10-02)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 52-10-00	AFL	3600	+20/-20			0			
52-10-00-220-804-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF MAIN DOOR COMPONENTS: - STOP & BACK UP STRUCTURES (SSI 52-10-03)						PKG			
	PKG 5016	MOS	96	+15d/-15d			26-JAN-2015			
		HRS/MSC	4000	+20/-20			532.4			
LOW UTILIZATION	REF: NDT 52-10-00	AFL	2000	+20/-20			280			
52-10-00-220-807-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF MAIN DOOR COMPONENTS: - STRUCTURE (SSI 52-10-01) (L650 ONLY)						PKG			
	PKG 5016	MOS	96	+15d/-15d						
		HRS/MSC	7200	+20/-20						
LOW UTILIZATION	REF: NDT 52-10-00	AFL	3600	+20/-20						
52-10-00-220-808-L00 (s)	DETAILED INSPECTION (INTERNAL) OF MAIN DOOR COMPONENTS: - STRUCTURE (SSI 52-10-01) (L650 ONLY)						PKG			
	PKG 5016	MOS	96	+15d/-15d						
		HRS/MSC	7200	+20/-20						
LOW UTILIZATION	REF: NDT 52-10-00	AFL	3600	+20/-20						

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
52-10-00-220-C01-L00	DETAILED INSPECTION (EXTERNAL) OF MAIN DOOR COMPONENTS: - STRUCTURE (SSI 52-10-01) (L600 ONLY)	MOS					16-DEC-2010			
STRUCTURAL	REF: CPM 52-10-00	HRS/MSC AFL	N/A				0 0			
52-10-00-220-C02-L00	DETAILED INSPECTION (INTERNAL) OF MAIN DOOR COMPONENTS: - STRUCTURE (SSI 52-10-01) (L600 ONLY)	MOS					16-DEC-2010			
STRUCTURAL	REF: CPM 52-10-00	HRS/MSC AFL	N/A				0 0			
52-11-00-640-001-A00 (s)	LUBRICATE STANDARD MAIN DOOR ACTUATING AND LOCKING MECHANISM	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	PKG 5008 REF: AMM 52-11-00	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
52-11-00-720-005-A00 (s)	FUNCTIONALLY CHECK STANDARD MAIN DOOR ACTUATING, LATCHING AND LOCKING MECHANISM	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	PKG 5008 REF: AMM 52-11-00	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
52-12-00-710-001-A00 (s)	OPERATIONALLY CHECK ALTERNATE OPENING SYSTEM	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	PKG 5008 REF: AMM 52-12-00	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
52-12-00-720-001-A00 (s)	FUNCTIONALLY CHECK MAIN DOOR HYDRAULIC ACCUMULATOR NITROGEN CHARGE	MOS	24	+15d/-15d			21-JAN-2017			
LOW UTILIZATION	PKG 5004 REF: AMM 52-12-00	HRS/MSC AFL	1000	+20/-20			884.1 443			
52-14-00-220-001-A00 (s)	INSPECT (DETAILED INSPECTION) MAIN DOOR DRAINING SYSTEM FOR OBSTRUCTION OR DAMAGE	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	PKG 5008 REF: AMM 52-14-01	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
52-21-00-220-801-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF PASSENGER CABIN ESCAPE HATCH COMPONENTS: - ESCAPE HATCH STRUCTURE (SSI 52-21-06) - ESCAPE HATCH WINDOW FRAME (SSI 52-21-07)	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	PKG 5016 REF: NDT 52-21-00	HRS/MSC AFL	7200 3600	+20/-20 +20/-20			0 0			
52-21-00-220-802-L00 (s)	DETAILED INSPECTION (INTERNAL) OF PASSENGER CABIN ESCAPE HATCH COMPONENTS: - ESCAPE HATCH STRUCTURE (SSI 52-21-06) - ESCAPE HATCH WINDOW FRAME (SSI 52-21-07)	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	PKG 5016 REF: NDT 52-21-00	HRS/MSC AFL	7200 3600	+20/-20 +20/-20			0 0			
52-21-00-640-001-A00 (s)	LUBRICATE PASSENGER CABIN ESCAPE HATCH SUPPORT PINS	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	PKG 5008 REF: AMM 52-21-00	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
52-21-00-710-001-A00 (s)	OPERATIONALLY CHECK PASSENGER CABIN ESCAPE HATCH MECHANISM						PKG			
	PKG 5,5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 52-21-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
52-22-00-710-001-A00 (s)	OPERATIONALLY CHECK COCKPIT EMERGENCY EXIT						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 56-11-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
52-22-01-640-001-A00 (s)	LUBRICATE COCKPIT EMERGENCY EXIT LOCKING MECHANISM						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 56-11-01	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
52-30-00-210-801-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF BAGGAGE DOOR COMPONENTS: - BAGGAGE DOOR STRUCTURE (SSI 52-30-08)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 52-30-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
52-30-00-210-802-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF BAGGAGE DOOR COMPONENTS: - BAGGAGE DOOR STRUCTURE (SSI 52-30-08) (L650 ONLY)						PKG			
	PKG 5016	MOS	96	+15d/-15d						
LOW UTILIZATION	REF: NDT 52-30-00	HRS/MSC	7200	+20/-20						
		AFL	3600	+20/-20						
52-30-00-210-C01-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF BAGGAGE DOOR COMPONENTS: - BAGGAGE DOOR STRUCTURE (SSI 52-30-08) (L600 ONLY)									
		MOS					16-DEC-2010			
STRUCTURAL	REF: CPM 52-30-00	HRS/MSC	N/A				0			
		AFL					0			
52-30-00-220-801-L00	DETAILED INSPECTION (INTERNAL) OF BAGGAGE DOOR COMPONENTS: - BAGGAGE DOOR STOPS AND FITTINGS (SSI 52-30-09) NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. SB 145LEG-00-0007 (L600 ONLY)									
		MOS					16-DEC-2010			
STRUCTURAL	REF: NDT 52-30-00	HRS/MSC	N/A				0			
		AFL					0			
52-30-00-220-801-L01 (s)	DETAILED INSPECTION (INTERNAL) OF BAGGAGE DOOR COMPONENTS: - BAGGAGE DOOR STOPS AND FITTINGS (SSI 52-30-09) NOTE: APPLICABLE TO AIRCRAFT POST-MOD. SB 145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY INCORPORATED						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: NDT 52-30-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
52-31-00-640-001-A00 (s)	LUBRICATE BAGGAGE DOOR GEAR BOX						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 52-31-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
52-32-00-220-001-A00 (s)	INSPECT (DETAILED INSPECTION) BAGGAGE DOOR LIFTING AND LOWERING MECHANISM FOR GENERAL CONDITION AND TORSION BAR FOR TORSION						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 52-32-00	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
52-42-01-220-001-A00 (s)	INSPECT (DETAILED INSPECTION) COCKPIT UNDERFLOOR ACCESS HATCH MECHANISM						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 52-42-01	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
52-44-00-220-801-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF REAR ELECTRONIC COMPARTMENT DOOR COMPONENTS: - REAR ELECTRONIC COMPARTMENT DOOR STRUCTURE (SSI 52-44-01)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: NDT 52-44-00	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
52-44-00-220-802-L00 (s)	DETAILED INSPECTION (INTERNAL) OF REAR ELECTRONIC COMPARTMENT DOOR COMPONENTS: - REAR ELECTRONIC COMPARTMENT DOOR STRUCTURE (SSI 52-44-01)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: NDT 52-44-00	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
52-44-01-220-001-A00 (s)	INSPECT (DETAILED INSPECTION) REAR ELECTRONIC COMPARTMENT DOOR MECHANISM						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 52-44-01	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
52-71-00-710-001-A00 (s)	OPERATIONALLY CHECK FORWARD ELECTRONIC COMPARTMENT DOOR WARNING MESSAGE						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 52-71-00	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
52-72-00-710-001-A00 (s)	OPERATIONALLY CHECK RIGGING DOOR WARNING MESSAGE						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 52-72-00	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
52-73-00-710-001-A00 (s)	OPERATIONALLY CHECK MAIN DOOR WARNING MESSAGE						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 52-73-00	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
52-73-01-720-001-A00 (s)	FUNCTIONALLY CHECK MAIN DOOR WARNING MICROSWITCHES						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 52-73-01	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
52-75-00-710-001-A00 (s)	OPERATIONALLY CHECK EMERGENCY EXIT WARNING MESSAGE						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 52-75-00	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
52-76-00-710-001-A00 (s)	OPERATIONALLY CHECK BAGGAGE DOOR WARNING MESSAGE PKG 5008	MOS	48	+15d/-15d			PKG 26-JAN-2015 532.4 280			
LOW UTILIZATION	REF: AMM 52-76-00	HRS/MSC AFL	3600 1800	+20/-20 +20/-20						
52-77-00-710-001-A00 (s)	OPERATIONALLY CHECK REAR ELECTRONIC COMPARTMENT DOOR WARNING MESSAGE PKG 5008	MOS	48	+15d/-15d			PKG 26-JAN-2015 532.4 280			
LOW UTILIZATION	REF: AMM 52-77-00	HRS/MSC AFL	3600 1800	+20/-20 +20/-20						
52-Z811-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONE 811) PKG 5008	MOS	48	+15d/-15d			PKG 26-JAN-2015 532.4 280			
LOW UTILIZATION	REF: AMM 05-30-03	HRS/MSC AFL	3600 1800	+20/-20 +20/-20						
52-Z811-214-001-A00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONE 811) PKG 5004	MOS	24	+15d/-15d			PKG 21-JAN-2017 884.1 443			
LOW UTILIZATION	REF: AMM 05-30-04	HRS/MSC AFL	1000	+20/-20						
52-Z812-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONE 812 AND 822) PKG 5016	MOS	96	+15d/-15d			PKG 16-DEC-2010 0 0			
LOW UTILIZATION	REF: AMM 05-30-05	HRS/MSC AFL	7200 3600	+20/-20 +20/-20						
52-Z812-214-001-A00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONE 812 AND 822) PKG 5016	MOS	96	+15d/-15d			PKG 16-DEC-2010 0 0			
LOW UTILIZATION	REF: AMM 05-30-06	HRS/MSC AFL	7200 3600	+20/-20 +20/-20						
52-Z813-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONE 813) PKG 5008	MOS	48	+15d/-15d			PKG 26-JAN-2015 532.4 280			
LOW UTILIZATION	REF: AMM 05-30-07	HRS/MSC AFL	3600 1800	+20/-20 +20/-20						
52-Z813-214-001-A00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONE 813) PKG 5004	MOS	24	+15d/-15d			PKG 21-JAN-2017 884.1 443			
LOW UTILIZATION	REF: AMM 05-30-08	HRS/MSC AFL	1000	+20/-20						
521000-0101	PAX CABIN DOOR 135-12294-423 0000627054 REF:	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		16-DEC-2010 0 0			
521001-0101	FORWARD PANEL, DOOR RELEASE CONTROL MODULE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
521100-0101	PAX DOOR DAMPER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
521100-0201	BOX LOCK ASSEMBLY 145-39936-409 0000544258 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
521100-0202	BOX LOCK ASSEMBLY 145-39936-411 0000550462 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
521200-0101	MID ACCUMULATOR -HYDRAULIC SYS, ELECTRONIC COMPT ASSEMBLY 2704-0001-003 00621 REF: AMM 52-12-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
521200-0201	MID PRESSURE RELIEF VALVE ASSEMBLY 2214-0100-401 00733 REF: AMM 52-12-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
521200-0301	MAIN DOOR HYDRAULIC PRESSURE SWITCH 6607A9-88 K008334 REF: AMM 52-12-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
521200-0401	LEFT CHECK-TYPE RETAINER, HYDRAULIC SYSTEM VALVE 2662T-4EE 09-0303241 REF: AMM 52-12-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
521200-0501	MAIN DOOR - LIFTING AND LOWERING SYSTEM, ACCUMULATOR ISOLATION VALVE 5835-5 1248 REF: AMM 52-12-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			22-AUG-2012 79 63			
521200-0701	LEFT HYDRAULIC ASSY-DRIVING,PAX DOOR ACTUATOR 2106-0500-001 01280 REF: AMM 52-12-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
521200-0702	RIGHT HYDRAULIC ASSY-DRIVING,PAX DOOR ACTUATOR 2106-0500-001 01281 REF: AMM 52-12-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
522100-0101	RIGHT EMERGENCY DOOR ASSEMBLY 145-25737-421 0000625799 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
523000-0101	LH REAR CARGO COMPT, DOOR ASSEMBLY 135-04976-423 SA2134 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
524100-0101	BATTERY COMPARTMENT,FWD FUSELAGE, DOOR ASSEMBLY PN SN-UNKNOWN REF: AMM 52-41-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
524100-0102	HYDRAULIC COMPARTMENT,FWD FUSELAGE, DOOR ASSEMBLY PN SN-UNKNOWN REF: AMM 52-41-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
524200-0101	FORWARD ACCESS ASSY-FWD CONTROL FUSELAGE DOOR PN SN-UNKNOWN REF: AMM 52-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
524400-0101	RH REAR STATION 00 ACCESS DOOR PN SN-UNKNOWN REF: AMM 52-44-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
524400-0201	BAGGAGE COMPARTMENT DOOR ASSY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
528100-0101	LH DOOR -MLG UPPER ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
528100-0102	RH DOOR -MLG UPPER ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
528100-0103	LH DOOR -MLG LOWER ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
528100-0104	RIGHT LW DOOR -MAIN LANDING GEAR,LOWER ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
528100-0201	LH DOOR ASSY 135-25246-401 0000637082 REF: AMM 32-10-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING	
528100-0202	RH DOOR ASSY 135-25246-402 0000637083 REF: AMM 32-10-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0				
528100-0301	LH LDG DOOR ASSY 135-25247-401 0000637084 REF: AMM 32-10-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0				
528100-0302	RH LDG DOOR ASSY 135-25247-402 0000633124 REF: AMM 32-10-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0				
CHAPTER 53 FUSELAGE											
53-00-01-220-001-A00 (s)	INSPECT (DETAILED INSPECTION) FUSELAGE DRAINS FOR OBSTRUCTION OR DAMAGE						PKG				
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015				
LOW UTILIZATION	REF: AMM 53-00-01	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280				
53-11-00-210-C01-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - BULKHEAD 1 STRUCTURE (SSI 53-10-23) - BATTERY COMPARTMENT CUT- OUT STRUCTURE (SSI 53-10-44) - HYDRAULIC COMPARTMENT CUTOOUT STRUCTURE (SSI 53-10-45) - LONGERONS (SSI 53-10-46)						PKG				
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010				
LOW UTILIZATION	REF: CPM 53-11-00	HRS/MSC AFL	7200 3600	+20/-20 +20/-20			0 0				
53-11-00-210-C02-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULKHEADS, AND SPLICES (SSI 53-10-07) - FUSELAGE SKIN PANEL AT PRESSURE BULKHEAD (SSI 53-10-15)						PKG				
	PKG 5009,5016	MOS	96	+15d/-15d			16-DEC-2010				
LOW UTILIZATION	REF: CPM 53-11-00	HRS/MSC AFL	4000 2000	+20/-20 +20/-20			0 0				
53-11-00-220-801-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-10-07)						PKG				
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010				
LOW UTILIZATION	REF: NDT 53-11-00	HRS/MSC AFL	7200 3600	+20/-20 +20/-20			0 0				
53-11-00-220-C01-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - NOSE LANDING GEAR FITTING, INCLUDING BEARING CAP AND TRUNNION FITTING (SSI 53-10-25)						PKG				
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015				
LOW UTILIZATION	REF: CPM 53-11-00	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280				



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-11-00-220-C02-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULKHEADS, AND SPLICES (SSI 53-10-07)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: CPM 53-11-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
53-11-00-220-C03-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN CIRCUMFERENTIAL SPLICE (SSI 53-10-14) - FUSELAGE SKIN PANEL AT PRESSURE BULKHEAD (SSI 53-10-15) - FRAMES (SSI 53-10-43)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: CPM 53-11-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
53-11-00-220-C04-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN LONGITUDINAL SPLICE (SSI 53-10-08)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: CPM 53-11-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
53-11-00-220-C05-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - NOSE LANDING GEAR BAY STRUCTURE (SSI 53-10-24)						PKG			
	PKG 5009,5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: CPM 53-11-00	HRS/MSC	4000	+20/-20			0			
		AFL	2000	+20/-20			0			
53-11-00-220-C06-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - NOSE LANDING GEAR BAY STRUCTURE (SSI 53-10-24)						PKG			
	PKG 5009,5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: CPM 53-11-00	HRS/MSC	4000	+20/-20			0			
		AFL	2000	+20/-20			0			
53-11-00-250-801-L00 (s)	SPECIAL DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS BY USING EDDY CURRENT INSPECTION METHOD: - NOSE LANDING GEAR FITTING, INCLUDING BEARING CAP AND TRUNNION FITTING (SSI 53-10-25)						PKG			
	PKG 5032,5140	MOS	288	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 53-11-00	HRS/MSC	12000	+20/-20			0			
		AFL	6000	+20/-20			0			
53-11-01-220-001-A00 (s)	INSPECT (DETAILED INSPECTION) THE PRESENCE OF WATER ON THE RADOME						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 53-11-01	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
53-11-05-212-001-A00 (s)	INSPECT (VISUAL INSPECTION) THE RADOME POLYURETHANE FILM						PKG			
	PKG 5004	MOS	24	+15d/-15d			21-JAN-2017			
LOW UTILIZATION	REF: AMM 53-11-05	HRS/MSC	1000	+20/-20			884.1			
		AFL					443			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-12-00-210-801-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COM- PONENTS: - WINDSHIELD PANEL (SSI 53-10-21)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 53-12-00	AFL	3600	+20/-20			0			
53-12-00-210-802-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - WINDSHIELD PANEL (SSI 53-10-21) (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: NDT 53-12-00	AFL	1800	+20/-20			280			
53-12-00-210-C01-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULK-HEADS, AND SPLICES (SSI 53-10-07)						PKG			
	PKG 5009,5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	4000	+20/-20			0			
LOW UTILIZATION	REF: CPM 53-12-00	AFL	2000	+20/-20			0			
53-12-00-210-C02-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT PRESSURE BULKHEAD (SSI 53-10-15)						PKG			
	PKG 5009,5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	4000	+20/-20			0			
LOW UTILIZATION	REF: CPM 53-12-00	AFL	2000	+20/-20			0			
53-12-00-210-C04-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - WINDSHIELD PANEL (SSI 53-10-21) (L600 ONLY)									
		MOS					16-DEC-2010			
		HRS/MSC	N/A				0			
STRUCTURAL	REF: CPM 53-12-00	AFL					0			
53-12-00-210-C05-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - MAINTENANCE DOOR CUTOUT STRUCTURE (SSI 53-10-49)						PKG			
	PKG 5009,5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	4000	+20/-20			0			
LOW UTILIZATION	REF: CPM 53-12-00	AFL	2000	+20/-20			0			
53-12-00-220-801-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - WINDSHIELD CUTOUT STRUCTURE (SSI 53-10-17) - COCKPIT WINDOW CUTOUT STRUCTURE (SSI 53-10-18)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 53-12-00	AFL	3600	+20/-20			0			
53-12-00-220-802-L00	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - WINDSHIELD CENTER POST AND ITS ATTACHMENT (SSI 53-10-19)									
	PKG 5032	MOS	192	+15d/-15d			16-DEC-2010	16-DEC-2026	31-DEC-2026	3537 d (+15)
		HRS/MSC	8000	+20/-20			0	8000	8020	7096.7 (+20)
LOW UTILIZATION	REF: NDT 53-12-00	AFL	4000	+20/-20			0	4000	4020	3550 (+20)
53-12-00-220-803-L00	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - WINDSHIELD LATERAL POST AND ITS ATTACHMENT (SSI 53-10-20) - COCKPIT WINDOW REAR POST AND ITS ATTACHMENT (SSI 53-10-22)									
	PKG 5032	MOS	192	+15d/-15d			16-DEC-2010	16-DEC-2026	31-DEC-2026	3537 d (+15)
		HRS/MSC	8000	+20/-20			0	8000	8020	7096.7 (+20)
LOW UTILIZATION	REF: NDT 53-12-00	AFL	4000	+20/-20			0	4000	4020	3550 (+20)

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-12-00-220-804-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FORWARD PRESSURE BULKHEAD (SSI 53-10-26)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 53-12-00	AFL	3600	+20/-20			0			
53-12-00-220-805-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-10-07) - FUSELAGE SKIN LONGITUDINAL SPLICE (SSI 53-10-08) - FUSELAGE SKIN PANEL AT PRESSURE BULKHEAD (SSI 53-10-15)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 53-12-00	AFL	3600	+20/-20			0			
53-12-00-220-806-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - COCKPIT WINDOW CUTOUT STRUCTURE (SSI 53-10-18)						PKG			
	PKG 5016	MOS	96	+15d/-15d			26-JAN-2015			
		HRS/MSC	4000	+20/-20			532.4			
LOW UTILIZATION	REF: NDT 53-12-00	AFL	2000	+20/-20			280			
53-12-00-220-807-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-10-07) - FUSELAGE SKIN LONGITUDINAL SPLICE (SSI 53-10-08)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 53-12-00	AFL	3600	+20/-20			0			
53-12-00-220-808-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - COCKPIT WINDOW REAR POST AND ITS ATTACHMENT (SSI 53-10-22)						PKG			
	PKG 5016	MOS	96	+15d/-15d			26-JAN-2015			
		HRS/MSC	4000	+20/-20			532.4			
LOW UTILIZATION	REF: NDT 53-12-00	AFL	2000	+20/-20			280			
53-12-00-220-809-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - COCKPIT FLOOR BEAMS AND COL- UMNS (SSI 53-10-27) NOTE: APPLICABLE TO AIRCRAFT POST-MOD. S.B. 145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY INCORPORATED						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 53-12-00	AFL	3600	+20/-20			0			
53-12-00-220-C01-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULKHEADS, AND SPLICES (SSI 53-10-07)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: CPM 53-12-00	AFL	3600	+20/-20			0			
53-12-00-220-C02-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN CIRCUMFERENTIAL SPLICE (SSI 53-10-14) - FRAMES (SSI 53-10-43)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: CPM 53-12-00	AFL	3600	+20/-20			0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-12-00-220-C03-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - COCKPIT FLOOR BEAMS AND COLUMNS (SSI 53-10-27) - MAINTENANCE DOOR CUTOUT STRUCTURE (SSI 53-10-49)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: CPM 53-12-00	AFL	3600	+20/-20			0			
53-12-00-220-C04-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT PRESSURE BULKHEAD (SSI 53-10-15)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: CPM 53-12-00	AFL	3600	+20/-20			0			
53-12-00-250-804-L00	SPECIAL DETAILED INSPECTION (INTERNAL) OF FUSELAGE COM- PONENTS BY USING EDDY CUR- RENT INSPECTION METHOD: - WINDSHIELD CENTER POST, INCLUDING ITS ATTACHMENTS AND LOWER FITTING (SSI 53-10-19) NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. S.B. 145LEG-00-0007 AND PRE-MOD. S.B. 145LEG-53-0021 (L600 ONLY)						PKG			
	PKG 5032	MOS					16-DEC-2010			
		HRS/MSC	N/A				0			
STRUCTURAL	REF: NDT 53-12-00	AFL					0			
53-12-00-250-804-L01	SPECIAL DETAILED INSPECTION (INTERNAL) OF FUSELAGE COM- PONENTS BY USING EDDY CUR- RENT INSPECTION METHOD: - WINDSHIELD CENTER POST, INCLUDING ITS ATTACHMENTS AND LOWER FITTING (SSI 53-10-19) NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. S.B. 145LEG-00-0007 AND POST-MOD. S.B. 145LEG-53-0021 OR WITH AN EQUIVALENT MODIFICATION FACTORY INCORPORATED (L600 ONLY)									
		MOS					16-DEC-2010			
		HRS/MSC	N/A				0			
	REF: NDT 53-12-00	AFL					0			
53-12-00-250-804-L02	SPECIAL DETAILED INSPECTION (INTERNAL) OF FUSELAGE COM- PONENTS BY USING EDDY CUR- RENT INSPECTION METHOD: - WINDSHIELD CENTER POST, INCLUDING ITS ATTACHMENTS AND LOWER FITTING (SSI 53-10-19) NOTE: APPLICABLE TO AIRCRAFT POST-MOD. S.B. 145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED AND PRE-MOD. S.B. 145LEG-53-0021 (L600 ONLY)						PKG			
	PKG 5016	MOS					16-DEC-2010			
		HRS/MSC	N/A				0			
	REF: NDT 53-12-00	AFL					0			
53-12-00-250-804-L03 (s)	SPECIAL DETAILED INSPECTION (INTERNAL) OF FUSELAGE COM- PONENTS BY USING EDDY CUR- RENT INSPECTION METHOD: - WINDSHIELD CENTER POST, INCLUDING ITS ATTACHMENTS AND LOWER FITTING (SSI 53-10-19) NOTE: APPLICABLE TO AIRCRAFT POST-MOD. S.B. 145LEG-00-0007 AND POST-MOD. S.B. 145LEG-53-0021 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 53-12-00	AFL	3600	+20/-20			0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-12-00-250-805-L00	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENT BY USING EDDY CURRENT INSPECTION METHOD: - WINDSHIELD LATERAL POST AND ITS ATTACHMENT (SSI 53-10-20). NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. S.B.145LEG-00-0007 AND PRE-MOD. S.B. 145LEG-53-0030. (L600 ONLY)	MOS						16-DEC-2010		
	REF: NDT 53-12-00	HRS/MSC AFL	N/A				0 0			
53-12-00-250-806-L00 (s)	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENT BY USING EDDY CURRENT INSPECTION METHOD: - WINDSHIELD LATERAL POST AND ITS ATTACHMENT (SSI 53-10-20). NOTE: APPLICABLE TO AIRCRAFT POST-MOD. S.B.145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPO- RATED AND PRE-MOD. S.B.145LEG-53-0030.	MOS	96	+15d/-15d				16-DEC-2010		
	PKG 5016,5140	HRS/MSC AFL	7200 3600	+20/-20 +20/-20			0 0			
LOW UTILIZATION	REF: NDT 53-12-00						0			
53-12-00-250-807-L00	SPECIAL DETAILED INSPECTION (INTERNAL) OF FUSELAGE COM- PONENT BY USING EDDY CURRENT INSPECTION METHOD: - WINDSHIELD LATERAL POST AND ITS ATTACHMENT (SSI 53-10-20). NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. S.B.145LEG-00-0007 AND PRE-MOD. S.B.145LEG-53-0030. (L600 ONLY)	MOS						16-DEC-2010		
	REF: NDT 53-12-00	HRS/MSC AFL	N/A				0 0			
53-12-00-250-808-L00	SPECIAL DETAILED INSPECTION (INTERNAL) OF FUSELAGE COM- PONENT BY USING EDDY CURRENT INSPECTION METHOD: - WINDSHIELD LATERAL POST AND ITS ATTACHMENT (SSI 53-10-20). NOTE: APPLICABLE TO AIRCRAFT POST-MOD. S.B.145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICA- TION FACTORY-INCORPO- RATED AND PRE-MOD. S.B.145LEG-53-0030.	MOS	144	+15d/-15d				16-DEC-2010	16-DEC-2022	31-DEC-2022 2076 d (+15)
	PKG 5011	HRS/MSC AFL	10800 5400	+20/-20 +20/-20			0 0		10800 5400	10820 5420 9896.7 (+20) 4950 (+20)
LOW UTILIZATION	REF: NDT 53-12-00						0			
53-12-00-250-809-L00	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENT BY USING EDDY CURRENT INSPECTION METHOD: - WINDSHIELD LATERAL POST AND ITS ATTACHMENT (SSI 53-10-20). NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. S.B.145LEG-00-0007 AND POST-MOD. S.B.145LEG-53-0030 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED. (L600 ONLY)	MOS						16-DEC-2010		
	REF: NDT 53-12-00	HRS/MSC AFL	N/A				0 0			
53-12-00-250-810-L00	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENT BY USING EDDY CURRENT INSPECTION METHOD: - WINDSHIELD LATERAL POST AND ITS ATTACHMENT (SSI 53-10-20). NOTE: APPLICABLE TO AIRCRAFT POST-MOD. S.B.145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPO- RATED AND POST- MOD. S.B.145LEG-53-0030 OR WITH AN EQUIVALENT MODIFICATION FACTORY INCORPORATED.	MOS	96	+15d/-15d				16-DEC-2010	16-DEC-2018	31-DEC-2018 615 d (+15)
	PKG 5017	HRS/MSC AFL	7200 3600	+20/-20 +20/-20			0 0		7200 3600	7220 3620 6296.7 (+20) 3150 (+20)
LOW UTILIZATION	REF: NDT 53-12-00						0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-21-00-210-C01-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - MAIN DOOR ATTACHMENTS FITTINGS AND INTERFACE PARTS (SSI 53-20-04)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: CPM 53-21-00	AFL	1800	+20/-20			280			
53-21-00-210-C02-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - MAIN DOOR ATTACHMENTS FITTINGS AND INTERFACE PARTS (SSI 53-20-04)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: CPM 53-21-00	AFL	3600	+20/-20			0			
53-21-00-220-801-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - PASSENGER DOOR CUTOUT REINFORCING STRUCTURES (SSI 53-20-09)						PKG			
	PKG 5016	MOS	96	+15d/-15d			26-JAN-2015			
		HRS/MSC	4000	+20/-20			532.4			
LOW UTILIZATION	REF: NDT 53-21-00	AFL	2000	+20/-20			280			
53-21-00-220-802-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - STOPS AND BACKUP STRUCTURES FOR MAIN DOOR (SSI 53-20-01)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: NDT 53-21-00	AFL	1800	+20/-20			280			
53-21-00-220-803-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - STOPS AND BACKUP STRUCTURES FOR MAIN DOOR (SSI 53-20-01) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: NDT 53-21-00	AFL	1800	+20/-20			280			
53-21-00-220-804-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 53-21-00	AFL	3600	+20/-20			0			
53-21-00-220-805-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FRAME 15 & 18 LHS SPLICES AT STRINGERS 3L & 16L (SSI 53-20-12) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 53-21-00	AFL	3600	+20/-20			0			
53-21-00-220-806-L00	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - PASSENGER CABIN WINDOW FRAME (SSI 53-20-06) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI NOTE: IF INSTALLED IN THE ZONE. (L600 ONLY)									
		MOS					16-DEC-2010			
		HRS/MSC	N/A				0			
STRUCTURAL	REF: NDT 53-21-00	AFL					0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-21-00-220-807-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - FRAME 15 & 18 LHS SPLICES AT STRINGERS 3L & 16L (SSI 53-20-12)						PKG			
	PKG 5016	MOS	96	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: NDT 53-21-00	HRS/MSC	4000	+20/-20			532.4			
		AFL	2000	+20/-20			280			
53-21-00-220-808-L00	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - PASSENGER CABIN WINDOW FRAME (SSI 53-20-06) NOTE: IF INSTALLED IN THE ZONE. (L600 ONLY)									
		MOS					16-DEC-2010			
STRUCTURAL	REF: NDT 53-21-00	HRS/MSC	N/A				0			
		AFL					0			
53-21-00-220-810-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - PASSENGER DOOR CUTOUT REINFORCING STRUCTURES (SSI 53-20-09) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 53-21-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
53-21-00-220-811-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN LONGITUDINAL SPLICES AT MAIN DOOR CUTOUT (SSI 53-20-41) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 53-21-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
53-21-00-220-812-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: NDT 53-21-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
53-21-00-220-813-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - MACHINED SHEAR CLIP AT FRAMES 23, 33 AND 35 (SSI 53-20-79)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 53-21-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
53-21-00-220-814-L00	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN LONGITUDINAL SPLICE (SSI 53-20-08) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR (SSI 53-20-08) (L600 ONLY)									
		MOS					16-DEC-2010			
	REF: NDT 53-21-00	HRS/MSC	N/A				0			
		AFL					0			
53-21-00-220-816-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - FORWARD AUXILIARY FUEL TANK FITTING, DOUBLER AND PIN AT FRAMES 23, 33 AND 35 (SSI 53-20-82)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 53-21-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-21-00-220-818-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07) NOTE: DO NOT REMOVE THE FUEL TANK						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: NDT 53-21-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
53-21-00-220-819-L00	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN LONGITUDINAL SPLICE (SSI 53-20-08) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR (SSI 53-20-08). (L650 ONLY)									
		MOS	96				16-DEC-2010	16-DEC-2018		615 d
LOW UTILIZATION	REF: NDT 53-21-00	HRS/MSC					0			
		AFL	10000				0	10000		9550
53-21-00-220-C01-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - PASSENGER CABIN FLOOR BEAMS AND COLUMNS (SSI 53-20-11)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: CPM 53-21-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
53-21-02-640-001-A00 (s)	LUBRICATE MAIN DOOR FRAME ROLLERS						PKG			
	PKG 5002	MOS	12	+15d/-15d			21-JAN-2017			
LOW UTILIZATION	REF: AMM 53-21-02	HRS/MSC	500	+20/-20			884.1			
		AFL					443			
53-22-00-210-801-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULK-HEADS, AND SPLICES (SSI 53-20-07)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 53-22-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
53-22-00-210-802-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULK-HEADS, AND SPLICES (SSI 53-20-07)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 53-22-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
53-22-00-210-803-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COM- PONENTS: - MACHINED SHEAR CLIP AT FRAMES 23, 33 AND 35 (SSI 53-20-79) - MACHINED SHEAR CLIP AT FRAMES 25 AND 31 (SSI 53-20-80)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 53-22-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
53-22-00-210-804-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULK-HEADS, AND SPLICES (SSI 53-20-07)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 53-22-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
53-22-00-210-805-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FORWARD AUXILIARY FUEL TANK (SSI 53-20-81)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 53-22-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-22-00-210-806-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - FORWARD AUXILIARY FUEL TANK (SSI 53-20-81)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 53-22-00	AFL	3600	+20/-20			0			
53-22-00-220-802-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07) - FUSELAGE SKIN CIRCUMFERENTIAL SPLICE (SSI 53-20-14) - FRAMES (SSI 53-20-43)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 53-22-00	AFL	3600	+20/-20			0			
53-22-00-220-804-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN LONGITUDINAL SPLICE (SSI 53-20-08)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 53-22-00	AFL	3600	+20/-20			0			
53-22-00-220-806-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - FORWARD AUXILIARY FUEL TANK FITTING, DOUBLER AND PIN AT FRAMES 23, 33 AND 35 (SSI 53-20-82) - FORWARD AUXILIARY FUEL TANK FITTING, DOUBLER AND PIN AT FRAMES 25 AND 31 (SSI 53-20-83)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 53-22-00	AFL	3600	+20/-20			0			
53-22-00-220-807-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - PASSENGER CABIN WINDOW FRAME (SSI 53-20-06)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 53-22-00	AFL	3600	+20/-20			0			
53-22-00-220-808-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - MACHINED SHEAR CLIP AT FRAMES 23, 33 AND 35 (SSI 53-20-79)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 53-22-00	AFL	3600	+20/-20			0			
53-22-00-220-C01-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - PASSENGER CABIN FLOOR BEAMS AND COLUMNS (SSI 53-20-11)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: CPM 53-22-00	AFL	3600	+20/-20			0			
53-23-00-210-801-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COM- PONENTS: - OVERWING FUSELAGE SKIN PANEL (SSI 53-20-16) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 53-23-00	AFL	3600	+20/-20			0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-23-00-210-804-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - OVERWING FUSELAGE SKIN PANEL (SSI 53-20-16)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 53-23-00	AFL	3600	+20/-20			0			
53-23-00-210-C02-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - PASSENGER CABIN WINDOW FRAME (SSI 53-20-06)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: CPM 53-23-00	AFL	3600	+20/-20			0			
53-23-00-220-801-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE MACHINED BULKHEAD (SSI 53-20-30) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR ZONES 151/152 AND 153/154						PKG			
	PKG 5032,5140	MOS	288	+15d/-15d			16-DEC-2010			
		HRS/MSC	12000	+20/-20			0			
LOW UTILIZATION	REF: NDT 53-23-00	AFL	6000	+20/-20			0			
53-23-00-220-802-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 53-23-00	AFL	3600	+20/-20			0			
53-23-00-220-803-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - SKIN AND REINFORCEMENT AROUND ESCAPE HATCH CUTOUT (SSI 53-20-51)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 53-23-00	AFL	3600	+20/-20			0			
53-23-00-220-804-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FRAMES (SSI 53-20-43)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 53-23-00	AFL	3600	+20/-20			0			
53-23-00-220-805-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FRAMES (SSI 53-20-43)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 53-23-00	AFL	3600	+20/-20			0			
53-23-00-220-806-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE MACHINED BULK- HEAD (SSI 53-20-30) - FRAMES (SSI 53-20-43) - SKIN AND REINFORCEMENT AROUND ESCAPE HATCH CUTOUT (SSI 53-20-51) - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR (SSI 53-20-30)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 53-23-00	AFL	3600	+20/-20			0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-23-00-220-808-L00	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07) NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. S.B. 145LEG-00-0007 (L600 ONLY)	MOS						16-DEC-2010	0	
	REF: NDT 53-23-00	HRS/MSC AFL	N/A					0	0	
53-23-00-220-808-L01 (s)	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07) NOTE: APPLICABLE TO AIRCRAFT POST-MOD. S.B. 145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED.						PKG			
	PKG 5016	MOS	96	+15d/-15d				16-DEC-2010	0	
LOW UTILIZATION	REF: NDT 53-23-00	HRS/MSC AFL	7200 3600	+20/-20 +20/-20				0	0	
53-23-00-220-809-L00	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07) NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. S.B. 145LEG-00-0007 (L600 ONLY)	MOS						16-DEC-2010	0	
	REF: NDT 53-23-00	HRS/MSC AFL	N/A					0	0	
53-23-00-220-810-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - MACHINED FRAME AT VENTRAL FUEL TANK ATTACHMENT POINTS (SSI 53-20-84) (L650 ONLY)						PKG			
	PKG 5016	MOS	96	+15d/-15d				16-DEC-2010	0	
LOW UTILIZATION	REF: NDT 53-23-00	HRS/MSC AFL	7200 3600	+20/-20 +20/-20				0	0	
53-23-00-220-811-L00	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - PASSENGER CABIN FLOOR BEAMS AND COLUMNS (SSI 53-20-11) NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. S.B. 145LEG-00-0007. (L600 ONLY)	MOS						16-DEC-2010	0	
	REF: NDT 53-23-00	HRS/MSC AFL	N/A					0	0	
53-23-00-220-811-L01 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - PASSENGER CABIN FLOOR BEAMS AND COLUMNS (SSI 53-20-11) NOTE: APPLICABLE TO AIRCRAFT POST-MOD. S.B. 145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED.						PKG			
	PKG 5016	MOS	96	+15d/-15d				16-DEC-2010	0	
LOW UTILIZATION	REF: NDT 53-23-00	HRS/MSC AFL	7200 3600	+20/-20 +20/-20				0	0	
53-23-00-220-812-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07). (L650 ONLY)						PKG			
	PKG 5016	MOS	96	+15d/-15d						
LOW UTILIZATION	REF: NDT 53-23-00	HRS/MSC AFL	7200 3600	+20/-20 +20/-20						

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-23-00-220-C01-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULKHEADS, AND SPLICES (SSI 53-20-07)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: CPM 53-23-00	AFL	1800	+20/-20			280			
53-23-00-220-C03-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN LONGITUDINAL SPLICE (SSI 53-20-08)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: CPM 53-23-00	AFL	3600	+20/-20			0			
53-23-00-220-C04-L00	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULKHEADS, AND SPLICES (SSI 53-20-07) (L600 ONLY)							16-DEC-2010		
		MOS					0			
STRUCTURAL	REF: CPM 53-23-00	HRS/MSC	N/A				0			
		AFL					0			
53-23-00-250-801-L00	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENT BY USING EDDY CURRENT HIGH FREQUENCY INSPECTION METHOD: - PASSENGER CABIN WINDOW FRAME (SSI 53-20-06) NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. S.B. 145LEG-00-0007 (L600 ONLY)							16-DEC-2010		
		MOS					0			
	REF: NDT 53-23-00	HRS/MSC	N/A				0			
		AFL					0			
53-24-00-210-C01-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - PASSENGER CABIN WINDOW FRAME (SSI 53-20-06)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: CPM 53-24-00	AFL	3600	+20/-20			0			
53-24-00-210-C07-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF VENTRAL FUEL TANK COMPONENTS: - VENTRAL FUEL TANK STRUCTURE (SSI 53-20-85) - FRONTAL SIDE OF VENTRAL FUEL TANK STRUCTURE (SSI 53-20-87) (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: CPM 53-24-00	AFL	1800	+20/-20			280			
53-24-00-220-801-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 53-24-00	AFL	3600	+20/-20			0			
53-24-00-220-802-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN LONGITUDINAL SPLICE (SSI 53-20-08)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 53-24-00	AFL	3600	+20/-20			0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-24-00-220-803-L00	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN CIRCUMFERENTIAL SPLICE (SSI 53-20-14) - FRAMES (SSI 53-20-43) (L600 ONLY)						PKG			
	PKG 5016	MOS					16-DEC-2010			
		HRS/MSC	N/A				0			
	REF: NDT 53-24-00	AFL					0			
53-24-00-220-804-L00	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07) - FUSELAGE SKIN LONGITUDINAL SPLICE (SSI 53-20-08) NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. S.B. 145LEG-00-0007 (L600 ONLY)									
		MOS					16-DEC-2010			
		HRS/MSC	N/A				0			
STRUCTURAL	REF: NDT 53-24-00	AFL					0			
53-24-00-220-805-L00	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07) (L600 ONLY)						PKG			
	PKG 5032	MOS					16-DEC-2010			
		HRS/MSC	N/A				0			
STRUCTURAL	REF: NDT 53-24-00	AFL					0			
53-24-00-220-813-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - MACHINED FRAME AT VENTRAL FUEL TANK ATTACHMENT POINTS (SSI 53-20-84) (L650 ONLY)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 53-24-00	AFL	3600	+20/-20			0			
53-24-00-220-814-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF VENTRAL FUEL TANK COMPONENTS: - VENTRAL FUEL TANK ATTACHMENT POINTS, INCLUDING MAIN BOLTS (SSI 53-20-86) (L650 ONLY)						PKG			
	PKG 5016	MOS	96	+15d/-15d						
		HRS/MSC	7200	+20/-20						
LOW UTILIZATION	REF: NDT 53-24-00	AFL	3600	+20/-20						
53-24-00-220-815-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN CIRCUMFERENTIAL SPLICE (SSI 53-20-14) FRAMES (SSI 53-20-43) (L650 ONLY)						PKG			
	PKG 5016	MOS	96	+15d/-15d						
		HRS/MSC	7200	+20/-20						
LOW UTILIZATION	REF: NDT 53-24-00	AFL	3600	+20/-20						
53-24-00-220-816-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-20-07) (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: NDT 53-24-00	AFL	1800	+20/-20			280			
53-24-00-220-C01-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULKHEADS, AND SPLICES (SSI 53-20-07)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: CPM 53-24-00	AFL	1800	+20/-20			280			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-24-00-220-C02-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - PASSENGER CABIN FLOOR BEAMS AND COLUMNS (SSI 53-20-11)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: CPM 53-24-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
53-24-00-220-C03-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULKHEADS, AND SPLICES (SSI 53-20-07). NOTE: APPLICABLE TO AIRCRAFT POST-MOD. S.B. 145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY- INCORPORATED						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: CPM 53-24-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
53-24-00-220-C04-L00 (s)	DETAILED INSPECTION (INTERNAL) OF VENTRAL FUEL TANK COMPONENTS: - VENTRAL FUEL TANK STRUCTURE (SSI 53-20-85) (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: CPM 53-24-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
53-24-00-220-C05-L00 (s)	DETAILED INSPECTION (INTERNAL) OF VENTRAL FUEL TANK COMPONENTS: - FRONTAL SIDE OF VENTRAL FUEL TANK STRUCTURE (SSI 53-20-87) (L650 ONLY)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: CPM 53-24-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
53-31-00-210-801-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COM- PONENTS: - REAR AUXILIARY FUEL TANK FITTING AT ATTACHMENTS (SSI 53-30-56)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 53-31-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
53-31-00-210-802-L00	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - BAGGAGE DOOR LATERAL L- SHAPE (SSI 53-30-03)									
	PKG 5032	MOS	192	+15d/-15d			16-DEC-2010	16-DEC-2026	31-DEC-2026	3537 d (+15)
LOW UTILIZATION	REF: NDT 53-31-00	HRS/MSC	8000	+20/-20			0	8000	8020	7096.7 (+20)
		AFL	4000	+20/-20			0	4000	4020	3550 (+20)
53-31-00-210-803-L00	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - BAGGAGE DOOR CUTOUT STRUC- TURE (SSI 53-30-48) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI (L600 ONLY)									
		MOS					16-DEC-2010			
STRUCTURAL	REF: NDT 53-31-00	HRS/MSC	N/A				0			
		AFL					0			
53-31-00-210-804-L00	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - REAR ELECTRONIC COMPARTMENT DOOR CUTOUT STRUCTURE (SSI 53-30-49) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI. NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. S.B. 145LEG-00-0007 (L600 ONLY)									
		MOS					16-DEC-2010			
STRUCTURAL	REF: NDT 53-31-00	HRS/MSC	N/A				0			
		AFL					0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-31-00-210-804-L01	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - REAR ELECTRONIC COMPARTMENT DOOR CUTOUT STRUCTURE (SSI 53-30-49) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI. NOTE: APPLICABLE TO AIRCRAFT POST-MOD. S.B. 145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED (L600 ONLY)	MOS						16-DEC-2010		
STRUCTURAL	REF: NDT 53-31-00	HRS/MSC AFL	N/A					0 0		
53-31-00-210-807-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-30-07) NOTE: REMOVE BUMPER PLATES, IF INSTALLED (L600 ONLY)	MOS						16-DEC-2010		
STRUCTURAL	REF: NDT 53-31-00	HRS/MSC AFL	N/A					0 0		
53-31-00-210-810-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - REAR ELECTRONIC COMPARTMENT DOOR CUTOUT STRUCTURE (SSI 53-30-49) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI. (L650 ONLY)							PKG		
LOW UTILIZATION	REF: NDT 53-31-00	PKG 5016 MOS HRS/MSC AFL	96 7200 3600	+15d/-15d +20/-20 +20/-20						
53-31-00-220-801-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - BAGGAGE COMPARTMENT FLOOR BEAMS AND COLUMNS (SSI 53-30-28)							PKG		
LOW UTILIZATION	REF: NDT 53-31-00	PKG 5016 MOS HRS/MSC AFL	96 7200 3600	+15d/-15d +20/-20 +20/-20				16-DEC-2010 0 0		
53-31-00-220-802-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - FRAME REINFORCEMENT - MACHINED SHEAR CLIP (SSI 53-30-55)							PKG		
LOW UTILIZATION	REF: NDT 53-31-00	PKG 5016 MOS HRS/MSC AFL	96 7200 3600	+15d/-15d +20/-20 +20/-20				16-DEC-2010 0 0		
53-31-00-220-804-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT PRESSURE BULKHEAD (SSI 53-30-15) - FUSELAGE MACHINED BULK- HEAD (SSI 53-30-30) - REAR PRESSURE BULKHEAD (SSI 53-30-36)							PKG		
LOW UTILIZATION	REF: NDT 53-31-00	PKG 5016 MOS HRS/MSC AFL	96 7200 3600	+15d/-15d +20/-20 +20/-20				16-DEC-2010 0 0		
53-31-00-220-805-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FRAME REINFORCEMENT - MACHINED SHEAR CLIP (SSI 53-30-55)							PKG		
LOW UTILIZATION	REF: NDT 53-31-00	PKG 5016 MOS HRS/MSC AFL	96 7200 3600	+15d/-15d +20/-20 +20/-20				16-DEC-2010 0 0		

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-31-00-220-806-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT PRESSURE BULKHEAD (SSI 53-30-15)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 53-31-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
53-31-00-220-807-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN LONGITUDINAL SPLICE (SSI 53-30-08) - FUSELAGE SKIN CIRCUMFERENTIAL SPLICE (SSI 53-30-14)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 53-31-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
53-31-00-220-808-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - BAGGAGE DOOR CUTOUT STRUCTURE (SSI 53-30-48)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 53-31-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
53-31-00-220-809-L00	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - REAR ELECTRONIC COMPARTMENT DOOR CUTOUT STRUCTURE (SSI 53-30-49) (L600 ONLY)						PKG			
	PKG 5016	MOS					16-DEC-2010			
STRUCTURAL	REF: NDT 53-31-00	HRS/MSC	N/A				0			
		AFL					0			
53-31-00-220-810-L00	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT PRES- SURE BULKHEAD (SSI 53-30-15) - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-30-07) - BULKHEAD-TO-ENGINE PYLON ATTACHMENT (SSI 53-30-35) - REAR PRESSURE BULKHEAD (SSI 53-30-36) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR SSIS 53-30-07 AND 53-30-35 (L600 ONLY)									
		MOS					16-DEC-2010			
STRUCTURAL	REF: NDT 53-31-00	HRS/MSC	N/A				0			
		AFL					0			
53-31-00-220-811-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE MACHINED BULK- HEAD (SSI 53-30-30)						PKG			
	PKG 5032	MOS	192	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 53-31-00	HRS/MSC	8000	+20/-20			0			
		AFL	4000	+20/-20			0			
53-31-00-220-813-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-30-07) - FUSELAGE SKIN PANEL AT PRES- SURE BULKHEAD (SSI 53-30-15) - FUSELAGE TO VERTICAL STABILIZER SPAR ATTACHMENT FITTING (SSI 53-30-38) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR SSI 53-30-38						PKG			
	PKG 5016	MOS	96	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: NDT 53-31-00	HRS/MSC	4000	+20/-20			532.4			
		AFL	2000	+20/-20			280			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-31-00-220-814-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - REAR PRESSURE BULKHEAD (SSI 53-30-36) - FUSELAGE TO VERTICAL STABILIZER SPAR ATTACHMENT FITTING (SSI 53-30-38) - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-30-07) - FUSELAGE SKIN PANEL AT PRES- SURE BULKHEAD (SSI 53-30-15) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR (SSI 53-30-36)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 53-31-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
53-31-00-220-815-L00	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE MACHINED BULKHEAD (SSI 53-30-30)						16-DEC-2010	16-DEC-2026	31-DEC-2026	3537 d (+15)
	PKG 5032	MOS	192	+15d/-15d			0	14400	14420	13496.7 (+20)
LOW UTILIZATION	REF: NDT 53-31-00	HRS/MSC	14400	+20/-20			0	7200	7220	6750 (+20)
		AFL	7200	+20/-20			0			
53-31-00-220-816-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - BAGGAGE DOOR CUTOFF STRUCTURE (SSI 53-30-48) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI (L650 ONLY)						PKG			
	PKG 5016	MOS	96	+15d/-15d						
LOW UTILIZATION	REF: NDT 53-31-00	HRS/MSC	7200	+20/-20						
		AFL	3600	+20/-20						
53-31-00-220-817-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-30-07) NOTE: REMOVE BUMPER PLATES, IF INSTALLED (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: NDT 53-31-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
53-31-00-220-818-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - REAR ELECTRONIC COMPARTMENT DOOR CUTOFF STRUCTURE (SSI 53-30-49) (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: NDT 53-31-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
53-31-00-220-819-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT PRESSURE BULKHEAD (SSI 53-30-15) - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-30-07) - BULKHEAD-TO-ENGINE PYLON ATTACHMENT (SSI 53-30-35) - REAR PRESSURE BULKHEAD (SSI 53-30-36) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR SSIS 53-30-07 AND 53-30-35 (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: NDT 53-31-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
53-31-00-220-C01-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - TOILET WASTE DRAIN VALVE SUPPORT (SSI 53-30-29) - FRAMES (SSI 53-30-43)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: CPM 53-31-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-31-00-220-C02-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULK HEADS, AND SPLICES (SSI 53-30-07)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: CPM 53-31-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
53-31-00-220-C03-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT PRESSURE BULKHEAD (SSI 53-30-15)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: CPM 53-31-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
53-31-00-220-C04-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - TOILET WASTE DRAIN VALVE SUPPORT (SSI 53-30-29)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: CPM 53-31-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
53-31-00-220-C05-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FRAMES (SSI 53-30-43)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: CPM 53-31-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
53-31-00-250-801-L00 (s)	SPECIAL DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENT BY USING EDDY CURRENT HIGH FREQUENCY INSPECTION METHOD: - TOILET WASTE DRAIN VALVE SUPPORT (SSI 53-30-29) NOTE: APPLICABLE TO AIRCRAFT POST-MOD. S.B. 145LEG-00-0007 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED.						PKG			
	PKG 5032,5140	MOS	192	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 53-31-00	HRS/MSC	14400	+20/-20			0			
		AFL	7200	+20/-20			0			
53-31-00-250-802-L00	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENT BY USING EDDY CURRENT LOW FREQUENCY INSPECTION METHOD: - BAGGAGE DOOR CUTOUT STRUCTURE (SSI 53-30-48) (L600 ONLY)									
		MOS					16-DEC-2010			
	REF: NDT 53-31-00	HRS/MSC	N/A				0			
		AFL					0			
53-31-00-250-803-L00	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENT BY USING EDDY CURRENT HIGH FREQUENCY INSPECTION METHOD: - BAGGAGE DOOR CUTOUT STRUCTURE (SSI 53-30-48) (L600 ONLY)									
		MOS					16-DEC-2010			
	REF: NDT 53-31-00	HRS/MSC	N/A				0			
		AFL					0			
53-31-00-270-801-L00	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENT BY THE ULTRASONIC INSPECTION METHOD: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-30-07) (L600 ONLY)						PKG			
	PKG 5032	MOS					16-DEC-2010			
STRUCTURAL	REF: NDT 53-31-00	HRS/MSC	N/A				0			
		AFL					0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-31-00-270-803-L00 (s)	SPECIAL DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENT BY THE ULTRASONIC INSPECTION METHOD: - REAR PRESSURE BULKHEAD (SSI 53-30-36)						PKG			
	PKG 5032,5140	MOS	288	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 53-31-00	HRS/MSC	12000	+20/-20			0			
		AFL	6000	+20/-20			0			
53-31-00-270-804-L00	SPECIAL DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENT BY THE ULTRASONIC INSPECTION METHOD: - FRAMES (SSI 53-30-43) (L600 ONLY)						PKG			
	PKG 5032	MOS					16-DEC-2010			
STRUCTURAL	REF: NDT 53-31-00	HRS/MSC	N/A				0			
		AFL					0			
53-31-00-270-806-L00	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENT BY THE ULTRASONIC INSPECTION METHOD: - FUSELAGE SKIN PANEL AT PRESSURE BULKHEAD (SSI 53-30-15) (L600 ONLY)						PKG			
	PKG 5032	MOS					16-DEC-2010			
STRUCTURAL	REF: NDT 53-31-00	HRS/MSC	N/A				0			
		AFL					0			
53-31-00-270-807-L00	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENT BY THE ULTRASONIC INSPECTION METHOD: - FUSELAGE MACHINED BULKHEAD (SSI 53-30-30) (L600 ONLY)						PKG			
	PKG 5032	MOS					16-DEC-2010			
STRUCTURAL	REF: NDT 53-31-00	HRS/MSC	N/A				0			
		AFL					0			
53-31-00-270-809-L00	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS BY THE ULTRASONIC INSPECTION METHOD: - FUSELAGE TO VERTICAL STABILIZER SPAR ATTACHMENT FITTING (SSI 53-30-38) (L600 ONLY)						PKG			
	PKG 5032	MOS					16-DEC-2010			
STRUCTURAL	REF: NDT 53-31-00	HRS/MSC	N/A				0			
		AFL					0			
53-31-00-270-810-L00 (s)	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS BY THE ULTRASONIC INSPECTION METHOD: - BAGGAGE DOOR CUTOUT STRUCTURE (SSI 53-30-48) (L650 ONLY)						PKG			
	PKG 5032	MOS	192	+15d/-15d						
LOW UTILIZATION	REF: NDT 53-31-00	HRS/MSC	8000	+20/-20						
		AFL	4000	+20/-20						
53-31-00-270-811-L00 (s)	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS BY THE ULTRASONIC INSPECTION METHOD: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/ BULKHEADS, AND SPLICES (SSI 53-30-07) (L650 ONLY)						PKG			
	PKG 5024,5140	MOS	144	+15d/-15d						
LOW UTILIZATION	REF: NDT 53-31-00	HRS/MSC	10800	+20/-20						
		AFL	5400	+20/-20						
53-31-00-270-812-L00 (s)	SPECIAL DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS BY THE ULTRASONIC INSPECTION METHOD: - FRAMES (SSI 53-30-43) (L650 ONLY)						PKG			
	PKG 5024,5140	MOS	14							
LOW UTILIZATION	REF: NDT 53-31-00	HRS/MSC	10800							
		AFL	5400							

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-31-00-270-813-L00 (s)	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS BY THE ULTRASONIC INSPECTION METHOD: - FUSELAGE SKIN PANEL AT PRES- SURE BULKHEAD (SSI 53-30-15) (L650 ONLY)						PKG			
	PKG 5024,5140	MOS	144	+15d/-15d						
LOW UTILIZATION	REF: NDT 53-31-00	HRS/MSC	10800	+20/-20						
		AFL	5400	+20/-20						
53-31-00-270-814-L00 (s)	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS BY THE ULTRASONIC INSPECTION METHOD: - FUSELAGE MACHINED BULK- HEAD (SSI 53-30-30) (L650 ONLY)						PKG			
	PKG 5024,5140	MOS	144	+15d/-15d						
LOW UTILIZATION	REF: NDT 53-31-00	HRS/MSC	10800	+20/-20						
		AFL	5400	+20/-20						
53-31-00-270-815-L00 (s)	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS BY THE ULTRASONIC INSPECTION METHOD: - FUSELAGE TO VERTICAL STABILIZER SPAR ATTACHMENT FITTING (SSI 53-30-38) (L650 ONLY)						PKG			
	PKG 5024,5140	MOS	144	+15d/-15d						
LOW UTILIZATION	REF: NDT 53-31-00	HRS/MSC	10800	+20/-20						
		AFL	5400	+20/-20						
53-32-00-210-801-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - APU MOUNTING (SSI 53-30-40)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 53-32-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
53-32-00-210-802-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - TAIL CONE ACCESS DOOR CUT- OUT STRUCTURE (SSI 53-30-50)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 53-32-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
53-32-00-210-C01-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULKHEADS, AND SPLICES (SSI 53-30-07)						PKG			
	PKG 5009,5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: CPM 53-32-00	HRS/MSC	4000	+20/-20			0			
		AFL	2000	+20/-20			0			
53-32-00-210-C02-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE SKIN PANEL AT STRINGERS, FRAMES/BULKHEADS, AND SPLICES (SSI 53-30-07) - FUSELAGE SKIN LONGITUDINAL SPLICE (SSI 53-30-08) - FUSELAGE SKIN CIRCUMFERENTIAL SPLICE (SSI 53-30-14) - TAIL CONE FRAME AT APU MOUNTING ATTACHMENT (SSI 53-30-39)						PKG			
	PKG 5009,5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: CPM 53-32-00	HRS/MSC	4000	+20/-20			0			
		AFL	2000	+20/-20			0			
53-32-00-220-801-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE TO VERTICAL STABILIZER SPAR ATTACHMENT FITTING (SSI 53-30-38)						PKG			
	PKG 5032	MOS	192	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 53-32-00	HRS/MSC	8000	+20/-20			0			
		AFL	4000	+20/-20			0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-32-00-220-802-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FUSELAGE MACHINED BULKHEAD (SSI 53-30-30)						PKG			
	PKG 5032	MOS	192	+15d/-15d			16-DEC-2010			
		HRS/MSC	8000	+20/-20			0			
LOW UTILIZATION	REF: NDT 53-32-00	AFL	4000	+20/-20			0			
53-32-00-220-803-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF FUSELAGE COMPONENTS: - L PROFILE STRAKE ATTACHMENT (SSI 53-30-53)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 53-32-00	AFL	3600	+20/-20			0			
53-32-00-220-804-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - TAIL CONE ACCESS DOOR CUT- OUT STRUCTURE (SSI 53-30-50)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 53-32-00	AFL	3600	+20/-20			0			
53-32-00-220-C01-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - REAR PRESSURE BULKHEAD (SSI 53-30-36)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: CPM 53-32-00	AFL	1800	+20/-20			280			
53-32-00-220-C02-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FUSELAGE COMPONENTS: - FRAMES (SSI 53-30-43)						PKG			
	PKG 5009,5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	4000	+20/-20			0			
LOW UTILIZATION	REF: CPM 53-32-00	AFL	2000	+20/-20			0			
53-Z111-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONE 111)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 05-20-01	AFL	1800	+20/-20			280			
53-Z111-214-001-A00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONE 111)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 05-20-01	AFL	1800	+20/-20			280			
53-Z113-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONE 113, 114)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 05-20-03	AFL	1800	+20/-20			280			
53-Z113-214-001-A00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONE 113)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 05-20-03	AFL	1800	+20/-20			280			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-Z114-214-001-A00	GENERAL VISUAL INSPECTION (INTERNAL) (ZONE 114) (L600 ONLY)	MOS								
ZONAL	REF:	HRS/MSC AFL	N/A							
53-Z114-214-001-A01 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONE 114) NOTE:EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-20-03	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
53-Z123-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONE 123, 124)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-20-10	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
53-Z123-214-001-A00	GENERAL VISUAL INSPECTION (INTERNAL) (ZONE 121, 122, 123 AND 124) (L600 ONLY)	MOS						16-DEC-2010		
REF:		HRS/MSC AFL	N/A				0 0			
53-Z123-214-001-A01 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONE 121, 122, 123 AND 124) NOTE:EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-20-10	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
53-Z131-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 131 AND 132)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-20-17	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
53-Z131-214-001-A00	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 131 AND 132) (L600 ONLY)	MOS						16-DEC-2010		
REF:		HRS/MSC AFL	N/A				0 0			
53-Z131-214-001-A01 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 131 AND 132) NOTE:EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-20-17	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
53-Z141-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 141 AND 142)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: AMM 05-20-21	HRS/MSC AFL	7200 3600	+20/-20 +20/-20			0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-Z141-214-001-A00	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 225 AND 226) (L600 ONLY)	MOS						16-DEC-2010		
	REF:	HRS/MSC AFL	N/A					0 0		
53-Z141-214-001-A01 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 141 AND 142) NOTE:EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d				26-JAN-2015		
LOW UTILIZATION	REF: AMM 05-20-21	HRS/MSC AFL	3600 1800	+20/-20 +20/-20				532.4 280		
53-Z151-214-002-A00	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 151, 152, 153, 154, 155, 156, 157) (L600 ONLY)	MOS						16-DEC-2010		
	REF:	HRS/MSC AFL	N/A					0 0		
53-Z151-214-002-A01 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 151, 152, 153, 154, 155, 156, 157) NOTE:EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d				26-JAN-2015		
LOW UTILIZATION	REF: AMM 05-20-26	HRS/MSC AFL	3600 1800	+20/-20 +20/-20				532.4 280		
53-Z155-214-001-A00	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 155, 156 AND 157) (L600 ONLY)	MOS						16-DEC-2010		
	REF:	HRS/MSC AFL	N/A					0 0		
53-Z155-214-001-A01 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 155, 156 AND 157) NOTE:EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d				26-JAN-2015		
LOW UTILIZATION	REF: AMM 05-20-28	HRS/MSC AFL	3600 1800	+20/-20 +20/-20				532.4 280		
53-Z161-214-001-A00	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 161, 162) (L600 ONLY)	MOS						16-DEC-2010		
	REF:	HRS/MSC AFL	N/A					0 0		
53-Z161-214-001-A01 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 161, 162) NOTE:EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d				26-JAN-2015		
LOW UTILIZATION	REF: AMM 05-20-33	HRS/MSC AFL	3600 1800	+20/-20 +20/-20				532.4 280		
53-Z171-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 171 AND 172)						PKG			
	PKG 5008	MOS	48	+15d/-15d				26-JAN-2015		
LOW UTILIZATION	REF: AMM 05-20-38	HRS/MSC AFL	3600 1800	+20/-20 +20/-20				532.4 280		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-Z171-214-001-A00	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 171 AND 172) (L600 ONLY)	MOS						16-DEC-2010	0	
	REF:	HRS/MSC	N/A					0	0	
53-Z171-214-001-A01 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 171 AND 172) NOTE:EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d				26-JAN-2015	532.4	
LOW UTILIZATION	REF: AMM 05-20-38	HRS/MSC	3600	+20/-20				280		
		AFL	1800	+20/-20						
53-Z191-213-001-A00	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 191, 192, 193, 194, 195, 196, 197,198, 199, 1921, 1922, 1923, 1971, 1981, 1982, 1991 and 1992). NOTE: DO NOT REMOVE THE FUEL TANK (L600 ONLY)						PKG			
	PKG 5008	MOS						16-DEC-2010	0	
	REF:	HRS/MSC	N/A					0	0	
		AFL								
53-Z191-213-002-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 191, 192, 193, 194, 195, 196, 197, 198, 199, 1921, 1922, 1923, 1971, 1981, 1982, 1991 and 1992). NOTE: DO NOT REMOVE THE FUEL TANK (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d				26-JAN-2015	532.4	
LOW UTILIZATION	REF: AMM 05-20-95	HRS/MSC	3600	+20/-20				280		
		AFL	1800	+20/-20						
53-Z191-214-001-A00	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 191, 192, 193, 194, 195, 196, 198, 199, 1921, 1922, 1923, 1971, 1981, 1982, 1991 and 1992). (L600 ONLY)							16-DEC-2010	0	
	REF:	MOS						0	0	
		HRS/MSC	N/A							
		AFL								
53-Z191-214-003-A00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 191, 192, 1921, 1922, 1923, 1924, 193, 1932, 194, 195, 196, 1971, 198, 1981, 1982, 199, 1991, 1992). NOTE:EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d				26-JAN-2015	532.4	
LOW UTILIZATION	REF: AMM 05-20-95	HRS/MSC	3600	+20/-20				280		
		AFL	1800	+20/-20						
53-Z197-214-001-A00	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 197) (L600 ONLY)									
ZONAL	REF:	MOS								
		HRS/MSC	N/A							
		AFL								
53-Z197-214-001-A01 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONE 197) NOTE:EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d				26-JAN-2015	532.4	
LOW UTILIZATION	REF: AMM 05-20-96	HRS/MSC	3600	+20/-20				280		
		AFL	1800	+20/-20						

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-Z197-214-002-A00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONE 1972) NOTE:EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-30-37	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
53-Z213-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONE 213, 214)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-20-06	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
53-Z213-214-001-A00	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 113, 114, 213, 214, 215, 216) (L600 ONLY)									
ZONAL	REF:	MOS								
		HRS/MSC	N/A							
		AFL								
53-Z213-214-001-A01 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONE 113, 114, 213, 214, 215, 216) NOTE:EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-20-06	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
53-Z223-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 223, 224)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-20-13	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
53-Z223-214-001-A00	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 221, 222, 223 AND 224) (L600 ONLY)									
		MOS					16-DEC-2010			
REF:		HRS/MSC	N/A				0			
		AFL					0			
53-Z223-214-001-A01 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 221, 222, 223 AND 224) NOTE:EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-20-13	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
53-Z225-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 225 AND 226)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: AMM 05-20-15	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
53-Z225-214-001-A00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 225 AND 226)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: AMM 05-20-15	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-Z231-213-001-A00	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 231 AND 232) NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. SB 145LEG-53-0031.	MOS						21-JAN-2017		
	REF: AMM 05-20-18	HRS/MSC AFL	N/A					884.1 443		
53-Z231-213-001-A01 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 231 AND 232) NOTE: APPLICABLE TO AIRCRAFT POST-MOD. SB 145LEG-53-0031 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED.						PKG			
	PKG 5008	MOS	48	+15d/-15d				26-JAN-2015		
LOW UTILIZATION	REF:	HRS/MSC AFL	3600 1800	+20/-20 +20/-20				532.4 280		
53-Z231-214-001-A00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 231 AND 232)						PKG			
	PKG 5008	MOS	48	+15d/-15d				26-JAN-2015		
LOW UTILIZATION	REF: AMM 05-20-18	HRS/MSC AFL	3600 1800	+20/-20 +20/-20				532.4 280		
53-Z233-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 233 AND 234)						PKG			
	PKG 5008	MOS	48	+15d/-15d				26-JAN-2015		
LOW UTILIZATION	REF: AMM 05-20-19	HRS/MSC AFL	3600 1800	+20/-20 +20/-20				532.4 280		
53-Z233-214-001-A00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 233 AND 234)						PKG			
	PKG 5016	MOS	96	+15d/-15d				16-DEC-2010		
LOW UTILIZATION	REF: AMM 05-20-19	HRS/MSC AFL	7200 3600	+20/-20 +20/-20				0 0		
53-Z241-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 241 AND 242)						PKG			
	PKG 5016	MOS	96	+15d/-15d				16-DEC-2010		
LOW UTILIZATION	REF: AMM 05-20-23	HRS/MSC AFL	7200 3600	+20/-20 +20/-20				0 0		
53-Z241-214-001-A00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 241 AND 242)						PKG			
	PKG 5008	MOS	48	+15d/-15d				26-JAN-2015		
LOW UTILIZATION	REF: AMM 05-20-23	HRS/MSC AFL	3600 1800	+20/-20 +20/-20				532.4 280		
53-Z243-213-003-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 243 AND 244)						PKG			
	PKG 5016	MOS	96	+15d/-15d				16-DEC-2010		
LOW UTILIZATION	REF: AMM 05-20-25	HRS/MSC AFL	7200 3600	+20/-20 +20/-20				0 0		
53-Z243-214-001-A00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 243 AND 244)						PKG			
	PKG 5016	MOS	96	+15d/-15d				16-DEC-2010		
LOW UTILIZATION	REF: AMM 05-20-25	HRS/MSC AFL	7200 3600	+20/-20 +20/-20				0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-Z251-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 251 AND 252)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: AMM 05-20-30	AFL	3600	+20/-20			0			
53-Z251-214-001-A00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 251 AND 252)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: AMM 05-20-30	AFL	3600	+20/-20			0			
53-Z253-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 253 AND 254)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: AMM 05-20-31	AFL	3600	+20/-20			0			
53-Z253-214-001-A00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 253 AND 254)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: AMM 05-20-31	AFL	3600	+20/-20			0			
53-Z261-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 261, 262)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: AMM 05-20-35	AFL	3600	+20/-20			0			
53-Z261-214-001-A00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 261, 262)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 05-20-35	AFL	1800	+20/-20			280			
53-Z263-213-002-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 263 AND 264)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: AMM 05-20-36	AFL	3600	+20/-20			0			
53-Z263-214-001-A00	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 263 AND 264) (L600 ONLY)									
		MOS					16-DEC-2010			
		HRS/MSC	N/A				0			
	REF:	AFL					0			
53-Z263-214-001-A01 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 263 AND 264) NOTE:EWIS (L650 ONLY)						PKG			
	PKG 5016	MOS	96	+15d/-15d						
		HRS/MSC	7200	+20/-20						
LOW UTILIZATION	REF: AMM 05-20-36	AFL	3600	+20/-20						

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-Z271-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 271, 272)						PKG			
	PKG 5004	MOS	24	+15d/-15d			21-JAN-2017			
LOW UTILIZATION	REF: AMM 05-20-40	HRS/MSC AFL	1000	+20/-20			884.1 443			
53-Z271-214-001-A00	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 271, 272) (L600 ONLY)									
		MOS					16-DEC-2010			
	REF:	HRS/MSC AFL	N/A				0 0			
53-Z271-214-001-A01 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 271, 272) NOTE:EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-20-40	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
53-Z273-213-002-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 273 AND 274)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: AMM 05-20-44	HRS/MSC AFL	7200 3600	+20/-20 +20/-20			0 0			
53-Z273-214-002-A00	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 273 AND 274) (L600 ONLY)									
		MOS					16-DEC-2010			
	REF:	HRS/MSC AFL	N/A				0 0			
53-Z273-214-002-A01 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 273 AND 274) NOTE:EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-20-44	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
53-Z275-214-001-A00	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 275 AND 276) (L600 ONLY)									
		MOS								
ZONAL	REF:	HRS/MSC AFL	N/A							
53-Z275-214-001-A01 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 275 AND 276) NOTE:EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-20-41	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
53-Z311-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 311 AND 312)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-20-46	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
53-Z311-214-001-A00	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 311 AND 312) (L600 ONLY)	MOS						16-DEC-2010		
	REF:	HRS/MSC AFL	N/A					0 0		
53-Z311-214-001-A01 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 311 AND 312) NOTE:EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d				26-JAN-2015		
LOW UTILIZATION	REF: AMM 05-20-46	HRS/MSC AFL	3600 1800	+20/-20 +20/-20				532.4 280		
53-Z313-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONE 313)						PKG			
	PKG 5004	MOS	24	+15d/-15d				21-JAN-2017		
LOW UTILIZATION	REF: AMM 05-20-47	HRS/MSC AFL	1000	+20/-20				884.1 443		
53-Z313-214-001-A00	GENERAL VISUAL INSPECTION (INTERNAL) (ZONE 313) (L600 ONLY)	MOS						16-DEC-2010		
	REF:	HRS/MSC AFL	N/A					0 0		
53-Z313-214-001-A01 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONE 313) NOTE:EWIS (L650 ONLY)						PKG			
	PKG 5004	MOS	24	+15d/-15d				21-JAN-2017		
LOW UTILIZATION	REF: AMM 05-20-47	HRS/MSC AFL	1000	+20/-20				884.1 443		
53-Z315-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 315, 316, 317, 318)						PKG			
	PKG 5016	MOS	96	+15d/-15d				16-DEC-2010		
LOW UTILIZATION	REF: AMM 05-20-45	HRS/MSC AFL	7200 3600	+20/-20 +20/-20				0 0		
530401-0101	LH FAIRING ASSY									
	PN	MOS				TSN:0		16-DEC-2010		
	SN-UNKNOWN	HRS/MSC	O/C			TSN:0		0		
	REF: AMM 53-04-01	AFL				TSN:0		0		
530401-0102	RH FAIRING ASSY									
	PN	MOS				TSN:0		16-DEC-2010		
	SN-UNKNOWN	HRS/MSC	O/C			TSN:0		0		
	REF: AMM 53-04-01	AFL				TSN:0		0		
530410-0101	MID FAIRING ASSY									
	PN	MOS				TSN:0		16-DEC-2010		
	SN-UNKNOWN	HRS/MSC	O/C			TSN:0		0		
	REF: AMM 53-04-10	AFL				TSN:0		0		

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING	
530420-0101	LH FAIRING ASSY PN SN-UNKNOWN REF: AMM 53-04-20	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0				
530420-0102	RH FAIRING ASSY PN SN-UNKNOWN REF: AMM 53-04-20	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0				
530430-0101	FAIRING ASSY PN SN-UNKNOWN REF: AMM 53-04-30	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0				
531400-0101	RADOME ANTENNA 4980-101-V3 1315 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0				
531500-0101	CENTER FUSELAGE ASSY STRUCTURE 135-16140-403 0000641630 REF: AMM 53-04-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0				
533200-0101	REAR FUS ACCESS TAIL CONE 120-24234-043 0000628172 REF: AMM 53-32-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0				
533210-0101	SILENCER -EXHAUST,APU ASSEMBLY 4503801C 1114 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0				
533500-0101	TAIL LEADING EDGE,VERTICAL FIN ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0				
CHAPTER 54	NACELLES/PYLONS										
54-50-00-210-801-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF PYLON COMPONENTS: - PYLON SKIN (SSI 54-50-04)						PKG				
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015				
LOW UTILIZATION	REF: NDT 54-50-00	HRS/MSC	3600	+20/-20			532.4				
		AFL	1800	+20/-20			280				
54-50-00-220-802-L00	DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENT: - FWD ENGINE MOUNTS (INCLUDING BOLTS) (SSI 54-50-03) (L600 ONLY)										
		MOS					16-DEC-2010				
	REF: NDT 54-50-00	HRS/MSC	N/A				0				
		AFL					0				



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
54-50-00-220-803-L00	DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENTS: - PYLON SPARS I, II, III AND IV (SSI 54-50-01) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI (L600 ONLY)	MOS					16-DEC-2010			
STRUCTURAL	REF: NDT 54-50-00	HRS/MSC AFL	N/A				0 0			
54-50-00-220-804-L00 (s)	DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENTS: - PYLON SPARS I, II, III AND IV (SSI 54-50-01) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI. (L650 ONLY)						PKG			
LOW UTILIZATION	REF: NDT 54-50-00	PKG 5016 MOS HRS/MSC AFL	96 7200 3600	+15d/-15d +20/-20 +20/-20						
54-50-00-220-805-L00 (s)	DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENT: - FWD ENGINE MOUNTS (INCLUDING BOLTS) (SSI 54-50-03) (L650 ONLY)						PKG			
LOW UTILIZATION	REF: NDT 54-50-00	PKG 5008 MOS HRS/MSC AFL	48 3600 1800	+15d/-15d +20/-20 +20/-20			26-JAN-2015 532.4 280			
54-50-00-220-806-L00	DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENT: - AFT ENGINE MOUNTS (INCLUDING BOLTS) (SSI 54-50-07) (L600 ONLY)	MOS								
LOW UTILIZATION	REF: NDT 54-50-00	HRS/MSC AFL	N/A							
54-50-00-220-807-L00 (s)	DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENT: - AFT ENGINE MOUNTS (INCLUDING BOLTS) (SSI 54-50-07) (L650 ONLY)						PKG			
LOW UTILIZATION	REF: NDT 54-50-00	PKG 5008 MOS HRS/MSC AFL	48 3600 1800	+15d/-15d +20/-20 +20/-20			26-JAN-2015 532.4 280			
54-50-00-220-C01-L00 (s)	DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENTS: - PYLON YOKES III AND IV (SSI 54-50-02)						PKG			
LOW UTILIZATION	REF: CPM 54-50-00	PKG 5008 MOS HRS/MSC AFL	48 3600 1800	+15d/-15d +20/-20 +20/-20			26-JAN-2015 532.4 280			
54-50-00-220-C02-L00 (s)	DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENTS: - PYLON YOKES I AND II (SSI 54-50-05)						PKG			
LOW UTILIZATION	REF: CPM 54-50-00	PKG 5008 MOS HRS/MSC AFL	48 3600 1800	+15d/-15d +20/-20 +20/-20			26-JAN-2015 532.4 280			
54-50-00-220-C03-L00 (s)	DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENTS: - PYLON YOKES I AND II UPPER FLANGE (SSI 54-50-06).						PKG			
LOW UTILIZATION	REF: CPM 54-50-00	PKG 5008 MOS HRS/MSC AFL	48 3600 1800	+15d/-15d +20/-20 +20/-20			26-JAN-2015 532.4 280			
54-50-00-230-801-L00 (s)	SPECIAL DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENTS BY LIQUID PENETRANT INSPECTION METHOD: - FWD ENGINE MOUNTS (INCLUDING BOLTS) (SSI 54-50-03) (L650 ONLY)						PKG			
LOW UTILIZATION	REF: NDT 54-50-00	PKG 5032,5140 MOS HRS/MSC AFL	192 14400 7200	+15d/-15d +20/-20 +20/-20						

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
54-50-00-250-801-L00 (s)	SPECIAL DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENTS BY THE EDDY CURRENT METHOD: - PYLON YOKES I AND II (SSI 54-50-05)						PKG			
	PKG 5032,5140	MOS	288	+15d/-15d						
LOW UTILIZATION	REF: NDT 54-50-00	HRS/MSC AFL	12000 6000	+20/-20 +20/-20						
54-50-00-250-802-L00 (s)	SPECIAL DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENTS BY THE EDDY CURRENT METHOD: - PYLON YOKES I AND II UPPER FLANGE (SSI 54-50-06) NOTE: APPLICABLE TO AIRCRAFT PRE-MOD SB 145LEG-54-0001						PKG			
	PKG 5016	MOS	96	+15d/-15d						
LOW UTILIZATION	REF: NDT 54-50-00	HRS/MSC AFL	7200 3600	+20/-20 +20/-20						
54-50-00-250-802-L01 (s)	SPECIAL DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENTS BY THE EDDY CURRENT METHOD: - PYLON YOKES I AND II UPPER FLANGE (SSI 54-50-06) NOTE: APPLICABLE TO AIRCRAFT POST-MOD SB 145LEG-54-0001 OR WITH AN EQUIVALENT MODIFICATION FACTORY-INCORPORATED.						PKG			
	PKG 5024,5140	MOS	144	+15d/-15d						
LOW UTILIZATION	REF: NDT 54-50-00	HRS/MSC AFL	10800 5400	+20/-20 +20/-20						
54-50-00-290-801-L00 (s)	SPECIAL DETAILED INSPECTION (INTERNAL) OF PYLON COMPONENT USING BOROSCOPE: - PYLON SKIN (SSI 54-50-04) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI						PKG			
	PKG 5008	MOS	48				(EBT)			
LOW UTILIZATION	REF:	HRS/MSC AFL	3600 1800							
54-Z414-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 414 AND 424)						PKG			
	PKG 5004	MOS	24	+15d/-15d			21-JAN-2017			
LOW UTILIZATION	REF: AMM 05-20-72	HRS/MSC AFL	1000	+20/-20			884.1 443			
54-Z414-214-001-A00	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 414 AND 424) (L600 ONLY)						PKG			
		MOS					16-DEC-2010			
LOW UTILIZATION	REF:	HRS/MSC AFL	N/A				0 0			
54-Z414-214-001-A01 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 414 AND 424) NOTE:EWIS (L650 ONLY)						PKG			
	PKG 5004	MOS	24	+15d/-15d			21-JAN-2017			
LOW UTILIZATION	REF: AMM 05-20-72	HRS/MSC AFL	1000	+20/-20			884.1 443			
CHAPTER 55 STABILIZERS										
55-10-00-210-802-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS: - SKIN, FROM RIB STA. YH=350 TO RIB STA. YH=990 - UPPER SURFACE (SSI 55-10-07)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 55-10-00	HRS/MSC AFL	7200 3600	+20/-20 +20/-20			0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
55-10-00-210-805-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS: - SUPPORT PULLEY CENTRAL STA- BILIZER (SSI 55-10-14)									
	PKG 5032	MOS	192	+15d/-15d				?	?	?
		HRS/MSC	8000	+20/-20				?	?	?
LOW UTILIZATION	REF: NDT 55-10-00	AFL	4000	+20/-20				?	?	?
55-10-00-210-C01-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF HORIZON- TAL STABILIZER COMPONENTS: - U SHAPE, L SHAPE AND BOX STRUCTURE - ELEVATOR COMMAND (SSI 55-10-22)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: CPM 55-10-00	AFL	1800	+20/-20			280			
55-10-00-210-C02-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF HORIZON- TAL STABILIZER COMPONENTS: - SUPPORT QUADRANT ASSY, STABILIZER (SSI 55-10-23)						PKG			
	PKG 5009,5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	4000	+20/-20			0			
LOW UTILIZATION	REF: CPM 55-10-00	AFL	2000	+20/-20			0			
55-10-00-220-801-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS: - ELEVATOR SUPPORT FITTINGS (SSI 55-10-15)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: NDT 55-10-00	AFL	1800	+20/-20			280			
55-10-00-220-802-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS: - FITTING HINGE SUPPORT STABILIZER (SSI 55-10-21)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 55-10-00	AFL	3600	+20/-20			0			
55-10-00-220-803-L00 (s)	DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENT: - REAR SPAR WEB AND CAP, FROM FIN TO RIB STA. YH=350, INCLUDING CENTER FITTING/SPAR ATTACHMENT (SSI 55-10-12)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 55-10-00	AFL	3600	+20/-20			0			
55-10-00-220-804-L00 (s)	DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENTS: - ROOT RIB (SSI 55-10-17)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 55-10-00	AFL	3600	+20/-20			0			
55-10-00-220-805-L00	DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS: - SKIN, FROM FIN TO STA. YH=350 - LOWER SURFACE (SSI 55-10-06) - SKIN, FROM FIN TO STA. YH=350 - UPPER SURFACE (SSI 55-10-01) (L600 ONLY)						PKG			
	PKG 5016	MOS					16-DEC-2010			
		HRS/MSC	N/A				0			
STRUCTURAL	REF: NDT 55-10-00	AFL					0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
55-10-00-220-806-L00	DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENTS: - SKIN SPLICE AT UPPER AND LOWER SURFACE (SSI 55-10-16) - FRONT/ REAR AUXILIARY SPAR CENTER FITTING (SSI 55-10-19) - REAR SPAR CENTER FITTING (SSI 55-10-18) - FRONT SPAR CENTER FITTINGS (SSI 55-10-20) (L600 ONLY)	PKG 5016	MOS				16-DEC-2010	0	0	
STRUCTURAL	REF: NDT 55-10-00	HRS/MSC	N/A				0	0		
55-10-00-220-808-L00	DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS: - SKIN, FROM RIB STA YH=350 TO RIB YH=990 - UPPER SURFACE (SSI 55-10-02) (L600 ONLY)	PKG 5016	MOS				16-DEC-2010	0	0	
STRUCTURAL	REF: NDT 55-10-00	HRS/MSC	N/A				0	0		
55-10-00-220-809-L00	DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENTS: - FRONT AND REAR AUXILIARY SPAR WEBS AND CAPS, INCLUDING CENTER FIT- TING/SPAR ATTACHMENT (SSI 55-10-11) (L600 ONLY)	PKG 5016	MOS				16-DEC-2010	0	0	
STRUCTURAL	REF: NDT 55-10-00	HRS/MSC	N/A				0	0		
55-10-00-220-810-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS: - SKIN, FROM RIB STA. YH=990 TO RIB STA. YH=2965- UPPER SURFACE (SSI 55-10-03)	PKG 5016	MOS	96	+15d/-15d		26-JAN-2015	532.4	280	
LOW UTILIZATION	REF: NDT 55-10-00	HRS/MSC	4000		+20/-20		280			
55-10-00-220-811-L00 (s)	DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENTS: - RIBS, FROM RIB STA. YH=30 TO RIB STA. YH=990 (SSI 55-10-04) - RIBS, FROM RIB STA. YH=990 TO RIB STA. YH=2965 (SSI 55-10-05)	PKG 5016	MOS	96	+15d/-15d		16-DEC-2010	0	0	
LOW UTILIZATION	REF: NDT 55-10-00	HRS/MSC	7200		+20/-20		0	0		
55-10-00-220-812-L00	DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENTS: - FRONT SPAR WEB AND CAP, FROM RIB STA. YH=350 TO RIB STA. YH=2965 (SSI 55-10-10) (L600 ONLY)		MOS				26-JAN-2015	532.4	280	
STRUCTURAL	REF: NDT 55-10-00	HRS/MSC	N/A				280			
55-10-00-220-813-L00	DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENTS: - FRONT SPAR WEB AND CAP, FROM FIN TO RIB STA. YH=350, INCLUDING CENTER FITTING / SPAR ATTACHMENT (SSI 55-10-09) (L600 ONLY)		MOS				16-DEC-2010	0	0	
STRUCTURAL	REF: NDT 55-10-00	HRS/MSC	N/A				0	0		
55-10-00-220-814-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS: - SKIN, FROM FIN TO STA. YH=350 - LOWER SURFACE (SSI 55-10-06) - SKIN, FROM FIN TO STA. YH=350 - UPPER SURFACE (SSI 55-10-01) (L650 ONLY)	PKG 5008	MOS	48	+15d/-15d		26-JAN-2015	532.4	280	
LOW UTILIZATION	REF: NDT 55-10-00	HRS/MSC	3600		+20/-20		280			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
55-10-00-220-815-L00 (s)	DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENTS: - SKIN SPLICE AT UPPER AND LOWER SURFACE (SSI 55-10-16) - FRONT/ REAR AUXILIARY SPAR CENTER FITTING (SSI 55-10-19) - REAR SPAR CENTER FITTING (SSI 55-10-18) - FRONT SPAR CENTER FITTINGS (SSI 55-10-20) (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: NDT 55-10-00	AFL	1800	+20/-20			280			
55-10-00-220-816-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS: - SKIN, FROM RIB STA YH=350 TO RIB YH=990 - UPPER SURFACE (SSI 55-10-02) (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: NDT 55-10-00	AFL	1800	+20/-20			280			
55-10-00-220-817-L00	DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENTS: - FRONT AND REAR AUXILIARY SPAR WEBS AND CAPS, INCLUDING CENTER FITTING/SPAR ATTACHMENT (SSI 55-10-11) (L650 ONLY)									
	PKG 5032	MOS	192	+15d/-15d				?	?	?
		HRS/MSC	8000	+20/-20				?	?	?
LOW UTILIZATION	REF: NDT 55-10-00	AFL	4000	+20/-20				?	?	?
55-10-00-220-818-L00 (s)	DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENTS: - FRONT SPAR WEB AND CAP, FROM RIB STA. YH=350 TO RIB STA. YH=2965 (SSI 55-10-10) (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: NDT 55-10-00	AFL	1800	+20/-20			280			
55-10-00-220-C01-L00 (s)	DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENTS: - FRONT SPAR WEB AND CAP, FROM FIN TO RIB STA. YH=350, INCLUDING CENTER FITTING/ SPAR ATTACHMENT (SSI 55-10-09) - REAR SPAR WEB & CAP, FROM RIB STA. YH=350 TO RIB STA. YH=2965, INCLUDING FITTING HINGE STABILIZER ATTACH TO ELEVATOR (SSI 55-10-13)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: CPM 55-10-00	AFL	1800	+20/-20			280			
55-10-00-220-C02-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS: - SKIN, FROM RIB STA. YH=990 TO RIB STA. YH=2965- LOWER SURFACE (SSI 55-10-08)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: CPM 55-10-00	AFL	1800	+20/-20			280			
55-10-00-220-C03-L00 (s)	DETAILED INSPECTION (INTERNAL) OF HORIZONTAL STABILIZER COMPONENTS: - PIN, INTERNAL AND EXTERNAL HINGE, STABILIZER (SSI 55-10-24)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: CPM 55-10-00	AFL	1800	+20/-20			280			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
55-10-00-240-801-L00 (s)	SPECIAL DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS BY THE MAGNETIC PARTICLE INSPECTION METHOD: - PIN, INTERNAL AND EXTERNAL HINGE, STABILIZER (SSI 55-10-24)						PKG			
	PKG 5032,5140	MOS	288	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 55-10-00	HRS/MSC	12000	+20/-20			0			
		AFL	6000	+20/-20			0			
55-10-00-250-805-L00	SPECIAL DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD: - SKIN, FROM FIN TO STA. YH=350 - UPPER SURFACE (SSI 55-10-01) (L600 ONLY)									
		MOS					16-DEC-2010			
	REF: NDT 55-10-00	HRS/MSC	N/A				0			
		AFL					0			
55-10-00-250-806-L00	SPECIAL DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD: - SKIN, FROM RIB TO STA. YH=350 TO RIB YH=990 - UPPER SURFACE (SSI 55-10-02) (L600 ONLY)									
		MOS					16-DEC-2010			
STRUCTURAL	REF: NDT 55-10-00	HRS/MSC	N/A				0			
		AFL					0			
55-10-00-250-807-L00	SPECIAL DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD: - SKIN, FROM FIN TO STA. YH=350 - LOWER SURFACE (SSI 55-10-06) (L600 ONLY)									
		MOS					16-DEC-2010			
	REF: NDT 55-10-00	HRS/MSC	N/A				0			
		AFL					0			
55-10-00-250-808-L00	SPECIAL DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS BY USING EDDY CURRENT LOW FREQUENCY INSPECTION METHOD: - FRONT SPAR WEB AND CAP, FROM FIN TO RIB STA. YH=350, INCLUDING CENTER FITTING/SPAR ATTACHMENT (SSI 55-10-09). (L600 ONLY)						PKG			
	PKG 5016	MOS					16-DEC-2010			
	REF: NDT 55-10-00	HRS/MSC	N/A				0			
		AFL					0			
55-10-00-250-809-L00	SPECIAL DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS BY USING EDDY CURRENT LOW FREQUENCY INSPECTION METHOD: - FRONT AND REAR AUXILIARY SPAR WEBS AND CAPS, INCLUDING CENTER FITTING/SPAR ATTACHMENT (SSI 55-10-11) (L600 ONLY)						PKG			
	PKG 5016	MOS					16-DEC-2010			
	REF: NDT 55-10-00	HRS/MSC	N/A				0			
		AFL					0			
55-10-00-250-810-L00	SPECIAL DETAILED INSPECTION (EXTERNAL) OF HORIZONTAL STABILIZER COMPONENTS BY USING EDDY CURRENT LOW FREQUENCY INSPECTION METHOD: - REAR SPAR WEB AND CAP, FROM FIN TO RIB STA. YH=350, INCLUDING CENTER FITTING/SPAR ATTACHMENT (SSI 55-10-12) (L600 ONLY)						PKG			
	PKG 5016	MOS					16-DEC-2010			
	REF: NDT 55-10-00	HRS/MSC	N/A				0			
		AFL					0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
55-20-00-210-801-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF ELEVATOR COMPONENTS: - ELEVATOR HORN MASS BALANCE WEIGHTS AND ATTACHMENTS (SSI 55-20-90)						PKG			
	PKG 5008	MOS	48	+15d/-15d			21-JAN-2017			
LOW UTILIZATION	REF: NDT 55-20-00	HRS/MSC	2000	+20/-20			884.1			
		AFL	1000	+20/-20			443			
55-20-00-210-C01-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF ELEVATOR COMPONENTS: - SKIN, BETWEEN ROOT AND STA. YH=160 (SSI 55-20-26) - SKIN, BETWEEN STA. YH=160 AND STA. YH=3320 (SSI 55-20-28)						PKG			
	PKG 5009,5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: CPM 55-20-00	HRS/MSC	4000	+20/-20			0			
		AFL	2000	+20/-20			0			
55-20-00-210-C02-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF ELEVATOR COMPONENTS: - SPARS BETWEEN ROOT AND STA. YH=160 (SSI 55-20-25) - SPARS, BETWEEN STA. YH=160 AND STA. YH=3320 (SSI 55-20-27)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: CPM 55-20-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
55-20-00-210-C03-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF ELEVATOR COMPONENTS: - TAB (SSI 55-20-37)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: CPM 55-20-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
55-20-00-220-801-L00 (s)	DETAILED INSPECTION (INTERNAL) OF ELEVATOR COMPONENTS: - TORQUE TUBE FITTINGS (SSI 55-20-34) - TAB WHEEL DRIVE SUPPORT FITTINGS (SSI 55-20-35)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 55-20-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
55-20-00-220-802-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF ELEVATOR COMPONENTS: - TAB HINGE FITTINGS (SSI 55-20-36)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 55-20-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
55-20-00-220-C01-L00 (s)	DETAILED INSPECTION (INTERNAL) OF ELEVATOR COMPONENTS: - RIBS, BETWEEN ROOT AND STA. YH=160 (SSI 55-20-29) - RIBS, BETWEEN STA. YH=160 AND STA. YH=983.4 (SSI 55-20-30) - RIBS, BETWEEN STA. YH=3001 AND STA. YH=3320 (SSI 55-20-33)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: CPM 55-20-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
55-20-00-290-C01-L00 (s)	DETAILED INSPECTION (INTERNAL) OF ELEVATOR COMPONENTS USING A BOROSCOPE: - RIBS, BETWEEN STA. YH=983,4 AND STA. YH=1898 (SSI 55-20-31) - RIBS, BETWEEN STA. YH=1898 AND STA. YH=3001 (SSI 55-20-32)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: CPM 55-20-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
55-30-00-210-802-L00	GENERAL VISUAL INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS: - SPAR 2 (WEB AND CAP), FROM FUSELAGE CONTOUR LINE TO TIP RIB STA. ZV=3015 (SSI 55-30-67) - SPAR 1 (WEB AND CAP), FROM FUSELAGE CONTOUR LINE TO TIP RIB (SSI 55-30-68) (L600 ONLY)	MOS						16-DEC-2010		
STRUCTURAL	REF: NDT 55-30-00	HRS/MSC AFL	N/A					0 0		
55-30-00-210-804-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF VERTICAL STABILIZER COMPONENTS: - TRAILING EDGE RIBS (SSI 55-30-74)	MOS								PKG
	PKG 5016	HRS/MSC AFL	N/A							
REF: NDT 55-30-00										
55-30-00-210-C01-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF VERTICAL STABILIZER COMPONENTS: - SKIN AT WINDOWS FROM FUSELAGE TO STA. ZV=1169 (SSI 55-30-44)	MOS	96	+15d/-15d				16-DEC-2010		
	PKG 5009,5016	HRS/MSC AFL	4000 2000	+20/-20 +20/-20				0 0		
LOW UTILIZATION	REF: CPM 55-30-00									
55-30-00-210-C02-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF VERTICAL STABILIZER COMPONENTS: - SKIN AT SPAR 3, AUXILIARY SPAR 52%, AND STRINGERS 46.5% & 57.65%, BETWEEN FUSELAGE & RIB STA. ZV=1169 (SSI 55-30-39) - SKIN AT SPAR 3, AUXILIARY SPAR 52%, AND STRINGERS 46.5% & 57.65%, BETWEEN RIBS STA. ZV=1169 & STA. ZV=2799 (SSI 55-30-41) - SKIN AT SPAR 3, AUXILIARY SPAR 52%, AND STRINGERS 46.5% & 57.65%, BETWEEN RIB STA. ZV=2799 & HORIZONTAL STABILIZER (SSI 55-30-43) - SKIN AT WINDOWS BETWEEN STA. ZV=1169 & STA. ZV=2799 (SSI 55-30-45) - SKIN AT RIBS, BETWEEN STA. ZV=1169 AND STA. ZV=2799 (SSI 55-30-48) - SKIN AT RIBS, BETWEEN STA. ZV=2799 AND HORIZONTAL STABILIZER (SSI 55-30-49)	MOS	48	+15d/-15d				26-JAN-2015		
	PKG 5008	HRS/MSC AFL	3600 1800	+20/-20 +20/-20				532.4 280		
LOW UTILIZATION	REF: CPM 55-30-00									
55-30-00-210-C03-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF VERTICAL STABILIZER COMPONENTS: - SKIN AT RIBS FROM FUSELAGE TO STA. ZV=1169 (SSI 55-30-47)	MOS	96	+15d/-15d				16-DEC-2010		
	PKG 5009,5016	HRS/MSC AFL	4000 2000	+20/-20 +20/-20				0 0		
LOW UTILIZATION	REF: CPM 55-30-00									
55-30-00-210-C04-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS: - RIBS (STA. ZV=3461, ZV=2538, ZV=1677, ZV=1550.5, ZV=1430.5, ZV=1423, ZV=1302, ZV=1169 AND ZV=915) (SSI 55-30-73)	MOS	96	+15d/-15d				16-DEC-2010		
	PKG 5009,5016	HRS/MSC AFL	4000 2000	+20/-20 +20/-20				0 0		
LOW UTILIZATION	REF: CPM 55-30-00									

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
55-30-00-210-C05-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF VERTICAL STABILIZER COMPONENTS: - SKIN AT SPARS 1, 2, AUXIL- IARY SPAR 41% AND STRINGERS 20% & 35.5% BETWEEN FUSELAGE & RIB STA. ZV=1169 (SSI 55-30-38) - SKIN AT SPARS 1, 2, AUXIL- IARY SPAR 41% AND STRING- ERS 20% & 35.5% BETWEEN RIBS STA. ZV=1169 & STA. ZV=2799 (SSI 55-30-40) - SKIN AT SPARS 1, 2, AUXILIARY SPAR 41% AND STRINGERS 20% & 35.5% BETWEEN RIB STA. ZV=2799 & HORIZONTAL STABILIZER (SSI 55-30-42) - SKIN AT WINDOWS BETWEEN STA. ZV=2799 AND HORIZONTAL STABILIZER (SSI 55-30-46)						PKG			
	PKG 5009,5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: CPM 55-30-00	HRS/MSC	4000	+20/-20			0			
		AFL	2000	+20/-20			0			
55-30-00-220-801-L00 (s)	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS: - TIP RIB (SSI 55-30-69)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 55-30-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
55-30-00-220-802-L00	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS: - FIN-TO-FUSELAGE ATTACHMENT FITTING TO SPAR 1 (SSI 55-30-58) - FIN-TO-FUSELAGE ATTACHMENT FITTING TO BULKHEAD 77 (SSI 55-30-59) (L600 ONLY)									
		MOS					16-DEC-2010			
STRUCTURAL	REF: NDT 55-30-00	HRS/MSC	N/A				0			
		AFL					0			
55-30-00-220-804-L00	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS: - FITTING HINGE SUPPORT (SSI 55-30-76) (L600 ONLY)									
		MOS					16-DEC-2010			
STRUCTURAL	REF: NDT 55-30-00	HRS/MSC	N/A				0			
		AFL					0			
55-30-00-220-805-L00	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS: - FIN-TO-FUSELAGE ATTACH- MENT FITTING TO SPAR 3 (SSI 55-30-54) - FIN-TO-FUSELAGE ATTACH- MENT FITTING TO BULKHEAD 78 (SSI 55-30-60) - FIN-TO-FUSELAGE ATTACH- MENT FITTING TO BULKHEAD 79 (SSI 55-30-61) - FIN-TO-FUSELAGE ATTACH- MENT FITTING TO BULKHEAD 80 (SSI 55-30-62) - SPAR 41% (WEB AND CAP), FROM STA. ZV=1550.5, INCLUDING ATTACHMENT BOLTS (SSI 55-30-66) (L600 ONLY)									
		MOS					16-DEC-2010			
STRUCTURAL	REF: NDT 55-30-00	HRS/MSC	N/A				0			
		AFL					0			
55-30-00-220-806-L00	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS: - FIN-TO-FUSELAGE ATTACH- MENT FITTING TO AUXILIARY SPAR 52% (SSI 55-30-55) - FIN-TO-FUSELAGE ATTACH- MENT FITTING TO AUXILIARY SPAR 41% (SSI 55-30-56) - SPAR 3 (WEB AND CAP), FROM FUSELAGE CONTOUR LINE TO TIP RIB, INCLUDING ATTACHMENT BOLTS (SSI 55-30-63) - SPAR 52% (WEB AND CAP), FROM FUSELAGE CONTOUR LINE TO TIP RIB, INCLUDING ATTACHMENT BOLTS (SSI 55-30-64) - SPAR 41% (WEB AND CAP), FROM STA. ZV=2538 TO TIP RIB, INCLUDING ATTACHMENT BOLTS (SSI 55-30-65) - FIN-TO-HORIZONTAL STABILIZER SUPPORT ACTUATORS, INCLUDING BOLT (SSI 55-30-75) - ACTUATOR SUPPORT FITTINGS (RUDDER) (SSI 55-30-79) - PCU SUPPORT FITTINGS (SSI 55-30-80) (L600 ONLY)									
		MOS					16-DEC-2010			
STRUCTURAL	REF: NDT 55-30-00	HRS/MSC	N/A				0			
		AFL					0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
55-30-00-220-807-L00	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS: - FIN-TO-FUSELAGE ATTACH- MENT FITTING TO SPAR 2 (SSI 55-30-57) (L600 ONLY)	MOS						16-DEC-2010		
STRUCTURAL	REF: NDT 55-30-00	HRS/MSC AFL	N/A					0 0		
55-30-00-220-808-L00 (s)	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS: - SPAR 2 (WEB AND CAP), FROM FUSELAGE CONTOUR LINE TO TIP RIB STA. ZV=3015 (SSI 55-30-67) - SPAR 1 (WEB AND CAP), FROM FUSELAGE CONTOUR LINE TO TIP RIB (SSI 55-30-68) (L650 ONLY)	MOS	96	+15d/-15d			PKG			
LOW UTILIZATION	REF: NDT 55-30-00	HRS/MSC AFL	7200 3600	+20/-20 +20/-20						
55-30-00-220-809-L00 (s)	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS: - FIN-TO-FUSELAGE ATTACHMENT FITTING TO SPAR 1 (SSI 55-30-58) - FIN-TO-FUSELAGE ATTACHMENT FITTING TO BULKHEAD 77 (SSI 55-30-59) (L650 ONLY)	MOS	96	+15d/-15d			PKG			
LOW UTILIZATION	REF: NDT 55-30-00	HRS/MSC AFL	7200 3600	+20/-20 +20/-20						
55-30-00-220-810-L00 (s)	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS: - FITTING HINGE SUPPORT (SSI 55-30-76) (L650 ONLY)	MOS	48	+15d/-15d			PKG			
LOW UTILIZATION	REF: NDT 55-30-00	HRS/MSC AFL	3600 1800	+20/-20 +20/-20				26-JAN-2015 532.4 280		
55-30-00-220-811-L00 (s)	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS: - FIN-TO-FUSELAGE ATTACHMENT FITTING TO SPAR 3 (SSI 55-30-54) - FIN-TO-FUSELAGE ATTACHMENT FITTING TO BULKHEAD 78 (SSI 55-30-60) - FIN-TO-FUSELAGE ATTACHMENT FITTING TO BULKHEAD 79 (SSI 55-30-61) - FIN-TO-FUSELAGE ATTACHMENT FITTING TO BULKHEAD 80 (SSI 55-30-62) - SPAR 41% (WEB AND CAP), FROM STA. ZV=1550.5, INCLUDING ATTACHMENT BOLTS (SSI 55-30-66) (L650 ONLY)	MOS	96	+15d/-15d			PKG			
LOW UTILIZATION	REF: NDT 55-30-00	HRS/MSC AFL	7200 3600	+20/-20 +20/-20						
55-30-00-220-812-L00	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS: - FIN-TO-FUSELAGE ATTACHMENT FITTING TO AUXILIARY SPAR 52% (SSI 55-30-55) - FIN-TO-FUSELAGE ATTACH- MENT FITTING TO AUXILIARY SPAR 41% (SSI 55-30-56) - SPAR 3 (WEB AND CAP), FROM FUSELAGE CONTOUR LINE TO TIP RIB, INCLUDING ATTACH- MENT BOLTS (SSI 55-30-63) - SPAR 52% (WEB AND CAP), FROM FUSELAGE CONTOUR LINE TO TIP RIB, INCLUDING ATTACH- MENT BOLTS (SSI 55-30- 64) - SPAR 41% (WEB AND CAP), FROM STA. ZV=2538 TO TIP RIB, INCLUDING ATTACHMENT BOLTS (SSI 55-30-65) - FIN-TO-HORIZONTAL STABILIZER SUPPORT ACTUATORS, INCLUD- ING BOLT (SSI 55-30-75) - ACTUATOR SUPPORT FITTINGS (RUDDER) (SSI 55-30-79) - PCU SUPPORT FITTINGS (SSI 55-30-80) (L650 ONLY)	MOS	144	+15d/-15d			PKG			
LOW UTILIZATION	REF: NDT 55-30-00	HRS/MSC AFL	6000 3000	+20/-20 +20/-20				16-DEC-2010 0 0	16-DEC-2022 6000 3000	31-DEC-2022 2076 d (+15) 5096.7 (+20) 2550 (+20)
55-30-00-220-813-L00 (s)	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS: - FIN-TO-FUSELAGE ATTACHMENT FITTING TO SPAR 2 (SSI 55-30-57) (L650 ONLY)	MOS	144	+15d/-15d			PKG			
LOW UTILIZATION	REF: NDT 55-30-00	HRS/MSC AFL	6000 3000	+20/-20 +20/-20						

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
55-30-00-220-C01-L00 (s)	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS: - ROOT RIB, INCLUDING BOLTS (SSI 55-30-70) - RIBS OF ACTUATOR AREA (STA. ZV=1932 AND ZV=2277) (SSI 55-30-72)						PKG			
	PKG 5009,5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: CPM 55-30-00	HRS/MSC	4000	+20/-20			0			
		AFL	2000	+20/-20			0			
55-30-00-220-C02-L00 (s)	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS: - RIBS OF HORIZONTAL STABILIZER ACTUATORS (STA. ZV=3145, ZV=3015 AND ZV=2799) (SSI 55-30-71) - REAR SPAR ACTUATOR SUPPORT FITTING (ELEVA- TOR) (SSI 55-30-77)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: CPM 55-30-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
55-30-00-220-C03-L00 (s)	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS: - SPAR 1 - TIP RIB ATTACH- MENT (SSI 55-30-53)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: CPM 55-30-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
55-30-00-220-C04-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF VERTICAL STABILIZER COMPONENTS: - RUDDER HINGE FITTINGS (SSI 55-30-78)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: CPM 55-30-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
55-30-00-220-C05-L00 (s)	DETAILED INSPECTION (INTERNAL) OF VERTICAL STABILIZER COMPONENTS: - FIN-TO-HORIZONTAL STABILIZER ATTACHMENT FITTING TO SPAR 3 (SSI 55-30-50) - FIN-TO-HORIZONTAL STABILIZER ATTACHMENT FITTING TO AUXILIARY SPAR 52% (SSI 55-30-51) - FIN-TO-HORIZONTAL STABILIZER ATTACHMENT FITTING TO AUXILIARY SPAR 41% (SSI 55-30-52)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: CPM 55-30-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
55-30-00-250-801-L00 (s)	SPECIAL DETAILED INSPECTION (EXTERNAL) OF VERTICAL STABILIZER COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD: - FITTING HINGE SUPPORT (SSI 55-30-76)						PKG			
	PKG 5032,5140	MOS	288	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 55-30-00	HRS/MSC	12000	+20/-20			0			
		AFL	6000	+20/-20			0			
55-40-00-210-C01-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF RUDDER COMPONENTS: - FRONT SPAR - SKIN ATTACHMENT (RUDDER I) (SSI 55-40-81) - REAR SPAR - SKIN ATTACHMENT (RUDDER I) (SSI 55-40-82) - LT & RT SKIN - SPAR CAP ATTACHMENT (RUDDER I) (SSI 55-40-83) - RIBS - SKIN ATTACHMENT (RUDDER I) (SSI 55-40-84) - HINGES - RUDDER I (SSI 55-40-85)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: CPM 55-40-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
55-40-00-210-C02-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF RUDDER COMPONENTS: - SPAR - SKIN ATTACHMENT (RUDDER II) (SSI 55-40-86) - LT & RT SKIN - SPAR CAP ATTACHMENT (RUDDER II) (SSI 55-40-87) - RIBS - SKIN ATTACHMENT (RUDDER II) (SSI 55-40-88) - HINGES - RUDDER II (SSI 55-40-89)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: CPM 55-40-00	AFL	1800	+20/-20			280			
55-40-00-220-C01-L00 (s)	DETAILED INSPECTION (INTERNAL) OF RUDDER COMPONENTS: - FRONT SPAR - SKIN ATTACHMENT (RUDDER I) (SSI 55-40-81) - REAR SPAR - SKIN ATTACHMENT (RUDDER I) (SSI 55-40-82) - LT & RT SKIN - SPAR CAP ATTACHMENT (RUDDER I) (SSI 55-40-83) - RIBS - SKIN ATTACHMENT (RUDDER I) (SSI 55-40-84) - HINGES - RUDDER I (SSI 55-40-85)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: CPM 55-40-00	AFL	1800	+20/-20			280			
55-40-00-220-C02-L00 (s)	DETAILED INSPECTION (INTERNAL) OF RUDDER COMPONENTS: - SPAR - SKIN ATTACHMENT (RUDDER II) (SSI 55-40-86) - LT & RT SKIN - SPAR CAP ATTACHMENT (RUDDER II) (SSI 55-40-87) - RIBS - SKIN ATTACHMENT (RUDDER II) (SSI 55-40-88) - HINGES - RUDDER II (SSI 55-40-89)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: CPM 55-40-00	AFL	1800	+20/-20			280			
55-Z321-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 321, 322, 323)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 05-20-65	AFL	1800	+20/-20			280			
55-Z321-214-001-A00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 321, 322, 323, 337)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 05-20-65	AFL	1800	+20/-20			280			
55-Z324-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 324, 325)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: AMM 05-20-58	AFL	1800	+20/-20			280			
55-Z324-214-001-A00	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 324, 325) (L600 ONLY)									
		MOS					16-DEC-2010			
		HRS/MSC	N/A				0			
	REF:	AFL					0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
55-Z324-214-001-A01 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 324, 325) NOTE:EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-20-58	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
55-Z326-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 326, 327)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-20-48	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
55-Z326-214-001-A00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 326, 327)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-20-48	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
55-Z333-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 331, 332, 333, 334)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-20-52	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
55-Z333-214-001-A00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 331, 332, 333, 334)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-20-52	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
55-Z335-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONE 335, 336)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-20-62	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
55-Z335-214-001-A00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONE 335, 336)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-20-62	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
551500-0101	LEFT LEADING EDGE HORIZ STABILIZER ASSEMBLY									
	PN	MOS				TSN:0	16-DEC-2010			
	SN-UNKNOWN	HRS/MSC	O/C			TSN:0	0			
	REF: AMM 55-15-00	AFL				TSN:0	0			
551500-0102	RIGHT LEADING EDGE HORIZ STABILIZER ASSEMBLY									
	PN	MOS				TSN:0	16-DEC-2010			
	SN-UNKNOWN	HRS/MSC	O/C			TSN:0	0			
	REF: AMM 55-15-00	AFL				TSN:0	0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
551500-0201	LH FAIRING ASSY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
551500-0202	RH FAIRING ASSY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
551500-0301	LH FAIRING ASSY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
551500-0302	RH FAIRING ASSY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
553400-0101	REAR FUS DORSAL FIN ASSY 145-26756-407 0000636027 REF: AMM 55-34-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
553600-0101	FRONT FIXED FAIRING ASSY PN SN-UNKNOWN REF: AMM 55-36-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
553600-0102	REAR FIXED FAIRING ASSY 145-21646-403 0000637528 REF: AMM 55-36-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
553600-0103	FRONT MOVING FAIRING ASSY 145-21644-401 0000642079 REF: AMM 55-36-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
553600-0104	REAR MOVING FAIRING ASSY 145-03535-409 0000639867 REF: AMM 55-36-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
CHAPTER 56	WINDOWS									
56-10-01-220-001-A00 (s)	INSPECT (DETAILED INSPECTION) THE WINDSHIELD HUMP SEAL PKG 5001	MOS HRS/MSC AFL	6 450	+15d/-15d +20/-20			PKG 21-JAN-2017 884.1 443			
LOW UTILIZATION	REF: AMM 56-10-01									

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
56-10-01-720-001-A00	FUNCTIONALLY CHECK TORQUE OF WINDSHIELD ATTACHING BOLTS NOTE: APPLICABLE TO AIRCRAFT PRE-MOD. SB 145LEG-56-0001 (L600 ONLY)	MOS						16-DEC-2010		
EMB-RECOMM	REF:	HRS/MSC	N/A				0			
		AFL					0			
56-10-01-720-001-A01	FUNCTIONAL CHECK LEFT ELECTRICALLY HEATED, WITH RRC - FRONTAL WINDSHIELD - TORQUE OF WINDSHIELD ATTACHING BOLTS	MOS						07-FEB-2015		
	NP-151311-17	HRS/MSC	10000				548.9		10548.9	9645.6
EMB-RECOMM	REF: AMM 56-10-01	AFL					287			
56-10-01-720-001-A01	FUNCTIONAL CHECK RIGHT ELECTRICALLY HEATED, WITH RRC - FRONTAL WINDSHIELD - TORQUE OF WINDSHIELD ATTACHING BOLTS	MOS						07-FEB-2015		
	NP-151311-18	HRS/MSC	10000				548.9		10548.9	9645.6
EMB-RECOMM	REF: AMM 56-10-01	AFL					287			
561000-0101	LEFT ELECTRICALLY HEATED, WITH RRC - FRONTAL WINDSHIELD	MOS						16-DEC-2010		
	NP-151311-17	HRS/MSC	O/C		TSN:0		0			
	10182H2046	AFL			TSN:0		0			
REF:	AMM 56-10-01				TSN:0		0			
561000-0102	RIGHT ELECTRICALLY HEATED, WITH RRC - FRONTAL WINDSHIELD	MOS						16-DEC-2010		
	NP-151311-18	HRS/MSC	O/C		TSN:0		0			
	10181H1777	AFL			TSN:0		0			
REF:	AMM 56-10-01				TSN:0		0			
561100-0101	PILOT FITTING -MECHANISM,STORM WINDOW ASSEMBLY	MOS						16-DEC-2010		
	120-42177-515	HRS/MSC	O/C		TSN:0		0			
	0000640840	AFL			TSN:0		0			
REF:					TSN:0		0			
561100-0102	COPILOT FITTING -MECHANISM,STORM WINDOW ASSEMBLY	MOS						16-DEC-2010		
	120-42177-516	HRS/MSC	O/C		TSN:0		0			
	0000640843	AFL			TSN:0		0			
REF:					TSN:0		0			
CHAPTER 57	WINGS									
57-01-00-220-C01-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS: - WING STUB - LOWER SKIN - RIB 2A ATTACHMENT (SSI 57-01-15) - WING STUB - SPAR 2 - BRACKETS RIBS 2A ATTACHMENTS (SSI 57-01-17) - WING STUB - SPAR 1 - BRACKETS RIBS 2A ATTACHMENTS (SSI 57-01-16)									PKG
	PKG 5016	MOS	96	+15d/-15d				16-DEC-2010		
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: CPM 57-01-00	AFL	3600	+20/-20			0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-01-00-220-C02-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS: - WING STUB - RIB 2A SKIN SUPPORTS AND THEIR ATTACHMENTS TO WEB, LOWER FLANGE, AND FWD & AFT WEB SUPPORTS (SSI 57-01-18) - WING STUB - UPPER SKIN - RIB 2A ATTACHMENTS (SSI 57-01-19)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: CPM 57-01-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
57-01-00-220-C03-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS: - WING STUB - LOWER SKIN - RIB 2A ATTACHMENT (SSI 57-01-15)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: CPM 57-01-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
57-01-00-220-C04-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS: - WING STUB - UPPER SKIN - RIB 2A ATTACHMENTS (SSI 57-01-19)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: CPM 57-01-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
57-10-00-210-801-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING STUB COMPONENTS: - SPAR 2 - BRACKETS AND RIB 2A WEB ATTACHMENTS (SSI 57-10-27)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 57-10-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
57-10-00-210-C01-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING STUB COMPONENTS: - UPPER SKIN - TIRE COMPARTMENT COMPOSITE PANEL (SSI 57-10-14)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: CPM 57-10-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
57-10-00-220-801-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS: - SPAR 1 - AUXILIARY CAP ATTACHMENTS & AUXILIARY CAP SPLICE AT WING ATTACHMENTS (SSI 57-10-05) - LOWER SKIN - RIBS 1, 2 & 3 ATTACHMENTS AND TIRE COMPARTMENT WALL ATTACHMENTS (SSI 57-10-02) - SPAR 1 - LOWER SKIN ATTACHMENTS (SSI 57-10-03) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THESE SSIS						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: NDT 57-10-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
57-10-00-220-802-L00	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS: - SPAR 2 - BRACKETS AND RIB 2A WEB ATTACHMENTS (SSI 57-10-27) - SPAR 1 - LOWER SKIN ATTACHMENTS (SSI 57-10-03) - SPAR 1 - AUXILIARY CAP ATTACHMENTS & AUXILIARY CAP SPLICE AT WING ATTACHMENTS (SSI 57-10-05) (L600 ONLY)									
		MOS					16-DEC-2010			
STRUCTURAL	REF: NDT 57-10-00	HRS/MSC	N/A				0			
		AFL					0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-10-00-220-803-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS: - LOWER SKIN - RIBS 1, 2 & 3 ATTACHMENTS AND TIRE COMPARTMENT WALL ATTACHMENTS (SSI 57-10-02) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: NDT 57-10-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
57-10-00-220-804-L00	DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS: - LOWER SKIN - SPANWISE SPLICE AT SPAR 2, ACCESS HOLES, STRINGERS, INTEGRAL MILLED PANELS & SPANWISE SPLICE OF INTEGRAL PANEL (SSI 57-10-01) - SPAR 2 - LOWER SKIN ATTACHMENTS (SSI 57-10-06) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI _L S (L600 ONLY)									
		MOS					16-DEC-2010			
STRUCTURAL	REF: NDT 57-10-00	HRS/MSC	N/A				0			
		AFL					0			
57-10-00-220-805-L00	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS: - LOWER SKIN - SPANWISE SPLICE AT SPAR 2, ACCESS HOLES, STRINGERS, INTEGRAL MILLED PANELS & SPANWISE SPLICE OF INTEGRAL PANEL (SSI 57-10-01) - SPAR 2 - LOWER SKIN ATTACHMENTS (SSI 57-10-06) - SPAR 2 - AUXILIARY CAP ATTACHMENTS AND AUXILIARY CAP SPLICE AT WING ATTACHMENTS (SSI 57-10-08) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI _L S 57-10-06 AND 57-10-08 (L600 ONLY)									
		MOS					16-DEC-2010			
STRUCTURAL	REF: NDT 57-10-00	HRS/MSC	N/A				0			
		AFL					0			
57-10-00-220-806-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS: - SPAR 2 - BRACKETS AND RIB 2A WEB ATTACHMENTS (SSI 57-10-27) - SPAR 1 - LOWER SKIN ATTACHMENTS (SSI 57-10-03) - SPAR 1 - AUXILIARY CAP ATTACHMENTS & AUXILIARY CAP SPLICE AT WING ATTACHMENTS (SSI 57-10-05) (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: NDT 57-10-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
57-10-00-220-807-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS: - LOWER SKIN - SPANWISE SPLICE AT SPAR 2, ACCESS HOLES, STRINGERS, INTEGRAL MILLED PANELS & SPANWISE SPLICE OF INTEGRAL PANEL (SSI 57-10-01) - SPAR 2 - LOWER SKIN ATTACHMENTS (SSI 57-10-06) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI _L S (L650 ONLY)						PKG			
	PKG 5012	MOS	72	+15d/-15d			21-JAN-2017			
LOW UTILIZATION	REF: NDT 57-10-00	HRS/MSC	5400	+20/-20			884.1			
		AFL	2700	+20/-20			443			
57-10-00-220-808-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS: - LOWER SKIN - SPANWISE SPLICE AT SPAR 2, ACCESS HOLES, STRINGERS, INTEGRAL MILLED PANELS & SPANWISE SPLICE OF INTEGRAL PANEL (SSI 57-10-01) - SPAR 2 - LOWER SKIN ATTACHMENTS (SSI 57-10-06) - SPAR 2 - AUXILIARY CAP ATTACHMENTS AND AUXILIARY CAP SPLICE AT WING ATTACHMENTS (SSI 57-10-08) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI _L S 57-10-06 AND 57-10-08 (L650 ONLY)						PKG			
	PKG 5012	MOS	72	+15d/-15d			21-JAN-2017			
LOW UTILIZATION	REF: NDT 57-10-00	HRS/MSC	5400	+20/-20			884.1			
		AFL	2700	+20/-20			443			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-10-00-220-C01-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS: - SPAR 1 - BRACKETS, RIBS 1 AND 3 ATTACHMENTS (SSI 57-10-04) - SPAR 2 - CENTER BRACKETS & RIB 2 ATTACHMENTS AND RIBS 1 & 3 WEB ATTACHMENTS (SSI 57-10-07)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: CPM 57-10-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
57-10-00-220-C02-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS: - UPPER SKIN - RIB 1 ATTACHMENTS AND SPANWISE SPLICE OF INTEGRAL PANEL (SSI 57-10-13)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: CPM 57-10-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
57-10-00-220-C03-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS: - RIB 4 - LOWER FLANGE AND WEB (SSI 57-10-11)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: CPM 57-10-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
57-10-00-220-C04-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS: - SPAR 3 - LOWER SKIN ATTACHMENTS (SSI 57-10-09)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: CPM 57-10-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
57-10-00-220-C05-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS: - SPAR 3 - LOWER SKIN ATTACHMENTS (SSI 57-10-09) - UPPER SKIN - TIRE COMPARTMENT COMPOSITE PANEL (SSI 57-10-14)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: CPM 57-10-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
57-10-00-220-C06-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS: - UPPER SKIN - RIB 1 ATTACHMENTS AND SPANWISE SPLICE OF INTEGRAL PANEL (SSI 57-10-13)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: CPM 57-10-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
57-10-00-220-C07-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS: - RIB 4 - LOWER FLANGE AND WEB (SSI 57-10-11) - RIB 2 - LONGITUDINAL STRINGER- TO- WEB ATTACHMENTS (SSI 57-10-12)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: CPM 57-10-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
57-10-00-220-C08-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS: - SPAR 3 - CENTER BRACKET AND RIB 2 ATTACHMENTS (SSI 57-10-10)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: CPM 57-10-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-10-00-250-803-L00	SPECIAL DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS BY THE ULTRA- SONIC INSPECTION METHOD: - LOWER SKIN - SPANWISE SPLICE AT SPAR 2, ACCESS HOLES, STRINGERS, INTEGRAL MILLED PANELS & SPANWISE SPLICE OF INTEGRAL PANEL (SSI 57-10-01) (L600 ONLY)	MOS					16-DEC-2010			
STRUCTURAL	REF: NDT 57-10-00	HRS/MSC AFL	N/A				0 0			
57-11-00-220-801-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS: - LOWER SKIN - REAR FITTING-TO- SKIN ATTACHMENTS AND SPARS 1 & 2 - STUB- TO- WING ATTACHMENTS (SSI 57-11-17) - FUSELAGE BULKHEAD AT FRAME 50 AND ITS ATTACH- MENTS TO FRAME 50 (SSI 57-11-25) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THESE SSIS	PKG 5016	MOS	96	+15d/-15d		16-DEC-2010			
LOW UTILIZATION	REF: NDT 57-11-00	HRS/MSC AFL	7200 3600	+20/-20 +20/-20			0 0			
57-11-00-220-802-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS: - LOWER SKIN - REAR FITTING-TO- SKIN ATTACHMENTS AND SPARS 1 & 2 - STUB-TO-WING ATTACHMENTS (SSI 57-11-17) - FUSELAGE BULKHEAD AT FRAME 50 AND ITS ATTACHMENTS TO FRAME 50 (SSI 57-11-25) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR SSI 57-11-25	PKG 5016	MOS	96	+15d/-15d		16-DEC-2010			
LOW UTILIZATION	REF: NDT 57-11-00	HRS/MSC AFL	7200 3600	+20/-20 +20/-20			0 0			
57-11-00-220-803-L00	DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS: - SPAR 1 - LOWER FRONT FITTING ATTACHMENTS AND SPAR 2 - LOWER REAR FITTING ATTACH- MENTS (SSI 57-11-18) - SPAR 2 - TITANIUM FITTING ATTACHMENTS AND FUSELAGE BULKHEAD AT FRAME 46 (SSI 57-11-20) - SPAR 3 - FUSELAGE BULKHEAD ATTACHMENTS AT FRAME 50, L- SHAPE FUSELAGE FRAME 50 ATTACHMENTS & FUSELAGE STRINGERS ATTACH- MENTS (SSI 57-11-21) - SPAR 1 - TITANIUM FITTING ATTACHMENTS, FUSELAGE BULKHEAD ATTACHMENTS AT FRAME 40, L SHAPE FUSE- LAGE FRAME 40 ATTACHMENTS & FUSELAGE STRINGERS (SSI 57-11-19) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR SSIS 57-11-18 AND 57-11-20 (L600 ONLY)	MOS					16-DEC-2010			
STRUCTURAL	REF: NDT 57-11-00	HRS/MSC AFL	N/A				0 0			
57-11-00-220-805-L00	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS: - SPAR 1 - TITANIUM FITTING ATTACHMENTS, FUSELAGE BULKHEAD ATTACHMENTS AT FRAME 40, L SHAPE FUSELAGE FRAME 40 ATTACHMENTS & FUSELAGE STRINGERS ATTACHMENTS (SSI 57-11-19) - SPAR 3 - FUSELAGE BULKHEAD ATTACHMENTS AT FRAME 50, SHALL L- SHAPE FUSELAGE FRAME 50 ATTACHMENTS & FUSELAGE STRINGERS ATTACHMENTS (SSI 57-11-21) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR SSI 57-11-21	PKG 5032	MOS	192	+15d/-15d		16-DEC-2010	16-DEC-2026	31-DEC-2026	3537 d (+15)
LOW UTILIZATION	REF: NDT 57-11-00	HRS/MSC AFL	8000 4000	+20/-20 +20/-20			0 0	8000 4000	8020 4020	7096.7 (+20) 3550 (+20)
57-11-00-220-806-L00	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS: - SPAR 1 - LOWER FRONT FITTING ATTACHMENTS AND SPAR 2 -LOWER REAR FITTING ATTACHMENTS (SSI 57-11-18) - SPAR 2 - TITANIUM FITTING ATTACHMENTS AND FUSELAGE BULKHEAD AT FRAME 46 (SSI 57-11-20) (L600 ONLY)	MOS					16-DEC-2010			
STRUCTURAL	REF: NDT 57-11-00	HRS/MSC AFL	N/A				0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-11-00-220-807-L00	DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS: - SPAR 3 AND RIB 4 - ROD-END LINK (SSI 57-11-22) - FUSELAGE BULKHEAD AT FRAME 40 AND ITS ATTACHMENTS TO FRAME (SSI 57-11-23) - FUSELAGE BULKHEAD ATTACHMENT TO FRAME 46 (SSI 57-11-24) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THESE SSIS (L600 ONLY)	MOS					16-DEC-2010			
STRUCTURAL	REF: NDT 57-11-00	HRS/MSC AFL	N/A				0 0			
57-11-00-220-808-L00	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS: - FUSELAGE BULKHEAD AT FRAME 40 AND ITS ATTACHMENTS TO FRAME 40 (SSI 57-11-23) - FUSELAGE BULKHEAD ATTACHMENT TO FRAME 46 (SSI 57-11-24) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR SSI 57-11-24 (L600 ONLY)	MOS					16-DEC-2010			
STRUCTURAL	REF: NDT 57-11-00	HRS/MSC AFL	N/A				0 0			
57-11-00-220-809-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS: - SPAR 1 - LOWER FRONT FITTING ATTACHMENTS AND SPAR 2 - LOWER REAR FITTING ATTACHMENTS (SSI 57-11-18) - SPAR 2 - TITANIUM FITTING ATTACHMENTS AND FUSELAGE BULKHEAD AT FRAME 46 (SSI 57-11-20) - SPAR 3 - FUSELAGE BULKHEAD ATTACHMENTS AT FRAME 50, L-SHAPE FUSELAGE FRAME 50 ATTACHMENTS & FUSELAGE STRINGERS ATTACHMENTS (SSI 57-11-21) - SPAR 1 - TITANIUM FITTING ATTACHMENTS, FUSELAGE BULKHEAD ATTACHMENTS AT FRAME 40, L-SHAPE FUSELAGE FRAME 40 ATTACHMENTS & FUSELAGE STRINGERS (SSI 57-11-19) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR SSIS 57-11-18 AND 57-11-20 (L650 ONLY)	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 57-11-00	HRS/MSC AFL	7200 3600	+20/-20 +20/-20			0 0			
57-11-00-220-810-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS: - SPAR 1 - LOWER FRONT FITTING ATTACHMENTS AND SPAR 2 - LOWER REAR FITTING ATTACHMENTS (SSI 57-11-18) - SPAR 2 - TITANIUM FITTING ATTACHMENTS AND FUSELAGE BULKHEAD AT FRAME 46 (SSI 57-11-20) (L650 ONLY)	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 57-11-00	HRS/MSC AFL	7200 3600	+20/-20 +20/-20			0 0			
57-11-00-220-811-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF WING STUB COMPONENTS: - SPAR 3 AND RIB 4 - ROD-END LINK (SSI 57-11-22) - FUSELAGE BULKHEAD AT FRAME 40 AND ITS ATTACHMENTS TO FRAME (SSI 57-11-23) - FUSELAGE BULKHEAD ATTACHMENT TO FRAME 46 (SSI 57-11-24) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THESE SSIS (L650 ONLY)	MOS	72	+15d/-15d			21-JAN-2017			
LOW UTILIZATION	REF: NDT 57-11-00	HRS/MSC AFL	5400 2700	+20/-20 +20/-20			884.1 443			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-11-00-220-812-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS: - FUSELAGE BULKHEAD AT FRAME 40 AND ITS ATTACHMENTS TO FRAME 40 (SSI 57-11-23) - FUSELAGE BULKHEAD ATTACHMENT TO FRAME 46 (SSI 57-11-24) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR SSI 57-11-24 (L650 ONLY)						PKG			
	PKG 5024	MOS	144	+15d/-15d			21-JAN-2017			
		HRS/MSC	6000	+20/-20			884.1			
LOW UTILIZATION	REF: NDT 57-11-00	AFL	3000	+20/-20			443			
57-11-00-250-801-L00 (s)	SPECIAL DETAILED INSPECTION (INTERNAL) OF WING STUB COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD: - LOWER SKIN - REAR FITTING-TO- SKIN ATTACHMENTS AND SPARS 1 & 2 - STUB-TO-WING ATTACHMENTS (SSI 57-11-17)						PKG			
	PKG 5032,5140	MOS	288	+15d/-15d			16-DEC-2010			
		HRS/MSC	12000	+20/-20			0			
LOW UTILIZATION	REF: NDT 57-11-00	AFL	6000	+20/-20			0			
57-21-00-210-801-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - LOWER SKIN/SPAR ATTACH- MENTS (SSI 57-21-36)						PKG			
	PKG 5008	MOS	48	+15d/-15d			21-JAN-2017			
		HRS/MSC	2000	+20/-20			884.1			
LOW UTILIZATION	REF: NDT 57-21-00	AFL	1000	+20/-20			443			
57-21-00-210-806-L00	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS: - UPPER SKIN/SPAR ATTACH- MENT (SSI 57-21-37) (L600 ONLY)									
		MOS					16-DEC-2010			
		HRS/MSC	N/A				0			
STRUCTURAL	REF: NDT 57-21-00	AFL					0			
57-21-00-210-809-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS: - LOWER SKIN ACCESS HOLES (SSI 57-21-32)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 57-21-00	AFL	3600	+20/-20			0			
57-21-00-210-812-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - LOWER SKIN PANEL SPANWISE JOINT (SSI 57-21-30) - UPPER SKIN PANEL SPANWISE JOINT (SSI 57-21-31) - UPPER SKIN/SPAR ATTACHMENT (SSI 57-21-37)						PKG			
	PKG 5008	MOS	48	+15d/-15d			21-JAN-2017			
		HRS/MSC	2000	+20/-20			884.1			
LOW UTILIZATION	REF: NDT 57-21-00	AFL	1000	+20/-20			443			
57-21-00-210-813-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS: - LOWER SKIN PANEL CHORD- WISE JOINT (SSI 57-21-29) - LOWER SKIN PANEL SPANWISE JOINT (SSI 57-21-30)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 57-21-00	AFL	3600	+20/-20			0			
57-21-00-210-814-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS: - LOWER SKIN ACCESS HOLES (SSI 57-21-32)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 57-21-00	AFL	3600	+20/-20			0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-21-00-210-815-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - LOWER SKIN PANEL SPANWISE JOINT (SSI 57-21-30) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 57-21-00	HRS/MSC AFL	7200 3600	+20/-20 +20/-20			0 0			
57-21-00-210-816-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - LOWER SKIN PANEL CHORD- WISE JOINT (SSI 57-21-29) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 57-21-00	HRS/MSC AFL	7200 3600	+20/-20 +20/-20			0 0			
57-21-00-210-821-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS: - LOWER SKIN/ SPAR ATTACH- MENTS (SSI 57-21-36)						PKG			
	PKG 5016	MOS	96	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: NDT 57-21-00	HRS/MSC AFL	4000 2000	+20/-20 +20/-20			532.4 280			
57-21-00-210-822-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS: - LOWER SKIN PANEL SPANWISE JOINT (SSI 57-21-30)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 57-21-00	HRS/MSC AFL	7200 3600	+20/-20 +20/-20			0 0			
57-21-00-210-823-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS: - SKIN PANELS (SSI 57-21-26)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 57-21-00	HRS/MSC AFL	7200 3600	+20/-20 +20/-20			0 0			
57-21-00-210-824-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS: - UPPER SKIN PANEL AT SPANWISE JOINT (SSI 57-21-31)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 57-21-00	HRS/MSC AFL	7200 3600	+20/-20 +20/-20			0 0			
57-21-00-210-825-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS: - UPPER SKIN/SPAR ATTACHMENT (SSI 57-21-37) (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: NDT 57-21-00	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
57-21-00-210-826-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - LOWER SKIN ACCESS HOLES (SSI 57-21-32)						PKG			
	PKG 5016	MOS	96	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: NDT 57-21-00	HRS/MSC AFL	4000 2000	+20/-20 +20/-20			532.4 280			
57-21-00-210-C01-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - LOWER VENT HOLE (SSI 57-21-33) - GRAVITY FUEL HOLE (SSI 57-21-35)						PKG			
	PKG 5009,5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: CPM 57-21-00	HRS/MSC AFL	4000 2000	+20/-20 +20/-20			0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-21-00-210-C02-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - UPPER SKIN/ SPAR ATTACHMENT (SSI 57-21-37)						PKG			
	PKG 5009,5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	4000	+20/-20			0			
LOW UTILIZATION	REF: CPM 57-21-00	AFL	2000	+20/-20			0			
57-21-00-210-C04-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS: - UPPER SKIN PANEL SPAN- WISE JOINT (SSI 57-21-31)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: CPM 57-21-00	AFL	1800	+20/-20			280			
57-21-00-210-C06-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS: - UPPER SKIN/ SPAR STUB ATTACHMENT (SSI 57-21-39)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: CPM 57-21-00	AFL	1800	+20/-20			280			
57-21-00-210-C08-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS: - SKIN PANELS (SSI 57-21-26) - UPPER SKIN PANEL SPAN- WISE JOINT (SSI 57-21-31) - UPPER SKIN/ SPAR ATTACH- MENT (SSI 57-21-37)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: CPM 57-21-00	AFL	3600	+20/-20			0			
57-21-00-210-C09-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - LOWER SKIN ACCESS HOLES (SSI 57-21-32)						PKG			
	PKG 5009,5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	4000	+20/-20			0			
LOW UTILIZATION	REF: CPM 57-21-00	AFL	2000	+20/-20			0			
57-21-00-210-C10-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - LOWER SKIN/ WING STUB ATTACHMENT (SSI 57-21-38)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: CPM 57-21-00	AFL	1800	+20/-20			280			
57-21-00-210-C11-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS: - GRAVITY FUEL HOLE (SSI 57-21-35)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: CPM 57-21-00	AFL	3600	+20/-20			0			
57-21-00-210-C13-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - UPPER SKIN/ WING STUB ATTACHMENT (SSI 57-21-39)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: CPM 57-21-00	AFL	1800	+20/-20			280			
57-21-00-210-C14-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - SKIN PANELS (SSI 57-21-26) - UPPER SKIN PANEL SPAN- WISE JOINT (SSI 57-21-31) (L600 ONLY)									
		MOS					16-DEC-2010			
		HRS/MSC	N/A				0			
STRUCTURAL	REF: CPM 57-21-00	AFL					0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-21-00-210-C15-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - UPPER SKIN/ SPAR ATTACHMENT (SSI 57-21-37)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: CPM 57-21-00	AFL	1800	+20/-20			280			
57-21-00-210-C16-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS: - LOWER SKIN PANEL SPAN- WISE JOINT (SSI 57-21-30)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: CPM 57-21-00	AFL	3600	+20/-20			0			
57-21-00-210-C17-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS: - LOWER SKIN/WING STUB ATTACHMENT (SSI 57-21-38)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: CPM 57-21-00	AFL	3600	+20/-20			0			
57-21-00-210-C18-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - LOWER SKIN PANEL SPAN- WISE JOINT (SSI 57-21-30) (L600 ONLY)									
		MOS					16-DEC-2010			
		HRS/MSC	N/A				0			
STRUCTURAL	REF: CPM 57-21-00	AFL					0			
57-21-00-220-801-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS: - SKIN PANELS (SSI 57-21-26)						PKG			
	PKG 5016	MOS	96	+15d/-15d			26-JAN-2015			
		HRS/MSC	4000	+20/-20			532.4			
LOW UTILIZATION	REF: NDT 57-21-00	AFL	2000	+20/-20			280			
57-21-00-220-802-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS: - LOWER SKIN ACCESS HOLES (SSI 57-21-32)						PKG			
	PKG 5016	MOS	96	+15d/-15d			26-JAN-2015			
		HRS/MSC	4000	+20/-20			532.4			
LOW UTILIZATION	REF: NDT 57-21-00	AFL	2000	+20/-20			280			
57-21-00-220-803-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS: - LOWER SKIN/SPAR ATTACH- MENTS (SSI 57-21-36)						PKG			
	PKG 5016	MOS	96	+15d/-15d			26-JAN-2015			
		HRS/MSC	4000	+20/-20			532.4			
LOW UTILIZATION	REF: NDT 57-21-00	AFL	2000	+20/-20			280			
57-21-00-220-804-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS: - ACTUATOR ACCESS HOLES (SSI 57-21-34) - LOWER SKIN/SPAR ATTACH- MENTS (SSI 57-21-36)						PKG			
	PKG 5016	MOS	96	+15d/-15d			26-JAN-2015			
		HRS/MSC	4000	+20/-20			532.4			
LOW UTILIZATION	REF: NDT 57-21-00	AFL	2000	+20/-20			280			
57-21-00-220-805-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS: - ACTUATOR ACCESS HOLES (SSI 57-21-34)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 57-21-00	AFL	3600	+20/-20			0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-21-00-220-806-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS: - LOWER SKIN ACCESS HOLES (SSI 57-21-32)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 57-21-00	AFL	3600	+20/-20			0			
57-21-00-220-807-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS: - UPPER SKIN / SPAR ATTACH- MENT (SSI 57-21-37) - SKIN PANELS (SSI 57-21-26)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 57-21-00	AFL	3600	+20/-20			0			
57-21-00-220-C01-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS: - LOWER VENT HOLE (SSI 57-21-33)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: CPM 57-21-00	AFL	3600	+20/-20			0			
57-21-00-220-C02-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS: - SKIN PANELS (SSI 57-21-26) - UPPER SKIN PANEL SPAN- WISE JOINT (SSI 57-21-31) (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: CPM 57-21-00	AFL	1800	+20/-20			280			
57-21-00-220-C03-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS: - LOWER SKIN PANEL SPAN- WISE JOINT (SSI 57-21-30) (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: CPM 57-21-00	AFL	1800	+20/-20			280			
57-21-00-250-802-L00	SPECIAL DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS BY USING EDDY CURRENT LOW FREQUENCY INSPECTION METHOD: - LOWER SKIN PANEL CHORD- WISE JOINT (SSI 57-21-29). (L600 ONLY)									
		MOS					16-DEC-2010			
		HRS/MSC	N/A				0			
	REF: NDT 57-21-00	AFL					0			
57-21-00-250-803-L00 (s)	SPECIAL DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS BY USING EDDY CURRENT LOW FREQUENCY INSPECTION METHOD: - LOWER SKIN PANEL CHORDWISE JOINT (SSI 57-21-29) (L650 ONLY)						PKG			
	PKG 5032,5140	MOS	192	+15d/-15d						
		HRS/MSC	14400	+20/-20						
LOW UTILIZATION	REF: NDT 57-21-00	AFL	7200	+20/-20						
57-21-00-250-804-L00 (s)	SPECIAL DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS BY USING EDDY CURRENT INSPECTION METHOD: - LOWER SKIN/SPAR ATTACHMENTS (SSI 57-21-36) (L650 ONLY)						PKG			
	PKG 5024,5140	MOS	144	+15d/-15d						
		HRS/MSC	10800	+20/-20						
LOW UTILIZATION	REF: NDT 57-21-00	AFL	5400	+20/-20						

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-22-00-210-801-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS: - SPAR 1/ WING STUB ATTACH- MENT (SSI 57-22-44)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 57-22-00	AFL	3600	+20/-20			0			
57-22-00-210-802-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS: - SPAR 1 CAP (SSI 57-22-41)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 57-22-00	AFL	3600	+20/-20			0			
57-22-00-210-803-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - SPAR 1/ LEADING EDGE ATTACH- MENTS (SSI 57-22-43) (L600 ONLY)									
		MOS					16-DEC-2010			
		HRS/MSC	N/A				0			
STRUCTURAL	REF: NDT 57-22-00	AFL					0			
57-22-00-210-804-L00	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS: - SPAR 1/ LEADING EDGE ATTACHMENTS (SSI 57-22-43)									
	PKG 5032	MOS	192	+15d/-15d			16-DEC-2010	16-DEC-2026	31-DEC-2026	3537 d (+15)
		HRS/MSC	8000	+20/-20			0	8000	8020	7096.7 (+20)
LOW UTILIZATION	REF: NDT 57-22-00	AFL	4000	+20/-20			0	4000	4020	3550 (+20)
57-22-00-210-805-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS: - SPAR 1 CAP (SSI 57-22-41)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 57-22-00	AFL	3600	+20/-20			0			
57-22-00-210-806-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS: - SPAR 1/ LEADING EDGE ATTACHMENTS (SSI 57-22-43)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 57-22-00	AFL	3600	+20/-20			0			
57-22-00-210-807-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - SPAR 1/WING STUB ATTACHMENT (SSI 57-22-44) (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: NDT 57-22-00	AFL	1800	+20/-20			280			
57-22-00-210-C01-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - SPAR 1/ LEADING EDGE ATTACHMENTS (SSI 57-22-43)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: CPM 57-22-00	AFL	1800	+20/-20			280			
57-22-00-220-801-L00	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS: - SPAR 1/ WEB AND STIFFENERS (SSI 57-22-40)									
	PKG 5032	MOS	192	+15d/-15d			16-DEC-2010	16-DEC-2026	31-DEC-2026	3537 d (+15)
		HRS/MSC	8000	+20/-20			0	8000	8020	7096.7 (+20)
LOW UTILIZATION	REF: NDT 57-22-00	AFL	4000	+20/-20			0	4000	4020	3550 (+20)

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-22-00-220-802-L00	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS: - SPAR 1/ WEB AND STIFFENERS (SSI 57-22-40) - SPAR 1, WEB CUTOUTS (SSI 57-22-42)									
	PKG 5032	MOS	192	+15d/-15d			16-DEC-2010	16-DEC-2026	31-DEC-2026	3537 d (+15)
		HRS/MSC	8000	+20/-20			0	8000	8020	7096.7 (+20)
LOW UTILIZATION	REF: NDT 57-22-00	AFL	4000	+20/-20			0	4000	4020	3550 (+20)
57-22-00-220-803-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS: - SPAR 1, WEB CUTOUTS (SSI 57-22-42)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 57-22-00	AFL	3600	+20/-20			0			
57-22-00-220-804-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WINGLET COMPONENTS: - FRONT SPAR - WINGLET (SSI 57-22-45)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 57-22-00	AFL	3600	+20/-20			0			
57-22-00-220-805-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS: - SPAR 1, WEB AND STIFFENERS (SSI 57-22-40) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 57-22-00	AFL	3600	+20/-20			0			
57-22-00-220-806-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS: - SPAR 1, WEB AND STIFFENERS (SSI 57-22-40) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 57-22-00	AFL	3600	+20/-20			0			
57-22-00-220-807-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS: - SPAR 1/ LEADING EDGE ATTACHMENTS (SSI 57-22-43) (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: NDT 57-22-00	AFL	1800	+20/-20			280			
57-22-00-290-801-L00	SPECIAL DETAILED INSPECTION (INTERNAL) OF WINGLET COMPONENTS USING BORO- SCOPE: - FRONT SPAR - WINGLET (SSI 57-22-45) NOTE: THIS TASK SUPERSEDES THE TASK 57-22-00-220-804-L00 OF THE SECTION 4									
		MOS					16-DEC-2010			
		HRS/MSC	N/A				0			
STRUCTURAL	REF: NDT 57-22-00	AFL					0			
57-23-00-210-801-L00	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS: - SPAR 2 CAP (SSI 57-23-46) (L600 ONLY)									
		MOS					16-DEC-2010			
		HRS/MSC	N/A				0			
STRUCTURAL	REF: NDT 57-23-00	AFL					0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-23-00-210-802-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - SPAR 2/ WING STUB ATTACH- MENTS (SSI 57-23-48) (L600 ONLY)	MOS						16-DEC-2010		
STRUCTURAL	REF: NDT 57-23-00	HRS/MSC AFL	N/A					0 0		
57-23-00-210-803-L00	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS: - SPAR 2/ WING STUB ATTACH- MENTS (SSI 57-23-48) (L600 ONLY)	MOS						16-DEC-2010		
STRUCTURAL	REF: NDT 57-23-00	HRS/MSC AFL	N/A					0 0		
57-23-00-210-804-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS: - SPAR 2 CAP (SSI 57-23-46) (L650 ONLY)							PKG		
LOW UTILIZATION	REF: NDT 57-23-00	PKG 5016 MOS HRS/MSC AFL	96 7200 3600	+15d/-15d +20/-20 +20/-20						
57-23-00-210-805-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - SPAR 2/ WING STUB ATTACHMENTS (SSI 57-23-48) (L650 ONLY)	MOS						PKG		
LOW UTILIZATION	REF: NDT 57-23-00	HRS/MSC AFL	96 7200 3600	+15d/-15d +20/-20 +20/-20						
57-23-00-210-806-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS: - SPAR 2/ WING STUB ATTACHMENTS (SSI 57-23-48) (L650 ONLY)	MOS						PKG		
LOW UTILIZATION	REF: NDT 57-23-00	HRS/MSC AFL	96 7200 3600	+15d/-15d +20/-20 +20/-20						
57-23-00-220-801-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS: - SPAR 2, WEB AND STIFFENERS (SSI 57-23-45)	MOS						PKG		
LOW UTILIZATION	REF: NDT 57-23-00	HRS/MSC AFL	96 7200 3600	+15d/-15d +20/-20 +20/-20				16-DEC-2010 0 0		
57-23-00-220-803-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS: - REAR SPAR - WINGLET (SSI 57-23-49) (L650 ONLY)	MOS						PKG		
LOW UTILIZATION	REF: NDT 57-23-00	HRS/MSC AFL	96 7200 3600	+15d/-15d +20/-20 +20/-20				16-DEC-2010 0 0		
57-23-00-220-804-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS: - SPAR 2, WEB CUTOUTS (SSI 57-23-47)	MOS						PKG		
LOW UTILIZATION	REF: NDT 57-23-00	HRS/MSC AFL	96 7200 3600	+15d/-15d +20/-20 +20/-20				16-DEC-2010 0 0		
57-23-00-220-805-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS: - SPAR 2, WEB CUTOUTS (SSI 57-23-47)	MOS						PKG		
LOW UTILIZATION	REF: NDT 57-23-00	HRS/MSC AFL	96 7200 3600	+15d/-15d +20/-20 +20/-20				16-DEC-2010 0 0		

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-23-00-220-C01-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS: - SPAR 2, WEB AND STIFFEN-ERS (SSI 57-23-45) - SPAR 2, WEB CUTOUTS (SSI 57-23-47)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: CPM 57-23-00	AFL	1800	+20/-20			280			
57-23-00-290-801-L00	SPECIAL DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS USING BOROSCOPE: - REAR SPAR - WINGLET (SSI 57-23-49) (L600 ONLY)									
		MOS					16-DEC-2010			
		HRS/MSC	N/A				0			
	REF:	AFL					0			
57-24-00-210-801-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS: - SPAR 3, CAP (SSI 57-24-50)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 57-24-00	AFL	3600	+20/-20			0			
57-24-00-210-802-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - SPAR 3, WING STUB ATTACH- MENT (SSI 57-24-52) (L600 ONLY)									
		MOS					16-DEC-2010			
		HRS/MSC	N/A				0			
STRUCTURAL	REF: NDT 57-24-00	AFL					0			
57-24-00-210-C01-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - SPAR 3, WEB AND STIFFEN-ERS (SSI 57-24-49) - SPAR 3, WEB CUTOUTS (SSI 57-24-51)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: CPM 57-24-00	AFL	1800	+20/-20			280			
57-24-00-210-C02-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS: - SPAR 3, WEB AND STIFFEN-ERS (SSI 57-24-49) - SPAR 3, WEB CUTOUTS (SSI 57-24-51)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: CPM 57-24-00	AFL	1800	+20/-20			280			
57-24-00-220-801-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS: - SPAR 3, WING STUB ATTACHMENT (SSI 57-24-52) (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: NDT 57-24-00	AFL	1800	+20/-20			280			
57-25-00-210-C01-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS: - RIBS, MAIN BOX (SSI 57-25-53) - LOWER SKIN/ RIB ATTACHMENT (SSI 57-25-54) - UPPER SKIN/ RIB ATTACHMENT (SSI 57-25-55)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: CPM 57-25-00	AFL	3600	+20/-20			0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-25-00-210-C02-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - LOWER SKIN/ RIB ATTACHMENT (SSI 57-25-54) - UPPER SKIN/ RIB ATTACHMENT (SSI 57-25-55)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: CPM 57-25-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
57-25-00-290-801-L00 (s)	SPECIAL DETAILED INSPECTION (INTERNAL) OF WINGLET COM- PONENTS USING BOROSCOPE: - RIB 25 - WINGLET (SSI 57-25-56)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 57-25-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
57-26-00-220-801-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS: - FWD & AFT SIDE BRACE FITTINGS, MLG (SSI 57-26-56)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: NDT 57-26-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
57-26-00-220-C01-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS: - FWD & AFT SIDE BRACE FIT- TINGS MLG (SSI 57-26-56) - BEARING CAP (SSI 57-26-94) - TRUNNION FITTING (SSI 57-26-95)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: CPM 57-26-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
57-26-00-250-801-L00	SPECIAL DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD: - FWD & AFT SIDE BRACE FITTINGS, MLG (SSI 57-26-56)									
	PKG 5032	MOS	192	+15d/-15d			16-DEC-2010	16-DEC-2026	31-DEC-2026	3537 d (+15)
LOW UTILIZATION	REF: NDT 57-26-00	HRS/MSC	8000	+20/-20			0	8000	8020	7096.7 (+20)
		AFL	4000	+20/-20			0	4000	4020	3550 (+20)
57-26-00-250-802-L00	SPECIAL DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD: - BEARING CAP - MLG (SSI 57-26-94) (L600 ONLY)									
		MOS					16-DEC-2010			
STRUCTURAL	REF: NDT 57-26-00	HRS/MSC	N/A				0			
		AFL					0			
57-26-00-250-803-L00 (s)	SPECIAL DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD: - FWD & AFT SIDE BRACE FIT- TINGS, MLG (SSI 57-26-56)						PKG			
	PKG 5032,5140	MOS	288	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 57-26-00	HRS/MSC	12000	+20/-20			0			
		AFL	6000	+20/-20			0			
57-26-00-250-804-L00 (s)	SPECIAL DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD: - TRUNNION FITTINGS (SSI 57-26-95)						PKG			
	PKG 5032,5140	MOS	288	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 57-26-00	HRS/MSC	12000	+20/-20			0			
		AFL	6000	+20/-20			0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-26-00-250-805-L00	SPECIAL DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD: - BEARING CAP - MLG (SSI 57-26-94) (L650 ONLY)									
	PKG 5032	MOS	192	+15d/-15d				?	?	?
		HRS/MSC	8000	+20/-20				?	?	?
LOW UTILIZATION	REF: NDT 57-26-00	AFL	4000	+20/-20				?	?	?
57-28-00-210-801-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS: - SPAR ATTACHMENT, TORQUE BOX (SSI 57-28-57)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 57-28-00	AFL	3600	+20/-20			0			
57-28-00-210-804-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - SPAR 3 ATTACHMENT, TORQUE BOX (SSI 57-28-63) - OUTBOARD FLAP CENTER TRACK ATTACHMENT (SSI 57-28-68) (L600 ONLY)									
		MOS					16-DEC-2010			
		HRS/MSC	N/A				0			
STRUCTURAL	REF: NDT 57-28-00	AFL					0			
57-28-00-210-806-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS: - SPAR 3 ATTACHMENT, TORQUE BOX 2 (SSI 57-28-63)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 57-28-00	AFL	3600	+20/-20			0			
57-28-00-210-807-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - ATTACHMENT LUGS AILERON (SSI 57-28-66) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI (L600 ONLY)									
	PKG 5016	MOS					16-DEC-2010			
		HRS/MSC	N/A				0			
	REF: NDT 57-28-00	AFL					0			
57-28-00-210-808-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS: - UPPER SKIN, TORQUE BOX (SSI 57-28-61) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI									
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 57-28-00	AFL	3600	+20/-20			0			
57-28-00-210-809-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - SPAR ATTACHMENT, TORQUE BOX (SSI 57-28-57) (L650 ONLY)									
	PKG 5016	MOS	96	+15d/-15d						
		HRS/MSC	7200	+20/-20						
LOW UTILIZATION	REF: NDT 57-28-00	AFL	3600	+20/-20						
57-28-00-210-C01-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - LOWER SKIN, TORQUE BOX (SSI 57-28-58) (L600 ONLY)									
		MOS					16-DEC-2010			
		HRS/MSC	N/A				0			
STRUCTURAL	REF: CPM 57-28-00	AFL					0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-28-00-210-C02-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - SPAR ATTACHMENT, TORQUE BOX (SSI 57-28-57) (L600 ONLY)	MOS						16-DEC-2010		
STRUCTURAL	REF: CPM 57-28-00	HRS/MSC AFL	N/A					0 0		
57-28-00-210-C03-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - UPPER SKIN, TORQUE BOX (SSI 57-28-61)						PKG			
LOW UTILIZATION	REF: CPM 57-28-00	PKG 5009,5016 MOS HRS/MSC AFL	96 4000 2000	+15d/-15d +20/-20 +20/-20				16-DEC-2010 0 0		
57-28-00-210-C04-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - FLAP ACTUATOR ATTACHMENT FITTINGS (SSI 57-28-67)						PKG			
LOW UTILIZATION	REF: CPM 57-28-00	PKG 5009,5016 MOS HRS/MSC AFL	96 4000 2000	+15d/-15d +20/-20 +20/-20				16-DEC-2010 0 0		
57-28-00-210-C05-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS: - SPAR ATTACHMENT, TORQUE BOX (SSI 57-28-57)						PKG			
LOW UTILIZATION	REF: CPM 57-28-00	PKG 5016 MOS HRS/MSC AFL	96 7200 3600	+15d/-15d +20/-20 +20/-20				16-DEC-2010 0 0		
57-28-00-210-C07-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS: - LOWER SKIN, TORQUE BOX (SSI 57-28-58)						PKG			
LOW UTILIZATION	REF: CPM 57-28-00	PKG 5008 MOS HRS/MSC AFL	48 3600 1800	+15d/-15d +20/-20 +20/-20				26-JAN-2015 532.4 280		
57-28-00-210-C09-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF WING COMPONENTS: - UPPER SKIN, TORQUE BOX (SSI 57-28-61)						PKG			
LOW UTILIZATION	REF: CPM 57-28-00	PKG 5009,5016 MOS HRS/MSC AFL	96 4000 2000	+15d/-15d +20/-20 +20/-20				16-DEC-2010 0 0		
57-28-00-210-C10-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - SPAR ATTACHMENT, TORQUE BOX (SSI 57-28-57)						PKG			
LOW UTILIZATION	REF: CPM 57-28-00	PKG 5009,5016 MOS HRS/MSC AFL	96 4000 2000	+15d/-15d +20/-20 +20/-20				16-DEC-2010 0 0		
57-28-00-220-801-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS: - SPAR ATTACHMENT, TORQUE BOX (SSI 57-28-57)						PKG			
LOW UTILIZATION	REF: NDT 57-28-00	PKG 5016 MOS HRS/MSC AFL	96 7200 3600	+15d/-15d +20/-20 +20/-20				16-DEC-2010 0 0		
57-28-00-220-804-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS: - CENTER TRACK AND RIB 15 TRAILING EDGE (SSI 57-28-69)						PKG			
LOW UTILIZATION	REF: NDT 57-28-00	PKG 5016 MOS HRS/MSC AFL	96 7200 3600	+15d/-15d +20/-20 +20/-20				16-DEC-2010 0 0		

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-28-00-220-805-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS: - TRACKS/ RIBS ATTACHMENT, TORQUE BOX (SSI 57-28-62)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 57-28-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
57-28-00-220-806-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS: - SPAR 3 ATTACHMENT, TORQUE BOX (SSI 57-28-63) - OUTBOARD FLAP CENTER TRACK ATTACHMENT (SSI 57-28-68) (L650 ONLY)						PKG			
	PKG 5016	MOS	96	+15d/-15d						
LOW UTILIZATION	REF: NDT 57-28-00	HRS/MSC	7200	+20/-20						
		AFL	3600	+20/-20						
57-28-00-220-807-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS: - ATTACHMENT LUGS AILERON (SSI 57-28-66) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI. (L650 ONLY)						PKG			
	PKG 5016	MOS	96	+15d/-15d						
LOW UTILIZATION	REF: NDT 57-28-00	HRS/MSC	7200	+20/-20						
		AFL	3600	+20/-20						
57-28-00-220-808-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS: - RIBS, TORQUE BOX (SSI 57-28-60) (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: NDT 57-28-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
57-28-00-220-809-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS: - RIBS, TORQUE BOX 3 (SSI 57-28-64) - TRACKS/ RIB ATTACHMENT, TORQUE BOX 3 (SSI 57-28-65) (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: NDT 57-28-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
57-28-00-220-C01-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS: - SPAR ATTACHMENT, TORQUE BOX (SSI 57-28-57)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: CPM 57-28-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
57-28-00-220-C02-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS: - FLAP TRACK, TORQUE BOX (SSI 57-28-59)						PKG			
	PKG 5009,5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: CPM 57-28-00	HRS/MSC	4000	+20/-20			0			
		AFL	2000	+20/-20			0			
57-28-00-220-C03-L00	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS: - RIBS, TORQUE BOX 3 (SSI 57-28-64) - TRACKS/ RIB ATTACHMENT, TORQUE BOX 3 (SSI 57-28-65) (L600 ONLY)									
		MOS					16-DEC-2010			
STRUCTURAL	REF: CPM 57-28-00	HRS/MSC	N/A				0			
		AFL					0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-28-00-220-C04-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS: - ATTACHMENT ACTUATOR LUGS, INBOARD/ OUTBOARD SPOILERS (SSI 57-28-70)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: CPM 57-28-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
57-28-00-220-C05-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS: - TRACKS/ RIBS ATTACHMENT, TORQUE BOX (SSI 57-28-62)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: CPM 57-28-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
57-28-00-220-C06-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS: - RIBS, TORQUE BOX 3 (SSI 57-28-64) - TRACKS/ RIB ATTACHMENT, TORQUE BOX 3 (SSI 57-28-65)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: CPM 57-28-00	HRS/MSC	7200	+20/-20			0			
		AFL	3600	+20/-20			0			
57-28-00-220-C07-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS: - RIBS, TORQUE BOX 3 (SSI 57-28-60)						PKG			
	PKG 5009,5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: CPM 57-28-00	HRS/MSC	4000	+20/-20			0			
		AFL	2000	+20/-20			0			
57-28-00-220-C08-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS: - RIBS, TORQUE BOX (SSI 57-28-60)						PKG			
	PKG 5009,5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: CPM 57-28-00	HRS/MSC	4000	+20/-20			0			
		AFL	2000	+20/-20			0			
57-28-00-220-C09-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS: - RIBS, TORQUE BOX (SSI 57-28-60)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: CPM 57-28-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
57-28-00-220-C10-L00	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS: - RIBS, TORQUE BOX (SSI 57-28-60) (L600 ONLY)									
		MOS					16-DEC-2010			
STRUCTURAL	REF: CPM 57-28-00	HRS/MSC	N/A				0			
		AFL					0			
57-28-00-220-C11-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS: - LOWER SKIN, TORQUE BOX (SSI 57-28-58) (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: CPM 57-28-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
57-28-00-250-801-L00 (s)	SPECIAL DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD: - SPAR ATTACHMENT, TORQUE BOX (SSI 57-28-57)						PKG			
	PKG 5032,5140	MOS	288	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 57-28-00	HRS/MSC	12000	+20/-20			0			
		AFL	6000	+20/-20			0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-28-00-250-802-L00 (s)	SPECIAL DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD: - RIBS, TORQUE BOX (SSI 57-28-60)						PKG			
	PKG 5032,5140	MOS	288	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 57-28-00	HRS/MSC AFL	12000 6000	+20/-20 +20/-20			0 0			
57-28-00-250-803-L00 (s)	SPECIAL DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD: - SPAR ATTACHMENT, TORQUE BOX (SSI 57-28-57)						PKG			
	PKG 5032,5140	MOS	288	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 57-28-00	HRS/MSC AFL	12000 6000	+20/-20 +20/-20			0 0			
57-28-00-250-804-L00 (s)	SPECIAL DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD: - RIBS, TORQUE BOX (SSI 57-28-60)						PKG			
	PKG 5032,5140	MOS	288	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 57-28-00	HRS/MSC AFL	12000 6000	+20/-20 +20/-20			0 0			
57-28-00-250-805-L00 (s)	SPECIAL DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD: - FLAP TRACK, TORQUE BOX (SSI 57-28-59)						PKG			
	PKG 5032,5140	MOS	288	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 57-28-00	HRS/MSC AFL	12000 6000	+20/-20 +20/-20			0 0			
57-29-00-220-801-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS: - SKIN/ RIB ATTACHMENT, MLGB (SSI 57-29-72)						PKG			
	PKG 5016	MOS	96	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: NDT 57-29-00	HRS/MSC AFL	4000 2000	+20/-20 +20/-20			532.4 280			
57-29-00-220-802-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING COMPONENTS: - RIBS, MAIN LANDING GEAR BAY (SSI 57-29-71) - SKIN/ RIB ATTACHMENT, MLGB (SSI 57-29-72)						PKG			
	PKG 5016	MOS	96	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: NDT 57-29-00	HRS/MSC AFL	4000 2000	+20/-20 +20/-20			532.4 280			
57-41-00-210-801-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING LEADING EDGE COMPONENTS: - WING LEADING EDGE 1 SKIN (SSI 57-41-94) (L650 ONLY)						PKG			
	PKG 5016	MOS	96	+15d/-15d						
LOW UTILIZATION	REF: NDT 57-41-00	HRS/MSC AFL	7200 3600	+20/-20 +20/-20						
57-41-00-210-C01-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING LEADING EDGE COMPONENTS: - WING LEADING EDGE 1 SKIN (SSI 57-41-94) (L600 ONLY)									
		MOS					16-DEC-2010			
STRUCTURAL	REF: CPM 57-41-00	HRS/MSC AFL	N/A				0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-41-00-220-801-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING LEADING EDGE COMPONENTS: - MACHINED RIB FLANGE (SSI 57-41-98)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 57-41-00	AFL	3600	+20/-20			0			
57-42-00-210-801-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING LEADING EDGE COMPONENTS: - WING LEADING EDGE 2 SKIN (SSI 57-42-95) (L650 ONLY)						PKG			
	PKG 5016	MOS	96	+15d/-15d						
		HRS/MSC	7200	+20/-20						
LOW UTILIZATION	REF: NDT 57-42-00	AFL	3600	+20/-20						
57-42-00-210-C01-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING LEADING EDGE COMPONENTS: - WING LEADING EDGE 2 SKIN (SSI 57-42-95) (L600 ONLY)									
		MOS					16-DEC-2010			
		HRS/MSC	N/A				0			
STRUCTURAL	REF: CPM 57-42-00	AFL					0			
57-42-00-220-801-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING LEADING EDGE COMPONENTS: - MACHINED RIB FLANGE (SSI 57-42-98)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 57-42-00	AFL	3600	+20/-20			0			
57-42-00-220-802-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF WING LEADING EDGE COMPONENTS: - WING LEADING EDGE 2 BOTTOM SKIN AT CONNECTIONS TO LOWER REAR GIRDER & WING LOWER SPAR CAP (SSI 57-42-97)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: NDT 57-42-00	AFL	1800	+20/-20			280			
57-43-00-210-801-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF LEADING EDGE COMPONENTS: - WING LEADING EDGE 3 SKIN (SSI 57-43-96) (L650 ONLY)						PKG			
	PKG 5016	MOS	96	+15d/-15d						
		HRS/MSC	7200	+20/-20						
LOW UTILIZATION	REF: NDT 57-43-00	AFL	3600	+20/-20						
57-43-00-210-C01-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF LEADING EDGE COMPONENTS: - WING LEADING EDGE 3 SKIN (SSI 57-43-96) (L600 ONLY)									
		MOS					16-DEC-2010			
		HRS/MSC	N/A				0			
STRUCTURAL	REF: CPM 57-43-00	AFL					0			
57-43-00-220-801-L00 (s)	DETAILED INSPECTION (INTERNAL) OF WING LEADING EDGE COMPONENTS: - MACHINED RIB FLANGE (SSI 57-43-98)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 57-43-00	AFL	3600	+20/-20			0			
57-50-00-220-801-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF FLAP COMPONENTS: - FITTING, ROOT SPAR, FLAPS (SSI 57-50-74)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 57-50-00	AFL	3600	+20/-20			0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-50-00-220-802-L00	DETAILED INSPECTION (INTERNAL) OF FLAP COMPONENTS: - FITTING, ROOT SPAR, FLAPS (SSI 57-50-74)									
	PKG 5032	MOS	192	+15d/-15d			16-DEC-2010	16-DEC-2026	31-DEC-2026	3537 d (+15)
		HRS/MSC	8000	+20/-20			0	8000	8020	7096.7 (+20)
LOW UTILIZATION	REF: NDT 57-50-00	AFL	4000	+20/-20			0	4000	4020	3550 (+20)
57-50-00-220-803-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF FLAP COMPONENTS: - ROLLER ATTACHMENT, FLAPS (SSI 57-50-76)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	7200	+20/-20			0			
LOW UTILIZATION	REF: NDT 57-50-00	AFL	3600	+20/-20			0			
57-50-00-220-804-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF FLAP COMPONENTS: - TRACKS, FLAPS (SSI 57-50-80)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
		HRS/MSC	3600	+20/-20			532.4			
LOW UTILIZATION	REF: NDT 57-50-00	AFL	1800	+20/-20			280			
57-50-00-220-C01-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF FLAP COMPONENTS: - TRACKS/ RIB ATTACHMENT, FLAPS (SSI 57-50-77)						PKG			
	PKG 5009,5016	MOS	96	+15d/-15d			16-DEC-2010			
		HRS/MSC	4000	+20/-20			0			
LOW UTILIZATION	REF: CPM 57-50-00	AFL	2000	+20/-20			0			
57-50-00-250-801-L00 (s)	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FLAP COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD: - ROLLER ATTACHMENT, FLAPS (SSI 57-50-76)						PKG			
	PKG 5032,5140	MOS	288	+15d/-15d			16-DEC-2010			
		HRS/MSC	12000	+20/-20			0			
LOW UTILIZATION	REF: NDT 57-50-00	AFL	6000	+20/-20			0			
57-50-00-250-802-L00	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FLAP COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD: - TRACKS, FLAPS (SSI 57-50-80) (L600 ONLY)									
		MOS					16-DEC-2010			
		HRS/MSC	N/A				0			
STRUCTURAL	REF: NDT 57-50-00	AFL					0			
57-50-00-250-803-L00 (s)	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FLAP COMPONENTS BY THE EDDY CURRENT INSPECTION METHOD: - TRACKS, FLAPS (SSI 57-50-80) (L650 ONLY)						PKG			
	PKG 5032,5140	MOS	192	+15d/-15d						
		HRS/MSC	14400	+20/-20						
LOW UTILIZATION	REF: NDT 57-50-00	AFL	7200	+20/-20						
57-52-00-210-801-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF FLAP COMPONENTS: - RIBS/ SKIN ATTACHMENT, INBOARD FLAP (SSI 57-52-79) - VANE INBOARD/ OUTBOARD FIT- TINGS, INBOARD FLAP (SSI 57-52-81)						PKG			
	PKG 5008,5016	MOS	96	+15d/-15d			26-JAN-2015			
		HRS/MSC	4000	+20/-20			532.4			
LOW UTILIZATION	REF: NDT 57-52-00	AFL	2000	+20/-20			280			
57-52-00-210-802-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF FLAP COMPONENTS: - RIBS/SKIN ATTACHMENT, INBOARD FLAP (SSI 57-52-79)						PKG			
	PKG 5032,5140	MOS	288	+15d/-15d			16-DEC-2010			
		HRS/MSC	12000	+20/-20			0			
LOW UTILIZATION	REF: NDT 57-52-00	AFL	6000	+20/-20			0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-52-00-210-803-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF FLAP COMPONENTS: - VANE CENTER FITTING, INBOARD FLAP (SSI 57-52-78) (L600 ONLY)	MOS					16-DEC-2010			
STRUCTURAL	REF: NDT 57-52-00	HRS/MSC AFL	N/A				0 0			
57-52-00-210-804-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF FLAP COMPONENTS: - PIN AND ACTUATOR LUGS, INBOARD FLAP (SSI 57-52-75) (L600 ONLY)	MOS					16-DEC-2010			
STRUCTURAL	REF: NDT 57-52-00	HRS/MSC AFL	N/A				0 0			
57-52-00-210-805-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF FLAP COMPONENTS: - PIN AND ACTUATOR LUGS, INBOARD FLAP (SSI 57-52-75) (L650 ONLY)	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: NDT 57-52-00	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
57-52-00-220-801-L00 (s)	DETAILED INSPECTION (INTERNAL) OF FLAP COMPONENTS: - FITTING TIP, INBOARD FLAP (SSI 57-52-73)	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 57-52-00	HRS/MSC AFL	7200 3600	+20/-20 +20/-20			0 0			
57-52-00-220-802-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF FLAP COMPONENTS: - FITTING TIP SPAR, INBOARD FLAP (SSI 57-52-73)	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 57-52-00	HRS/MSC AFL	7200 3600	+20/-20 +20/-20			0 0			
57-52-00-220-803-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF FLAP COMPONENTS: - VANE CENTER FITTING, INBOARD FLAP (SSI 57-52-78) (L650 ONLY)	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: NDT 57-52-00	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
57-52-00-250-801-L00 (s)	SPECIAL DETAILED INSPECTION (EXTERNAL) OF FLAP COMPONENTS BY USING EDDY CURRENT INSPECTION METHOD: - RIBS/ SKIN ATTACHMENT, INBOARD FLAP (SSI 57-52-79) (L650 ONLY)	MOS	192	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 57-52-00	HRS/MSC AFL	14400 7200	+20/-20 +20/-20			0			
57-53-00-210-801-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF FLAP COMPONENTS: - VANE CENTER FITTING, OUTBOARD FLAP (SSI 57-53-85) (L600 ONLY)	MOS					16-DEC-2010			
STRUCTURAL	REF: NDT 57-53-00	HRS/MSC AFL	N/A				0 0			
57-53-00-210-802-L00	GENERAL VISUAL INSPECTION (INTERNAL) OF FLAP COMPONENTS: - RIBS/ SKIN ATTACHMENT, OUT- BOARD FLAP (SSI 57-53-86)	MOS	192	+15d/-15d			16-DEC-2010	16-DEC-2026	31-DEC-2026	3537 d (+15)
LOW UTILIZATION	REF: NDT 57-53-00	HRS/MSC AFL	8000 4000	+20/-20 +20/-20			0 0	8000 4000	8020 4020	7096.7 (+20) 3550 (+20)

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-53-00-210-803-L00 (s)	GENERAL VISUAL INSPECTION (INTERNAL) OF FLAP COMPONENTS: - CENTER RIBS ATTACHMENT, OUTBOARD FLAP (SSI 57-53-87)						PKG			
	PKG 5032,5140	MOS	288	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 57-53-00	HRS/MSC AFL	12000 6000	+20/-20 +20/-20			0 0			
57-53-00-210-804-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF FLAP COMPONENTS: - RIBS/ SKIN ATTACHMENT, OUT- BOARD FLAP (SSI 57-53-86)						PKG			
	PKG 5016	MOS	96	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: NDT 57-53-00	HRS/MSC AFL	4000 2000	+20/-20 +20/-20			532.4 280			
57-53-00-210-805-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF FLAP COMPONENTS: - VANE INBOARD/ OUTBOARD FITTINGS, OUTBOARD FLAP (SSI 57-53-88)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 57-53-00	HRS/MSC AFL	7200 3600	+20/-20 +20/-20			0 0			
57-53-00-210-806-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF FLAP COMPONENTS: - PIN AND ACTUATOR LUGS, OUTBOARD FLAP (SSI 57-53-84) (L600 ONLY)						PKG			
	PKG 5016	MOS					16-DEC-2010			
STRUCTURAL	REF: NDT 57-53-00	HRS/MSC AFL	N/A				0 0			
57-53-00-210-807-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF FLAP COMPONENTS: - PIN AND ACTUATOR LUGS, OUT- BOARD FLAP (SSI 57-53-84) (L650 ONLY)						PKG			
	PKG 5016	MOS	96	+15d/-15d						
LOW UTILIZATION	REF: NDT 57-53-00	HRS/MSC AFL	7200 3600	+20/-20 +20/-20						
57-53-00-210-C01-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF FLAP COMPONENTS: - CENTER RIBS ATTACHMENT, OUTBOARD FLAP (SSI 57-53-87) (L600 ONLY)						PKG			
	PKG 5016	MOS					16-DEC-2010			
STRUCTURAL	REF: CPM 57-53-00	HRS/MSC AFL	N/A				0 0			
57-53-00-220-801-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF FLAP COMPONENTS: - FITTING, TIP SPAR, OUTBOARD FLAP (SSI 57-53-83)						PKG			
	PKG 5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: NDT 57-53-00	HRS/MSC AFL	7200 3600	+20/-20 +20/-20			0 0			
57-53-00-220-802-L00	DETAILED INSPECTION (INTERNAL) OF FLAP COMPONENTS: - FITTING, TIP SPAR, OUTBOARD FLAP (SSI 57-53-83)						PKG			
	PKG 5032	MOS	192	+15d/-15d			16-DEC-2010	16-DEC-2026	31-DEC-2026	3537 d (+15)
LOW UTILIZATION	REF: NDT 57-53-00	HRS/MSC AFL	8000 4000	+20/-20 +20/-20			0 0	8000 4000	8020 4020	7096.7 (+20) 3550 (+20)

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-53-00-220-803-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF FLAP COMPONENTS: - VANE CENTER FITTING, OUTBOARD FLAP (SSI 57-53-85) (L650 ONLY)						PKG			
	PKG 5016	MOS	96	+15d/-15d						
LOW UTILIZATION	REF: NDT 57-53-00	HRS/MSC	7200	+20/-20						
		AFL	3600	+20/-20						
57-53-00-220-C01-L00	DETAILED INSPECTION (EXTERNAL) OF FLAP COMPONENTS: - CENTER RIBS ATTACHMENT, OUTBOARD FLAP (SSI 57-53-87) (L650 ONLY)									
	PKG 5009	MOS	96	+15d/-15d				?	?	?
LOW UTILIZATION	REF: CPM 57-53-00	HRS/MSC	4000	+20/-20				4000	4020	3096.7 (+20)
		AFL	2000	+20/-20				2000	2020	1550 (+20)
57-61-00-210-801-L00	GENERAL VISUAL INSPECTION (EXTERNAL) OF WING COMPONENTS: - HINGES ATTACHMENT, AILERON (SSI 57-61-89) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI (L600 ONLY)									
		MOS					16-DEC-2010			
LOW UTILIZATION	REF: NDT 57-61-00	HRS/MSC	N/A				0			
		AFL					0			
57-61-00-210-C01-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF AILERON COMPONENTS: - SPAR CAP, AILERON (SSI 57-61-91)						PKG			
	PKG 5009,5016	MOS	96	+15d/-15d			16-DEC-2010			
LOW UTILIZATION	REF: CPM 57-61-00	HRS/MSC	4000	+20/-20			0			
		AFL	2000	+20/-20			0			
57-61-00-220-801-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF AILERON COMPONENTS: - ACTUATOR ATTACHMENT, AILERON (SSI 57-61-90)						PKG			
	PKG 5016	MOS	96	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: NDT 57-61-00	HRS/MSC	4000	+20/-20			532.4			
		AFL	2000	+20/-20			280			
57-61-00-220-802-L00	DETAILED INSPECTION (INTERNAL) OF AILERON COMPONENTS: - ACTUATOR ATTACHMENT, AILERON (SSI 57-61-90)									
	PKG 5032	MOS	192	+15d/-15d			16-DEC-2010	16-DEC-2026	31-DEC-2026	3537 d (+15)
LOW UTILIZATION	REF: NDT 57-61-00	HRS/MSC	8000	+20/-20			0	8000	8020	7096.7 (+20)
		AFL	4000	+20/-20			0	4000	4020	3550 (+20)
57-61-00-220-804-L00	DETAILED INSPECTION (INTERNAL) OF AILERON COMPONENTS: - AILERON ACTUATOR FITTINGS (SSI 57-61-12)									
		MOS					16-DEC-2010			
LOW UTILIZATION	REF: NDT 57-61-00	HRS/MSC	N/A				0			
		AFL					0			
57-61-00-220-805-L00 (s)	DETAILED INSPECTION (EXTERNAL) OF WING COMPONENTS: - HINGES ATTACHMENT, AILERON (SSI 57-61-89) NOTE: DURING THIS INSPECTION, THE CPCP BASIC TASK SHALL ALSO BE PERFORMED FOR THIS SSI. (L650 ONLY)						PKG			
	PKG 5016	MOS	96	+15d/-15d						
LOW UTILIZATION	REF: NDT 57-61-00	HRS/MSC	7200	+20/-20						
		AFL	3600	+20/-20						
57-70-00-210-C01-L00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) OF SPOILER COMPONENTS: - HINGES ATTACHMENT, SPOILERS (SSI 57-70-92) - ACTUATOR ATTACHMENT, SPOILERS (SSI 57-70-93)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: CPM 57-70-00	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-Z511-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 511, 611, 512, 612, 513 AND 613)						PKG			
	PKG 5004	MOS	24	+15d/-15d			21-JAN-2017			
LOW UTILIZATION	REF: AMM 05-20-76	HRS/MSC AFL	1000	+20/-20			884.1 443			
57-Z511-214-001-A00	GENERAL VISUAL INSPECTION (INTERNAL) (L600 ONLY) (ZONES 511, 611, 512, 612, 513 AND 613)									
		MOS					16-DEC-2010			
	REF:	HRS/MSC AFL	N/A				0 0			
57-Z511-214-001-A01 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 511, 611, 512, 612, 513 and 613) NOTE:EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-20-76	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
57-Z531-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 531, 631)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-20-82	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
57-Z531-214-001-A00	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 531, 631) (L600 ONLY)									
		MOS					16-DEC-2010			
	REF:	HRS/MSC AFL	N/A				0 0			
57-Z531-214-001-A01 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 531, 631) NOTE:EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-20-82	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
57-Z532-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 532 AND 632)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-20-84	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
57-Z532-214-001-A00	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 532 AND 632) (L600 ONLY)									
		MOS					16-DEC-2010			
	REF:	HRS/MSC AFL	N/A				0 0			
57-Z532-214-001-A01 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 532 AND 632) NOTE:EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-20-84	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-Z541-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 541 AND 641)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-20-86	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
57-Z541-214-001-A00	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 541 AND 641) (L600 ONLY)									
ZONAL	REF:	MOS HRS/MSC AFL	N/A							
57-Z541-214-001-A01 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 541 AND 641) NOTE:EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-20-86	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
57-Z551-213-002-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 551, 561, 651, 661)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-20-88	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
57-Z551-214-002-A00	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 551, 561, 651, 661) (L600 ONLY)									
ZONAL	REF:	MOS HRS/MSC AFL	N/A							
57-Z551-214-002-A01 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 551, 561, 651, 661) NOTE:EWIS (L650 ONLY)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-20-88	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
57-Z571-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 571, 671, 5711, 6711, 5712, 6712, 5713, 6713)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-20-90	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
57-Z571-214-001-A00	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 571, 671, 5711, 6711, 5712, 6712, 5713, 6713) (L600 ONLY)									
		MOS					16-DEC-2010			
REF:		HRS/MSC AFL	N/A				0 0			
57-Z571-214-001-A01 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 571, 671, 5711, 6711, 5712, 6712, 5713, 6713) NOTE:EWIS (L650 ONLY)						PKG			
	PKG 5004	MOS	24	+15d/-15d			21-JAN-2017			
LOW UTILIZATION	REF: AMM 05-20-90	HRS/MSC AFL	1000	+20/-20			884.1 443			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
57-Z572-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 572, 672, 5721, 6721, 5722, 6722)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-20-92	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
57-Z572-214-001-A00	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 572, 672, 5721, 6721, 5722, 6722) (L600 ONLY)									
ZONAL	REF:	MOS HRS/MSC AFL	N/A							
57-Z572-214-001-A01 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 572, 672, 5721, 6721, 5722, 6722). NOTE:EWIS (L650 ONLY)						PKG			
	PKG 5004	MOS	24	+15d/-15d			21-JAN-2017			
LOW UTILIZATION	REF: AMM 05-20-92	HRS/MSC AFL	1000	+20/-20			884.1 443			
57-Z573-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 573, 673, 5731, 6731, 5732, 6732)						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
LOW UTILIZATION	REF: AMM 05-20-94	HRS/MSC AFL	3600 1800	+20/-20 +20/-20			532.4 280			
57-Z573-214-001-A00	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 573, 673, 5731, 6731, 5732, 6732) (L600 ONLY)									
ZONAL	REF:	MOS HRS/MSC AFL	N/A							
57-Z573-214-001-A01 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 573, 673, 5731, 6731, 5732, 6732) NOTE:EWIS (L650 ONLY)						PKG			
	PKG 5004	MOS	24	+15d/-15d			21-JAN-2017			
LOW UTILIZATION	REF: AMM 05-20-94	HRS/MSC AFL	1000	+20/-20			884.1 443			
574000-0201	LH WING LEADING EDGE WING ASSEMBLY									
	135-21595-401	MOS		TSN:0			16-DEC-2010			
	SA5120	HRS/MSC	O/C	TSN:0			0			
	REF: See Workcard	AFL		TSN:0			0			
574000-0202	LH WING LEADING EDGE WING ASSEMBLY									
	135-21596-401	MOS		TSN:0			16-DEC-2010			
	SA2116	HRS/MSC	O/C	TSN:0			0			
	REF: See Workcard	AFL		TSN:0			0			
574000-0203	LH WING LEADING EDGE WING ASSEMBLY									
	135-21597-403	MOS		TSN:0			16-DEC-2010			
	SA2116	HRS/MSC	O/C	TSN:0			0			
	REF: See Workcard	AFL		TSN:0			0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
574000-0204	RH WING LEADING EDGE WING ASSEMBLY 135-21595-402 SA2127 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
574000-0205	RH WING LEADING EDGE WING ASSEMBLY 135-21596-402 SA2119 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
574000-0206	RH WING LEADING EDGE WING ASSEMBLY 135-21597-404 SA2132 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
575600-0101	LH WING SHROUD ASSY 135-25292-401 0000644035 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
575600-0102	RH WING SHROUD ASSY 135-25292-402 0000637086 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
575600-0201	LH WING SHROUD ASSY 135-25293-401 0000639303 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
575600-0202	RH WING SHROUD ASSY 135-25293-402 0000633122 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
575600-0301	LH MOBILE SHROUD ASSY 135-25294-401 0000637089 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
575600-0302	RH MOBILE SHROUD ASSY 135-25294-402 0000637090 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
576600-0101	LHUP SHROUD ASSY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
576600-0102	RHUP SHROUD ASSY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
576600-0201	LH WING FIXED SHROUD ASSY 135-25295-401 0000639836 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
576600-0202	RH WING FIXED SHROUD ASSY 135-25295-402 0000644041 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
CHAPTER 71 POWER PLANT										
71-10-00-211-001-A00 (s)	VISUALLY CHECK COWLING SEALS PKG 5008	MOS HRS/MSC AFL	48 3600 1800	+15d/-15d +20/-20 +20/-20			26-JAN-2015 532.4 280			
LOW UTILIZATION	REF: AMM 71-10-00									
71-10-00-220-001-A00 (s)	INSPECT (DETAILED INSPECTION) COWLING INBOARD/ OUTBOARD ATTACHMENT AND SURROUNDING STRUCTURE PKG 5008	MOS HRS/MSC AFL	48 3600 1800	+15d/-15d +20/-20 +20/-20			26-JAN-2015 532.4 280			
LOW UTILIZATION	REF: AMM 71-10-00									
71-20-00-220-001-A00 (s)	INSPECT (DETAILED INSPECTION) ENGINE MOUNTING ASSY PKG 5008	MOS HRS/MSC AFL	48 3600 1800	+15d/-15d +20/-20 +20/-20			26-JAN-2015 532.4 280			
LOW UTILIZATION	REF: AMM 71-20-00									
71-60-01-211-001-A00 (s)	VISUALLY CHECK AIR INTAKE ATTACHMENT PKG 5008	MOS HRS/MSC AFL	48 3600 1800	+15d/-15d +20/-20 +20/-20			26-JAN-2015 532.4 280			
LOW UTILIZATION	REF: AMM 71-60-01									
71-60-01-211-002-A00 (s)	VISUALLY CHECK AIR INTAKE REAR BULKHEAD AND FIRE SHIELD PKG 5008	MOS HRS/MSC AFL	48 3600 1800	+15d/-15d +20/-20 +20/-20			26-JAN-2015 532.4 280			
LOW UTILIZATION	REF: AMM 71-60-01									
71-Z411-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 411, 412, 413, 421, 422, 423) PKG 5004	MOS HRS/MSC AFL	24 1000	+15d/-15d +20/-20			21-JAN-2017 884.1 443			
LOW UTILIZATION	REF: AMM 05-20-70									
71-Z411-214-001-A00	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 411, 412, 413, 421, 422, 423 AND 425) (L600 ONLY) REF:	MOS HRS/MSC AFL	N/A				16-DEC-2010 0 0			
71-Z411-214-001-A01 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 411, 412, 413, 415, 421, 422, 423 AND 425) NOTE:EWIS (L650 ONLY) PKG 5004	MOS HRS/MSC AFL	24 1000	+15d/-15d +20/-20			21-JAN-2017 884.1 443			
LOW UTILIZATION	REF: AMM 05-20-70									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
711000-0101	LEFT UP COWLING -NACELLE ASSEMBLY 145-76830-401 1157 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
711000-0102	RIGHT UP COWLING -NACELLE ASSEMBLY 145-76830-402 1162 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
711000-0103	LEFT LW ENGINE COWLING ASSEMBLY 135-04972-405 0000644869 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
711000-0104	RIGHT LW ENGINE COWLING ASSEMBLY 135-04974-405 0000644868 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
711000-0201	LH ENG STRUCTURE -APRON, COWLING ASSEMBLY 145-77030-401 1146 REF: AMM 71-13-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
711000-0202	RH ENG STRUCTURE -APRON, COWLING ASSEMBLY 145-77030-402 1147 REF: AMM 71-13-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
711000-0301	LHLW COWLING ASSEMBLY 145-76810-401 1170 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
711000-0302	RHLW COWLING ASSEMBLY 145-76820-401 1169 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
712000-0201	LH ENG AFT SHOCKMOUNT ASSEMBLY LM-223-SA8 LK5624 REF: AMM 71-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
712000-0202	RH ENG AFT SHOCKMOUNT ASSEMBLY LM-223-SA8 LK5656 REF: AMM 71-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
712000-0203	LH ENG AFT SHOCKMOUNT ASSEMBLY LM-223-SA8 LK5663 REF: AMM 71-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
712000-0204	RH ENG AFT SHOCKMOUNT ASSEMBLY LM-223-SA8 LK5659 REF: AMM 71-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
712000-0301	LH ENG FORWARD FLUIDLASTIC NL TUN ISOLATOR LM-223-SA5-2 LK8450 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
712000-0302	RH ENG FORWARD FLUIDLASTIC NL TUN ISOLATOR LM-223-SA5-2 LK8385 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
712000-0303	LH ENG FORWARD FLUIDLASTIC NL TUN ISOLATOR LM-223-SA5-2 LK8530 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
712000-0304	RH ENG FORWARD FLUIDLASTIC NL TUN ISOLATOR LM-223-SA5-2 LK8409 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
716000-0101	LH ENGINE AIR INLET MODULE 135-04892-407 NC2249 REF: AMM 71-60-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
716000-0102	RH ENGINE AIR INLET MODULE 135-04892-407 NC2274 REF: AMM 71-60-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
71EN1	NO. 1 ENGINE 23087636 CAE-313249 REF: AMM 71-00-00	MOS HRS/MSC AFL	E/C							
71EN2	NO. 2 ENGINE 23087636 CAE-313246 REF: AMM 71-00-00	MOS HRS/MSC AFL	E/C							
CHAPTER 72 ENGINE										
72-00-00-970-001-A00	DOWNLOAD ENGINE TREND DOWNLOAD/ANALYSIS PKG 1 REF:	MOS HRS/MSC AFL	100 70				22-MAR-2017 903.3 450	1003.3 520		100 70
72-20-00-212-001-A00	GENERAL VISUAL INSPECTION ENGINE AIR INLET SECTION REF:	MOS HRS/MSC AFL	500				21-JAN-2017 884.1 443	1384.1		480.8

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
720000-0101	RH ENG TURBOFAN,WT/FADEC,WT/SENSOR UNIT PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
720000-0102	LH ENG TURBOFAN,WT/FADEC,WT/SENSOR UNIT PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
ENGINE NO. 1 Model : AE3007A2 Serial # CAE-313249 Part # 23087636										
72-21-20-220-002-A00	NO. 1 ENGINE - DETAIL INSPECT REF: GENERIC NO REF	FAN SPINNER P/N 23054034, 23064250, OR 23065046 ONLY MOS HRS/MSC ENC	N/A				14-OCT-2010 0 0			
72-62-01-212-001-A00	NO. 1 ENGINE - GENERAL VISUAL INSPECTION (L650 ONLY) REF: MM 72-63-10	ACCESSORY GEARBOX RETENTION CABLES MOS HRS/MSC ENC	1000				21-JAN-2017 884.1 443	(1884.1) 1884.1		980.8
720000-0103	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF ACCESSORY DRIVES SECTION (MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01) REF: MM 72-00-00	MOS HRS/MSC ENC	-				14-OCT-2010 0 0			
720000-0104	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF BYPASS SECTION (MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01) REF: MM 72-00-00	MOS HRS/MSC ENC	-				14-OCT-2010 0 0			
720000-0106	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF FUEL SYSTEM DISTRIBUTION (TUBES AND HOSES) (MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01) REF: MM 72-00-00	MOS HRS/MSC ENC	-				14-OCT-2010 0 0			
720000-0108	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF POWER CONTROL SECTION (HARNESSES) (MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01) REF: MM 72-00-00	MOS HRS/MSC ENC	-				14-OCT-2010 0 0			
720000-0109	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF TURBINE-INTERSTAGE THERMOCOUPLE (A) HARNES (MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01) REF: MM 72-00-00	MOS HRS/MSC ENC	-				14-OCT-2010 0 0			



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
720000-0110	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF TURBINE-INTERSTAGE THERMOCOUPLE (B) HARNESS (MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01)	MOS HRS/MSC - ENC					14-OCT-2010 0 0			
	REF: MM 72-00-00									
720000-0111	NO. 1 ENGINE - PERFORM SPECIAL PROCEDURES ON ENGINE	MOS HRS/MSC N/A ENC					14-OCT-2010 0 0			
	REF: GENERIC NO REF									
720038	NO. 1 ENGINE - ACCESS DRIVE GEARBOX MODULE	MOS		TSN:0			14-OCT-2010			
	23076096	HRS/MSC	O/C	TSN:0			0			
	XK10077	ENC		TSN:0			0			
	REF: GENERIC NO REF									
720039	NO. 1 ENGINE - ACCESSORY DRIVE GEARBOX	MOS		TSN:0			14-OCT-2010			
	23086770	HRS/MSC	O/C	TSN:0			0			
	XK10077	ENC		TSN:0			0			
	REF: GENERIC NO REF									
721000	NO. 1 ENGINE - FAN ROTOR ASSEMBLY	MOS		TSN:0			14-OCT-2010			
	23087158	HRS/MSC	O/C	TSN:0			0			
	MW64046	ENC		TSN:0			0			
	REF: GENERIC NO REF									
721003	NO. 1 ENGINE - INSPECT ENGINE 100 CYCLES	MOS					14-OCT-2010			
		HRS/MSC	A/R				0			
		ENC					0			
	REF: MM 05-13-00									
722100-0101	NO. 1 ENGINE - FAN WHEEL	MOS		TSN:0			14-OCT-2010			
	23086748	HRS/MSC		TSN:0			0			
	MW64046	ENC	20000	TSN:0			0		20000	19550
	REF: See Workcard									
722100-0102	NO. 1 ENGINE - FAN DRIVE SHAFT	MOS		TSN:0			14-OCT-2010			
	23074382	HRS/MSC		TSN:0			0			
	GV265949	ENC	20000	TSN:0			0		20000	19550
	REF: GENERIC NO REF									
722101-0101	NO. 1 ENGINE - FORWARD FAN BLADE RETAINER	MOS		TSN:0			14-OCT-2010			
	23086783	HRS/MSC		TSN:0			0			
	GX106248	ENC	20000	TSN:0			0		20000	19550
	REF: GENERIC NO REF									
722102	NO. 1 ENGINE - FAN SUPPORT BEARING HOUSING ASSEMBLY	MOS		TSN:0			14-OCT-2010			
	23081557	HRS/MSC	O/C	TSN:0			0			
	HN503059	ENC		TSN:0			0			
	REF: GENERIC NO REF									
722103	NO. 1 ENGINE - FRONT FRAME ASSEMBLY	MOS		TSN:0			14-OCT-2010			
	23083816	HRS/MSC	O/C	TSN:0			0			
	LA38198	ENC		TSN:0			0			
	REF: GENERIC NO REF									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
722103-0101	NO. 1 ENGINE - CLEAN AND DO THE DETAILED INSPECTION OF FAN BLADES	MOS					14-OCT-2010			
	REF: GENERIC NO REF	HRS/MSC ENC	N/A				0 0			
722104	NO. 1 ENGINE - FAN SPINNER ASSEMBLY	MOS		TSN:0			14-OCT-2010			
	23086790	HRS/MSC	O/C	TSN:0			0			
	FF380579	ENC		TSN:0			0			
	REF: GENERIC NO REF									
722107	NO. 1 ENGINE - FAN CASE ASSEMBLY	MOS		TSN:0			14-OCT-2010			
	23086777	HRS/MSC	O/C	TSN:0			0			
	GX108662	ENC		TSN:0			0			
	REF: GENERIC NO REF									
722109	NO. 1 ENGINE - SEG CARBON FAN SEAL ASSEMBLY	MOS		TSN:0			14-OCT-2010			
	23073567	HRS/MSC	O/C	TSN:0			0			
	KVA6144	ENC		TSN:0			0			
	REF: GENERIC NO REF									
722111	NO. 1 ENGINE - SPANNER NUT	MOS		TSN:0			14-OCT-2010			
	23061181	HRS/MSC	O/C	TSN:0			0			
	DD522219	ENC		TSN:0			0			
	REF: GENERIC NO REF									
722112	NO. 1 ENGINE - BEARING SELF-LOCKING NUT	MOS		TSN:0			14-OCT-2010			
	PN	HRS/MSC	O/C	TSN:0			0			
	SN-UNKNOWN	ENC		TSN:0			0			
	REF: GENERIC NO REF									
722113	NO. 1 ENGINE - ROLLER BEARING	MOS		TSN:0			14-OCT-2010			
	23054010	HRS/MSC	O/C	TSN:0			0			
	AF76818	ENC		TSN:0			0			
	REF: GENERIC NO REF									
722114 (01)	NO. 1 ENGINE - BLADE FAN	MOS		TSN:0			14-OCT-2010			
	PN	HRS/MSC	O/C	TSN:0			0			
	SN-UNKNOWN	ENC		TSN:0			0			
	REF: GENERIC NO REF									
722114 (02)	NO. 1 ENGINE - BLADE FAN	MOS		TSN:0			14-OCT-2010			
	PN	HRS/MSC	O/C	TSN:0			0			
	SN-UNKNOWN	ENC		TSN:0			0			
	REF: GENERIC NO REF									
722114 (03)	NO. 1 ENGINE - BLADE FAN	MOS		TSN:0			14-OCT-2010			
	PN	HRS/MSC	O/C	TSN:0			0			
	SN-UNKNOWN	ENC		TSN:0			0			
	REF: GENERIC NO REF									
722114 (04)	NO. 1 ENGINE - BLADE FAN	MOS		TSN:0			14-OCT-2010			
	PN	HRS/MSC	O/C	TSN:0			0			
	SN-UNKNOWN	ENC		TSN:0			0			
	REF: GENERIC NO REF									

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
722114 (05)	NO. 1 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
722114 (06)	NO. 1 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
722114 (07)	NO. 1 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
722114 (08)	NO. 1 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
722114 (09)	NO. 1 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
722114 (10)	NO. 1 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
722114 (11)	NO. 1 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
722114 (12)	NO. 1 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
722114 (13)	NO. 1 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
722114 (14)	NO. 1 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
722114 (15)	NO. 1 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
722114 (16)	NO. 1 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
722114 (17)	NO. 1 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
722114 (18)	NO. 1 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
722114 (19)	NO. 1 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
722114 (20)	NO. 1 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
722114 (21)	NO. 1 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
722114 (22)	NO. 1 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
722114 (23)	NO. 1 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
722114 (24)	NO. 1 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
722500-0101	NO. 1 ENGINE - BEVEL PINION - RADIAL DRIVE GEARSHAFT 23081447 UG42096 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
722501	NO. 1 ENGINE - FRONT SUMP BEVEL GEAR 23086721 UG45308 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
722502	NO. 1 ENGINE - FRONT-SUMP HOUSING ASSEMBLY 23083827 MQ518976 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
722503	NO. 1 ENGINE - MID-SPAN ROLLER BEARING 23069586 JJ259 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
722504	NO. 1 ENGINE - HORIZONTAL QUILL SHAFT 23075501 GV258614 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
722506	NO. 1 ENGINE - NO.4 CARBON-TANDEM SEAL ASSEMBLY 23085863 KVH1833 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
722508	NO. 1 ENGINE - 80 X 100 X 11 MM ROLLER BEARING 23062542 NWH100212 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
722509	NO. 1 ENGINE - 87 X 108 X 11 BALL BEARING 23056839 AF72811 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
722510	NO. 1 ENGINE - FLANGED ROLLER BEARING 23063132 NWD105148 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
722511	NO. 1 ENGINE - ROLLER BEARING 23077657 AF73267 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
722512	NO. 1 ENGINE - RADIAL DRIVE GEARSHAFT ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
722513	NO. 1 ENGINE - CONRAD BEARING 23064226 NWH100223 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
722514-0101	NO. 1 ENGINE - NO. 1 POWER TURBINE (LPT) BALL BEARING 23088547 NWH100564 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
723000	NO. 1 ENGINE - COMPRESSOR ROTOR ASSEMBLY 23086657 A22728 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
723017	NO. 1 ENGINE - COMP/TURBINE SHAFT 23073165 L346849 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
723018	NO. 1 ENGINE - COMPRESSOR STUB SHAFT 23077677 GV264403 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
723019	NO. 1 ENGINE - COMPRESSOR TIE BOLT 23076018 L351423 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
723020	NO. 1 ENGINE - 9TH STAGE COMPRESSOR CASE 23077726 JB228885 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
723500-0101	NO. 1 ENGINE - 1ST STAGE COMPRESSOR WHEEL 23084156 L349973 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0	15000		14550
723500-0102	NO. 1 ENGINE - 2ND STAGE COMPRESSOR WHEEL 23084157 L346430 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0	15000		14550
723500-0103	NO. 1 ENGINE - 3RD STAGE COMPRESSOR WHEEL 23084158 L355128 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0	15000		14550
723500-0104	NO. 1 ENGINE - 4TH STAGE COMPRESSOR WHEEL 23084159 L345505 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0	15000		14550
723500-0105	NO. 1 ENGINE - 5TH STAGE COMPRESSOR WHEEL 23084160 L357083 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0	15000		14550
723500-0106	NO. 1 ENGINE - 6TH STAGE COMPRESSOR WHEEL 23084161 L351107 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0	15000		14550

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
723500-0107	NO. 1 ENGINE - 7TH STAGE COMPRESSOR WHEEL 23084350 L333883	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0		15000	14550
LIFE LIMIT	REF: GENERIC NO REF									
723500-0108	NO. 1 ENGINE - 8TH STAGE COMPRESSOR WHEEL 23084163 L354544	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0		15000	14550
LIFE LIMIT	REF: GENERIC NO REF									
723500-0109	NO. 1 ENGINE - 9TH STAGE COMPRESSOR WHEEL 23084164 L347557	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0		15000	14550
LIFE LIMIT	REF: GENERIC NO REF									
723500-0110	NO. 1 ENGINE - 10TH STAGE COMPRESSOR WHEEL 23084165 L347728	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0		15000	14550
LIFE LIMIT	REF: GENERIC NO REF									
723500-0111	NO. 1 ENGINE - 11TH STAGE COMPRESSOR WHEEL 23084166 L354137	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0		15000	14550
LIFE LIMIT	REF: GENERIC NO REF									
723500-0112	NO. 1 ENGINE - 12TH STAGE COMPRESSOR WHEEL 23084167 L356582	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0		15000	14550
LIFE LIMIT	REF: GENERIC NO REF									
723500-0113	NO. 1 ENGINE - 13TH STAGE COMPRESSOR WHEEL 23084283 L331492	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0		15000	14550
LIFE LIMIT	REF: GENERIC NO REF									
723500-0114	NO. 1 ENGINE - 14TH STAGE COMPRESSOR WHEEL 23084284 L313699	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0		15000	14550
LIFE LIMIT	REF: GENERIC NO REF									
723500-0120	NO. 1 ENGINE - COMPRESSOR SHAFT CONE ASSEMBLY 23084170 L336934	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0		15000	14550
LIFE LIMIT	REF: GENERIC NO REF									
723700	NO. 1 ENGINE - COMPRESSOR CASE ASSEMBLY 23074746 JB228885	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
LIFE LIMIT	REF: GENERIC NO REF									
723705	NO. 1 ENGINE - COMPRESSOR DIFFUSER 23088638 NY218682	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
LIFE LIMIT	REF: GENERIC NO REF									

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
723707	NO. 1 ENGINE - SPLIT BALL BEARING 23080325 NWSETF10084 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
723902	NO. 1 ENGINE - NO. 6 CARBON CENTER SUMP SEAL ASSEMBLY 23074617 KVC2452 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
723903	NO. 1 ENGINE - NO. 5 CARBON CENTER SUMP SEAL ASSEMBLY 23074616 KVC2322 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
723904	NO. 1 ENGINE - CENTER SUMP HOUSING ASSEMBLY 23074615 NY218441 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
724500	NO. 1 ENGINE - COMBUSTION LINER ASSEMBLY 23077933 JE62734 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725000	NO. 1 ENGINE - HPT ROTOR ASSEMBLY 23074650 A73169 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725010	NO. 1 ENGINE - ROTOR ASSY-LPT ROTOR ASSEMBLY 23089031 A83145 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725181	NO. 1 ENGINE - NO.1 HP TURBINE 2ND STAGE VANE ASSEMBLY 23070987 377012 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725182	NO. 1 ENGINE - NO. 2 HP TURBINE 2ND STAGE VANE ASSEMBLY 23070987 377015 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725183	NO. 1 ENGINE - NO.3 HP TURBINE 2ND STAGE VANE ASSEMBLY 23070987 377018 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725184	NO. 1 ENGINE - NO.4 HP TURBINE 2ND STAGE VANE ASSEMBLY 23070987 377017 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725185	NO. 1 ENGINE - NO.5 HP TURBINE 2ND STAGE VANE ASSEMBLY 23070987 377020 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725186	NO. 1 ENGINE - NO.6 HP TURBINE 2ND STAGE VANE ASSEMBLY 23070987 377013 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725187	NO. 1 ENGINE - NO.7 HP TURBINE 2ND STAGE VANE ASSEMBLY 23070987 376958 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725188	NO. 1 ENGINE - NO.8 HP TURBINE 2ND STAGE VANE ASSEMBLY 23070987 376973 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725189	NO. 1 ENGINE - NO.9 HP TURBINE 2ND STAGE VANE ASSEMBLY 23070987 377016 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725190	NO. 1 ENGINE - NO.10 HP TURBINE 2ND STAGE VANE ASSEMBLY 23070987 376959 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725191	NO. 1 ENGINE - NO.11 HP TURBINE 2ND STAGE VANE ASSEMBLY 23070987 377010 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725192	NO. 1 ENGINE - NO.12 HP TURBINE 2ND STAGE VANE ASSEMBLY 23070987 376960 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725193	NO. 1 ENGINE - NO.13 HP TURBINE 2ND STAGE VANE ASSEMBLY 23070987 377024 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725194	NO. 1 ENGINE - NO.14 HP TURBINE 2ND STAGE VANE ASSEMBLY 23070987 377019 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725195	NO. 1 ENGINE - NO.15 HP TURBINE 2ND STAGE VANE ASSEMBLY 23070987 377023 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725196	NO. 1 ENGINE - NO.16 HP TURBINE 2ND STAGE VANE ASSEMBLY 23070987 377011 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725200-0101	NO. 1 ENGINE - 1ST STAGE GAS-GENERATOR TURBINE OR HP TURBINE WHEEL 23088906 MW65623 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0	15000		14550
725200-0102	NO. 1 ENGINE - 2ND STAGE GAS-GENERATOR TURBINE OR HP TURBINE WHEEL 23088817 MW64359 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0	15000		14550
725200-0105	NO. 1 ENGINE - HP TURBINE ROTOR 1ST TO 2ND STAGE TURBINE SPACER 23076778 TW521174 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0	15000		14550
725281	NO. 1 ENGINE - STAGE 1 TURBINE WHEEL RING SEAL 23060273 EU254140 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282	NO. 1 ENGINE - HPT 2ND STAGE (BLADED) WHEEL ASSEMBLY 23074464 MW64359 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (01)	NO. 1 ENGINE - NO.1 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (02)	NO. 1 ENGINE - NO.2 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (03)	NO. 1 ENGINE - NO.3 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (04)	NO. 1 ENGINE - NO.4 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (05)	NO. 1 ENGINE - NO.5 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725282 (06)	NO. 1 ENGINE - NO.6 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (07)	NO. 1 ENGINE - NO.7 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (08)	NO. 1 ENGINE - NO.8 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (09)	NO. 1 ENGINE - NO.9 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (10)	NO. 1 ENGINE - NO.10 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (11)	NO. 1 ENGINE - NO.11 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (12)	NO. 1 ENGINE - NO.12 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (13)	NO. 1 ENGINE - NO.13 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (14)	NO. 1 ENGINE - NO.14 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (15)	NO. 1 ENGINE - NO.15 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (16)	NO. 1 ENGINE - NO.16 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725282 (17)	NO. 1 ENGINE - NO.17 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (18)	NO. 1 ENGINE - NO.18 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (19)	NO. 1 ENGINE - NO.19 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (20)	NO. 1 ENGINE - NO.20 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (21)	NO. 1 ENGINE - NO.21 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (22)	NO. 1 ENGINE - NO.22 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (23)	NO. 1 ENGINE - NO.23 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (24)	NO. 1 ENGINE - NO.24 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (25)	NO. 1 ENGINE - NO.25 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (26)	NO. 1 ENGINE - NO.26 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (27)	NO. 1 ENGINE - NO.27 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725282 (28)	NO. 1 ENGINE - NO.28 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (29)	NO. 1 ENGINE - NO.29 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (30)	NO. 1 ENGINE - NO.30 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (31)	NO. 1 ENGINE - NO.31 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (32)	NO. 1 ENGINE - NO.32 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (33)	NO. 1 ENGINE - NO.33 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (34)	NO. 1 ENGINE - NO.34 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (35)	NO. 1 ENGINE - NO.35 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (36)	NO. 1 ENGINE - NO.36 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (37)	NO. 1 ENGINE - NO.37 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (38)	NO. 1 ENGINE - NO.38 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725282 (39)	NO. 1 ENGINE - NO.39 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (40)	NO. 1 ENGINE - NO.40 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (41)	NO. 1 ENGINE - NO.41 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (42)	NO. 1 ENGINE - NO.42 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (43)	NO. 1 ENGINE - NO.43 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (44)	NO. 1 ENGINE - NO.44 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (45)	NO. 1 ENGINE - NO.45 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (46)	NO. 1 ENGINE - NO.46 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (47)	NO. 1 ENGINE - NO.47 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (48)	NO. 1 ENGINE - NO.48 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (49)	NO. 1 ENGINE - NO.49 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725282 (50)	NO. 1 ENGINE - NO.50 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (51)	NO. 1 ENGINE - NO.51 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (52)	NO. 1 ENGINE - NO.52 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (53)	NO. 1 ENGINE - NO.53 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (54)	NO. 1 ENGINE - NO.54 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (55)	NO. 1 ENGINE - NO.55 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (56)	NO. 1 ENGINE - NO.56 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (57)	NO. 1 ENGINE - NO.57 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (58)	NO. 1 ENGINE - NO.58 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (59)	NO. 1 ENGINE - NO.59 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (60)	NO. 1 ENGINE - NO.60 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725282 (61)	NO. 1 ENGINE - NO.61 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (62)	NO. 1 ENGINE - NO.62 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (63)	NO. 1 ENGINE - NO.63 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (64)	NO. 1 ENGINE - NO.64 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (65)	NO. 1 ENGINE - NO.65 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (66)	NO. 1 ENGINE - NO.66 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (67)	NO. 1 ENGINE - NO.67 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (68)	NO. 1 ENGINE - NO.68 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (69)	NO. 1 ENGINE - NO.69 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (70)	NO. 1 ENGINE - NO.70 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (71)	NO. 1 ENGINE - NO.71 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725282 (72)	NO. 1 ENGINE - NO.72 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (73)	NO. 1 ENGINE - NO.73 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (74)	NO. 1 ENGINE - NO.74 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (75)	NO. 1 ENGINE - NO.75 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725282 (76)	NO. 1 ENGINE - NO.76 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725283	NO. 1 ENGINE - STAGE 2 TURBINE BLADES PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284	NO. 1 ENGINE - HPT 1ST STAGE (BLADED) WHEEL ASSEMBLY 23074355 MW65623 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (01)	NO. 1 ENGINE - NO.1 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (02)	NO. 1 ENGINE - NO.2 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (03)	NO. 1 ENGINE - NO.3 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (04)	NO. 1 ENGINE - NO.4 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725284 (05)	NO. 1 ENGINE - NO.5 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (06)	NO. 1 ENGINE - NO.6 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (07)	NO. 1 ENGINE - NO.7 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (08)	NO. 1 ENGINE - NO.8 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (09)	NO. 1 ENGINE - NO.9 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (10)	NO. 1 ENGINE - NO.10 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (11)	NO. 1 ENGINE - NO.11 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (12)	NO. 1 ENGINE - NO.12 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (13)	NO. 1 ENGINE - NO.13 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (14)	NO. 1 ENGINE - NO.14 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (15)	NO. 1 ENGINE - NO.15 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725284 (16)	NO. 1 ENGINE - NO.16 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (17)	NO. 1 ENGINE - NO.17 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (18)	NO. 1 ENGINE - NO.18 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (19)	NO. 1 ENGINE - NO.19 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (20)	NO. 1 ENGINE - NO.20 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (21)	NO. 1 ENGINE - NO.21 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (22)	NO. 1 ENGINE - NO.22 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (23)	NO. 1 ENGINE - NO.23 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (24)	NO. 1 ENGINE - NO.24 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (25)	NO. 1 ENGINE - NO.25 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (26)	NO. 1 ENGINE - NO.26 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725284 (27)	NO. 1 ENGINE - NO.27 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (28)	NO. 1 ENGINE - NO.28 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (29)	NO. 1 ENGINE - NO.29 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (30)	NO. 1 ENGINE - NO.30 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (31)	NO. 1 ENGINE - NO.31 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (32)	NO. 1 ENGINE - NO.32 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (33)	NO. 1 ENGINE - NO.33 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (34)	NO. 1 ENGINE - NO.34 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (35)	NO. 1 ENGINE - NO.35 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (36)	NO. 1 ENGINE - NO.36 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (37)	NO. 1 ENGINE - NO.37 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725284 (38)	NO. 1 ENGINE - NO.38 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (39)	NO. 1 ENGINE - NO.39 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (40)	NO. 1 ENGINE - NO.40 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (41)	NO. 1 ENGINE - NO.41 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (42)	NO. 1 ENGINE - NO.42 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (43)	NO. 1 ENGINE - NO.43 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (44)	NO. 1 ENGINE - NO.44 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (45)	NO. 1 ENGINE - NO.45 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (46)	NO. 1 ENGINE - NO.46 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (47)	NO. 1 ENGINE - NO.47 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (48)	NO. 1 ENGINE - NO.48 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725284 (49)	NO. 1 ENGINE - NO.49 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (50)	NO. 1 ENGINE - NO.50 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (51)	NO. 1 ENGINE - NO.51 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (52)	NO. 1 ENGINE - NO.52 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (53)	NO. 1 ENGINE - NO.53 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (54)	NO. 1 ENGINE - NO.54 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (55)	NO. 1 ENGINE - NO.55 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (56)	NO. 1 ENGINE - NO.56 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (57)	NO. 1 ENGINE - NO.57 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725284 (58)	NO. 1 ENGINE - NO.58 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725285	NO. 1 ENGINE - 1ST STAGE HPT BLADES PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725289	NO. 1 ENGINE - AIR DISTRIBUTION RING 23060842 LT222704 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725700	NO. 1 ENGINE - LPT TURBINE ASSEMBLY 23088277 LA37843 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725702	NO. 1 ENGINE - LPT CASE ASSEMBLY 23079336 LA37843 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725703	NO. 1 ENGINE - LP TURBINE STAGE 1 VANE RING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725707	NO. 1 ENGINE - INTERSHAFT CARBON SEAL 23072561 KV52M67 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725800	NO. 1 ENGINE - BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725800-0101	NO. 1 ENGINE - LP TURBINE ROTOR 1ST STAGE LOW PRESSURE TURBINE WHEEL 23076801 MW63847 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0	15000		14550
725800-0102	NO. 1 ENGINE - LP TURBINE ROTOR 2ND STAGE LOW PRESSURE TURBINE WHEEL 23088281 MW62207 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0	15000		14550
725800-0103	NO. 1 ENGINE - LP TURBINE ROTOR 3RD STAGE LOW PRESSURE TURBINE WHEEL 23079224 MW59446 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0	15000		14550
725800-0104	NO. 1 ENGINE - LOW PRESSURE TURBINE INTERSTAGE AFT SPACER 23054049 TW519378 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0	15000		14550
725800-0105	NO. 1 ENGINE - LOW PRESSURE TURBINE INTERSTAGE FORWARD SPACER 23054049 TW519777 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0	15000		14550

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725800-0106	NO. 1 ENGINE - LP TURBINE ROTOR LOW PRESSURE TURBINE FORWARD SHAFT 23074538 GV265160	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			14550
LIFE LIMIT	REF: GENERIC NO REF	ENC	15000	TSN:0			0		15000	
725802	NO. 1 ENGINE - REAR LPT SHAFT 23070352 GV264192	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725883	NO. 1 ENGINE - LPT-1 ROTATING SEAL 23073958 DD533981	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725884	NO. 1 ENGINE - LPT WHEEL ASSEMBLY 23088283 MW62207	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725885	NO. 1 ENGINE - LPT (BLADED) WHEEL ASSEMBLY 23070047 MW59446	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725886	NO. 1 ENGINE - LPT STAGE 1 (BLADED) WHEEL ASSEMBLY 23076827 MW63847	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725900	NO. 1 ENGINE - NO. 7 CARBON SEAL ASSEMBLY 23061737 KV4815H	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
725910	NO. 1 ENGINE - ROLLER BEARING 23071198 NWH100485	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
726303	NO. 1 ENGINE - RADIAL DRIVE QUILL SHAFT 23077207 GV263916	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
727100	NO. 1 ENGINE - RIGHT COMPRESSOR INNER DUCT ASSEMBLY 23080558 HQR0462CI	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
727101	NO. 1 ENGINE - LEFT COMPRESSOR INNER DUCT ASSEMBLY 23080559 HQL0445CI	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
727102	NO. 1 ENGINE - LOWER COMPRESSOR INNER DUCT ASSEMBLY 23074096 HQI0448CI REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
727300	NO. 1 ENGINE - OUTER BYPASS DUCT ASSEMBLY 23088394 HQ282923KJ REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
727302	NO. 1 ENGINE - BYPASS SUPPORT ASSEMBLY 23079823 33062200036 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
732501	NO. 1 ENGINE - NO. 1 FADEC 23089364 BX162722 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
732503	NO. 1 ENGINE - NO. 2 FADEC 23089364 BX162726 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
ENGINE NO. 2 Model : AE3007A2 Serial # CAE-313246 Part # 23087636										
72-21-20-220-002-A00	NO. 2 ENGINE - DETAIL INSPECT	FAN SPINNER P/N 23054034, 23064250, OR 23065046 ONLY								
		MOS HRS/MSC ENC	N/A				05-OCT-2010 0 0			
72-62-01-212-001-A00	NO. 2 ENGINE - GENERAL VISUAL INSPECTION	ACCESSORY GEARBOX RETENTION CABLES (L650 ONLY)								
		MOS HRS/MSC ENC	1000				21-JAN-2017 884.1 443	(1884.1) 1884.1		980.8
720000-0103	NO. 2 ENGINE - GENERAL VISUAL INSPECTION	OF ACCESSORY DRIVES SECTION (MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01)								
		MOS HRS/MSC ENC	-				05-OCT-2010 0 0			
720000-0104	NO. 2 ENGINE - GENERAL VISUAL INSPECTION	OF BYPASS SECTION (MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01)								
		MOS HRS/MSC ENC	-				05-OCT-2010 0 0			
720000-0106	NO. 2 ENGINE - GENERAL VISUAL INSPECTION	OF FUEL SYSTEM DISTRIBUTION (TUBES AND HOSES) (MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01)								
		MOS HRS/MSC ENC	-				05-OCT-2010 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
720000-0108	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF POWER CONTROL SECTION (HARNESSES) (MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01)	MOS HRS/MSC - ENC					05-OCT-2010 0 0			
	REF: MM 72-00-00									
720000-0109	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF TURBINE-INTERSTAGE THERMOCOUPLE (A) HARNESS (MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01)	MOS HRS/MSC - ENC					05-OCT-2010 0 0			
	REF: MM 72-00-00									
720000-0110	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF TURBINE-INTERSTAGE THERMOCOUPLE (B) HARNESS (MPG EQUIVALENT TASKS 71-Z411-214-001-A00 AND 71-Z411-214-001-A01)	MOS HRS/MSC - ENC					05-OCT-2010 0 0			
	REF: MM 72-00-00									
720000-0111	NO. 2 ENGINE - PERFORM SPECIAL PROCEDURES ON ENGINE	MOS HRS/MSC N/A ENC					05-OCT-2010 0 0			
	REF: GENERIC NO REF									
720038	NO. 2 ENGINE - ACCESS DRIVE GEARBOX MODULE	MOS		TSN:0			05-OCT-2010			
	23076096	HRS/MSC O/C		TSN:0			0			
	XK10062	ENC		TSN:0			0			
	REF: GENERIC NO REF									
720039	NO. 2 ENGINE - ACCESSORY DRIVE GEARBOX	MOS		TSN:0			05-OCT-2010			
	23086770	HRS/MSC O/C		TSN:0			0			
	XK10062	ENC		TSN:0			0			
	REF: GENERIC NO REF									
721000	NO. 2 ENGINE - FAN ROTOR ASSEMBLY	MOS		TSN:0			05-OCT-2010			
	23087158	HRS/MSC O/C		TSN:0			0			
	MW64035	ENC		TSN:0			0			
	REF: GENERIC NO REF									
721003	NO. 2 ENGINE - INSPECT ENGINE 100 CYCLES	MOS HRS/MSC A/R ENC					05-OCT-2010 0 0			
	REF: MM 05-13-00									
722100-0101	NO. 2 ENGINE - FAN WHEEL	MOS		TSN:0			05-OCT-2010			
	23086748	HRS/MSC		TSN:0			0			
	MW64035	ENC	20000	TSN:0			0	20000	19550	
LIFE LIMIT	REF: See Workcard									
722100-0102	NO. 2 ENGINE - FAN DRIVE SHAFT	MOS		TSN:0			05-OCT-2010			
	23074382	HRS/MSC		TSN:0			0			
	GV265933	ENC	20000	TSN:0			0	20000	19550	
LIFE LIMIT	REF: GENERIC NO REF									

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
722101-0101	NO. 2 ENGINE - FORWARD FAN BLADE RETAINER 23086783 GX106218	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
LIFE LIMIT	REF: GENERIC NO REF	ENC	20000	TSN:0			0	20000		19550
722102	NO. 2 ENGINE - FAN SUPPORT BEARING HOUSING ASSEMBLY 23081557 HN503044	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722103	NO. 2 ENGINE - FRONT FRAME ASSEMBLY 23083816 LA38162	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722103-0101	NO. 2 ENGINE - CLEAN AND DO THE DETAILED INSPECTION OF FAN BLADES MOS HRS/MSC ENC	N/A					05-OCT-2010 0 0			
722104	NO. 2 ENGINE - FAN SPINNER ASSEMBLY 23086790 FF380573	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722107	NO. 2 ENGINE - FAN CASE ASSEMBLY 23086777 GX108660	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722109	NO. 2 ENGINE - SEG CARBON FAN SEAL ASSEMBLY 23073567 KVA6115	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722111	NO. 2 ENGINE - SPANNER NUT 23061181 DD522294	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722112	NO. 2 ENGINE - BEARING SELF-LOCKING NUT PN SN-UNKNOWN	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722113	NO. 2 ENGINE - ROLLER BEARING 23054010 AF76791	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722114 (01)	NO. 2 ENGINE - BLADE FAN PN SN-UNKNOWN	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
722114 (02)	NO. 2 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722114 (03)	NO. 2 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722114 (04)	NO. 2 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722114 (05)	NO. 2 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722114 (06)	NO. 2 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722114 (07)	NO. 2 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722114 (08)	NO. 2 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722114 (09)	NO. 2 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722114 (10)	NO. 2 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722114 (11)	NO. 2 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722114 (12)	NO. 2 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
722114 (13)	NO. 2 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722114 (14)	NO. 2 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722114 (15)	NO. 2 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722114 (16)	NO. 2 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722114 (17)	NO. 2 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722114 (18)	NO. 2 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722114 (19)	NO. 2 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722114 (20)	NO. 2 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722114 (21)	NO. 2 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722114 (22)	NO. 2 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722114 (23)	NO. 2 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
722114 (24)	NO. 2 ENGINE - BLADE FAN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722500-0101	NO. 2 ENGINE - BEVEL PINION - RADIAL DRIVE GEARSHAFT 23081447 UG41793 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722501	NO. 2 ENGINE - FRONT SUMP BEVEL GEAR 23086721 UG45451 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722502	NO. 2 ENGINE - FRONT-SUMP HOUSING ASSEMBLY 23083827 MQ518973 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722503	NO. 2 ENGINE - MID-SPAN ROLLER BEARING 23069586 JJ218 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722504	NO. 2 ENGINE - HORIZONTAL QUILL SHAFT 23075501 GV258592 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722506	NO. 2 ENGINE - NO.4 CARBON-TANDEM SEAL ASSEMBLY 23085863 KVH1706 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722508	NO. 2 ENGINE - 80 X 100 X 11 MM ROLLER BEARING 23062542 NWG101062 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722509	NO. 2 ENGINE - 87 X 108 X 11 BALL BEARING 23056839 AF72839 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722510	NO. 2 ENGINE - FLANGED ROLLER BEARING 23063132 NWF108325 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722511	NO. 2 ENGINE - ROLLER BEARING 23077657 AF73638 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
722512	NO. 2 ENGINE - RADIAL DRIVE GEARSHAFT ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722513	NO. 2 ENGINE - CONRAD BEARING 23064226 NWH100217 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
722514-0101	NO. 2 ENGINE - NO. 1 POWER TURBINE (LPT) BALL BEARING 23088547 NWH100561 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
723000	NO. 2 ENGINE - COMPRESSOR ROTOR ASSEMBLY 23086657 A22696 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
723017	NO. 2 ENGINE - COMP/TURBINE SHAFT 23073165 L347005 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
723018	NO. 2 ENGINE - COMPRESSOR STUB SHAFT 23077677 GV264393 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
723019	NO. 2 ENGINE - COMPRESSOR TIE BOLT 23076018 L351437 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
723020	NO. 2 ENGINE - 9TH STAGE COMPRESSOR CASE 23077726 JB228882 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
723500-0101	NO. 2 ENGINE - 1ST STAGE COMPRESSOR WHEEL 23084156 L349766 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0	15000	14550	
723500-0102	NO. 2 ENGINE - 2ND STAGE COMPRESSOR WHEEL 23084157 L346459 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0	15000	14550	
723500-0103	NO. 2 ENGINE - 3RD STAGE COMPRESSOR WHEEL 23084158 L355076 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0	15000	14550	



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
723500-0104	NO. 2 ENGINE - 4TH STAGE COMPRESSOR WHEEL 23084159 L345424	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0		15000	14550
LIFE LIMIT	REF: GENERIC NO REF									
723500-0105	NO. 2 ENGINE - 5TH STAGE COMPRESSOR WHEEL 23084160 L349025	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0		15000	14550
LIFE LIMIT	REF: GENERIC NO REF									
723500-0106	NO. 2 ENGINE - 6TH STAGE COMPRESSOR WHEEL 23084161 L351061	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0		15000	14550
LIFE LIMIT	REF: GENERIC NO REF									
723500-0107	NO. 2 ENGINE - 7TH STAGE COMPRESSOR WHEEL 23084350 L333899	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0		15000	14550
LIFE LIMIT	REF: GENERIC NO REF									
723500-0108	NO. 2 ENGINE - 8TH STAGE COMPRESSOR WHEEL 23084163 L342839	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0		15000	14550
LIFE LIMIT	REF: GENERIC NO REF									
723500-0109	NO. 2 ENGINE - 9TH STAGE COMPRESSOR WHEEL 23084164 L347550	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0		15000	14550
LIFE LIMIT	REF: GENERIC NO REF									
723500-0110	NO. 2 ENGINE - 10TH STAGE COMPRESSOR WHEEL 23084165 L348007	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0		15000	14550
LIFE LIMIT	REF: GENERIC NO REF									
723500-0111	NO. 2 ENGINE - 11TH STAGE COMPRESSOR WHEEL 23084166 L354096	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0		15000	14550
LIFE LIMIT	REF: GENERIC NO REF									
723500-0112	NO. 2 ENGINE - 12TH STAGE COMPRESSOR WHEEL 23084167 L349558	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0		15000	14550
LIFE LIMIT	REF: GENERIC NO REF									
723500-0113	NO. 2 ENGINE - 13TH STAGE COMPRESSOR WHEEL 23084283 L331482	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0		15000	14550
LIFE LIMIT	REF: GENERIC NO REF									
723500-0114	NO. 2 ENGINE - 14TH STAGE COMPRESSOR WHEEL 23084284 L313691	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0		15000	14550
LIFE LIMIT	REF: GENERIC NO REF									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
723500-0120	NO. 2 ENGINE - COMPRESSOR SHAFT CONE ASSEMBLY 23084170 L336964	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
LIFE LIMIT	REF: GENERIC NO REF		15000					15000		14550
723700	NO. 2 ENGINE - COMPRESSOR CASE ASSEMBLY 23074746 JB228882	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
723705	NO. 2 ENGINE - COMPRESSOR DIFFUSER 23088638 NY218674	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
723707	NO. 2 ENGINE - SPLIT BALL BEARING 23080325 NWSETF10064	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
723902	NO. 2 ENGINE - NO. 6 CARBON CENTER SUMP SEAL ASSEMBLY 23074617 KVC2528	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
723903	NO. 2 ENGINE - NO. 5 CARBON CENTER SUMP SEAL ASSEMBLY 23074616 KVC2379	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
723904	NO. 2 ENGINE - CENTER SUMP HOUSING ASSEMBLY 23074615 NY218438	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
724500	NO. 2 ENGINE - COMBUSTION LINER ASSEMBLY 23077933 JE62746	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725000	NO. 2 ENGINE - HPT ROTOR ASSEMBLY 23074650 A73160	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725010	NO. 2 ENGINE - ROTOR ASSY-LPT ROTOR ASSEMBLY 23089031 A83140	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725181	NO. 2 ENGINE - NO.1 HP TURBINE 2ND STAGE VANE ASSEMBLY 23070987 371753	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725182	NO. 2 ENGINE - NO. 2 HP TURBINE 2ND STAGE VANE ASSEMBLY 23070987 376817 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725183	NO. 2 ENGINE - NO.3 HP TURBINE 2ND STAGE VANE ASSEMBLY 23070987 371741 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725184	NO. 2 ENGINE - NO.4 HP TURBINE 2ND STAGE VANE ASSEMBLY 23070987 371737 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725185	NO. 2 ENGINE - NO.5 HP TURBINE 2ND STAGE VANE ASSEMBLY 23070987 371735 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725186	NO. 2 ENGINE - NO.6 HP TURBINE 2ND STAGE VANE ASSEMBLY 23070987 371715 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725187	NO. 2 ENGINE - NO.7 HP TURBINE 2ND STAGE VANE ASSEMBLY 23070987 371714 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725188	NO. 2 ENGINE - NO.8 HP TURBINE 2ND STAGE VANE ASSEMBLY 23070987 371713 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725189	NO. 2 ENGINE - NO.9 HP TURBINE 2ND STAGE VANE ASSEMBLY 23070987 371712 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725190	NO. 2 ENGINE - NO.10 HP TURBINE 2ND STAGE VANE ASSEMBLY 23070987 371711 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725191	NO. 2 ENGINE - NO.11 HP TURBINE 2ND STAGE VANE ASSEMBLY 23070987 371710 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725192	NO. 2 ENGINE - NO.12 HP TURBINE 2ND STAGE VANE ASSEMBLY 23070987 371709 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725193	NO. 2 ENGINE - NO.13 HP TURBINE 2ND STAGE VANE ASSEMBLY 23070987 371708 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725194	NO. 2 ENGINE - NO.14 HP TURBINE 2ND STAGE VANE ASSEMBLY 23070987 371701 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725195	NO. 2 ENGINE - NO.15 HP TURBINE 2ND STAGE VANE ASSEMBLY 23070987 371694 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725196	NO. 2 ENGINE - NO.16 HP TURBINE 2ND STAGE VANE ASSEMBLY 23070987 371691 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725200-0101	NO. 2 ENGINE - 1ST STAGE GAS-GENERATOR TURBINE OR HP TURBINE WHEEL 23088906 MW65578 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0	15000		14550
725200-0102	NO. 2 ENGINE - 2ND STAGE GAS-GENERATOR TURBINE OR HP TURBINE WHEEL 23088817 MW64125 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0	15000		14550
725200-0105	NO. 2 ENGINE - HP TURBINE ROTOR 1ST TO 2ND STAGE TURBINE SPACER 23076778 TW521182 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0	15000		14550
725281	NO. 2 ENGINE - STAGE 1 TURBINE WHEEL RING SEAL 23060273 EU253766 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282	NO. 2 ENGINE - HPT 2ND STAGE (BLADED) WHEEL ASSEMBLY 23074464 MW64125 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (01)	NO. 2 ENGINE - NO.1 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (02)	NO. 2 ENGINE - NO.2 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725282 (03)	NO. 2 ENGINE - NO.3 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (04)	NO. 2 ENGINE - NO.4 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (05)	NO. 2 ENGINE - NO.5 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (06)	NO. 2 ENGINE - NO.6 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (07)	NO. 2 ENGINE - NO.7 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (08)	NO. 2 ENGINE - NO.8 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (09)	NO. 2 ENGINE - NO.9 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (10)	NO. 2 ENGINE - NO.10 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (11)	NO. 2 ENGINE - NO.11 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (12)	NO. 2 ENGINE - NO.12 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (13)	NO. 2 ENGINE - NO.13 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725282 (14)	NO. 2 ENGINE - NO.14 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (15)	NO. 2 ENGINE - NO.15 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (16)	NO. 2 ENGINE - NO.16 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (17)	NO. 2 ENGINE - NO.17 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (18)	NO. 2 ENGINE - NO.18 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (19)	NO. 2 ENGINE - NO.19 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (20)	NO. 2 ENGINE - NO.20 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (21)	NO. 2 ENGINE - NO.21 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (22)	NO. 2 ENGINE - NO.22 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (23)	NO. 2 ENGINE - NO.23 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (24)	NO. 2 ENGINE - NO.24 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725282 (25)	NO. 2 ENGINE - NO.25 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (26)	NO. 2 ENGINE - NO.26 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (27)	NO. 2 ENGINE - NO.27 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (28)	NO. 2 ENGINE - NO.28 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (29)	NO. 2 ENGINE - NO.29 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (30)	NO. 2 ENGINE - NO.30 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (31)	NO. 2 ENGINE - NO.31 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (32)	NO. 2 ENGINE - NO.32 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (33)	NO. 2 ENGINE - NO.33 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (34)	NO. 2 ENGINE - NO.34 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (35)	NO. 2 ENGINE - NO.35 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725282 (36)	NO. 2 ENGINE - NO.36 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (37)	NO. 2 ENGINE - NO.37 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (38)	NO. 2 ENGINE - NO.38 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (39)	NO. 2 ENGINE - NO.39 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (40)	NO. 2 ENGINE - NO.40 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (41)	NO. 2 ENGINE - NO.41 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (42)	NO. 2 ENGINE - NO.42 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (43)	NO. 2 ENGINE - NO.43 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (44)	NO. 2 ENGINE - NO.44 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (45)	NO. 2 ENGINE - NO.45 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (46)	NO. 2 ENGINE - NO.46 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725282 (47)	NO. 2 ENGINE - NO.47 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (48)	NO. 2 ENGINE - NO.48 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (49)	NO. 2 ENGINE - NO.49 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (50)	NO. 2 ENGINE - NO.50 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (51)	NO. 2 ENGINE - NO.51 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (52)	NO. 2 ENGINE - NO.52 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (53)	NO. 2 ENGINE - NO.53 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (54)	NO. 2 ENGINE - NO.54 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (55)	NO. 2 ENGINE - NO.55 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (56)	NO. 2 ENGINE - NO.56 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (57)	NO. 2 ENGINE - NO.57 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725282 (58)	NO. 2 ENGINE - NO.58 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (59)	NO. 2 ENGINE - NO.59 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (60)	NO. 2 ENGINE - NO.60 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (61)	NO. 2 ENGINE - NO.61 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (62)	NO. 2 ENGINE - NO.62 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (63)	NO. 2 ENGINE - NO.63 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (64)	NO. 2 ENGINE - NO.64 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (65)	NO. 2 ENGINE - NO.65 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (66)	NO. 2 ENGINE - NO.66 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (67)	NO. 2 ENGINE - NO.67 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (68)	NO. 2 ENGINE - NO.68 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725282 (69)	NO. 2 ENGINE - NO.69 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (70)	NO. 2 ENGINE - NO.70 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (71)	NO. 2 ENGINE - NO.71 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (72)	NO. 2 ENGINE - NO.72 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (73)	NO. 2 ENGINE - NO.73 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (74)	NO. 2 ENGINE - NO.74 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (75)	NO. 2 ENGINE - NO.75 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725282 (76)	NO. 2 ENGINE - NO.76 HP TURBINE 2ND STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725283	NO. 2 ENGINE - STAGE 2 TURBINE BLADES PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284	NO. 2 ENGINE - HPT 1ST STAGE (BLADED) WHEEL ASSEMBLY 23074355 MW65578 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (01)	NO. 2 ENGINE - NO.1 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725284 (02)	NO. 2 ENGINE - NO.2 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (03)	NO. 2 ENGINE - NO.3 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (04)	NO. 2 ENGINE - NO.4 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (05)	NO. 2 ENGINE - NO.5 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (06)	NO. 2 ENGINE - NO.6 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (07)	NO. 2 ENGINE - NO.7 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (08)	NO. 2 ENGINE - NO.8 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (09)	NO. 2 ENGINE - NO.9 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (10)	NO. 2 ENGINE - NO.10 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (11)	NO. 2 ENGINE - NO.11 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (12)	NO. 2 ENGINE - NO.12 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725284 (13)	NO. 2 ENGINE - NO.13 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (14)	NO. 2 ENGINE - NO.14 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (15)	NO. 2 ENGINE - NO.15 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (16)	NO. 2 ENGINE - NO.16 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (17)	NO. 2 ENGINE - NO.17 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (18)	NO. 2 ENGINE - NO.18 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (19)	NO. 2 ENGINE - NO.19 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (20)	NO. 2 ENGINE - NO.20 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (21)	NO. 2 ENGINE - NO.21 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (22)	NO. 2 ENGINE - NO.22 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (23)	NO. 2 ENGINE - NO.23 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725284 (24)	NO. 2 ENGINE - NO.24 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (25)	NO. 2 ENGINE - NO.25 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (26)	NO. 2 ENGINE - NO.26 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (27)	NO. 2 ENGINE - NO.27 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (28)	NO. 2 ENGINE - NO.28 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (29)	NO. 2 ENGINE - NO.29 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (30)	NO. 2 ENGINE - NO.30 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (31)	NO. 2 ENGINE - NO.31 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (32)	NO. 2 ENGINE - NO.32 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (33)	NO. 2 ENGINE - NO.33 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (34)	NO. 2 ENGINE - NO.34 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725284 (35)	NO. 2 ENGINE - NO.35 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (36)	NO. 2 ENGINE - NO.36 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (37)	NO. 2 ENGINE - NO.37 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (38)	NO. 2 ENGINE - NO.38 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (39)	NO. 2 ENGINE - NO.39 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (40)	NO. 2 ENGINE - NO.40 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (41)	NO. 2 ENGINE - NO.41 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (42)	NO. 2 ENGINE - NO.42 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (43)	NO. 2 ENGINE - NO.43 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (44)	NO. 2 ENGINE - NO.44 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (45)	NO. 2 ENGINE - NO.45 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725284 (46)	NO. 2 ENGINE - NO.46 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (47)	NO. 2 ENGINE - NO.47 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (48)	NO. 2 ENGINE - NO.48 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (49)	NO. 2 ENGINE - NO.49 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (50)	NO. 2 ENGINE - NO.50 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (51)	NO. 2 ENGINE - NO.51 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (52)	NO. 2 ENGINE - NO.52 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (53)	NO. 2 ENGINE - NO.53 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (54)	NO. 2 ENGINE - NO.54 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (55)	NO. 2 ENGINE - NO.55 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (56)	NO. 2 ENGINE - NO.56 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725284 (57)	NO. 2 ENGINE - NO.57 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725284 (58)	NO. 2 ENGINE - NO.58 HP TURBINE 1ST STAGE BLADE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725285	NO. 2 ENGINE - 1ST STAGE HPT BLADES PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725289	NO. 2 ENGINE - AIR DISTRIBUTION RING 23060842 LT222762 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725700	NO. 2 ENGINE - LPT TURBINE ASSEMBLY 23088277 LA37838 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725702	NO. 2 ENGINE - LPT CASE ASSEMBLY 23079336 LA37838 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725703	NO. 2 ENGINE - LP TURBINE STAGE 1 VANE RING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725707	NO. 2 ENGINE - INTERSHAFT CARBON SEAL 23072561 KV52M64 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725800	NO. 2 ENGINE - BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
725800-0101	NO. 2 ENGINE - LP TURBINE ROTOR 1ST STAGE LOW PRESSURE TURBINE WHEEL 23076801 MW62149 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0	15000		14550
725800-0102	NO. 2 ENGINE - LP TURBINE ROTOR 2ND STAGE LOW PRESSURE TURBINE WHEEL 23088281 MW62218 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0	15000		14550



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
725800-0103	NO. 2 ENGINE - LP TURBINE ROTOR 3RD STAGE LOW PRESSURE TURBINE WHEEL 23079224 MW59438	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0		15000	14550
LIFE LIMIT	REF: GENERIC NO REF		15000							
725800-0104	NO. 2 ENGINE - LOW PRESSURE TURBINE INTERSTAGE AFT SPACER 23054049 TW519795	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0		15000	14550
LIFE LIMIT	REF: GENERIC NO REF		15000							
725800-0105	NO. 2 ENGINE - LOW PRESSURE TURBINE INTERSTAGE FORWARD SPACER 23054049 TW519770	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0		15000	14550
LIFE LIMIT	REF: GENERIC NO REF		15000							
725800-0106	NO. 2 ENGINE - LP TURBINE ROTOR LOW PRESSURE TURBINE FORWARD SHAFT 23074538 GV265093	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0		15000	14550
LIFE LIMIT	REF: GENERIC NO REF		15000							
725802	NO. 2 ENGINE - REAR LPT SHAFT 23070352 GV264159	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
LIFE LIMIT	REF: GENERIC NO REF									
725883	NO. 2 ENGINE - LPT-1 ROTATING SEAL 23073958 DD533977	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
LIFE LIMIT	REF: GENERIC NO REF									
725884	NO. 2 ENGINE - LPT WHEEL ASSEMBLY 23088283 MW62218	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
LIFE LIMIT	REF: GENERIC NO REF									
725885	NO. 2 ENGINE - LPT (BLADED) WHEEL ASSEMBLY 23070047 MW59438	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
LIFE LIMIT	REF: GENERIC NO REF									
725886	NO. 2 ENGINE - LPT STAGE 1 (BLADED) WHEEL ASSEMBLY 23076827 MW62149	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
LIFE LIMIT	REF: GENERIC NO REF									
725900	NO. 2 ENGINE - NO. 7 CARBON SEAL ASSEMBLY 23061737 KV4812H	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
LIFE LIMIT	REF: GENERIC NO REF									
725910	NO. 2 ENGINE - ROLLER BEARING 23071198 NWE106351	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
LIFE LIMIT	REF: GENERIC NO REF									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING	
726303	NO. 2 ENGINE - RADIAL DRIVE QUILL SHAFT 23077207 GV263959 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0				
727100	NO. 2 ENGINE - RIGHT COMPRESSOR INNER DUCT ASSEMBLY 23080558 HQR0529CI REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0				
727101	NO. 2 ENGINE - LEFT COMPRESSOR INNER DUCT ASSEMBLY 23080559 HQL0644CI REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0				
727102	NO. 2 ENGINE - LOWER COMPRESSOR INNER DUCT ASSEMBLY 23074096 HQ10688CI REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0				
727300	NO. 2 ENGINE - OUTER BYPASS DUCT ASSEMBLY 23088394 HQ371574KJ REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0				
727302	NO. 2 ENGINE - BYPASS SUPPORT ASSEMBLY 23079823 33062200043 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0				
732501	NO. 2 ENGINE - NO. 1 FADEC 23089364 BX162723 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0				
732503	NO. 2 ENGINE - NO. 2 FADEC 23089364 BX162712 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0				
CHAPTER 73	ENGINE FUEL AND CONTROL										
73-22-01-720-003-A00 (s)	FUNCTIONALLY CHECK MULTI-FUNCTION DISPLAY FOR ENG() LT FAULT AND ENG() SCHED MAINT REPAIR MAINTENANCE MESSAGES						PKG				
	PKG 5001	MOS	6	+15d		-36	21-JAN-2017				
LOW U - STRUCTURED	REF: AMM 73-22-01	HRS/MSC AFL	250	+20			884.1 443				
732200-0101	LEFT ENGINE PRESSURE DERIVATION SENSOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0				
732200-0102	LEFT ENGINE PRESSURE DERIVATION SENSOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0				

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
732200-0103	RIGHT ENGINE PRESSURE DERIVATION SENSOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
732200-0104	RIGHT ENGINE PRESSURE DERIVATION SENSOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
732201-0201	L ENG 1A FADEC, BASIC, ELECTRICAL CONTROL UNIT 23089364 BX162722 REF: AMM 73-22-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
732201-0202	L ENG 1B FADEC, BASIC, ELECTRICAL CONTROL UNIT 23089364 BX162726 REF: AMM 73-22-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
732201-0203	R ENG 2A FADEC, BASIC, ELECTRICAL CONTROL UNIT 23089364 BX162712 REF: AMM 73-22-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
732201-0204	R ENG 2B FADEC, BASIC, ELECTRICAL CONTROL UNIT 23089364 BX162723 REF: AMM 73-22-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
ENGINE NO. 1 Model : AE3007A2 Serial # CAE-313249 Part # 23087636										
73-11-00-960-001-A00	NO. 1 ENGINE - DISCARD OF ENGINE FUEL FILTER ELEMENT	MOS HRS/MSC ENC	2000				21-JAN-2017 884.1 443	(2884.1) 2884.1		1980.8
SYSTEM	REF:									
73-25-10-200-801	NO. 1 ENGINE - INSPECTION OF FADEC FAULT	MOS HRS/MSC ENC	A/R				14-OCT-2010 0 0			
REF:	MM 73-25-10									
731101	NO. 1 ENGINE - FUEL NOZZLE ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
731101 (01)	NO. 1 ENGINE - NO.1 FUEL NOZZLE ASSEMBLY 23087207 VN1BKN0971 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
731101 (02)	NO. 1 ENGINE - NO.2 FUEL NOZZLE ASSEMBLY 23087207 VN1BKL1169 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
731101 (03)	NO. 1 ENGINE - NO.3 FUEL NOZZLE ASSEMBLY 23087207 VN1BKN0953 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
731101 (04)	NO. 1 ENGINE - NO.4 FUEL NOZZLE ASSEMBLY 23087207 VN1BKL1154 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
731101 (05)	NO. 1 ENGINE - NO.5 FUEL NOZZLE ASSEMBLY 23087207 VN1BKF1632 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
731101 (06)	NO. 1 ENGINE - NO.6 FUEL NOZZLE ASSEMBLY 23087207 VN1BKL1160 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
731101 (07)	NO. 1 ENGINE - NO.7 FUEL NOZZLE ASSEMBLY 23087207 VN1BKN0955 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
731101 (08)	NO. 1 ENGINE - NO.8 FUEL NOZZLE ASSEMBLY 23087207 VN1BKB0857 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
731101 (09)	NO. 1 ENGINE - NO.9 FUEL NOZZLE ASSEMBLY 23087207 VN1BKL1172 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
731101 (10)	NO. 1 ENGINE - NO.10 FUEL NOZZLE ASSEMBLY 23087207 VN1BKL1167 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
731101 (11)	NO. 1 ENGINE - NO.11 FUEL NOZZLE ASSEMBLY 23087207 VN1BKU1490 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
731101 (12)	NO. 1 ENGINE - NO.12 FUEL NOZZLE ASSEMBLY 23087207 VN1BKU1492 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
731101 (13)	NO. 1 ENGINE - NO.13 FUEL NOZZLE ASSEMBLY 23087207 VN1BKL1159 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
731101 (14)	NO. 1 ENGINE - NO.14 FUEL NOZZLE ASSEMBLY 23087207 VN1BKF0958 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
731101 (15)	NO. 1 ENGINE - NO.15 FUEL NOZZLE ASSEMBLY 23087207 VN1BKL1173 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
731101 (16)	NO. 1 ENGINE - NO.16 FUEL NOZZLE ASSEMBLY 23087207 VN1BKF1631 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
732101	NO. 1 ENGINE - METERING UNIT AND FUEL PUMP 23083988 SCP10043 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
732510	NO. 1 ENGINE - INSPECT MAINTENANCE MESSAGES (MPG EQUIVALENT TASK:73-22-01-720-003-A00) DAYS HRS/MSC ENC REF: GENERIC NO REF		-				21-JAN-2014 323.8 180			
733001	NO. 1 ENGINE - FUEL FLOWMETER 23052613 JQ-13463 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
733100	NO. 1 ENGINE - FUEL TEMPERATURE SENSOR 23087698 12139 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
ENGINE NO. 2 Model : AE3007A2 Serial # CAE-313246 Part # 23087636										
73-11-00-960-001-A00	NO. 2 ENGINE - DISCARD OF ENGINE FUEL FILTER ELEMENT MOS HRS/MSC ENC REF:		2000				21-JAN-2017 884.1 443	(2884.1) 2884.1		1980.8
73-25-10-200-801	NO. 2 ENGINE - INSPECTION OF FADEC FAULT MOS HRS/MSC ENC REF: MM 73-25-10		A/R				05-OCT-2010 0 0			
731101	NO. 2 ENGINE - FUEL NOZZLE ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
731101 (01)	NO. 2 ENGINE - NO.1 FUEL NOZZLE ASSEMBLY 23087207 VN1BKR0694 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
731101 (02)	NO. 2 ENGINE - NO.2 FUEL NOZZLE ASSEMBLY 23087207 VN1BKR0705 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
731101 (03)	NO. 2 ENGINE - NO.3 FUEL NOZZLE ASSEMBLY 23087207 VN1BKP0216 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
731101 (04)	NO. 2 ENGINE - NO.4 FUEL NOZZLE ASSEMBLY 23087207 VN1BKR0689 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
731101 (05)	NO. 2 ENGINE - NO.5 FUEL NOZZLE ASSEMBLY 23087207 VN1BKR0701 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
731101 (06)	NO. 2 ENGINE - NO.6 FUEL NOZZLE ASSEMBLY 23087207 VN1BKR0700 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
731101 (07)	NO. 2 ENGINE - NO.7 FUEL NOZZLE ASSEMBLY 23087207 VN1BKR0683 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
731101 (08)	NO. 2 ENGINE - NO.8 FUEL NOZZLE ASSEMBLY 23087207 VN1BKP0214 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
731101 (09)	NO. 2 ENGINE - NO.9 FUEL NOZZLE ASSEMBLY 23087207 VN1BKR0708 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
731101 (10)	NO. 2 ENGINE - NO.10 FUEL NOZZLE ASSEMBLY 23087207 VN1BKR0707 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
731101 (11)	NO. 2 ENGINE - NO.11 FUEL NOZZLE ASSEMBLY 23087207 VN1BKP0219 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
731101 (12)	NO. 2 ENGINE - NO.12 FUEL NOZZLE ASSEMBLY 23087207 VN1BKN1497 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
731101 (13)	NO. 2 ENGINE - NO.13 FUEL NOZZLE ASSEMBLY 23087207 VN1BKP0221 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
731101 (14)	NO. 2 ENGINE - NO.14 FUEL NOZZLE ASSEMBLY 23087207 VN1BKR0693 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
731101 (15)	NO. 2 ENGINE - NO.15 FUEL NOZZLE ASSEMBLY 23087207 VN1BKR0706 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
731101 (16)	NO. 2 ENGINE - NO.16 FUEL NOZZLE ASSEMBLY 23087207 VN1BKR0710 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
732101	NO. 2 ENGINE - METERING UNIT AND FUEL PUMP 23083988 SCP10-037 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
732510	NO. 2 ENGINE - INSPECT MAINTENANCE MESSAGES (MPG EQUIVALENT TASK:73-22-01-720-003-A00) REF: GENERIC NO REF	DAYS HRS/MSC ENC	-				21-JAN-2014 323.8 180			
733001	NO. 2 ENGINE - FUEL FLOWMETER 23052613 JQ-13400 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
733100	NO. 2 ENGINE - FUEL TEMPERATURE SENSOR 23087698 12148 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
CHAPTER 74		IGNITION								
ENGINE NO. 1 Model : AE3007A2 Serial # CAE-313249 Part # 23087636										
741102	NO. 1 ENGINE - PMA ROTOR 23075490 UN13390 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
741103	NO. 1 ENGINE - (PMA) ALTERNATOR STATOR 23075489 UN10260009 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
741301	NO. 1 ENGINE - LEFT EXCITOR IGNITION 23077617 UY10380013 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
741303	NO. 1 ENGINE - RIGHT EXCITOR IGNITION 23077617 UY10340076 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
742101	NO. 1 ENGINE - TOP IGNITOR 23062672 JH1002617 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
742103	NO. 1 ENGINE - BOTTOM IGNITOR 23062672 JH1002615 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
742105A	NO. 1 ENGINE - SPARK IGNITER (A) LEAD ASSY 23087695 UM10350042 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
742107B	NO. 1 ENGINE - SPARK IGNITER (B) LEAD ASSY 23087696 UM10360007 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
ENGINE NO. 2 Model : AE3007A2 Serial # CAE-313246 Part # 23087636										
741102	NO. 2 ENGINE - PMA ROTOR 23075490 UN10020014 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
741103	NO. 2 ENGINE - (PMA) ALTERNATOR STATOR 23075489 UN10100037 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
741301	NO. 2 ENGINE - LEFT EXCITOR IGNITION 23077617 UY10340072 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
741303	NO. 2 ENGINE - RIGHT EXCITOR IGNITION 23077617 UY10340065 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
742101	NO. 2 ENGINE - TOP IGNITOR 23062672 JH1002160 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
742103	NO. 2 ENGINE - BOTTOM IGNITOR 23062672 JH1002157 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
742105A	NO. 2 ENGINE - SPARK IGNITER (A) LEAD ASSY 23087695 UM09530036 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
742107B	NO. 2 ENGINE - SPARK IGNITER (B) LEAD ASSY 23087696 UM10170045 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
CHAPTER 75 AIR										
ENGINE NO. 1 Model : AE3007A2 Serial # CAE-313249 Part # 23087636										
753101	NO. 1 ENGINE - BLEED AIR-COMPR ACCEL VALVE ASSEMBLY 23075190 DUNHCA229 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
753302	NO. 1 ENGINE - INT LUDT HYDRAULIC ACTUATOR ASSEMBLY 23079713 SAN10241 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
754301	NO. 1 ENGINE - NO. 1 P2.5 PRESSURE TRANSDUCER SENSOR 23055446 QWKU0001949 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
754302	NO. 1 ENGINE - NO. 2 P2.5 PRESSURE TRANSDUCER SENSOR 23055446 QWKU0001694 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
ENGINE NO. 2 Model : AE3007A2 Serial # CAE-313246 Part # 23087636										
753101	NO. 2 ENGINE - BLEED AIR-COMPR ACCEL VALVE ASSEMBLY 23075190 DUNHCA233 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
753302	NO. 2 ENGINE - INT LUDT HYDRAULIC ACTUATOR ASSEMBLY 23079713 SAN10218 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
754301	NO. 2 ENGINE - NO. 1 P2.5 PRESSURE TRANSDUCER SENSOR 23055446 QWKU0001537 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
754302	NO. 2 ENGINE - NO. 2 P2.5 PRESSURE TRANSDUCER SENSOR 23055446 QWKU0001541 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
CHAPTER 76 ENGINE CONTROLS										
76-11-04-720-001-A00	FUNCTIONALLY CHECK FRICTION LOCK ASSEMBLY FOR PRE-LOAD VALUE. REF: AMM 76-11-04	MOS HRS/MSC AFL	N/A				21-JAN-2017 884.1 443			
76-12-00-710-001-A00 (s)	OPERATIONAL CHECK WOW INPUT SIGNAL TO FADEC PKG 5016 REF: AMM 76-12-00	MOS HRS/MSC AFL	96 7200 3600	+15d/-15d +20/-20 +20/-20			PKG 16-DEC-2010 0 0			
LOW UTILIZATION										
76-12-01-212-001-A00 (s)	GENERAL VISUAL INSPECTION RESOLVERS ATTACHMENTS TO THE THRUST LEVERS.(NOTE: CHECK TOGETHER WITH TASK 78-33-00-720-001-A00) PKG 5016 REF: AMM 76-12-01	MOS HRS/MSC AFL	96 7200 3600	+15d/-15d +20/-20 +20/-20			PKG 16-DEC-2010 0 0			
LOW UTILIZATION										
76-13-03-710-001-A00 (s)	OPERATIONAL CHECK IDLE LOCKOUT MICROSWITCH PKG 5001 REF: AMM 76-13-03	MOS HRS/MSC AFL	6 450	+15d/-15d +20/-20			PKG 21-JAN-2017 884.1 443			
LOW UTILIZATION										
76-20-00-710-001-A00 (s)	OPERATIONAL CHECK EMERGENCY SHUTDOWN SYSTEM. PKG 5004 REF: AMM 76-20-00	MOS HRS/MSC AFL	24 1000	+15d/-15d +20/-20			PKG 21-JAN-2017 884.1 443			
LOW UTILIZATION										
761000-0101	CREW CAB CONTROL BOX,-THRUST REVERSER/GUST LOCK,ENGINE,CTL CONSOL ASSEMBLY 145-47958-419 14501155 REF: AMM 76-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
761000-0201	C FLOOR BOX -POWER SUPPLY DIODE ASSEMBLY 145-40553-401 0000639899 REF: AMM 76-12-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
761200-0101	OVERH P CONTROL ASSY-POWER PLANT CONTROL,COCKPIT MODULE 145-30503-415 0000638507 REF: AMM 76-12-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
761200-0201	CREW CAB THRUST RATING SELECTION MODULE 145-35059-401 0000638550 REF: AMM 76-12-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			

ENGINE NO. 1 Model : AE3007A2 Serial # CAE-313249 Part # 23087636

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
761100	NO. 1 ENGINE - INT ENGINE (B) HARNESS ASSEMBLY 23061470 UM10300030 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
761101	NO. 1 ENGINE - ENGINE CONTROL WIRING HARNESS 23066759 UM09490060 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
761102	NO. 1 ENGINE - EXT ENGINE WIRING HARNESS ASSEMBLY 23062387 UM10300054 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
761103	NO. 1 ENGINE - INT ENGINE (A) HARNESS ASSEMBLY 23061469 UM10380018 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
761301	NO. 1 ENGINE - EXT-ENGINE INDICATING HARNESS ASSEMBLY 23077618 UM10290026 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
761302	NO. 1 ENGINE - INT-ENG INDICATING HARNESS ASSEMBLY 23070210 UM10340036 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
ENGINE NO. 2 Model : AE3007A2 Serial # CAE-313246 Part # 23087636										
761100	NO. 2 ENGINE - INT ENGINE (B) HARNESS ASSEMBLY 23061470 UM10330068 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
761101	NO. 2 ENGINE - ENGINE CONTROL WIRING HARNESS 23066759 UM10270024 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
761102	NO. 2 ENGINE - EXT ENGINE WIRING HARNESS ASSEMBLY 23062387 UM10260038 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
761103	NO. 2 ENGINE - INT ENGINE (A) HARNESS ASSEMBLY 23061469 UM10340012 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
761301	NO. 2 ENGINE - EXT-ENGINE INDICATING HARNESS ASSEMBLY 23077618 UM10340026 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
761302	NO. 2 ENGINE - INT-ENG INDICATING HARNESS ASSEMBLY 23070210 UM09088651 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
CHAPTER 77 ENGINE INDICATING										
774000-0101	REAR VIBRATION MONITORING-ENGINE,EVMU,REAR FUSLG I UNIT 241-244-013-002 AE96252 REF: AMM 77-41-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
ENGINE NO. 1 Model : AE3007A2 Serial # CAE-313249 Part # 23087636										
771100	NO. 1 ENGINE - NO. 1 GAS PRODUCER SENSOR 23087683 ENL469 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
771101	NO. 1 ENGINE - NO. 2 GAS PRODUCER SENSOR 23087683 ENL473 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
771103	NO. 1 ENGINE - NO. 1 FAN SPEED PICKUP SENSOR 23087704 ENA759 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
771105	NO. 1 ENGINE - NO. 2 FAN SPEED PICKUP SENSOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
772101	NO. 1 ENGINE - TURBINE (1-16) THERMOCOUPLE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
772101 (01)	NO. 1 ENGINE - NO.1 TURBINE THERMOCOUPLE 23039952 FF366769 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
772101 (02)	NO. 1 ENGINE - NO.2 TURBINE THERMOCOUPLE 23039952 FF364338 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
772101 (03)	NO. 1 ENGINE - NO.3 TURBINE THERMOCOUPLE 23039952 FF366781 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
772101 (04)	NO. 1 ENGINE - NO.4 TURBINE THERMOCOUPLE 23039952 FF366296 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
772101 (05)	NO. 1 ENGINE - NO.5 TURBINE THERMOCOUPLE 23039952 FF364190 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
772101 (06)	NO. 1 ENGINE - NO.6 TURBINE THERMOCOUPLE 23039952 FF366787 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
772101 (07)	NO. 1 ENGINE - NO.7 TURBINE THERMOCOUPLE 23039952 FF366750 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
772101 (08)	NO. 1 ENGINE - NO.8 TURBINE THERMOCOUPLE 23039952 FF364197 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
772101 (09)	NO. 1 ENGINE - NO.9 TURBINE THERMOCOUPLE 23039952 FF366778 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
772101 (10)	NO. 1 ENGINE - NO.10 TURBINE THERMOCOUPLE 23039952 FF367068 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
772101 (11)	NO. 1 ENGINE - NO.11 TURBINE THERMOCOUPLE 23039952 FF366297 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
772101 (12)	NO. 1 ENGINE - NO.12 TURBINE THERMOCOUPLE 23039952 FF367035 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
772101 (13)	NO. 1 ENGINE - NO.13 TURBINE THERMOCOUPLE 23039952 FF367033 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
772101 (14)	NO. 1 ENGINE - NO.14 TURBINE THERMOCOUPLE 23039952 FF366779 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
772101 (15)	NO. 1 ENGINE - NO.15 TURBINE THERMOCOUPLE 23039952 FF367067 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
772101 (16)	NO. 1 ENGINE - NO.16 TURBINE THERMOCOUPLE 23039952 FF364374 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
772102	NO. 1 ENGINE - T/C WIRING HARNESS 23059920 UM10130002 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
772103	NO. 1 ENGINE - T/C WIRING ASSEMBLY 23059921 UM10370120 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
774102-0101	NO. 1 ENGINE - ACCELEROMETER VIBRATION SENSOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
774102-0102	NO. 1 ENGINE - ACCELEROMETER VIBRATION SENSOR 23087686 EG90326 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
ENGINE NO. 2 Model : AE3007A2 Serial # CAE-313246 Part # 23087636										
771100	NO. 2 ENGINE - NO. 1 GAS PRODUCER SENSOR 23087683 ENL420 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
771101	NO. 2 ENGINE - NO. 2 GAS PRODUCER SENSOR 23087683 ENL399 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
771103	NO. 2 ENGINE - NO. 1 FAN SPEED PICKUP SENSOR 23087704 ENA753 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
771105	NO. 2 ENGINE - NO. 2 FAN SPEED PICKUP SENSOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
772101	NO. 2 ENGINE - TURBINE (1-16) THERMOCOUPLE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
772101 (01)	NO. 2 ENGINE - NO.1 TURBINE THERMOCOUPLE 23039952 FF366324 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
772101 (02)	NO. 2 ENGINE - NO.2 TURBINE THERMOCOUPLE 23039952 FF366323 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
772101 (03)	NO. 2 ENGINE - NO.3 TURBINE THERMOCOUPLE 23039952 FF366322 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
772101 (04)	NO. 2 ENGINE - NO.4 TURBINE THERMOCOUPLE 23039952 FF366343 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
772101 (05)	NO. 2 ENGINE - NO.5 TURBINE THERMOCOUPLE 23039952 FF366555 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
772101 (06)	NO. 2 ENGINE - NO.6 TURBINE THERMOCOUPLE 23039952 FF366495 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
772101 (07)	NO. 2 ENGINE - NO.7 TURBINE THERMOCOUPLE 23039952 FF366520 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
772101 (08)	NO. 2 ENGINE - NO.8 TURBINE THERMOCOUPLE 23039952 FF366513 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
772101 (09)	NO. 2 ENGINE - NO.9 TURBINE THERMOCOUPLE 23039952 FF366524 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
772101 (10)	NO. 2 ENGINE - NO.10 TURBINE THERMOCOUPLE 23039952 FF366500 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
772101 (11)	NO. 2 ENGINE - NO.11 TURBINE THERMOCOUPLE 23039952 FF366521 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
772101 (12)	NO. 2 ENGINE - NO.12 TURBINE THERMOCOUPLE 23039952 FF366510 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
772101 (13)	NO. 2 ENGINE - NO.13 TURBINE THERMOCOUPLE 23039952 FF366525 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
772101 (14)	NO. 2 ENGINE - NO.14 TURBINE THERMOCOUPLE 23039952 FF366514 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
772101 (15)	NO. 2 ENGINE - NO.15 TURBINE THERMOCOUPLE 23039952 FF366506 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
772101 (16)	NO. 2 ENGINE - NO.16 TURBINE THERMOCOUPLE 23039952 FF366507 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
772102	NO. 2 ENGINE - T/C WIRING HARNESS 23059920 UM10360018 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
772103	NO. 2 ENGINE - T/C WIRING ASSEMBLY 23059921 UM10340076 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
774102-0101	NO. 2 ENGINE - ACCELEROMETER VIBRATION SENSOR 23087686 EG90174 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
774102-0102	NO. 2 ENGINE - ACCELEROMETER VIBRATION SENSOR 23087686 EG90243 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
CHAPTER 78	EXHAUST									
78-10-01-212-002-A00 (s)	INSPECT (GENERAL VISUAL) PLAIN EXHAUST ASSY FOR DAMAGE, FAILURE OR IRREGULARITIES.(NOTE : NOT APPLICABLE TO AIRCRAFT WITH THRUST REVERSERS INSTALLED).						PKG			
	PKG 5012	MOS	72	+15d/-15d			21-JAN-2017			
LOW UTILIZATION	REF: AMM 78-10-01	HRS/MSC	5400	+20/-20			884.1			
		AFL	2700	+20/-20			443			
78-31-00-220-001-A00 (s)	INSPECT (DETAILED INSPECTION) THRUST REVERSER STRUCTURE						PKG			
	PKG 5012	MOS	72	+15d/-15d			21-JAN-2017			
LOW UTILIZATION	REF: AMM 78-31-00	HRS/MSC	3000	+20/-20			884.1			
		AFL	1500	+20/-20			443			

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
78-32-00-211-001-A00 (s)	VISUAL CHECK THRUST REVERSER 1RY AND 3RY LOCKS PKG 5001	MOS	12	+15d/-15d			PKG 21-JAN-2017 884.1			
LOW UTILIZATION	REF: AMM 78-32-00	AFL	500	+20/-20			443			
78-32-00-710-001-A00 (s)	OPERATIONAL CHECK THRUST REVERSER (TR) SECONDARY (2RY) AND TERTIARY (3RY) LOCKS PKG 5002	MOS	12	+15d/-15d			PKG 21-JAN-2017 884.1			
LOW UTILIZATION	REF: AMM 78-32-00	AFL	500	+20/-20			443			
78-33-00-710-001-A00 (s)	OPERATIONAL CHECK AIR/GROUND INPUT SIGNAL TO THRUST REVERSER (TR) SYSTEM PKG 5002	MOS	12	+15d/-15d			PKG 21-JAN-2017 884.1			
LOW UTILIZATION	REF: AMM 78-33-00	AFL	500	+20/-20			443			
78-33-00-710-002-A00 (s)	OPERATIONAL CHECK WHEEL-SPEED INPUT SIGNAL TO THE THRUST REVERSER SYSTEM PKG 5002	MOS	12	+15d/-15d			PKG 21-JAN-2017 884.1			
LOW UTILIZATION	REF: AMM 78-33-00	AFL	500	+20/-20			443			
78-33-00-720-001-A00 (s)	FUNCTIONAL CHECK THRUST-REVERSER (TR) CONTROL-LEVER MICROSWITCHES PKG 5016	MOS	96	+15d/-15d			PKG 16-DEC-2010 0			
LOW UTILIZATION	REF: AMM 78-33-00	AFL	7200 3600	+20/-20 +20/-20			0			
78-33-01-710-001-A00 (s)	OPERATIONAL CHECK ISOLATION CONTROL UNIT (ICU) PKG 5002	MOS	12	+15d/-15d			PKG 21-JAN-2017 884.1			
LOW UTILIZATION	REF: AMM 78-33-01	AFL	500	+20/-20			443			
78-34-00-710-001-A00 (s)	OPERATIONAL CHECK THRUST-REVERSER (TR) INDICATING SYSTEM PKG 5012	MOS	72	+15d/-15d			PKG 21-JAN-2017 884.1			
LOW UTILIZATION	REF: AMM 78-34-00	AFL	3000 1500	+20/-20 +20/-20			443			
78-34-01-720-001-A00	FUNCTIONAL CHECK STOW/TRANSIT THRUST REVERSER MICROSWITCHES FOR INSULATION PRE-MOD S.B. 145LEG-78-0006. (ELECTRICAL TEST) . (L600 ONLY)	MOS					27-NOV-2011 27.23			
SYSTEM	REF: AMM 78-34-01	AFL	N/A				19			
78-Z416-213-001-A00 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 416 AND 426) PKG 5004	MOS	24	+15d/-15d			PKG 21-JAN-2017 884.1			
LOW UTILIZATION	REF: AMM 05-20-74	AFL	1000	+20/-20			443			
78-Z416-213-001-A01 (s)	GENERAL VISUAL INSPECTION (EXTERNAL) (ZONES 416 AND 426). NOTE: FOR AIRCRAFT WITHOUT THRUST REVERSERS ONLY. PKG 5008	MOS	48	+15d/-15d			PKG 26-JAN-2015 532.4			
LOW UTILIZATION	REF:	AFL	3600 1800	+20/-20 +20/-20			280			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
78-Z416-214-001-A00	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 416 AND 426) (L600 ONLY)	MOS					16-DEC-2010			
	REF:	HRS/MSC	N/A				0			
		AFL					0			
78-Z416-214-001-A01 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 416 AND 426). NOTE: FOR AIRCRAFT WITHOUT THRUST REVERSERS ONLY.						PKG			
	PKG 5008	MOS	48	+15d/-15d			26-JAN-2015			
	REF:	HRS/MSC	3600	+20/-20			532.4			
		AFL	1800	+20/-20			280			
LOW UTILIZATION										
78-Z416-214-001-A02 (s)	GENERAL VISUAL INSPECTION (INTERNAL) (ZONES 416 AND 426). NOTE: EWIS. (L650 ONLY)						PKG			
	PKG 5004	MOS	24	+15d/-15d			21-JAN-2017			
	REF: AMM 05-20-74	HRS/MSC	1000	+20/-20			884.1			
		AFL					443			
LOW UTILIZATION										
783000-0201	LH ENG THRUST REVERSER ASSEMBLY									
	145-79600-407	MOS				TSN:0	16-DEC-2010			
	TR2057	HRS/MSC	O/C			TSN:0	0			
	REF: AMM 78-31-01	AFL				TSN:0	0			
783000-0202	RH ENG THRUST REVERSER ASSEMBLY									
	145-79600-407	MOS				TSN:0	16-DEC-2010			
	TR2055	HRS/MSC	O/C			TSN:0	0			
	REF: AMM 78-31-01	AFL				TSN:0	0			
783101-0101	LEFT UPPER THRUST REVERSER DOOR									
	145-79603-403	MOS				TSN:0	16-DEC-2010			
	UPD2055	HRS/MSC	O/C			TSN:0	0			
	REF: See Workcard	AFL				TSN:0	0			
783101-0102	LEFT LOWER THRUST REVERSER DOOR									
	145-79604-403	MOS				TSN:0	16-DEC-2010			
	LPD2055	HRS/MSC	O/C			TSN:0	0			
	REF: See Workcard	AFL				TSN:0	0			
783101-0103	RIGHT UPPER THRUST REVERSER DOOR									
	145-79603-403	MOS				TSN:0	16-DEC-2010			
	UPD2057	HRS/MSC	O/C			TSN:0	0			
	REF: See Workcard	AFL				TSN:0	0			
783101-0104	RIGHT LOWER THRUST REVERSER DOOR									
	145-79604-403	MOS				TSN:0	16-DEC-2010			
	LPD2057	HRS/MSC	O/C			TSN:0	0			
	REF: See Workcard	AFL				TSN:0	0			
783201-0101	LEFT UPPER PIVOT DOOR ACTUATOR									
	TY2039-14A	MOS				TSN:0	16-DEC-2010			
	4366	HRS/MSC				TSN:0	0			
	REF:	AFL	60250			TSN:0	0	60250		59800
LIFE LIMIT										
783201-0102	LEFT LOWER PIVOT DOOR ACTUATOR									
	TY2039-14A	MOS				TSN:0	16-DEC-2010			
	4351	HRS/MSC				TSN:0	0			
	REF:	AFL	60250			TSN:0	0	60250		59800
LIFE LIMIT										

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
783201-0103	RIGHT UPPER PIVOT DOOR ACTUATOR TY2039-14A 4372	MOS HRS/MSC AFL	60250	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0		60250	59800
LIFE LIMIT	REF:									
783201-0104	RIGHT LOWER PIVOT DOOR ACTUATOR TY2039-14A 4371	MOS HRS/MSC AFL	60250	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0		60250	59800
LIFE LIMIT	REF:									
783202-0101	LEFT 90 DEG PRIMARY DOOR LOCK ACTUATOR TY2038-02A 61454	MOS HRS/MSC AFL	60250	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0		60250	59800
LIFE LIMIT	REF: AMM 78-32-02									
783202-0102	LEFT 270 DEG PRIMARY DOOR LOCK ACTUATOR TY2038-02A 61455	MOS HRS/MSC AFL	60250	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0		60250	59800
LIFE LIMIT	REF: AMM 78-32-02									
783202-0103	RIGHT 90 DEG PRIMARY DOOR LOCK ACTUATOR TY2038-02A 61451	MOS HRS/MSC AFL	60250	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0		60250	59800
LIFE LIMIT	REF: AMM 78-32-02									
783202-0104	RIGHT 270 DEG PRIMARY DOOR LOCK ACTUATOR TY2038-02A 61450	MOS HRS/MSC AFL	60250	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0		60250	59800
LIFE LIMIT	REF: AMM 78-32-02									
783205-0101	LEFT UPPER TERTIARY LOCK TY2560-01A 04274	MOS HRS/MSC AFL	61500	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0		61500	61050
LIFE LIMIT	REF: AMM 78-32-05									
783205-0102	LEFT LOWER TERTIARY LOCK TY2560-01A 04273	MOS HRS/MSC AFL	61500	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0		61500	61050
LIFE LIMIT	REF: AMM 78-32-05									
783205-0103	RIGHT UPPER TERTIARY LOCK TY2560-01A 64270	MOS HRS/MSC AFL	61500	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0		61500	61050
LIFE LIMIT	REF: AMM 78-32-05									
783205-0104	RIGHT LOWER TERTIARY LOCK TY2560-01A 64269	MOS HRS/MSC AFL	61500	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0		61500	61050
LIFE LIMIT	REF: AMM 78-32-05									
783301-0101	LH REAR ISOLATION ASSY-THRUST REVERSER VALVE TY2041-03A 2159	MOS HRS/MSC AFL	60250	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0		60250	59800
LIFE LIMIT	REF: AMM 78-33-01									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
783301-0102	RH REAR ISOLATION ASSY-THRUST REVERSER VALVE TY2041-03A 2259	MOS HRS/MSC AFL					21-JAN-2017 884.1 443			60232
LIFE LIMIT	REF: AMM 78-33-01		60250	TSN:21 TSN:11					60682	
783305-0101	LEFT DIRECTIONAL CONTROL UNIT PN SN-UNKNOWN	MOS HRS/MSC AFL					16-DEC-2010 0 0			59800
LIFE LIMIT	REF: AMM 78-33-05		60250	TSN:0 TSN:0 TSN:0					60250	
783305-0102	RIGHT DIRECTIONAL CONTROL UNIT PN SN-UNKNOWN	MOS HRS/MSC AFL					16-DEC-2010 0 0			59800
LIFE LIMIT	REF: AMM 78-33-05		60250	TSN:0 TSN:0 TSN:0					60250	
783305-0201	LEFT LOCK SEQUENCER TY2047-03B 2139	MOS HRS/MSC AFL					16-DEC-2010 0 0			59800
LIFE LIMIT	REF:		60250	TSN:0 TSN:0 TSN:0					60250	
783305-0202	RIGHT LOCK SEQUENCER TY2047-03B 2137	MOS HRS/MSC AFL					16-DEC-2010 0 0			59800
LIFE LIMIT	REF:		60250	TSN:0 TSN:0 TSN:0					60250	
CHAPTER 79 OIL										
79-23-01-960-002-A00 (s)	DISCARD OIL FILTER PKG 5004	MOS HRS/MSC AFL	24 1000	+15d/-15d +20/-20			PKG 21-JAN-2017 884.1 443			
LOW UTILIZATION	REF: AMM 79-23-01									
79-34-00-212-001-A01	INSPECT (GENERAL VISUAL) MFD FOR ENG 1(2) OIL DEBRIS FOR ENGINE AE3007A1E OR AE3007A2 MAINTENANCE MESSAGE (NOTE: IF INSTALLED). PKG 1	DAYS HRS/MSC AFL	30 70				22-MAR-2017 903.3 450	21-APR-2017 973.3		11 d 70
ROUTINE	REF: AMM 79-34-00									
ENGINE NO. 1 Model : AE3007A2 Serial # CAE-313249 Part # 23087636										
790010	NO. 1 ENGINE - CHANGE OIL	MOS HRS/MSC ENC	A/R				14-OCT-2010 0 0			
REF: GENERIC NO REF										
791101	NO. 1 ENGINE - OIL TANK ASSEMBLY 23079447 XJ10196	MOS HRS/MSC ENC	O/C				14-OCT-2010 0 0			
REF: GENERIC NO REF										
792101	NO. 1 ENGINE - LUBE/SCAVENGE PUMP ASSEMBLY 23079382 QV507668	MOS HRS/MSC ENC	O/C				14-OCT-2010 0 0			
REF: GENERIC NO REF										

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
792103	NO. 1 ENGINE - OIL PRESS/TEMP SENSOR 23073715 QWKU0000453 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
792301	NO. 1 ENGINE - OIL FILTER ASSEMBLY 23087914 WQ209D REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
792501	NO. 1 ENGINE - OIL AIR COOLED COOLER 23075194 VR3345 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
792503	NO. 1 ENGINE - OIL-FUEL COOLED COOLER 23077047 VR3689 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
792507	NO. 1 ENGINE - NO. 1 P2.5 TRANSDUCER 23088647 QWKU0000845 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
792508	NO. 1 ENGINE - NO. 2 P2.5 TRANSDUCER 23088647 QWKU0000721 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
792509	NO. 1 ENGINE - RTD TOTAL TEMP SENSOR 23087684 RTAN985 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
793005-0101	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OIL TANK REF: MM 3007A-73-009	MOS HRS/MSC ENC	N/A				19-DEC-2013 295.1 168			
793301	NO. 1 ENGINE - LOW OIL PRESSURE SWITCH 23078098 KB12376 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
793704	NO. 1 ENGINE - MAGNETIC-INDICATE PLUG 23087999 AA39533 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-OCT-2010 0 0			
ENGINE NO. 2 Model : AE3007A2 Serial # CAE-313246 Part # 23087636										
790010	NO. 2 ENGINE - CHANGE OIL REF: GENERIC NO REF	MOS HRS/MSC ENC	A/R				05-OCT-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
791101	NO. 2 ENGINE - OIL TANK ASSEMBLY 23079447 XJ10609 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
792101	NO. 2 ENGINE - LUBE/SCAVENGE PUMP ASSEMBLY 23079382 QV507665 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
792103	NO. 2 ENGINE - OIL PRESS/TEMP SENSOR 23073715 QWKU0000459 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
792301	NO. 2 ENGINE - OIL FILTER ASSEMBLY 23087914 WQ198D REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
792501	NO. 2 ENGINE - OIL AIR COOLED COOLER 23075194 VR3331 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
792503	NO. 2 ENGINE - OIL-FUEL COOLED COOLER 23077047 VR3694 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
792507	NO. 2 ENGINE - NO. 1 P2.5 TRANSDUCER 23088647 QWKU0001035 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
792508	NO. 2 ENGINE - NO. 2 P2.5 TRANSDUCER 23088647 QWKU0001034 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
792509	NO. 2 ENGINE - RTD TOTAL TEMP SENSOR 23087684 RTAN961 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
793005-0101	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OIL TANK REF: MM 3007A-73-009	MOS HRS/MSC ENC	N/A				19-DEC-2013 295.1 168			
793301	NO. 2 ENGINE - LOW OIL PRESSURE SWITCH 23078098 KB12230 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			

Status Report

EMB-135BJ - LEGACY 650 S/N 14501134 (PK-RJA): 903.3 HRS, 450 AFL as of 18-Mar-2017

Owner/Operator: PT. PREMIAIR

Report Date: 10-APR-2017

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	TIME REMAINING
793704	NO. 2 ENGINE - MAGNETIC-INDICATE PLUG 23087999 AA39515 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			05-OCT-2010 0 0			
CHAPTER 80 STARTING										
80-10-01-720-001-A00 (s)	FUNCTIONALLY CHECK AIR TURBINE STARTER (ATS) INCLUDING OIL SERVICING. PKG 5001	MOS HRS/MSC AFL	6 250	+15d/-15d +20/-20			PKG 21-JAN-2017 884.1 443			
LOW UTILIZATION	REF: AMM 80-10-01									
80-10-02-160-001-A00 (s)	SERVICE (CLEANING) STARTER CONTROL VALVE FILTER PKG 5008	MOS HRS/MSC AFL	48 3600 1800	+15d/-15d +20/-20 +20/-20			PKG 26-JAN-2015 532.4 280			
LOW UTILIZATION	REF: AMM 80-10-02									
801100-0101	LH ENG PNEUMATIC STARTER UNIT 3505910-6 2482 REF:	MOS HRS/MSC AFL	O/C	TSN:1756 TSO:833 TSR:0			13-JUL-2011 26 15			
801100-0102	RH ENG PNEUMATIC STARTER UNIT 3505910-6 2810 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
801100-0201	LH ENG BUTTERFLY TYPE,STARTER SYS SHUTOFF VALVE 3215358-2 2553 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			
801100-0202	RH ENG BUTTERFLY TYPE,STARTER SYS SHUTOFF VALVE 3215358-2 2552 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2010 0 0			